Origina	What else prevents you from cycling, or cycling more?	Date	Summary of comment	Identifiabl	Priority	Quick	Short	Long	Disability	Weather	Poor	Lack of /	Poor	Luggage	Law /	Preferen	No	Journey	Poor	Secure	Air	Too busy	No bike /	Cycle	Ban	Other	Other				
	Tab methodology: This is a manual subjective log of 'other' comments from question 1.								59	37	35	25	23	22	14	12	12	11	9	7	4	3	2	2	4	10	0				
001	pollution	06/04/23	Air quality																		1										
002	Knee injury	06/04/23	Injury						1																						
003	Age	06/04/23	Age						1																						
004	My health	06/04/23	Health						1																						
005	I am disabled	06/04/23	Disability						1																						
006	Unable to cycle. Due to bed knees and vertigo	06/04/23	Health						1																						
007	I'm not fit enough	06/04/23	Health						1																						
008	My age, 76	06/04/23	Age						1																						
009	escooter, pedestrians, and e-bikes competing for space. Borough is not enforcing laws on ecycles use.	06/04/23	Improve e-scooter / e-bike behaviour & enforcement	1			1								1											1	e-scooter / e-bikes				
010	Poor driver behaviour, often hostile and inconsiderate, 20 mph resctriction is only obeyed by tiny minority.	06/04/23	Poor driver behaviour										1		1																
011	Hills and not having a direct route anyway useful	06/04/23	Cycle infrastructure / geography							1		1																			
012	The weather	06/04/23	Weather							1																					
013	I'm nearly 67 and haven't been on a bike since I was 12. Balance, age etc. I have no intention of learning to ride a bike again at my age.	06/04/23	Age						1																						
014	Cycling lanes are bumpy and poorly maintained, not to mention largely unprotected	06/04/23	Poor highway conditions and cycle infrastructure								1	1																			
015	Time and fitness	06/04/23	Time / fitness						1									1													
016	Rain, cold, carrying shopping or heavy items...	06/04/23	Weather / Luggage							1				1																	
017	Poor road surfaces	06/04/23	Poor highway conditions								1																				
018	Pot holes and rat runs	06/04/23	Poor highway conditions and poor driver behaviour								1		1																		
019	Other cyclists who disregard safety of pedestrians as they cross the road and walk on footpaths. They disregard red lights and act above the law. ALL adults should be registered, pass a test and have bikes taxed to put in funds for road improvements and safety. The	06/04/23	Poor cycle behaviour, test / register / tax cyclists, cyclists registration,	1			1	1							1				1					1							
020	I can cycle but prefer to walk or use public transport. Would like to see preference given to these more inclusive forms of travel across the Borough.	06/04/23	Preference for walking / public transport													1															
021	I did a lot of cycling in the countryside in my teens, but gave it up once I moved to London, because it simply cannot be safe to be sharing the road with cars, buses and trucks. I walk everywhere and use public transport if carrying loads or for greater distances. Nobody has	06/04/23	Preference for walking / public transport													1															
022	I go dinghy sailing a car journey away	06/04/23	Cargo / distance											1																	
023	roads are in very bad condition	06/04/23	Poor highway conditions								1																				
024	the physical state of the roads is poor and may force me to make dangerous manoeuvres. Some cycle lanes are not kept clear of vehicles or debris and not swept or become flooded because the drains are not being kept free-flowing	06/04/23	Poor highway conditions								1				1																
025	Health	06/04/23	Health						1																						
026	the weather	06/04/23	The weather							1																					
027	I hate cyclists. I'm almost hit by them many times. Ban cycling!	06/04/23	Ban cycling																						1						
028	Weather. Crazy drivers on the road. Local area doesn't have many places just to go and cycle	06/04/23	Weather / poor driver behaviour / destinations							1			1		1																
029	Poor road surface in dedicated cycle lanes	06/04/23	Poor highway								1																				

030	Bike in need of repair	06/04/23	Bike repair																					1											
031	Appallingly low standards of cycle lane marking,zero obstruction enforcement particularly outside fast food shops,appallingly bad carriageway maintenance ,potholes in abundance ,lack of debris clearance,broken glass remains of car bumpers etc Zero enforcement of	06/04/23	Highways, enforcement, street cleaning,								1				1																			
032	We are too old. Think about people who need cars to get around.	06/04/23	Age						1																										
033	dont want to	06/04/23	Preference														1																		
034	Cold, wet, sweaty. insufficient carrying capacity, range. I regard it as a leisure activity, not a serious mode of transport	06/04/23	Weather, cargo							1				1																					
035	weather; inconvenience of getting bike out of storage to go somewhere	06/04/23	Weather, convenience							1														1											
036	Potholes. Risk of bike theft while eg popping into a shop.	06/04/23	Highway condition, bike theft								1										1														
037	Poor weather and dark evenings	06/04/23	Weather / light							1																									
038	Poor road surface	06/04/23	Highways								1																								
039	Speeding by drivers, lack of speed enforcement, aggressive (or oblivious) drivers	06/04/23	Poor driver behaviour										1		1																				
040	I prefer weights exercise, as it's better for me.	06/04/23	Preference																																
041	cycling routes through Northala park and rectory park are a bit dangerous. The roads are not smooth and some paths are not surfaced properly. I used to take my children to school using this route but on several occasions the bikes and scooters get damaged and the	06/04/23	Poor park surfaces	1			1				1																								
042	I cannnot cycle for work so need my car	06/04/23	Business car											1																					
043	Cannot carry bulky or heavy items (e.g. a big food shop) safely on my bicycle	06/04/23	Cargo											1																					
044	Speed of traffic	06/04/23	Speeding										1		1																				
045	my age and fitness level; poor weather	06/04/23	Age / weather						1	1																									
046	Don't need to	06/04/23	Preference														1																		
047	Cycling is incompatible with transporting bulky or heavy loads, such as the weekly shop	06/04/23	Cargo											1																					
048	I am disabled and cannot cycle. I know how to cycle and have used a bike in the past	06/04/23	DIsabled						1																										
049	Too busy, not convenient to cycle.	06/04/23	Convenience																					1											
050	Walking or using public transport is a far more practical way of getting around where I live.	06/04/23	Preference for walking / public transport													1																			
051	I walk and use the excellent public transport!	06/04/23	Preference for walking / public transport													1																			
052	Age - need time to recover from fairly long rides	06/04/23	Age						1																										
053	What is off-putting for cyclists is the sheer volume of traffic using main and smaller roads all throughout Ealing. I am a confident cyclist but some of the driving scares the living hell out of me sometimes. Please please get segregated cycling facilities on the main roads and	06/04/23	Traffic volumes, lack of segregation	1				1				1	1																					
054	Bad weather and poor road surfaces (ruts and potholes)	06/04/23	Weather, road surfaces							1	1																								
055	health and age	06/04/23	Health and age						1																										
056	Too much sports equipment, large volume of shopping	06/04/23	Cargo											1																					
057	Poorly maintained roads by the council. Too many potholes to negotiate	06/04/23	Potholes								1																								
058	The weather	06/04/23	Weather							1																									
059	Amputee	06/04/23	Disabled						1																										

060	I'm in a wheelchair now following a cycling accident. I hope to get back to cycling one day.	06/04/23	Disabled						1																										
061	The roads are not wide enough for vehicles and bicycles. The laws need to be tougher on helmets being worn and some sort of insurance against accidents caused by any road user.	06/04/23	Infrastructure, cycling laws	1								1													1										
062	Age and decrepitude	06/04/23	Age / health						1																										
063	Pot holes on the road especially on the left near pavements. Makes me need to drift my bike to the busier centre of road to avoid them	06/04/23	Road condition								1																								
064	It's something I enjoy for leisure. I prefer walking, or using a bus, tube or train for most journeys. It's quicker, easier with a heavy load (my work bag or children) and no one is going to nick the tube. I can cycle, I simply do not want to. It's nothing to do with the roads	06/04/23	Preference for walking / public transport														1																		
065	I am getting older and it is more comfortable to use the car	06/04/23	Age and comfort						1																										
066	Owned and used a cycle for leisure and keeping fit, mainly cycling in parks like Gunnersbury and Blondine. Now too old to cycle (age 82) so use public transport or car when its not possible to use buses etc. Noted that some cycle lanes are a waste of money (eg Boston Rd)	06/04/23	Age						1																				1						
067	bad knees and vertigo	06/04/23	Health						1																										
068	Aggressive drivers and other cyclists on the road	06/04/23	Poor behaviour of other road users										1								1														
069	Two broken knees and 2.5 ins missing from one leg	06/04/23	Health						1																										
070	Disabled	06/04/23	Disability						1																										
071	Age	06/04/23	Age						1																										
072	Dangerous & impatient driving	06/04/23	Poor driver behaviour						1				1																						
073	Bad condition of roads, pot holes, worn and broken surfaces, tracking from vehicles meaning I have to pull out and position myself on parts of the road that other vehicles consider inconsiderate cycling. Also the traffic calming humps between Walpole and lamas	06/04/23	Potential issue on Dorset Road at junction with Gloucester Road. Poor highways. Humps between	1	1		1				1																								
074	Medical disability	06/04/23	Disability						1																										
075	I am 73 years old, have osteoporosis, osteoarthritis, spondylitis	06/04/23	Disability						1																										
076	Rain	06/04/23	Weather							1																									
077	Weather. Distance.	06/04/23	Weather and distance							1									1																
078	I am old and disabled, and was SEVERELY upset by LTNs and how it blighted my life. Many cyclists I find are very aggressive and have a strong sense of entitlement to the area we all live in...	06/04/23	Disabled						1											1														
079	Cycling is just a joke - as our local council, you have been given money to support all "Active" forms of travel, yet just about every penny of this money thus far has been spent on cycling, even though the numbers who cycle (or are ever likely to take-up cycling) would be vastly -	06/04/23	No reason - just a complaint about money only being spent on cycling																																
080	Other cyclists, especially the lycra types that jump red lights all the time. So annoying!	06/04/23	Poor cycle behaviour																	1														
081	Health reasons	06/04/23	Health						1																										
082	I prefer to walk. Better for the environment than cycling. Keep bikes off pavements so pedestrians are safe	06/04/23	Preference														1																		
083	Poor or no consideration of how cycle routes start, end, and deal with junctions	06/04/23	Lack of fully integrated cycle routes									1																							
084	The physical condition/state of the tarmac surfaces (rough patch repairs, loose/dropped access covers and defects otherwise considered 'minor' for motor vehicles severely impact both the safety AND comfort of cycling more than motorised transport including buses).		Poor highways								1																								
085	The cycle lanes are inconsistent. Sometimes they are very helpful, sometimes they stop suddenly forcing you to merge with traffic. A more consistent and comprehensive set of cycle lanes would encourage me to cycle more. I'd also be a more vocal advocate for cycling	06/04/23	Lack of fully integrated cycle routes									1																							
086	Lack of distinct cycle lanes in west ealing	06/04/23	Infrastructure in West Ealing	1			1	1				1																							
087	It's no use for shopping. I'm a pensioner and need my car. I live on a hill!	06/04/23	Cargo / Hill / Age						1	1				1																					
088	Thanks to my disability I cannot ride a bicycle	06/04/23	Disability						1																										
089	Long commute to work so have to use tube	06/04/23	Distance																1																

090	Children to get places with equipment/bags	06/04/23	Children / Cargo										1																					
091	Time. Weather. Potholes. Inconsiderate drivers	06/04/23								1	1		1					1																
092	I prefer to drive	06/04/23														1																		
093	The weather	06/04/23								1																								
094	Cycling should be discouraged in Ealing. Cyclists are slowing down traffic, and causing more danger for other vehicles and pedestrians. As Tax payer to Ealing council, I strongly urge Ealing council to ditch the cycling lanes idea. Residents need wider quicker roads for cars	06/04/23	Remove cycle infrastructure	1				1																		1							
095	Weather	07/04/23								1																								
096	I don't want to cycle. I want to be able to get to work on time on public transport or my own mode be it by car	07/04/23	Preference													1	1																	
097	I don't want to	07/04/23	Preference														1																	
098	I have an autistic grandson who lives 6 miles away and who I have to pick up from school.i slso look after his baby brother and at my age certainly cant take him around on my bike!	07/04/23	Various						1				1					1																
099	Age, carrying shopping	07/04/23							1				1																					
100	Too many cars - I live in a residential area that used to be an LTN but the council ripped it out and now rat run traffic is too dangerous to risk cycling. Have sold all family bikes.	07/04/23										1	1																					
101	I used to cycle to Ealing station and leave my bike to commute in. A couple of times it's been vandalised so then I am unable to cycle home. I tend to cycle now for pleasure as I am scared about leaving it in public spaces. It's crime that stops me more. I am also a fair	07/04/23								1										1														
102	Need to travel further afield with work	07/04/23											1																					
103	Sore backside	07/04/23							1																									
104	Injury, hills, safety at night, inconvenient and dangerous cycle paths (too narrow, suddenly finishing, difficult to cross main roads eg over ealing common. Not enough bike priority areas at front of lights eg where gunnersbury lane crosses A406, poor maintenance or	07/04/23	Lots of general improvements which have been identified within the other questions	1			1	1	1	1	1	1														1	Personal safety							
105	I often need to carry substantial items with me and/or travel longer distances. Plus it rains regularly and I don't enjoy the faff of getting wet.	07/04/23								1			1					1																
106	Weather	07/04/23								1																								
107	I work too far away to cycle on my regular commute	07/04/23																1																
108	Poor road surfaces	07/04/23					1				1																							
109	Lack of time and opportunity	07/04/23																					1											
110	disabled	07/04/23							1																									
111	mostly have to carry shopping	07/04/23											1																					
112	I cycle when needed	07/04/23																																
113	Too much traffic, too many accident.	07/04/23											1																					
114	The state of the roads. Many, particularly on the nearside of carriageways, have potholes, ruts and large puddles after rain. Uxbridge Road between Hanwell and Ealing Broadway is a classic example. Additionally, illegally parked cars, see the westbound carriageway in West	07/04/23	Various concerns also established in Q2 and Q3	1			1	1			1			1																				
115	too many dangerous joy riders showing off, cycling at a great speed	07/04/23											1						1															
116	I'm not super fit (I'm a 61 year old overweight Woman)	07/04/23							1																									
117	Weather, distance, time, sweating, fatigue	07/04/23								1								1																
118	Aggressive car drivers	07/04/23											1																					
119	I don't want to and physically can't. I ealk everywhere and use public transport.	07/04/23							1							1	1																	

120	Age	07/04/23							1																															
121	Ealing is a car-infested hellhole	07/04/23											1																											
122	Long Covid post exertion malaise	07/04/23							1																															
123	The weather	08/04/23								1																														
124	I cycled as a student but as a middle aged adult I am no longer interested in cycling. Prefer walking, catching the bus or driving as appropriate.	08/04/23														1	1																						
125	not practical for time reasons, weather, and need to haul family plus their sports gear.	08/04/23								1				1				1																					
126	2 children with lots of bags and music and sports equipment to get around on tight deadlines	08/04/23												1				1																					
127	Huge amount of parking in cycle lanes	08/04/23	Cycle lane parking	1			1								1																							
128	Danger from other vehicles. Most roads are car dominated, there's no enforcement of rules such as speeding, safe passing distamces, road hierarchy. Added danger of growing anger against cyclists. I have been purposely.driben st and even driven into on Ealing	08/04/23											1		1																							
129	Being cut up by scooters (motor, not E)	08/04/23											1																										
130	I am disable with mobility problem as well as I am over 70 I can not cycle , do not know, do want to risk my life neither have energy. I do not want to learn either cycling. Council seems to think everyone should cycle unrealistic thinking.	08/04/23							1																													
131	The quality of the roads	09/04/23									1																												
132	Lack of Motivation	09/04/23															1																						
133	weather	09/04/23								1																														
134	Health. No nearby public transport so have to use car	09/04/23							1																															
135	While I feel confident cycling I do not feel comfortable cycling with my children	09/04/23							1					1																									
136	I just don't want to cycle everywhere when it is raining or I am wearing nice clothes or need to carry stuff. Cycling will never replace a good public transport network so you shouldn't neglect and further deplete bus routes.	09/04/23								1				1																								1	Doesn't want bus routes
137	Disability	09/04/23							1																														
138	I'm a pensioner and even if I were to cycle I would be afraid of the appalling behaviour of other cyclists - on the pavement, no lights at night etc etc	10/04/23							1														1																
139	Never learnt due to poor balance.	10/04/23							1																														
140	The weather	10/04/23								1																														
141	Lack of street lights and holes in the road	10/04/23									1																													
142	age, weather, and endemic bike theft	10/04/23							1	1													1																
143	Mobility disability	10/04/23							1																														
144	I was side swiped by a Lynx lorry when cycling on the road and still have residual problems	10/04/23							1																														
145	Poor quality roads, badly designed cycle paths, can't to weekly shop on one	10/04/23									1	1		1																									
146	I am disabled, and have to drive to go anywhere	11/04/23							1																														
147	Bike lanes that disappear or suddenly have bus stops in them, e.g., Uxbridge Road.	11/04/23										1																											
148	Bad weather	11/04/23								1																														
149	The way we are being forced to cycle, the way the council listens only to the cycle lobby, this more than anything else makes me want to not cycle	11/04/23															1																						

150	Never learned to ride a bike when young.	11/04/23																									1	Didn't learn						
151	Disability	11/04/23							1																										
152	Can't ride a bike	12/04/23																									1	Didn't learn						
153	arthritus in ankles,knees and back	12/04/23							1																										
154	The condition of the most roads with their potholes and ruts, even when they have recently been repaired.	12/04/23									1																								
155	The attitude of drivers and other traffic on the roads make me feel unsafe	13/04/23											1																						
156	Potholes and raised manhole covers and the general poor state of the roads.	13/04/23									1																								
157	I am 72 years old with osteoarthritis I used to cycle. My neighbour now has my bike	13/04/23							1																										
158	Storage at home is ok but not enough sheltered and safe places to park a bike when out.	13/04/23																		1														
159	You can hear my knees and hips grating when I cycle.	13/04/23							1																										
160	Cycle security!! My bike has been stolen 5 times	13/04/23																		1															
161	Potholes and lorries on the roads	14/04/23									1		1																						
162	Safe parking of bike	15/04/23																		1															
163	I am 78 and not fit so I use my car to get about. This is true of many older residents but no-one takes that into accounts as The Mayor and most Councils are so obsessed with cycles and confusing cycle lanes particularly on Chiswick High Road .	15/04/23							1																										
164	The majority of male cyclists who see it as their right to cycle on the pavements, and become verbally abusive when challenged!	15/04/23																	1																
165	Age and unwillingness	16/04/23							1								1																		
166	Being forced to cycle alongside main roads - impact of breathing in all the pollution. It would be great to have more quieter routes	16/04/23										1									1														
167	Bad road surfaces, potholes	16/04/23									1																								
168	The cycle lanes are rubbish! please get rid of them, it was far safer and easier to cycle without them. I now get a false sense of safety and confidence with these awful schemes.	17/04/23										1																1							
169	Weather	18/04/23								1																									
170	Basically the weather conditions.	18/04/23								1																									
171	The Weather	19/04/23								1																									
172	The cycle lane down the Uxbridge road is a joke, especially the small bit of the Vale by the parade of shops. People permanently parked on a yellow line and in a cycle lane at all hours of the day. The traffic warders must be getting a backhander to not give anyone a	28/04/23										1			1																				
173	I am elderly but walk everywhere. The major problem I encounter is cyclist and electric scooters using the pavements at high speeds and have had several near misses with these thoughtless and dangerous people. Ealing Council should make cyclists follow rules of the	28/04/23										1							1															
174	Attitude of car drivers	28/04/23											1																						
175	Confusing state of roads with far too many cycle lanes , bus lanes roads all with own furniture signage, keep roads simple for a Safer experience	28/04/23									1	1																							
176	Terrible cycle lanes, with potholed surfaces, poor markings, and rarely with any separation from traffic	28/04/23									1	1																							
177	facilities at public locations such as secure provision and putting your cycle helmet somewhere so you don't have to carry it around	28/04/23																		1															
178	Carrying and storing of kit needed eg in bad weather. Health/pain reason. Distance vs time.	29/04/23							1	1								1																	
179	The conditions of the road surfaces in Ealing are truly terrible when compared to cycling anywhere else in London,	29/04/23									1																								

180	Lack of safe cycling routes, especially if cycling with children.	29/04/23										1																					
181	I don't need to be in the office as often anymore so don't need to do it everyday. I would other wise	29/04/23																									1	No need to travel					
182	Potholes, badly maintained roads, poor (worn out / invisible) road markings	29/04/23									1	1																					
183	Rain	29/04/23								1																							
184	Very bad cycle lane running adjacent to A40 between Northolt all the way to Acton. The new cycle lanes adjacent to the A40 start at Acton and carry on into central London,. This is quite unfair as the bulk of my route into central London, from Greenford adjacent to the	29/04/23		1			1	1				1																					
185	Age, health.	30/04/23							1																								
186	I don't want to cycle, I would rather walk then join the people who break all of the highway laws in rights of way and expect everyone from pedestrians in canal paths to drivers on the main road to give way to them when they don't have a right of way. So long as you're	30/04/23													1	1	1		1								1	Worried about loss of					
187	My age 70+	30/04/23							1																								
188	Potholes, speed humps and uneven Road surfaces in areas that don't have dedicated cycle lanes. Also, the amount of traffic and car exhaust fumes are detractors.	30/04/23									1	1									1												
189	Pot holes and glass. What are you doing? The roads are a disgrace and unsafe for cycling, particularly if you're new to cycling. Add in illegal food delivery drivers and it's a nightmare for any cyclist	01/05/23									1				1																		
190	Baby daughter not ready to be in back seat	01/05/23												1																			
191	I want to say better cycle paths would help, but far prefer better marked quiet ways and regular cycle path markings over the kind of not all that convenient, expensive and intermittent projects proposed like St Stephen's.	02/05/23										1																					
192	Lack of consistent stretches of cycle lanes. The lanes are stop start from ealing to Shepherd's Bush	02/05/23										1																					
193	Weather, and I have 3 kids	02/05/23								1				1																			
194	Hills	02/05/23								1																							
195	I don't want to. Public transport is good enough or I walk.	03/05/23														1	1																
196	Cars parked on narrow residential roads used as rat runs makes the space too narrow to safely pass oncoming vehicles that are on my side of the road.	07/05/23											1																				
197	I don't WANT to cycle anywhere!	09/05/23															1																
198	Lack of education for teaching my children to ride safely and confidently on roads.	09/05/23																									1	Lack of training					
199	I prefer to drive as I have to carry heavy kit. I also don't like to be classed as a cyclist as so many of them break so many laws and don't care about other traffic	09/05/23												1																			
200	Not all journeys are suitable for cycling.	09/05/23																				1											
201	Road quality - too many poor surfaces.	09/05/23									1																						
202	Massive potholes in the roads. It's so dangerous and feel like I need to watch the tarmac more than the hazards around me.	10/05/23									1																						
203	I work long shifts and just cycle for leisure	10/05/23																									1	Only cycle for leisure					
204	Poor standard of driving on London, Roads in particular lack of space given when overtaking. Use of door zone as bike lanes	16/05/23										1	1																				
205	Aggressive drivers bullying cyclists, honking, shouting, close passes for a few seconds. Also not giving way or indicating. Drivers complaining about cyclists but flaunting Highway Code constantly	16/05/23									1		1																				
206	Weather, uncontinuous cycling lanes, pollution on busy roads, safety	17/05/23								1		1	1								1												
					1	0	10	7	59	37	35	25	23	22	14	12	12	11	9	7	4	3	2	2	4	10	0	0	0	0	0		

Original order	Are there any existing routes / quietways that need improving? Place up to 5 pins.	Reviewed	Date	Google Maps link	Address of issue or pin	General area	Ward if known	Summary of comment	Identifiable action	Priority flag	Interesting / complicated suggestion	Valid and straight forward	Hot spot?	Quick	Short	Long	(Mainly Q3) General undefined route improvement	Uxbridge Road / A4020 etc (any section)	A406	Boston (Manor) Road	Canal / River improvements (nb quick	General poor road safety (without clear	Poor highway surfaces / potholes / lighting etc	Hedge / branch trimming	Street cleaning	Lack of cycle infrastructure	Improve cycle lane designation	Increase cycle lane physical segregation	Improve residential blue routes etc	Parking in cycle lanes	Traffic lights	Cargo bike issue or cycle lane too narrow etc	Cycle parking	Law / highway code enforcement	Poor driver behaviour	Poor cyclist behaviour	Reduce rat running	Speed bump concerns	Bus stop	Re-introduce LTNS	Personal safety	Remove cycle infrastructure etc	Remove Parking	Traffic Calming	School traffic	Other numeric	Other detail
	Tab methodology: This is a manual subjective log of comments left alongside the pin locations provided in question 2								1045	85	107	952	424	56	814	659	0	420	51	60	47	143	142	14	35	416	221	284	163	167	116	21	36	85	127	8	24	9	20	10	9	15	20	18	4	17	0
0001				https://www.google.com/maps/place/51.5504878630703%2C-0.371415053805757/@51.5504878630703,-0.371415053805757,17z																																										
0002			5/4/2023	https://www.google.com/maps/place/51.5109913747141%2C-0.302354142876724/@51.5109913747141,-0.302354142876724,17z																																										
0003			5/4/2023	https://www.google.com/maps/place/51.54989126778133%2C-0.3469011016528234/@51.54989126778133,-0.3469011016528234,17																																										
0004			5/4/2023	https://www.google.com/maps/place/51.54541942210961%2C-0.32876845135412003/@51.54541942210961,-0.32876845135412003,1																																										
0005			5/4/2023	https://www.google.com/maps/place/51.53612427381033%2C-0.40018741877967834/@51.53612427381033,-0.40018741877967834,1																																										
0006	YOU NEED TO THINK MORE ABOUT YOUR DISABLED RESIDENTS INSTEAD OF THE ABLE BODIED.	1	5/4/2023	https://www.google.com/maps/place/51.52659964198668%2C-0.28769513994536755/@51.52659964198668,-0.28769513994536755,1	26 Heathcroft, London, W5 3EZ	Park Royal		More concerned about disabled residents																																						
0007	YOU NEED TO THINK ABOUT YOUR DISABLED RESIDENTS MORE AND NOT THE ABLE BODIED ALL THE TIME.	1	5/4/2023	https://www.google.com/maps/place/51.51122980443668%2C-0.3168783989045654/@51.51122980443668,-0.3168783989045654,17	159 Uxbridge Rd, London, W13 9AU	West Ealing		More concerned about disabled residents																																						
0008	YOU NEED TO THINK ABOUT YOUR DISABLED RESIDENTS MORE AND NOT JUST THE ABLE BODIED.	1	5/4/2023	https://www.google.com/maps/place/51.510579564889746%2C-0.3211802958009935/@51.510579564889746,-0.3211802958009935,17	Ealing, London, W13 9LX	West Ealing		More concerned about disabled residents																																						
0009			5/4/2023	https://www.google.com/maps/place/51.51530235897481%2C-0.2918939053061642/@51.51530235897481,-0.2918939053061642,17																																										
0010			5/4/2023	https://www.google.com/maps/place/51.517434324469946%2C-0.2873981459621411/@51.517434324469946,-0.2873981459621411,17																																										
0011			5/4/2023	https://www.google.com/maps/place/51.52109233465007%2C-0.29156093435325436/@51.52109233465007,-0.29156093435325436,1																																										
0012			5/4/2023	https://www.google.com/maps/place/51.508392434408684%2C-0.2915061665112728/@51.508392434408684,-0.2915061665112728,17																																										
0013	I have not seen any cycle paths/cycle lanes on Olive road. Are there really any? There are just lots of parked cars.	1	6/4/2023	https://www.google.com/maps/place/51.49961556822043%2C-0.3040271685989637/@51.49961556822043,-0.3040271685989637,17	12 Olive Rd, London, W5 4JJ	South Ealing	Ealing Common	Blue route concern	1			1			1												1		1																		
0014	Uxbridge Road, is the obvious route to cycle East-West in the borough. However, the short sections of proper cycle lanes aren't joined up (stopping at junctions - the most dangerous points) and completely absent in the parts I'd like to cycle to the most (e.g. the shops in central Ealing).	1	6/4/2023	https://www.google.com/maps/place/51.51380005718896%2C-0.3030726214133894/@51.51380005718896,-0.3030726214133894,17	Haart Estate Agents, 17 The Broadway, London, W5 2NH	Ealing Broadway	Ealing Broadway	Increased cycle segregation on The Broadway in particular	1			1	1			1		1				1						1																			
0015	I cycled frequently between Ealing and Brentford/Kew/Chiswick using the route on Culmington Road during 2020. However, once it started being used as a cut-through by cars again I stopped. I now only cycle on this route early on Sundays when the traffic level is low enough.	1	6/4/2023	https://www.google.com/maps/place/51.50685561958397%2C-0.31068411982891897/@51.50685561958397,-0.31068411982891897,1	55A Culmington Rd, London, W13 9NJ	Walpole	Walpole	Cullington / Lammas rat run. Various concerns and suggestion on suggestions tab	1			1	1		1	1						1				1			1								1										
0016	Ealing is crossed by lots of train and tube lines which provide useful access, but also reduce walking/cycling routes to points where bridges exist to cross the lines. Unfortunately, many of those bridges lack any provision for cycling and have a high number of vehicles using them. As a result, these bridges are often the least comfortable part of cycle journeys.	1	6/4/2023	https://www.google.com/maps/place/51.513959502528316%2C-0.3143636623520307/@51.513959502528316,-0.3143636623520307,17	St Leonard's Rd, London, W5 2TU	Ealing Broadway	Ealing Broadway	Improve railway crossings in general, in particular St Leonards as a key north - south connection between cycle routes	1		1	1			1	1										1	1	1															1			1	Improve railway crossings
0017	Tring Avenue should be a good backstreet cycle route to get between Ealing and South Acton / Chiswick. However, the number of vehicles speeding here as a cut-through avoiding the North Circular makes it a poor route for cycling.	1	6/4/2023	https://www.google.com/maps/place/51.50623956904893%2C-0.28741805053609015/@51.50623956904893,-0.28741805053609015,1	72 Tring Ave, London W5 3QB	Ealing Common	Ealing Common	Rat running concerns	1			1			1																	1	1		1										
0018	There is a lack of viable East-West routes along Northcroft Road. Many cars use this area to cut-through and the narrow streets with many parked cars mean close passes are common here.	1	6/4/2023	https://www.google.com/maps/place/51.50208767323866%2C-0.3196285635109719/@51.50208767323866,-0.3196285635109719,17	38 Northcroft Rd, London, W13 9SX	Northfields	Northfield	Rat running concerns	1			1			1							1				1											1										
0019			6/4/2023	https://www.google.com/maps/place/51.51335900801286%2C-0.3296434839550977/@51.51335900801286,-0.3296434839550977,17																																										
0020			6/4/2023	https://www.google.com/maps/place/51.51343913073745%2C-0.32239079077882815/@51.51343913073745,-0.32239079077882815,1																																										
0021			6/4/2023	https://www.google.com/maps/place/51.51159627241708%2C-0.3307163675610547/@51.51159627241708,-0.3307163675610547,17																																										
0022			6/4/2023	https://www.google.com/maps/place/51.509673210338306%2C-0.3305447061841016/@51.509673210338306,-0.3305447061841016,17																																										
0023	Extremely dangerous and polluted	1	6/4/2023	https://www.google.com/maps/place/51.50812863138082%2C-0.2740511198722517/@51.50812863138082,-0.2740511198722517,17	239 High St, London, W3 9BY	Acton	South Acton	Styne / Uxbridge roundabout hotspot but no clear action				1	1									1																								1	Air Quality concern
0024	Cycle lane runs out. Dangerous	1	6/4/2023	https://www.google.com/maps/place/51.50684204959705%2C-0.26631562907330153/@51.50684204959705,-0.26631562907330153,1	50 High St, London, W3 6LG	Acton	South Acton	Cycle lane improvements	1			1			1			1									1																				
0025	No cycle lane. Dangerous	1	6/4/2023	https://www.google.com/maps/place/51.51428057252368%2C-0.3011199732505476/@51.51428057252368,-0.3011199732505476,17	1 The Mall, Ealing, London, W5 2PL	Ealing Broadway	Ealing Broadway	Lack of cycle infrastructure around Ealing Broadway	1			1	1		1	1		1								1																					
0026			6/4/2023	https://www.google.com/maps/place/51.520238082705184%2C-0.31090467173687575/@51.520238082705184,-0.31090467173687575,1																																										
0027	Cars constantly parked in bus / cycle lane	1	6/4/2023	https://www.google.com/maps/place/51.51169145525945%2C-0.3148992733024025/@51.51169145525945,-0.3148992733024025,17	The Castelbar, 78 Uxbridge Rd, London, W13 8RA	West Ealing	Ealing Broadway / Walpole	Bus / Cycle lane parking	1			1			1	1		1												1																	
0028	Scooters constantly blocking space	1	6/4/2023	https://www.google.com/maps/place/51.51357335656986%2C-0.30492126004122655/@51.51357335656986,-0.30492126004122655,1	Units 1/3/22C, The Arcadia Centre, 50/52 The Broadway,	Ealing Broadway	Ealing Broadway	E-scooters on pavement	1			1			1																																e-scooter / e-bikes
0029			6/4/2023	https://www.google.com/maps/place/51.50844523319395%2C-0.30925570980929296/@51.50844523319395,-0.30925570980929296,1																																										
0030	No defined space, not wide enough for cargo bike	1	6/4/2023	https://www.google.com/maps/place/51.51196146884666%2C-0.31420719317451606/@51.51196146884666,-0.31420719317451606,1	60-64 Uxbridge Rd, London, W13 8RA	West Ealing	Walpole / Ealing Broadway	Cycle lane designation	1			1			1	1		1								1	1						1														
0031	Cars drive much too fast down Gordon road, road surface is terrible for bikes.	1	6/4/2023	https://www.google.com/maps/place/51.51465893916942%2C-0.3112674920941938/@51.51465893916942,-0.3112674920941938,17	61 Gordon Rd, London, W5 2AL	Ealing	Ealing Broadway	Highway surfacing and poor driver behaviour	1			1			1								1						1					1	1												
0032	Not wide enough for bikes and pedestrians.	1	6/4/2023	https://www.google.com/maps/place/51.53183835409669%2C-0.3228803303005079/@51.53183835409669,-0.3228803303005079,17	St Mary's Church, Perivale Ln, Perivale, Greenford UB6 8SS	Pitshanger	Perivale	Narrow cycle path (possible hedge trimming etc)	1			1		1		1								1			1						1														
0033	Not possible to cycle a cargo bike here. Too many gates/ barriers that aren't wide enough.	1	6/4/2023	https://www.google.com/maps/place/51.50198142079092%2C-0.33840158162738776/@51.50198142079092,-0.33840158162738776,1	117 Studley Grange Rd, London, W7 2LU	Hanwell	Hanwell Broadway	Narrow cycle path	1			1				1																	1														
0034			6/4/2023	https://www.google.com/maps/place/51.508522704150465%2C-0.2744721708926412/@51.508522704150465,-0.2744721708926412,17																																										
0035			6/4/2023	https://www.google.com/maps/place/51.51355734271502%2C-0.3038704303314388/@51.51355734271502,-0.3038704303314388,17																																										
0036	The cycle lanes through Acton allow car parking, which means there isn't a safe lane at all, or there are a series of short stretches that cyclists have to swing in and out of and into traffic frequently, which is dangerous.	1	6/4/2023	https://www.google.com/maps/place/51.50790979856622%2C-0.2734051584113706/@51.50790979856622,-0.2734051584113706,17	216 High St, London, W3 9NX	Acton	South Acton	Cycle lane parking	1			1			1	1		1												1																	
0037			6/4/2023	https://www.google.com/maps/place/51.5074557128213%2C-0.2720318673957456/@51.5074557128213,-0.2720318673957456,17																																										
0038			6/4/2023	https://www.google.com/maps/place/51.50848407699798%2C-0.27613028277050145/@51.50848407699798,-0.27613028277050145,1																																										
0039			6/4/2023	https://www.google.com/maps/place/51.502297163617655%2C-0.316209881966798/@51.502297163617655,-0.316209881966798,17z																																										
0040			6/4/2023	https://www.google.com/maps/place/51.516878726533825%2C-0.3069188665740552/@51.516878726533825,-0.3069188665740552,17																																										
0041			6/4/2023	https://www.google.com/maps/place/51.519818101917224%2C-0.32289635374997516/@51.519818101917224,-0.32289635374997516,1																																										
0042			6/4/2023	https://www.google.com/maps/place/51.50467003079756%2C-0.32193741356629557/@51.50467003079756,-0.32193741356629557,1																																										
0043	The junction at northfields avenue is very busy and not safe on a bike. I've been knocked off my bike by a van. Also so many cars park in evening and at night	1	6/4/2023	https://www.google.com/maps/place/51.51090211994178%2C-0.3183864750449117/@51.51090211994178,-0.3183864750449117,17	217 Uxbridge Rd, London, W13 9AA	West Ealing	Hanwell Broadway / Walpole	Dean Garden / Lido hotspot junction	1			1	1		1	1		1								1	1			1	1																
0044	I don't feel safe changing lanes after the hospital	1	6/4/2023	https://www.google.com/maps/place/51.50912094657583%2C-0.35379088605090425/@51.50912094657583,-0.35379088605090425,1	14 Iron Bridge Cl, Southall UB2 4UF	Iron Bridge	Norwood Green / Southall Broadway / Dormers Wells	Lines appear faded and unclear route suggestion for continuing on Uxbridge Road. hotspot	1						1			1									1																				
0045			6/4/2023	https://www.google.com/maps/place/51.50306333748767%2C-0.2885794147964904/@51.50306333748767,-0.2885794147964904,17																																										
0046			6/4/2023	https://www.google.com/maps/place/51.51252197576567%2C-0.29197043673385936/@51.51252197576567,-0.29197043673385936,1																																										
0047			6/4/2023	https://www.google.com/maps/place/51.509637410821426%2C-0.3280193258940156/@51.509637410821426,-0.3280193258940156,17																																										
0048			6/4/2023	https://www.google.com/maps/place/51.53388343658422%2C-0.32424277560104686/@51.53388343658422,-0.32424277560104686,1																																										
0049			6/4/2023	https://www.google.com/maps/place/51.52138819839078%2C-0.26227301852096874/@51.52138819839078,-0.26227301852096874,1																																										
0050			6/4/2023	https://www.google.com/maps/place/51.50746744453655%2C-0.2679813591772917/@51.50746744453655,-0.2679813591772917,17																																										
0051			6/4/2023	https://www.google.com/maps/place/51.50642309027005%2C-0.301026792025052/@51.50642309027005,-0.301026792025052,17z																																										
0052	The shared cycle/pedestrian pavement behind the bus stop on the West side of Boston Manor Road requires clear line marking to demarcate cycle and pedestrians. Additionally the white line down the centre of the road on the Ealing (North) side requires relining.	1	6/4/2023	https://www.google.com/maps/place/51.49595529178677%2C-0.32487564751901843/@51.49595529178677,-0.32487564751901843,1	231 Boston Manor Rd, Greater, London, TW8 9LF	Boston Manor	Northfield	Improve lines North of Boston Manor. Potentially dangerous behind bus stop	1	1		1	1		1					1							1	1											1								
0053	The bus lane through Hanwell to Ealing Broadway needs to be resurfaced as it is unusable for cyclists.	1	6/4/2023	https://www.google.com/maps/place/51.51025210167391%2C-0.3242076866231236/@51.51025210167391,-0.3242076866231236,17	88 Broadway, London, W13 0SY	Hanwell	Hanwell Broadway / Walpole / Ealing Broadway	This section in particular appears poor	1			1	1		1			1					1																								
0054	Popes Lane between the junctions with Olive Road and Baronsmead Roads requires resurfacing as cycles have to cycle in the middle of the road to avoid the numerous potholes and very uneven surface.	1	6/4/2023	https://www.google.com/maps/place/51.500107596214455%2C-0.2987620003554281/@51.500107596214455,-0.2987620003554281,17	104 Popes Ln, London, W5 4NS	South Ealing	Ealing Common	This section in particular appears poor	1			1			1								1																								
0055			6/4/2023	https://www.google.com/maps/place/51.50722778171098%2C-0.33920178218256547/@51.50722778171098,-0.33920178218256547,1																																										

0056	The cycle lane along the east side (heading south) of the Boston Road between Jasamine Road and Townholme Crescent requires resurfacing. The cycle lane on the East side (heading north) of Boston Manor Road between Townholme Cresent and Humes Avenue requires resurfacing.	1	6/4/2023	https://www.google.com/maps/place/51.5045298713576 4%2C-0.33409485621821/@51.50452987135764,-0.33409485621821,17z	161 Boston Rd, London, W7 3QL	Boston Manor	Hanwell Broadway / Northfield	Road resurfacing- these sections appear poor	1			
0057	Cars do not slow at roundabout	1	6/4/2023	https://www.google.com/maps/place/51.50845888870551%2C-0.2959537830778114/@51.50845888870551,-0.2959537830778114,17	Charlottes Place, 16 St Matthew's Rd, London, W5 3JT	Ealing Common	Ealing Common	Poor driver behaviour	1			
0058	Potholes	1	6/4/2023	https://www.google.com/maps/place/51.50473107008366%2C-0.3036839090678445/@51.50473107008366,-0.3036839090678445,17	Orchard Music Ltd, 24 Ranelagh Rd, London, W5 5RJ	South Ealing	Ealing Common	This location does appear poor in general	1			
0059	Potholes	1	6/4/2023	https://www.google.com/maps/place/51.51009951255584%2C-0.29013264653203974/@51.51009951255584,-0.29013264653203974,1	1 Leopold Rd, London, W5 3PB	Ealing Common	Ealing Common	Appears poor in some sections	1			
0060	This roundabout has multiple entry lanes where drivers in L/H lane undertake a vehicle in right hand lane who is correctly giving way to a cyclist on the round about . Outcome many near misses ..BTW this is much worse at R/A Kent Gardens /Scotch Common where I have been knocked off twice (They drove off...)	1	6/4/2023	https://www.google.com/maps/place/51.52882713333022%2C-0.3271910448753035/@51.52882713333022,-0.3271910448753035,17	3 Ruislip Rd E, London, W13 0AZ	Pitshanger	Pitshanger	Dangerous roundabout for cyclists - this is part of the new Greenford to Ealing link and the route currently suggests a longer route utilising the zebra crossing.	1	1		
0060.1		1			2 Scotch Common, London, W13 8DL			Additional location for previous log	1	1		
0061	Cycle area at the lights would be beneficial here.	1	6/4/2023	https://www.google.com/maps/place/51.51199993732816%2C-0.32012105583155703/@51.51199993732816,-0.32012105583155703,1	2 Broadway London, W13 0NG	West Ealing	West Ealing / Walpole	No cycle infrastructure at the junction of Uxbridge / Northfield / Drayton Bridge roads. Lido Dean Gardens hotspot	1	1		
0062	Cars are perpetually parked along here making it dangerous.	1	6/4/2023	https://www.google.com/maps/place/51.51109184284192%2C-0.3261292040249164/@51.51109184284192,-0.3261292040249164,17	Lacock Court, 2 Singapore Rd, London, W13 0UJ	West Ealing	Hanwell Broadway	Car parking on route (could be a reference to Uxbridge Road hotspot)	1			
0062.1		1			104 The Broadway, London, W13 0SY			Additional location for previous log	1			
0063	Lorries, cars and bikes here make it very daunting for less confident cyclists	1	6/4/2023	https://www.google.com/maps/place/51.51402973013847%2C-0.30776143669093203/@51.51402973013847,-0.30776143669093203,1	Unit 31, Dickens Yard, Longfield Ave, London W5 2BF	Ealing Broadway	Ealing Broadway	Possibly referencing Uxbridge Road hotspot	1			
0064	With buses stopping, road works, lots of cars, South Ealing Road is difficult to navigate	1	6/4/2023	https://www.google.com/maps/place/51.499532580264685%2C-0.3038032971982263/@51.499532580264685,-0.3038032971982263,17	152 S Ealing Rd, London, W5 4QJ	South Ealing	Northfield / Ealing Common	Poor Road safety - no cycle infrastructructure (blue route adjacent)	1			
0065	This is not great to navigate	1	6/4/2023	https://www.google.com/maps/place/51.51328742579695%2C-0.30438207499677405/@51.51328742579695,-0.30438207499677405,1	Units 1/3/22C, The Arcadia Centre, 50/52 The Broadway,	Ealing Broadway	Ealing Broadway	Uxbridge Road hot spots lacking cycle infrastructure	1	1		
0066	The rote from Glade Lane to Park Avenue is covered in litter and very badly lit	1	6/4/2023	https://www.google.com/maps/place/51.50905281335179%2C-0.36669504242735185/@51.50905281335179,-0.36669504242735185,1	200 Park Ave, Southall UB1 3AN	Southall	Southall Broadway / Norwood Green	Cycle / Foot underpass connecting North / South requires street cleaning and improved lighting	1			
0067	The path is not wide enough for cyclists and walkers it's also poor quality and badly lit	1	6/4/2023	https://www.google.com/maps/place/51.5055684898453%2C-0.34810502835351587/@51.5055684898453,-0.34810502835351587,1	Hanwell Flight Of Locks, Grand Union Canal,	Hanwell	Norwood Green	Grand Union Canal narrow and badly lit	1			
0068	Uxbridge Road needs substantial improvement	1	6/4/2023	https://www.google.com/maps/place/51.50988778942447%2C-0.3546346479669804/@51.50988778942447,-0.3546346479669804,17	Iron Bridge, Uxbridge Rd, Southall UB1 3EG	Southall	Norwood Green / Southall Broadway / Dormers Wells	Uxbridge Road in general (Iron Bridge)	1			
0069	Please can you remove these cycle lanes on both sides of the road .. these have been a nightmare for both car drivers and people walking on the pavement. These have caused car traffic to build up .. hence more pollution. Also as a daily walker on this route cyclist still using the pavement not the cycle lanes. Worst thing I've ever seen in road planning and waste of money. Please remove its cycle	1	6/4/2023	https://www.google.com/maps/place/51.51100946299049%2C-0.36986810538889303/@51.51100946299049,-0.36986810538889303,1	Holy Trinity Church Southall, Uxbridge Rd, Southall UB1 3HH	Southall	Southall Broadway / Norwood Green	Remove cycle lanes (NB these cycle lanes have been here since at least 2008 and are not therefore the cause of increased congestion)	1			
0070			6/4/2023	https://www.google.com/maps/place/51.51103617195852%2C-0.37330133292795553/@51.51103617195852,-0.37330133292795553,1								
0071			6/4/2023	https://www.google.com/maps/place/51.51123648871958%2C-0.3686879334223403/@51.51123648871958,-0.3686879334223403,17								
0072			6/4/2023	https://www.google.com/maps/place/51.51130326077753%2C-0.375661676861061/@51.51130326077753,-0.375661676861061,17z								
0073			6/4/2023	https://www.google.com/maps/place/51.51099610850062%2C-0.36426765296579733/@51.51099610850062,-0.36426765296579733,1								
0074			6/4/2023	https://www.google.com/maps/place/51.503623424208904%2C-0.2892109652244246/@51.503623424208904,-0.2892109652244246,17								
0075	Road surface on Weymouth Avenue is poor. Speed bumps should have flattened sections for bikes.	1	6/4/2023	https://www.google.com/maps/place/51.501445180631194%2C-0.3098666761076463/@51.501445180631194,-0.3098666761076463,17	14 Weymouth Ave, London W5 4SA	South Ealing	Northfield	Road surface / speed bumps without flattened sections	1			
0076	The intersection between Broadway and Northfields Avenue is bike unfriendly, particularly on Broadway.	1	6/4/2023	https://www.google.com/maps/place/51.5108054353258 85%2C-0.320297632985016/@51.510805435325885,-0.320297632985016,17z	2 Broadway London, W13 0NG	West Ealing	West Ealing / Walpole	No cycle infrastructure at the junction of Uxbridge / Northfield / Drayton Bridge roads	1	1		
0077	Speed bumps should have flattened sections for bikes	1	6/4/2023	https://www.google.com/maps/place/51.50889303603615%2C-0.3146136031317037/@51.50889303603615,-0.3146136031317037,17	23 Churchfield Rd, London, W13 9NF	Walpole	Walpole	speed bumps without flattened sections	1			
0078			6/4/2023	https://www.google.com/maps/place/51.51323174608127%2C-0.3045034185366702/@51.51323174608127,-0.3045034185366702,17								
0079			6/4/2023	https://www.google.com/maps/place/51.511542832109605%2C-0.2919608023527065/@51.511542832109605,-0.2919608023527065,17								
0080			6/4/2023	https://www.google.com/maps/place/51.51554895542395%2C-0.3023248579862514/@51.51554895542395,-0.3023248579862514,17								
0081			6/4/2023	https://www.google.com/maps/place/51.51511958759494 5%2C-0.31575364149797336/@51.515119587594945,-0.31575364149797336,1								
0082			6/4/2023	https://www.google.com/maps/place/51.51648541392911%2C-0.32176255008639965/@51.51648541392911,-0.32176255008639965,1								
0083			6/4/2023	https://www.google.com/maps/place/51.509883048220516%2C-0.32044987607563025/@51.509883048220516,-0.32044987607563025,1								
0084	Very dangerous!	1	6/4/2023	https://www.google.com/maps/place/51.51161000268384%2C-0.3239294787131941/@51.51161000268384,-0.3239294787131941,17	30A Green Man Ln, London, W13 0SB	West Ealing	Hanwell Broadway	Nondescript but location is a school street				
0085	Very dangerous for cyclists and bikes can obstruct the road for cars. This road is too narrow for buses, cars and cycles all at once.	1	6/4/2023	https://www.google.com/maps/place/51.51118266269914%2C-0.35517184931866286/@51.51118266269914,-0.35517184931866286,1	8 Greenford Rd, London,, Southall UB1 3EB	Southall	Dormers Wells	General road safety concern on approach to Iron Bridge junction	1			
0086	Cycling needs to be a priority across Ealing and all other boroughs. Some supposed cycle lanes are not safe as there are wands with large gaps which vehicles drift into or park in. There is often debris or other obstructions. There need to be proper segregated routes across Ealing and all boroughs to make cycling a safe viable alternative for as many people as possible. Not to mention the	1	6/4/2023	https://www.google.com/maps/place/51.50677102295262%2C-0.25424009610650167/@51.50677102295262,-0.25424009610650167,1	125-127 The Vale, London, W3 7RQ	Acton	East Acton / Southfield	Uxbridge Road pin - general request for increase segregated cycle infrastructure	1			
0087			6/4/2023	https://www.google.com/maps/place/51.50677102295268%2C-0.24932341111450151/@51.50677102295268,-0.24932341111450151,1								
0088			6/4/2023	https://www.google.com/maps/place/51.5066107539067 84%2C-0.25863604081420855/@51.506610753906784,-0.25863604081420855,1								
0089			6/4/2023	https://www.google.com/maps/place/51.50049158428948 5%2C-0.3286791598814043/@51.500491584289485,-0.3286791598814043,17								
0090			6/4/2023	https://www.google.com/maps/place/51.51212788206439%2C-0.3126717364805254/@51.51212788206439,-0.3126717364805254,17								
0091			6/4/2023	https://www.google.com/maps/place/51.50844244926261%2C-0.3408515871751061/@51.50844244926261,-0.3408515871751061,17								
0092			6/4/2023	https://www.google.com/maps/place/51.5078516050058 04%2C-0.33941885584273246/@51.507851605005804,-0.33941885584273246,1								
0093			6/4/2023	https://www.google.com/maps/place/51.508833217330 5%2C-0.33656498545088676/@51.5088332173305,-0.33656498545088676,1								
0094			6/4/2023	https://www.google.com/maps/place/51.505715770642 2%2C-0.33668762198675317/@51.5057157706422,-0.33668762198675317,1								
0095			6/4/2023	https://www.google.com/maps/place/51.50344950923185%2C-0.33263592968840516/@51.50344950923185,-0.33263592968840516,1								
0096	Disused railway bridge under Coronation Road should be used to provide cycle path linking Masons Green Lane to the Coronation Road cycle track. Although this is within OPDC it forms a missing vital link in the Ealing cycle network.	1	6/4/2023	https://www.google.com/maps/place/51.52853889763143%2C-0.28269083321612154/@51.52853889763143,-0.28269083321612154,1	Unit 1 Coronation Rd, Johnsons Way, London,	Park Royal	North Acton / Hanger Hill	Improve access to Mason Green Lane from Coronation Road. Land ownership may make this proposal complicated but could removed cyclists from	1		1	
0097	Two way cycle track needed along east side of Haven Green linking Tesco roundabout to A4020.	1	6/4/2023	https://www.google.com/maps/place/51.51534783059063 5%2C-0.3014877539924887/@51.515347830590635,-0.3014877539924887,17	38-39 Haven Grn, London, W5 2NX	Ealing Broadway	Ealing Broadway	No cycle path adjacent to the station. Request for two way	1			
0098	Northbound cycle lane needed over railway bridge to link Hastings Road homezone to Gordon Road. The uphill left turn out of Hastings Road onto St Leonards Road is difficult for cyclists.	1	6/4/2023	https://www.google.com/maps/place/51.51411931813808 6%2C-0.3136757117561606/@51.514119318138086,-0.3136757117561606,17	20 Hastings Rd, London, W13 8QH	West Ealing	Ealing Broadway	Suggested cycle lane heading North linking homezone to the new Greenford - Ealing cycle route. Looks viable but narrow as a painted lane	1			
0099	If Barnes Pikle is to form part of the network, as has been proposed for decades, the southern exit across Mattock Lane to Walpole Park needs a raised table, with a footway build-out on the north footway and parking removed along the south side of Mattock Lane. Alternatively, make cycling through the Filmworks development legal.	1	6/4/2023	https://www.google.com/maps/place/51.51230319555974%2C-0.3076675635628012/@51.51230319555974,-0.3076675635628012,17	Barnes Pikle, London, W5 5BE	Ealing	Ealing Broadway	Improve cycle and pedestrian priority to Barnes Pickle. NB the respondent only references the southern entrance however it would be prudent to address the	1	1		
0100	Two-way cycle track needed along west side of Bollo Lane similar to the one south of Boston Manor station in Hounslow	1	6/4/2023	https://www.google.com/maps/place/51.50049663387028%2C-0.27736933053057466/@51.50049663387028,-0.27736933053057466,1	4-5 Roslin Rd, London, W3 8DH	Acton Town	South Acton	Request for cycle lane on Bollo Lane	1			
0101	This is really bad, unhelpful and not easy to use at all. How do you place pins?????	1	6/4/2023	https://www.google.com/maps/place/51.50958010205456%2C-0.3282639284812605/@51.50958010205456,-0.3282639284812605,17	156 Broadway, Ealing, London W13 9BE			Survey issue				Survey issue
0102			6/4/2023	https://www.google.com/maps/place/51.49826338521049%2C-0.3031819797719981/@51.49826338521049,-0.3031819797719981,17								
0103	From Mount Park Rd, it's difficult to cycle to the covered parking in front of Ealing Broadway station. The cyclist currently has two suboptimal options: (1) Join the roundabout: this means merging into the right hand lane, avoiding accelerating buses in front of the station, and risking	1	6/4/2023	https://www.google.com/maps/place/51.51624668552466%2C-0.3027938643210404/@51.51624668552466,-0.3027938643210404,17	9-10, Central Buildings, The Broadway, London, W5	Ealing Broadway	Ealing Broadway	Poor cycle access from the North to covered cycle parking at Ealing Broadway station. Needs cycle lane heading south on Haven Green and / or a small section	1	1		
0104	Cycling towards the station from Gordon Road means cycling on the crossing. There is often a choke point here as cyclists and pedestrians going both ways find it difficult to read intended direction. The narrow gap for cyclists between bollards also make it likely for	1	6/4/2023	https://www.google.com/maps/place/51.51523136396884%2C-0.3047598280028896/@51.51523136396884,-0.3047598280028896,17	5 Haven Grn, London, W5 2UU	Ealing Broadway	Ealing Broadway	Potentially dangerous junction / road markings connecting the cycle route to Ealing Broadway station and routes South / East - should be addressed urgently, clear		1		
0105	It feels extremely unsafe to turn from the A406 into Queen's drive (and vice versa) at this junction. The one-sided cycle lane on the A406 also makes navigating to North Acton difficult.	1	6/4/2023	https://www.google.com/maps/place/51.51709807673404%2C-0.2912804591725937/@51.51709807673404,-0.2912804591725937,17	36 Hanger Ln, London, W5 2JH	North Ealing	Hanger Hill / Ealing Common	Connecting to / from the cycle path alongside the A406 is dangerous at this junction and crossings are not adapted for cyclists	1	1		
0106	Please make it feel safer for cyclists to turn into the A406 from Uxbridge Road (and vice versa). This will help make the river and areas like Kew and Chiswick more accessible for cyclists. It would be great if Ealing could be connected to the popular C9 cycleway.	1	6/4/2023	https://www.google.com/maps/place/51.51140367879591 5%2C-0.2920101662209395 6/@51.511403678795915,-0.29201016622093956,1	1 Hanger Ln, London, W5 3HN	Ealing Common	Ealing Common	Difficult cyclist road conditions continuing straight or turning right at the Uxbridge Road / A406 junction. Difficult to see what cyclists are advised to do	1	1		
0107	The new C49 cycleway is great but poorly signed.	1	6/4/2023	https://www.google.com/maps/place/51.49883165965738 4%2C-0.26121914608666863/@51.498831659657384,-0.26121914608666863,1	96 Rusthall Ave, London W4 1BS	Bedford Park	Southfield	Improve C49 blue route	1			
0108			6/4/2023	https://www.google.com/maps/place/51.49276892757884%2C-0.31073198335721974/@51.49276892757884,-0.31073198335721974,1								
0109			6/4/2023	https://www.google.com/maps/place/51.49992837060505%2C-0.309959859533242/@51.49992837060505,-0.309959859533242,17z								
0110			6/4/2023	https://www.google.com/maps/place/51.50041868076521 5%2C-0.3268683777058601/@51.500418680765215,-0.3268683777058601,17								

0111			6/4/2023	https://www.google.com/maps/place/51.50950093836239%2C-0.32326348878984446/@51.50950093836239,-0.32326348878984446,1																																											
0112			6/4/2023	https://www.google.com/maps/place/51.51088982992476%2C-0.3124488220417976/@51.51088982992476,-0.3124488220417976,17																																											
0113	Because of the 4 lanes of traffic this stretch of uxbridge road is really unpleasant	1	6/4/2023	https://www.google.com/maps/place/51.509141814494114%2C-0.3484341402732527/@51.509141814494114,-0.3484341402732527,17	407 Uxbridge Rd, Southall UB1 3EW	Hanwell	Norwood Green	Section alongside the Hospital is unpleasant (NB segregation and defended bus lane appears possible on the south side.										1																													
0114	despite the speed limit, car drivers can be very pushy as there isn't much space to overtake	1	6/4/2023	https://www.google.com/maps/place/51.51672322157799%2C-0.29637459873635086/@51.51672322157799,-0.29637459873635086,1	39 Madeley Rd, London, W5 2LS	Ealing Broadway	Hanger Hill	Minimal road space														1													1												
0115	Going east the roundabout is still very challenging (because of he traffic coming from horn lane) Going west it is much better	1	6/4/2023	https://www.google.com/maps/place/51.5085180443913%2C-0.27515608636207833/@51.5085180443913,-0.27515608636207833,1	264 High St, London, W3 9BH	Acton	South Acton	Styne / Horn roundabout - Heading East the cycle route suggests using the crossing to the North of the roundabout however this crossing has not be optimised for cyclists who	1			1	1		1	1		1									1	1																			
0116	Although I use this street I never realised it was supposed to be a cycle way. Traffic is fast and aggressive on it.	1	6/4/2023	https://www.google.com/maps/place/51.51540231053994%2C-0.37555252553482354/@51.51540231053994,-0.37555252553482354,1	104-96 Lady Margaret Rd, Southall UB1 2RH	Southall	Lady Margaret	Lack of clear cycle infrastructure on this section of blue route. Other sections have very faded cycle lanes	1			1			1	1										1	1		1						1												
0117	This street is used as a rat run by car drivers wanted to avoid the traffic light between greenford road and ruislip road east. That would be great to add bollards to stop through traffic.	1	6/4/2023	https://www.google.com/maps/place/51.52926912118925%2C-0.3481388847763611/@51.52926912118925,-0.3481388847763611,17	62 Costons Ln, Greenford UB6 8RP	Greenford	Central Greenford	Blue Route 87 is a rat run on Costons Lane	1			1			1	1													1								1										
0118	Eastbound lane not protected	1	6/4/2023	https://www.google.com/maps/place/51.511559205858866%2C-0.2923773250575534/@51.511559205858866,-0.2923773250575534,17	1 Hanger Ln, London, W5 3HN	Ealing Common	Ealing Common	Uxbridge Road hotspot - difficult continuing East across junction	1			1	1		1	1		1				1				1																			
0119	Risky junction, delivery drivers park in edge of road cyclists must merge into central lane as a result	1	6/4/2023	https://www.google.com/maps/place/51.51332955920773%2C-0.30392068393213956/@51.51332955920773,-0.30392068393213956,1	Units 1/3/22C, The Arcadia Centre, 50/52 The Broadway,	Ealing Broadway	Ealing Broadway	Uxbridge Road hotspot Christ the saviour / M&S	1			1	1		1	1		1				1				1																			
0120	Ok westbound, risky eastbound, in both directions illegally parked cars cause danger	1	6/4/2023	https://www.google.com/maps/place/51.50696455015017%2C-0.27001658743553536/@51.50696455015017,-0.27001658743553536,1	136 High St, Greater, London, W3 6QZ	Acton	South Acton	Uxbridge Road in Acton - challenging + parking concerns	1			1	1		1	1		1				1								1				1													
0121			6/4/2023	https://www.google.com/maps/place/51.51350233501592%2C-0.30402701489165684/@51.51350233501592,-0.30402701489165684,1																																											
0122			6/4/2023	https://www.google.com/maps/place/51.508348434801626%2C-0.2750436862977823/@51.508348434801626,-0.2750436862977823,17																																											
0123	Parking blocking cycle infrastructure	1	6/4/2023	https://www.google.com/maps/place/51.507180258298256%2C-0.27019439812017154/@51.507180258298256,-0.27019439812017154,1	147, 151 High St, London, W3 6LP	Acton	South Acton	Uxbridge Road in Acton - challenging + parking concerns	1			1	1		1	1		1												1																	
0124			6/4/2023	https://www.google.com/maps/place/51.50916151488861%2C-0.33463994973755185/@51.50916151488861,-0.33463994973755185,1																																											
0125			6/4/2023	https://www.google.com/maps/place/51.50084880031791%2C-0.31558655028093074/@51.50084880031791,-0.31558655028093074,1																																											
0126			6/4/2023	https://www.google.com/maps/place/51.49828409464848%2C-0.31378410582292293/@51.49828409464848,-0.31378410582292293,1																																											
0127			6/4/2023	https://www.google.com/maps/place/51.50717419992157%2C-0.31947193660810447/@51.50717419992157,-0.31947193660810447,1																																											
0128			6/4/2023	https://www.google.com/maps/place/51.519460374754914%2C-0.32299151574364027/@51.519460374754914,-0.32299151574364027,1																																											
0129	Difficult to cross during busy periods. Cars race down this stretch of Northfield Ave	1	6/4/2023	https://www.google.com/maps/place/51.510038298120996%2C-0.3191195816244541/@51.510038298120996,-0.3191195816244541,17	63 Mattock Ln, London, W13 9LA	West Ealing	Walpole	Speeding cars near junction	1			1			1							1												1	1												
0130	This junction is dangerous for cyclists	1	6/4/2023	https://www.google.com/maps/place/51.51089528327534%2C-0.31943608046307137/@51.51089528327534,-0.31943608046307137,1	2 Broadway London, W13 0NG	West Ealing	West Ealing / Walpole	Uxbridge / Northfield / Drayton Green hotspot (Dean / Lido)	1	1		1				1		1				1				1					1																
0131	There's zero provisions for cyclists around the entire Northfields area. Cars exit side streets without breaking or speed.	1	6/4/2023	https://www.google.com/maps/place/51.50322976369683%2C-0.317080912330574/@51.50322976369683,-0.317080912330574,17z	112-92, Northfield Avenue, London, W13 9QR	Northfields	Northfield / Walpole	No cycle infrastructure	1			1			1							1				1								1	1												
0132	Leighton Road is a huge issue in the area because it's used as a major rat run. Cycling is very difficult due to constant stream of traffic. I would suggest making the entire road one way and adding a cycle counter flow.	1	6/4/2023	https://www.google.com/maps/place/51.50512638532837%2C-0.32296031449121854/@51.50512638532837,-0.32296031449121854,1	61-79 Leighton Rd., London, W13 9EJ	Hanwell	Hanwell Broadway / Northfield / Walpole	Leighton Road rat run. Suggestion of one way system with counter flow for cyclists may be challenging as the only direct route across and may inflame LTN tensions	1			1	1			1										1	1										1							1			
0133	The cycling path on the North side of Uxbridge Road is partly on the pavement and at one point it crosses the path of pedestrians. I am concerned for my safety as a pedestrian. The cycle path along Gunnersbury Avenue is not continuous. As a result cyclists are frequently on the wrong side of the road or on the pavement.	1	6/4/2023	https://www.google.com/maps/place/51.512509615801825%2C-0.29490494149716495/@51.512509615801825,-0.29490494149716495,1	18 N Common Rd London, W5 2QB	Ealing Common	Ealing Common	Bus stop EN on the North Side of Ealing Common - cycle path switches side of the pavement immediately adjacent to the bus stop which may cause conflict with pedestrians -	1	1		1			1			1									1												1								
0134			6/4/2023	https://www.google.com/maps/place/51.50908319889811%2C-0.333155991864309/@51.50908319889811,-0.333155991864309,17z																																											
0135			6/4/2023	https://www.google.com/maps/place/51.507316370609836%2C-0.33779888445377937/@51.507316370609836,-0.33779888445377937,1																																											
0136			6/4/2023	https://www.google.com/maps/place/51.510215261003935%2C-0.3237674352518849/@51.510215261003935,-0.3237674352518849,17																																											
0137			6/4/2023	https://www.google.com/maps/place/51.512200585934075%2C-0.31235408217558547/@51.512200585934075,-0.31235408217558547,1																																											
0138			6/4/2023	https://www.google.com/maps/place/51.513815916151245%2C-0.3027218116106223/@51.513815916151245,-0.3027218116106223,17																																											
0139			6/4/2023	https://www.google.com/maps/place/51.506689821813204%2C-0.2848523188868901/@51.506689821813204,-0.2848523188868901,17																																											
0140			6/4/2023	https://www.google.com/maps/place/51.53590515488468%2C-0.3909179125021245/@51.53590515488468,-0.3909179125021245,17																																											
0141			6/4/2023	https://www.google.com/maps/place/51.54111734730379%2C-0.3812624128121178/@51.54111734730379,-0.3812624128121178,17																																											
0142			6/4/2023	https://www.google.com/maps/place/51.535840378041534%2C-0.3701457818366083/@51.535840378041534,-0.3701457818366083,17																																											
0143			6/4/2023	https://www.google.com/maps/place/51.53839671928819%2C-0.3658017890594989/@51.53839671928819,-0.3658017890594989,17																																											
0144			6/4/2023	https://www.google.com/maps/place/51.53253185982196%2C-0.3786204200700971/@51.53253185982196,-0.3786204200700971,17																																											
0145	Cycling on Uxbridge Rd in Southall is dangerous due to heavy traffic. Cycling on pavement is a risk. Pavements are croweded with people illegally parked CARS and gods.	1	6/4/2023	https://www.google.com/maps/place/51.52902069725055%2C-0.3768769670051797/@51.52902069725055,-0.3768769670051797,17	1 High St, Southall UB1 3HA	Southall	Southall Broadway / Southall West	General issue with Uxbridge Road in Southall	1			1	1		1	1		1				1				1	1			1				1													
0146	Have frequent near misses here from vehicles jumping lights going west on Uxbridge road or north on Acton lane.	1	6/4/2023	https://www.google.com/maps/place/51.506708838688034%2C-0.2680343298738208/@51.506708838688034,-0.2680343298738208,17	86a Winchester St, London, W3 6NE	Acton	South Acton	Poor driver behaviour at junction around Acton Town Hall.	1			1			1			1													1			1	1												
0147	Feel unsafe at this junction when waiting at the traffic lights to go west from traffic trying to turn across the front of me, and eastwards from traffic that wants to get away quickly.	1	6/4/2023	https://www.google.com/maps/place/51.51148994580629%2C-0.2918523459260669/@51.51148994580629,-0.2918523459260669,17	1 Hanger Ln, London, W5 3HN	Ealing Common	Ealing Common	Uxbridge Road / A406 hotspot	1				1			1		1				1				1					1																
0148	Feel unsafe going west due to how close other vehicles are at the traffic lights. Not so bad coming the other way.	1	6/4/2023	https://www.google.com/maps/place/51.51098247779083%2C-0.3191465048616138/@51.51098247779083,-0.3191465048616138,17	2 Broadway London, W13 0NG	West Ealing	Hanwell Broadway / Walpole	Uxbridge Road / Northfield / Drayton Bridge hotspot	1	1			1			1		1				1				1					1																
0149	Often need to turn right here when going west, but it's really hard to do safely as there's usually a stream of traffic pushing past me. Signally that I'm pulling over often results in a toot and drivers accelerating to overtake me.	1	6/4/2023	https://www.google.com/maps/place/51.513289968509945%2C-0.3042224654818493/@51.513289968509945,-0.3042224654818493,17	Units 1/3/22C, The Arcadia Centre, 50/52 The Broadway,	Ealing Broadway	Ealing	Ealing Broadway Christ the Saviour hotspot	1				1			1		1				1				1					1																
0150	I don't feel safe cycling along the Uxbridge Road with the amount of vehicles and buses along the route.	1	6/4/2023	https://www.google.com/maps/place/51.51161000268394%2C-0.34856288630596755/@51.51161000268394,-0.34856288630596755,1	3, The Triangle Centre, 399 Uxbridge Rd, Southall UB1 3EJ	Hanwell	Norwood Green	Uxbridge Road general concern - seemingly around Ealing Hospital					1			1		1				1																									
0151	Always cautious when cycling along Ruislip Road East towards Perivale. I prefer to either cycle along the pathway (which can get extremely muddy) or on the pavement as cars get very close to cyclists. Cycle route towards Greenford is somewhat safer	1	6/4/2023	https://www.google.com/maps/place/51.52755125442569%2C-0.34804722669731447/@51.52755125442569,-0.34804722669731447,1	Greenford Bridge, Ruislip Rd E Greenford UB6 8RP	Greenford	North Hanwell	North Side of the road is shared pavement but it lacks clear markings which may help. South side (heading West towards Greenford) has a cycle lane on the road but	1			1			1							1					1																				
0152	Pathway along the Grand Union Canal should be extended all the way along the canal. I predominantly run, but also cycle, along the canal and frequently meet cyclists along the route. It can get unsafe when it's crowded with walkers, runners and cyclists on the narrower paths especially when cyclists are travelling at pace	1	6/4/2023	https://www.google.com/maps/place/51.50618152145465%2C-0.3489355081425738/@51.50618152145465,-0.3489355081425738,17	Hanwell Flight of locks, Grand Union Canal	Hanwell	Norwood Green	General extension and improvements to Grand Union Canal route	1			1	1		1	1					1						1					1															
0153			6/4/2023	https://www.google.com/maps/place/51.50912908073469%2C-0.34048610287306325/@51.50912908073469,-0.34048610287306325,1																																											
0154			6/4/2023	https://www.google.com/maps/place/51.511159001459426%2C-0.32537990170118825/@51.511159001459426,-0.32537990170118825,1																																											
0155			6/4/2023	https://www.google.com/maps/place/51.51350932298926%2C-0.30478053646681325/@51.51350932298926,-0.30478053646681325,1																																											
0156	Uxbridge Road is poor: too much traffic goes over the white line; parking on lane; speed of vehicles	1	6/4/2023	https://www.google.com/maps/place/51.51062482056395%2C-0.28624110775587575/@51.51062482056395,-0.28624110775587575,1	21 Station Parade, Uxbridge Rd, London, W5 3LD	Ealing Common	Ealing Common	Uxbridge road traffic concerns around Ealing Common station - lines are very faded and could be improved	1			1			1			1				1					1			1					1												
0157			6/4/2023	https://www.google.com/maps/place/51.51247898497558%2C-0.35473614366820394/@51.51247898497558,-0.35473614366820394,1																																											
0158			6/4/2023	https://www.google.com/maps/place/51.50905181749453%2C-0.34803370391875754/@51.50905181749453,-0.34803370391875754,1																																											
0159			6/4/2023	https://www.google.com/maps/place/51.51188402047119%2C-0.3137380398977685/@51.51188402047119,-0.3137380398977685,17																																											
0160			6/4/2023	https://www.google.com/maps/place/51.53453940715997%2C-0.33218059126605803/@51.53453940715997,-0.33218059126605803,1																																											
0161			6/4/2023	https://www.google.com/maps/place/51.49557595111614%2C-0.3723758891829587/@51.49557595111614,-0.3723758891829587,17																																											
0162			6/4/2023	https://www.google.com/maps/place/51.50636478861993%2C-0.26766568196270324/@51.50636478861993,-0.26766568196270324,1																																											
0163			6/4/2023	https://www.google.com/maps/place/51.50778835213034%2C-0.29096692653558076/@51.50778835213034,-0.29096692653558076,1																																											
0164			6/4/2023	https://www.google.com/maps/place/51.50276648932953%2C-0.3594301486708362/@51.50276648932953,-0.3594301486708362,17																																											
0165	Cycle lanes across the bridge at West Ealing station are required to join up existing cycle lanes. This bridge is dangerous on a bike. The pavement is too busy to cycle on	1	6/4/2023	https://www.google.com/maps/place/51.51399732503717%2C-0.3196525792911964/@51.51399732503717,-0.3196525792911964,17	55 Drayton Green Rd, London, W13 0NQ	West Ealing	West Ealing / Walpole / Ealing Broadway / Pitshanger	Blue route but lacking any cycle infrastructure at a pinch point	1	1	1				1	1										1			1																		
0166	A cycle lane from Haven Green to Uxbridge Road is needed to join up existing routes	1	6/4/2023	https://www.google.com/maps/place/51.515055075262936%2C-0.30291110610883853/@51.515055075262936,-0.30291110610883853,1	3, Central Buildings, 1 10 The Broadway, London, W5 2NR	Ealing Broadway	Ealing Broadway	hotspot - no cycle infrastructure at Ealing Broadway station	1	1	1				1	1										1																					
0167	The cycle lane ends abruptly and you have to cycle on narrow pavement to continue Northbound. Cycling Southbound this side is horrible	1	6/4/2023	https://www.google.com/maps/place/51.50616388288327%2C-0.2905794515775817/@51.50616388288327,-0.2905794515775817,17	25 Gunnersbury Ave, London, W5 3XD	Ealing Common	Ealing Common	Previously mentioned issue with heading North / South on A406 between Ealing Common and Popes Lane. Northbound rejoins carriageway	1				1		1	1			1								1	1				1															

0168	Weymouth Ave is dangerously busy during school drop off and pick up. Too many cars and irresponsible parking. Makes cycling along here with a child very scary	1	6/4/2023	https://www.google.com/maps/place/51.49868341394386%2C-0.30872554630665405/@51.49868341394386,-0.30872554630665405,1	70 Weymouth Ave, London W5 4SB	South Ealing	Northfield	General road safety concern on residential street which is a North / South Link over tracks. Might be worth adding road markings	1			1			1							1				1									1														
0169	No good route from Northfield Ave to the North side of Uxbridge Road	1	6/4/2023	https://www.google.com/maps/place/51.510840128489235%2C-0.32017655967178094/@51.510840128489235,-0.32017655967178094,1	2 Broadway London, W13 0NG	West Ealing	West Ealing / Walpole	Uxbridge / Northfield / Drayton Green hotspot	1	1			1			1		1								1					1																	
0170	Too dangerous to turn onto Uxbridge road, no segregated cycle lane	1	6/4/2023	https://www.google.com/maps/place/51.51138503739145%2C-0.3169319497643919/@51.51138503739145,-0.3169319497643919,17	Lovelace House, 96-122 Uxbridge Rd, London, W13 8RD	West Ealing	Walpole	Section of the Broadway with minimal cycle infrastructure	1		1				1	1		1								1		1																				
0171			6/4/2023	https://www.google.com/maps/place/51.51082975627975%2C-0.31675022128814456/@51.51082975627975,-0.31675022128814456,1																																											
0172	Broomfield road is too narrow, people park cars which overspill onto the road (which itself has no segregated cycleway), recommend adding no-parking zones close to the junction at either end of the road	1	6/4/2023	https://www.google.com/maps/place/51.510778617666745%2C-0.3167692850786108/@51.510778617666745,-0.3167692850786108,17	4 Broomfield Rd, London, W13 9AP	West Ealing	Walpole	Road is narrow but there are double yellow lines (which could be extended) at the junctions. A one way (with possible counterflow) might be more advisable	1		1					1						1				1																						
0173	People do not respect cycleways, cars parked / using lanes	1	6/4/2023	https://www.google.com/maps/place/51.51164665551074%2C-0.3150741289811987/@51.51164665551074,-0.3150741289811987,17	82A Uxbridge Rd, London, W13 8RA	West Ealing	Walpole	Section of Uxbridge Road / Broadway with minimal infrastructure and parking in cycle lanes outside of peak hours, faded lines	1			1			1			1									1			1				1	1													
0174	This cycleway should be connected to uxbridge road to support people looking for quieter options to reach ealing broadway station (alternative to cycling down uxbridge road which is busy and dangerous)	1	6/4/2023	https://www.google.com/maps/place/51.514812056523624%2C-0.31443085120137493/@51.514812056523624,-0.31443085120137493,1	97 Gordon Rd, London, W13 8PR	West Ealing	West Ealing / Ealing Broadway	Connecting new Greenford - Ealing route to the Broadway. Suggested elsewhere as part of connection to the Hastings Road home zone	1		1	1			1	1										1			1																			
0175			6/4/2023	https://www.google.com/maps/place/51.512357838011255%2C-0.31147429212551314/@51.512357838011255,-0.31147429212551314,1																																											
0176	North circular bike path needs improvement. The surface is very poor and there is no easy way to cross Uxbridge Road	1	6/4/2023	https://www.google.com/maps/place/51.51753392409023%2C-0.290798832961241/@51.51753392409023,-0.290798832961241,17z	56 Hanger Ln, London, W5 3HL	North Ealing	Hanger Hill	Cycle path on the west side of A406 could be improved and additional crossings may aid access to residential streets to the North East	1		1					1			1								1	1																				
0177			6/4/2023	https://www.google.com/maps/place/51.51027591995332%2C-0.3239552164359272/@51.51027591995332,-0.3239552164359272,17																																											
0178	Dangerous, unpleasant, to be avoided as is.	1	6/4/2023	https://www.google.com/maps/place/51.51324814887996%2C-0.3042935374998601/@51.51324814887996,-0.3042935374998601,17	Units 1/3/22C, The Arcadia Centre, 50/52 The Broadway,	Ealing Broadway	Ealing Broadway	Christ the Saviour / M&S hotspot	1	1			1			1		1				1									1																	
0179	Dangerous, unpleasant, to be avoided as is.	1	6/4/2023	https://www.google.com/maps/place/51.510925252288686%2C-0.3193721250876358/@51.510925252288686,-0.3193721250876358,17	2 Broadway London, W13 0NG	West Ealing	Hanwell Broadway / Walpole	Uxbridge Road / Northfield / Drayton Bridge hotspot	1	1			1			1		1				1				1					1																	
0180	Dangerous, unpleasant, to be avoided as is.	1	6/4/2023	https://www.google.com/maps/place/51.50879820140711%2C-0.33439573561169/@51.50879820140711,-0.33439573561169,17z	Adam's Roundabout, London, W7 3FE	Hanwell	Hanwell Broadway	Church Road / Uxbridge Road / Adams Roundabout - no cycle infrastructure	1			1			1	1		1				1				1																						
0181	Dangerous, unpleasant, to be avoided as is.	1	6/4/2023	https://www.google.com/maps/place/51.50926348672366%2C-0.353828459440404/@51.50926348672366,-0.353828459440404,17z	Ironbridge house, Southall UB2 4NJ	Hanwell	Norwood Green	East side of Ironbridge general concern					1			1		1				1					1				1																	
0182	Dangerous, unpleasant, to be avoided as is.	1	6/4/2023	https://www.google.com/maps/place/51.50975761903411%2C-0.35705247467630485/@51.50975761903411,-0.35705247467630485,1	220 Uxbridge Rd, Southall UB1 3DZ	Dormers Wells	Dormers Wells / Southall Broadway	West side of Iron Bridge general concern					1			1		1				1					1				1																	
0183			6/4/2023	https://www.google.com/maps/place/51.50167331115438%2C-0.27483432490460036/@51.50167331115438,-0.27483432490460036,1																																											
0184	Calling the 'cycle route' along the Uxbridge Road a Cycle Route is a sick joke. You permit parking in the cycle lanes. We need a proper Cycle Lane along the Uxbridge Road, similar in standard to Chiswick's C9.	1	6/4/2023	https://www.google.com/maps/place/51.51101756863336%2C-0.32305188284639685/@51.51101756863336,-0.32305188284639685,1	64a The Broadway, London, W13 0SU	West Ealing	Hanwell Broadway / Walpole	Unhappy with standard of Uxbridge Road.	1			1				1		1									1	1		1																		
0185	The Boston Manor Cycle route in Ealing is poor quality. It needs to be improved to bring it up to the standard of the route in Hounslow.	1	6/4/2023	https://www.google.com/maps/place/51.504232984843156%2C-0.33317990408663123/@51.504232984843156,-0.33317990408663123,1	146-152 Boston Rd, London, W7 2HJ	Boston Manor	Northfield	Requesting Boston Manor Road improvement	1			1				1				1								1																				
0186	The Mattock Lane/Grove cycle route is a good alternative to the Uxbridge Road but there are too many cars (including parking provision) and too much aggressive driving. The round abouts/junctions at the South Ealing Road are not safe.	1	6/4/2023	https://www.google.com/maps/place/51.51162373196006%2C-0.30729500278593225/@51.51162373196006,-0.30729500278593225,1	2 Mattock Ln, London, W5 5BG	Ealing Broadway	Walpole / Ealing / Ealing Common	Request for Mattock Lane improvements and roundabouts / junctions on St Marys / South Ealing Road	1			1			1	1										1			1						1													
0187	Again on the Uxbridge Road in Acton, like further west, the cycle lane is inadequate, fragmentary and often blocked by motorists parking.	1	6/4/2023	https://www.google.com/maps/place/51.5069708535929%2C-0.26841370090604943/@51.5069708535929,-0.26841370090604943,1	90 High St, London, W3 6QX	Acton	South Acton	Intermittent cycle lane on Uxbridge Road in Acton	1				1			1		1								1	1	1		1																		
0188	There are useful fragments here to go north, but they are not a complete route. We need joined up infrastructure.	1	6/4/2023	https://www.google.com/maps/place/51.52109896334275%2C-0.29901234134794397/@51.52109896334275,-0.29901234134794397,1	4A West Rd, London, W5 2QL	Montpelier	Ealing Broadway / Hanger Hill	This appears to be a reference to c85 sections of which are poorly designated	1			1			1														1																			
0189	Full of mud and gravel adjacent to the west side of the bridge. Many potholes between Kuya Fernando and the bridge on the eastbound side	1	6/4/2023	https://www.google.com/maps/place/51.50850575638516%2C-0.34341864864372074/@51.50850575638516,-0.34341864864372074,1	310-312 Uxbridge Rd, Southall UB1 3EP	Hanwell	Norwood Green / Hanwell Broadway	Street cleaning and resurfacing of the cycle / bus lane west of on the North Side of Uxbridge Road to the west of Hanwell Bridge	1			1		1	1			1					1		1																							
0190	Colebrooke Avenue is safer and quieter than using The Avenue and could usefully be signposted	1	6/4/2023	https://www.google.com/maps/place/51.51857333243552%2C-0.3194794915762955/@51.51857333243552,-0.3194794915762955,17	107 The Avenue, London, W13 8JT	West Ealing	Ealing Broadway	Suggestion of using Colebrook rather than the Avenue however the Avenue forms a key section of C86 and the new Greenford - Ealing route. Additionally the Avenue is	1																				1																			
0191	The on-footway cycle path east of Iron Bridge has lost all its markings and is poorly signposted. A cycle priority phase at the lights heading north from Windmill Lane would help cyclists' confidence at this busy and intimidating junction	1	6/4/2023	https://www.google.com/maps/place/51.50971487929003%2C-0.35352040126449547/@51.50971487929003,-0.35352040126449547,1	343, 345 Uxbridge Rd, Southall UB1 3ED	Iron Bridge	Norwood Green	Lines do need repainting on the cycle path. There are advanced stop lines at the junction at the top of Windmill Lane (which is lacking in any other cycle	1		1	1			1	1		1									1				1																	
0192	Some cycle safety measures over the railway bridge would be very welcome	1	6/4/2023	https://www.google.com/maps/place/51.51356383831172%2C-0.31973373954399475/@51.51356383831172,-0.31973373954399475,1	1, Castle Hill Parade, The Avenue, London, W13 8JP	West Ealing	Pitshanger / Ealing Broadway / West Ealing / Walpole	Lack of cycle infrastructure on the Drayton Green Road railway Bridge which forms part of C86. Difficult to see what could be put in place beyond highway surfacing but	1	1	1	1			1	1										1			1																			
0193	The bollard layout and tree pit positions at the southern end make for a difficult manoeuvre and can cause unnecessary conflict with pedestrians that could usefully be re-considered	1	6/4/2023	https://www.google.com/maps/place/51.49581470774259%2C-0.3017462383352787/@51.49581470774259,-0.3017462383352787,17	82 Claypond Gardens, London, W5 4RF	South Ealing	Northfield	C86 - South end of the route through South Ealing cemetery to occupation late has bollards to prevent vehicles. No obvious cause for concerns in relation to the	1			1			1												1		1																			
0194			6/4/2023	https://www.google.com/maps/place/51.506704007467484%2C-0.26559876972008345/@51.506704007467484,-0.26559876972008345,1																																											
0195			6/4/2023	https://www.google.com/maps/place/51.508613839687335%2C-0.26663028434330105/@51.508613839687335,-0.26663028434330105,1																																											
0196			6/4/2023	https://www.google.com/maps/place/51.5138913095887%2C-0.30259029338509214/@51.5138913095887,-0.30259029338509214,1																																											
0197			6/4/2023	https://www.google.com/maps/place/51.502146363270626%2C-0.30389983609897975/@51.502146363270626,-0.30389983609897975,1																																											
0198			6/4/2023	https://www.google.com/maps/place/51.52656595357648%2C-0.27735083548655837/@51.52656595357648,-0.27735083548655837,1																																											
0199			6/4/2023	https://www.google.com/maps/place/51.525270992218665%2C-0.2703985497199568/@51.525270992218665,-0.2703985497199568,17																																											
0200			6/4/2023	https://www.google.com/maps/place/51.52337520917082%2C-0.265549115821031/@51.52337520917082,-0.265549115821031,17z																																											
0201	Why does the cycle lane zig zag across the pavement? If pedestrians have right of way, where do I walk? Cyclists don't care about others If they have their own lane, then they don't care, why make pedestrians walk across that several times? And secondly, with the bus stop in place (which get very busy) there is no where to walk as you're forced into the cycle lane just to get past. Very ill thought	1	6/4/2023	https://www.google.com/maps/place/51.553593478549445%2C-0.3378773452358308/@51.553593478549445,-0.3378773452358308,17	1470 Greenford Rd, Greenford UB6 0HW	Sudbury Hill	North Greenford	No obvious cause for concern the cycle path crosses pavement owing to bus stop but there is tactile paving and an alternative route adjacent																											1			1									
0202	The towpath has received huge investment and improvement but there was no point doing this when canal and rivers trust (formerly british waterways) are so bad at keeping trees and bushes trimmed. Their customer service has also got worse, requiring repeated emails and photos.	1	6/4/2023	https://www.google.com/maps/place/51.54332307966906%2C-0.3556283171922825/@51.54332307966906,-0.3556283171922825,17	20, 21 Fairway Dr, Greenford UB6 8PW	Greenford	Central Greenford	Appears to be a narrow, potentially overgrown section of towpath	1			1		1							1			1																								
0203	The towpath has received huge investment and improvement but there was no point doing this when canal and rivers trust (formerly british waterways) are so bad at keeping trees and bushes trimmed. Their customer service has also got worse, requiring repeated emails and photos.	1	6/4/2023	https://www.google.com/maps/place/51.540941673700615%2C-0.3653434718330484/@51.540941673700615,-0.3653434718330484,17	Unit L metropolitan Park, Field Way, Greenford, Greater	Greenford	Central Greenford	Appears to be a narrow, potentially overgrown section of towpath	1			1		1							1			1																								
0204	The towpath has received huge investment and improvement but there was no point doing this when canal and rivers trust (formerly british waterways) are so bad at keeping trees and bushes trimmed. Their customer service has also got worse, requiring repeated emails and photos.	1	6/4/2023	https://www.google.com/maps/place/51.5359049709788%2C-0.36837856557002446/@51.5359049709788,-0.36837856557002446,1	216 Ferrymead Ave, Greenford UB6 9TP	Greenford	Greenford Broadway	Appears to be a narrow, potentially overgrown section of towpath	1			1		1							1			1																								
0205	The towpath has received huge investment and improvement but there was no point doing this when canal and rivers trust (formerly british waterways) are so bad at keeping trees and bushes trimmed. Their customer service has also got worse, requiring repeated emails and photos.	1	6/4/2023	https://www.google.com/maps/place/51.53033302811997%2C-0.3758070330955099/@51.53033302811997,-0.3758070330955099,17	45 Frensham Cl, Southall UB1 2YG	Greenford	Greenford Broadway / Lady Margaret	Appears to be a narrow, potentially overgrown section of towpath	1			1		1							1			1																								
0206	The towpath has received huge investment and improvement but there was no point doing this when canal and rivers trust (formerly british waterways) are so bad at keeping trees and bushes trimmed. Their customer service has also got worse, requiring repeated emails and photos.	1	6/4/2023	https://www.google.com/maps/place/51.52315410678542%2C-0.3780385277267073/@51.52315410678542,-0.3780385277267073,17	58 Kingsbridge Cres, Southall UB1 2DL	Southall	Lady Margaret	Appears to be a narrow, potentially overgrown section of towpath	1			1		1							1			1																								
0207	Here is a bit of a mess as the cycle route goes right through a narrow part of the pavement (trees) where there are people waiting at a bus stop. The cycle lane should go onto the pavement further down the road.	1	6/4/2023	https://www.google.com/maps/place/51.513039832744205%2C-0.29669582081696566/@51.513039832744205,-0.29669582081696566,1	32 The Mall Ealing, London, W5 3TJ	Ealing Common	Ealing Common	Bus stop EM on the North Side of Uxbridge Road. The respondent may have a point that a bus / cycle lane here with cyclists rejoin the pavement after the bus stop	1	1		1			1			1									1	1											1									
0208	The cycle lane and the pavement are very confusing here. Vehicles turning left into Hamilton road - very hard to see cycles coming eastwards and vehicles turning out of Hamilton Road right need to creep forward to get out at busy times of day - again blocking lane.	1	6/4/2023	https://www.google.com/maps/place/51.513774290822276%2C-0.29865919781586703/@51.513774290822276,-0.29865919781586703,1	46-47 The Mall, Ealing, London, W5 3TJ	Ealing	Ealing Broadway / Ealing Common	This junction does appear concerning - tree and wall reduce visibility for vehicles emerging from Hamilton Road but the raised table for pedestrians ends leaving	1	1	1	1			1	1		1									1	1																				
0209	Cycling should be banned. It's dangerous!	1	6/4/2023	https://www.google.com/maps/place/51.513839386208005%2C-0.3052127954690853/@51.513839386208005,-0.3052127954690853,17	6 Spring Bridge Rd, London, W5 2AA	Ealing Broadway	Ealing Broadway	Ban cycling																											1						1						
0210			6/4/2023	https://www.google.com/maps/place/51.51098161368252%2C-0.30469781133822593/@51.51098161368252,-0.30469781133822593,1																																											
0211			6/4/2023	https://www.google.com/maps/place/51.51536167782354%2C-0.3091610071390072/@51.51536167782354,-0.3091610071390072,17																																											
0212	Poor road surface	1	6/4/2023	https://www.google.com/maps/place/51.506746974224235%2C-0.2652261365430286/@51.506746974224235,-0.2652261365430286,17	7 Alfred Rd, London, W3 6LH	Acton central	South Acton	Southern end of Alfred Road requires resurfacing	1			1			1								1																									
0213	Poor road surface	1	6/4/2023	https://www.google.com/maps/place/51.50706751079401%2C-0.2517507184522083/@51.50706751079401,-0.2517507184522083,17	51 Bromyard Ave, London W3 7JY	East Acton	East Acton	South west section of Bromyard Avenue could do with improvement to pavement and highway for all users. Additionally cyclists are highly likely to use this	1			1			1	1		1					1				1	1	1																			
0214	Poor road surface	1	6/4/2023	https://www.google.com/maps/place/51.50909752337133%2C-0.2833364118115833/@51.50909752337133,-0.2833364118115833,17	51 Bromyard Ave, London W3 7JY			Duplicate of comment above therefore not re-logged																																							
0215			6/4/2023	https://www.google.com/maps/place/51.51042501374929%2C-0.27255794978487735/@51.51042501374929,-0.27255794978487735,1																																											
0216	Quality of the road is poor, needs resurfacing	1	6/4/2023	https://www.google.com/maps/place/51.51280187571353%2C-0.2763122772080817/@51.51280187571353,-0.2763122772080817,17	42 Rosemont Rd, London, W3 9LY	Acton	North Acton	Road surface on C41 Rosemont does appear Poor and includes full width speed humps.	1			1			1								1						1																			
0217			6/4/2023	https://www.google.com/maps/place/51.511907210930374%2C-0.2912317248513552/@51.511907210930374,-0.2912317248513552,17																																											
0218	Quality of the road needs improvement	1	6/4/2023	https://www.google.com/maps/place/51.50655912220671%2C-0.24934518864498045/@51.50655912220671,-0.24934518864498045,1	55 The Vale, London, W3 7RR	East Acton	East Acton / Southfield	Section of Uxbridge Road that does appear to be in poor condition	1			1			1			1					1																									
0219	Quality of the road needs improvement	1	6/4/2023	https://www.google.com/maps/place/51.50615154378999%2C-0.27055079435797325/@51.50615154378999,-0.27055079435797325,1	20 Coopers Court, Church Rd, London, W3 8PN	Acton	South Acton	Blue Route, condition of cycle lane and highway are poor in places				1			1								1						1																			
0220	Needs yellow lines where the pavement crosses to the canal.	1	6/4/2023	https://www.google.com/maps/place/51.52981645857129%2C-0.2682129614161788/@51.52981645857129,-0.2682129614161788,17	69 Park Royal Rd, London, NW10 7JJ	North Acton	North Acton	Pin appears incorrect - unsure of correct location													1																											
0221	Westgate is a nightmare. Single yellow lines so cars parked illegally all the time. Big lorries going to selco coming the other way so this is a death trap.	1	6/4/2023	https://www.google.com/maps/place/51.53283468886449%2C-0.2928923036743236/@51.53283468886449,-0.2928923036743236,17	5th Floor, West World, W Gate, London, W5 1DT	Hanger Lane	Hanger Hill	C85 and C40 - no cycle infrastructure and concerns appear justified - street as narrow with parking on both sides and lorries accessing industrial premises	1			1			1	1										1			1																			
0222			6/4/2023	https://www.google.com/maps/place/51.51107582707664%2C-0.3194233675681746/@51.51107582707664,-0.3194233675681746,17																																											
0223			6/4/2023	https://www.google.com/maps/place/51.509013959778294%2C-0.33617861535778726/@51.509013959778294,-0.33617861535778726,1																																											
0224			6/4/2023	https://www.google.com/maps/place/51.511578061614024%2C-0.2919328954481193/@51.511578061614024,-0.2919328954481193,17																																											

0281	Poor quality road surface	1	6/4/2023	https://www.google.com/maps/place/51.50697982683556%2C-0.2674719443013096/@51.50697982683556,-0.2674719443013096,17	70 High St, London, W3 6LE	Acton	South Acton	Assumed to be Uxbridge Road but original pin on Locarno Road which also looks like it would benefit from resurfacing	1			1			1			1					1																								
0282	Poor road surface	1	6/4/2023	https://www.google.com/maps/place/51.5068106544440834%2C-0.25549856325882914/@51.506810654440834,-0.25549856325882914,1	169 The Vale, London, W3 7RD	Acton Park	East Acton / Southfield	Assumed to be Uxbridge Road. No obvious cause for concern via Google Maps	1			1			1			1					1																								
0283			6/4/2023	https://www.google.com/maps/place/51.50846248307834%2C-0.27447028128605/@51.50846248307834,-0.27447028128605,17z																																												
0284			6/4/2023	https://www.google.com/maps/place/51.5078545644991405%2C-0.2728289482278434/@51.507854564991405,-0.2728289482278434,17																																												
0285			6/4/2023	https://www.google.com/maps/place/51.51015163807277%2C-0.2708119270486442/@51.51015163807277,-0.2708119270486442,17																																												
0286			6/4/2023	https://www.google.com/maps/place/51.508495620292365%2C-0.26909531327911296/@51.508495620292365,-0.26909531327911296,1																																												
0287			6/4/2023	https://www.google.com/maps/place/51.50894969567333%2C-0.2639025566262809/@51.50894969567333,-0.2639025566262809,17																																												
0288			6/4/2023	https://www.google.com/maps/place/51.52040225463061%2C-0.3068043067669346/@51.52040225463061,-0.3068043067669346,17																																												
0289	This is not a cycleway as there are *always* cars parked in it and restrictions are never enforced. It even makes me angry that you include it on the map, Ealing Council have no shame.	1	6/4/2023	https://www.google.com/maps/place/51.50902042202411%2C-0.3219657818842503/@51.50902042202411,-0.3219657818842503,17	25A Seaford Rd, London, W13 9HP	West Ealing	Hanwell Broadway / Walpole	Pin is on Seaford avenue which appears very faded but parking is not an issue as the cycle lane is on the main highway. It is likely this is a reference to the section of	1						1			1											1	1																	
0289.1		1			39 Broadway, Ealing, London, W13 9DA			Additional location for previous log	1						1			1											1	1																	
0290	What are you pretending is a cycleway here? The bike lane disappears through Ealing town centre, and there are always mopeds parked along the kerb	1	6/4/2023	https://www.google.com/maps/place/51.51199507277028%2C-0.3022942282504637/@51.51199507277028,-0.3022942282504637,17	45 High St, London, W5 5AW	Ealing Broadway	Ealing Broadway	Believed to be referring to the Broadway - general lack of cycle infrastructure and the short sections of cycle lane have illegal parking	1		1	1	1		1	1		1								1				1				1													
0291	There are always cars parked in the bike lane here. No enforcement.	1	6/4/2023	https://www.google.com/maps/place/51.50336192054058%2C-0.26553371114651503/@51.50336192054058,-0.26553371114651503,1	281 Acton Ln, London, W4 5DH	South Acton	South Acton / Southfield	Uncertain location. Parking in cycle lane	1			1			1			1												1				1													
0292	I don't recall any bike infrastructure here so why is it marked up as a bike lane?	1	6/4/2023	https://www.google.com/maps/place/51.49765308198995%2C-0.3295295573772261/@51.49765308198995,-0.3295295573772261,17	44 Southdown Ave, London W7 2AQ	Boston Manor	Northfield	Residential blue route with very minimal cycle infrastructure. Likely indicated as a blue route owing to Elthorne Park High School	1			1			1											1			1																		
0293	There's no segregated lane here and it's a really unpleasant place to ride	1	6/4/2023	https://www.google.com/maps/place/51.50210794378267%2C-0.34594978970682533/@51.50210794378267,-0.34594978970682533,1	Warren Farm Sports Centre, Southall UB2 4NE	Norwood Green	Norwood Green	Location unclear. Could be referring to Windmill Lane .								1												1																			
0294	Cyclists using this route represent a real danger to pedestrians and cyclists going in the other direction. While appreciating the lack of cars, unless there is new provision cyclists (eg a dedicated, boxed off lane) should be dissuaded rather than encouraged to use this route. I do not feel safe cycling here	1	6/4/2023	https://www.google.com/maps/place/51.51792615430015%2C-0.3463312884055769/@51.51792615430015,-0.3463312884055769,17	High Ln, London,	North Hanwell	North Hanwell	Consider lane markings on this route.	1			1			1											1	1																				
0295	Former LTN21 has become even more of a rat run since the filters were removed and is too dangerous for any cyclist (let alone for less confident ones like me). We need to remove parking on one side of wider streets (i.e. Northcroft Road, Erlesmere Road) and install segregated cycle lanes to make this area safer for cyclists and discourage commuters from using it as a shortcut.	1	6/4/2023	https://www.google.com/maps/place/51.50271516275778%2C-0.32245068566843615/@51.50271516275778,-0.32245068566843615,1	99 Salisbury Rd, London, W13 9TT	Northfield	Hanwell Broadway / Walpole / Northfield	Rat running in former LTN 21. Requesting cycle segregation on wider roads	1		1					1												1									1										
0296	Uxbridge Road is not safe to cycle on, since the cycle lane is not safe and segregated. This encourages motorists to park their cars on top of it and makes it even more dangerous for cycling.	1	6/4/2023	https://www.google.com/maps/place/51.5099273288311356%2C-0.3282871724848424/@51.509927328311356,-0.3282871724848424,17	154 - 156 Broadway, London, W13 0TL	West Ealing	Hanwell Broadway / Walpole	Uxbridge Road West Ealing - lack of cycle segregation and parking in cycle lanes	1			1	1		1	1		1										1		1																	
0297	Students should feel safe enough on their bikes to cycle to school and other places, but at the moment the children don't even feel safe walking around Ealing, let alone cycle anywhere. We need more safe, segregated cycle lanes that are connected to places like schools and discourage parents from using their cars to drop off their children.	1	6/4/2023	https://www.google.com/maps/place/51.50063143573228%2C-0.3296604635004674/@51.50063143573228,-0.3296604635004674,17	198 Boston Rd, London, W7 2AD	Boston Manor	Hanwell Broadway / Northfield	Pin drop near Elthorne Park High School etc. Increase cycle segregation in the area	1			1				1				1								1																	1		
0298	Fielding Primary School has turned their main playground into a staff car park since the introduction of PCN. Every morning staff turns up around the same time as the nursery school children. Pollution causes stunted lung growth and affects brain development in children. The council needs to find a solution with this school and do more to encourage staff, parents and the	1	6/4/2023	https://www.google.com/maps/place/51.50084515570943 5%2C-0.3200474263910924/@51.500845155709435,-0.3200474263910924,17	Fielding Primary School, Wyndham Rd, London, W13 9TE	Northfield	Northfield	Fielding primary school using playground as a staff car park and adding to school run traffic as a result	1		1				1	1																													1		
0299	This station is difficult to reach by bike and there is not enough bike storage, as much as in all other parts of Ealing. There is no way to safely store a cargo bike anywhere (which would be most suitable to replace a car for shopping trips etc.) let alone for enough bikes for a family with the size of local front gardens. We need more storage facilities and less spaces to park for cars, to	1	6/4/2023	https://www.google.com/maps/place/51.51382676452088%2C-0.3200474263910924/@51.51382676452088,-0.3200474263910924,17	53 Drayton Green Rd, London, W13 0NQ	West Ealing	West Ealing / Pitshanger	Insufficient cycle parking at West Ealing Station including for cargo bikes and difficult to reach by bike	1			1			1	1										1						1	1														
0300	Cycling west on the A40 is a delight until Concord Road, then the path shrinks, becomes mixed use, has low road signs, big puddles. This needs to be improved - ridiculus to detour via Alliance Road	1	6/4/2023	https://www.google.com/maps/place/51.525319175223615%2C-0.270639103760304/@51.525319175223615,-0.270639103760304,17z	30 Western Ave, London W3 0NJ	North Actcon	North Acton	New cycle lane ends at Cathleen Avenue - request for extension	1							1												1																			
0301	Cycle paths to and from North Acton, and from the A40 to Victoria Road are unusable; what exists is poorly signposted, requires a detour more uphill than needed. There needs to be a contra flow from A40 along the A4000 to Victoria Road, or take part of one of the pavements	1	6/4/2023	https://www.google.com/maps/place/51.522633221391494%2C-0.26006337958070835/@51.522633221391494,-0.26006337958070835,1	16 A4000, North Acton London, W3 6UL	North Acton	North Acton	Valid point - cycle infrastructure around North Acton appears poor quality and confusing.	1	1	1					1										1	1	1			1																
0302	My sons cycle along Queens Drive to (Ada Lovelace) school most days, the Ellen Wilkinson school is here too so there are lots of children with and without bikes. But there are also many parked cars, drivers racing to work and chicken running the chicanes. It is simple a question of whether a child needs to be killed before	1	6/4/2023	https://www.google.com/maps/place/51.51748507062562%2C-0.2857696707794388/@51.51748507062562,-0.2857696707794388,17	Inverness Court, Queen's Dr, London, W3 0HU	North Ealing	Hanger Hill	Queens drive is an obvious link route but lacks cycle provision despite there being a large high school. The road is wide therefore a segregated route could be considered.	1		1					1										1			1																		
0303	There is no provsion from Acton to Asda and Middlesex hospital. This is particularly needed as the road carries a lot of large wagons and has many pot holes	1	6/4/2023	https://www.google.com/maps/place/51.52697245104220 5%2C-0.26696782043180045/@51.526972451042205,-0.26696782043180045,1	Alchemy House, Park Royal Rd, London, NW10 7LQ	North Acton	North Acton	Park Royal Road has very limited cycle infrastructure for a major route. It may be possible to make the western pavement a shared segregated path.	1		1					1							1			1																					
0304	TfL promised that all Cross Rail stations would have cycle provision. Acton Main Line has NONE It has a great big open space perfect for cycle parking but not cycle racks at all. Now is there any cycle provision to get to Acton Main Line.	1	6/4/2023	https://www.google.com/maps/place/51.517226048190615%2C-0.2666674130221325/@51.517226048190615,-0.2666674130221325,17	9, London, W3 6AF	Acton Main Line	North Acton / East Acton	Lack of cycle parking at Acton Main Line, and lack of cycle infrastructure to connect to existing routes	1			1			1	1										1			1				1														
0305			6/4/2023	https://www.google.com/maps/place/51.50782147512239%2C-0.33437292210750424/@51.50782147512239,-0.33437292210750424,1																																												
0306			6/4/2023	https://www.google.com/maps/place/51.51243962849618%2C-0.3099269000705229/@51.51243962849618,-0.3099269000705229,17																																												
0307			6/4/2023	https://www.google.com/maps/place/51.50991695938709%2C-0.28661032236348305/@51.50991695938709,-0.28661032236348305,1																																												
0308			6/4/2023	https://www.google.com/maps/place/51.51011971793498%2C-0.32398893775214654/@51.51011971793498,-0.32398893775214654,1																																												
0309			6/4/2023	https://www.google.com/maps/place/51.50855355631503%2C-0.34421109939362093/@51.50855355631503,-0.34421109939362093,1																																												
0310	No cycle lean here, hard to filter safely and cars turn in after bus lane often without looking head east. Heading west also very bad, no cycle lane as bus lane ends before junction.	1	6/4/2023	https://www.google.com/maps/place/51.51082135021005%2C-0.3199007143805721/@51.51082135021005,-0.3199007143805721,17	10 Broadway, Ealing, London, W13 0SR	West Ealing	West Ealing / Walpole	Poor cycle infrastructure on Uxbridge Road in West Ealing	1			1			1	1		1								1																					
0311	Cars pull out in front of you as they have to turn their heads more to see you in the cycle lane turning out of Ingles road. The cycle lane is increasingly full of leaves and cars are impatient if you choose not to use it.	1	6/4/2023	https://www.google.com/maps/place/51.510923810039124%2C-0.28885628162305554/@51.510923810039124,-0.28885628162305554,1	13A Wolverton Gardens, London, W5 3LI	Ealing Common	Ealing Common	Poor driver behaviour could be improved with increased signage / road markings. Street cleaning needed	1			1			1			1							1		1																				
0312	Heading west pedestrians step into cycle lane without looking. Cyclist hit by pedestrian getting of bus illegally.	1	6/4/2023	https://www.google.com/maps/place/51.5130031309907 54%2C-0.2967927180576968/@51.513003130990754,-0.2967927180576968,17	4 The Common, London, W5 3TR	Ealing Common	Ealing Common	Frequency of cycle lane markings should be reviewed / increased throughout this new section of segregated / shared path - especially around the bus stops	1	1		1			1			1									1												1								
0313	Just a nightmare. First, the idea cyclists can behave like pedestrians and use pavements does not work. You have to cycle in the middle of the correct lane as changing lanes with speeding traffic is dangours. Moterista are particularly impatient here and almost every time I navigate these junctions I suffer a close pass with reving engine. I cycle this way so I can join the Paddington arm of	1	6/4/2023	https://www.google.com/maps/place/51.5226755010937 44%2C-0.25910515514275145/@51.522675501093744,-0.25910515514275145,1	3 Victoria Rd, Greater, North Acton London, W3 6UU	North Acton	North Acton	Infrastructure around North Acton station not feeling safe	1		1		1			1						1					1				1				1												
0314	I am generally okay on this roundabout but cars are often in the wrong lane heading east and heading west turning right you have to play chicken with eastbound traffic even though it's your right of way and you signal. I cycle fast on the curve so cars know I'm not going to let them out whilst also preparing to stop if it turns out they are nut cases!	1	6/4/2023	https://www.google.com/maps/place/51.50876871775274%2C-0.33420598682844416/@51.50876871775274,-0.33420598682844416,1	52 Uxbridge Rd, London, W7 3SU	Hanwell	Hanwell Broadway	Roundabout poor driver behaviour (a bit of a hotspot as routes converge but lacing cycle infrastructure)	1				1		1			1								1									1												
0315	Generally speaking most of the entrances in Northala Fields and Rectory park need to be resurfaced. The entrances to the park are bumpy and partially blocked by stones. They're not very inviting and make it difficult to move with buggies. The paths inside Northala fields are hazardous, especially those that aren't made from tarmac. They're bumpy as the rocks are exposed and	1	6/4/2023	https://www.google.com/maps/place/51.53882062342706%2C-0.37338673195716376/@51.53882062342706,-0.37338673195716376,1	Eighteen, Dolphin Rd, Northolt UB5 6UQ	Northala Fields	Greenford Broadway	Park entrances and paths need resurfacing (unable to confirm)	1			1			1								1																								Park pathways and entrances
0316			6/4/2023	https://www.google.com/maps/place/51.54232352244784%2C-0.37486690270533307/@51.54232352244784,-0.37486690270533307,1																																												
0317	we need a direct cycling lane from Target roundabout to Northolt station. Generally speaking the infrastructure for cycling in Northolt is poor. We can't rent bikes and there's no storage place for them.	1	6/4/2023	https://www.google.com/maps/place/51.54405719945857%2C-0.37546543822817746/@51.54405719945857,-0.37546543822817746,1	192 Church Rd, Northolt UB5 5AE	Northolt	Northolt Mandeville	C88 Church Road / Mandeville Road - lack of cycle infrastructure - should be reviewed. Respondent also feels there is a lack of hire bikes and bike storage in	1		1	1			1	1										1																					
0318	We need a direct cycling path from White Hart roundabout to Target Roundabout. Whenever you have a main road, there should be a cycling lane	1	6/4/2023	https://www.google.com/maps/place/51.54183523631199%2C-0.38071183906130734/@51.54183523631199,-0.38071183906130734,1	298 Church Rd, Northolt UB5 5AP	Northolt	Northolt Mandeville	Also C88 - this section is mainly shared bus lanes but only during peak hours - outside of these times most sections have no cycle infrastructure. Sections	1		1	1			1	1										1																					
0319	we need a designated cycling lane from Northolt station all the way down to Ealing Road and down Kensington Road towards Panson Roundabout. I know there will be some improvements coming up next year but i don't think there has been enough emphasis on cycling lanes.	1	6/4/2023	https://www.google.com/maps/place/51.536930519213975%2C-0.37124900565676633/@51.536930519213975,-0.37124900565676633,1	11 Hotspur Rd, Northolt UB5 6TN	Northolt	Northolt Mandeville	Good suggestion - add infrastructure and designation to Ealing Road heading South from Northfield station - much of this could be widening of existing	1		1	1			1	1										1			1																		
0320			6/4/2023	https://www.google.com/maps/place/51.52016491223926%2C-0.330727336866119/@51.52016491223926,-0.330727336866119,17z																																												
0321	Speeding traffic on Haslemere	1	6/4/2023	https://www.google.com/maps/place/51.49948267368368%2C-0.3237477708381875/@51.49948267368368,-0.3237477708381875,17	42 Haslemere Ave, London W13 9UJ	Boston Manor	Northfield	Speeding	1			1			1																			1	1												
0322	The design at his junction is dangerous and cycle lane is on wrong place; parking close to junction should also be prohibited 24/7 or at least in daylight hours	1	6/4/2023	https://www.google.com/maps/place/51.51006073179589 6%2C-0.31889755374593154/@51.510060731795896,-0.31889755374593154,1	63 Mattock Ln, London, W13 9LA	Lido	Walpole	Unhappy with junction design and parking adjacent. Parking restriction or double yellow line (south side of Mattock) could potentially be extended to provide more space for	1			1			1	1											1			1																	
0323	This gap between routes needs pavement cycleway on east side of bridge - particularly necessary for northbound cyclists	1	6/4/2023	https://www.google.com/maps/place/51.51359293047555%2C-0.31947154647511855/@51.51359293047555,-0.31947154647511855,1	Sinclair House, The Avenue, London, W13 8AG	West Ealing	Pitshanger / Ealing Broadway / Hanwell Broadway / Walpole	West Ealing / Drayton Green Road hotspot - no cycle infrastructure crossing bridge	1	1	1		1		1	1																															
0324	Improve road quality. Too many ditches and holes in the Ealing bike lanes	1	6/4/2023	https://www.google.com/maps/place/51.50985418299763%2C-0.2827734070012111/@51.50985418299763,-0.2827734070012111,17	354 Uxbridge Rd, London, W3 9SL			Believed to be referencing the cycle lane on Uxbridge Road which appears a little poor across the junction with Hale Lane	1			1			1			1					1																								
0325	Of the roads I cycle down marked up as quietways (mainly around South Ealing, Northfields, west Ealing and Boston Manor) I only identify with a couple as actually having cycle lanes and being cycle friendly - Boston Manor Road and Little Ealing lane - aside of the pedestrian/cycle lanes such as that in South ealing cemetery. So I'm not sure why they are classified as existing routes/quietways?	1	6/4/2023	https://www.google.com/maps/place/51.49947730555227%2C-0.30896963158548285/@51.49947730555227,-0.30896963158548285,1	46 Weymouth Ave, London W5 4SB	Walpole / Northfield	Walpole / Northfield	Culmington / Church rat running plus general residential blue route improvements	1			1			1														1								1										
0325.1		1			8 Church Ln, London, W5 5HB			Additional location for previous log	1			1			1														1								1										
0326			6/4/2023	https://www.google.com/maps/place/51.50728471141299%2C-0.26778512760394113/@51.50728471141299,-0.26778512760394113,1																																												
0327			6/4/2023	https://www.google.com/maps/place/51.509083028998226%2C-0.26596853106003016/@51.509083028998226,-0.26596853106003016,1																																												
0328			6/4/2023	https://www.google.com/maps/place/51.5099911635261%2C-0.28433629839401453/@51.5099911635261,-0.28433629839401453,1																																												
0329			6/4/2023	https://www.google.com/maps/place/51.50694617046843%2C-0.25656423854718335/@51.50694617046843,-0.25656423854718335,1																																												
0330			6/4/2023	https://www.google.com/maps/place/51.51357010 57041%2C-0.30574522304425367/@51.5135701057041,-0.30574522304425367,1																																												
0331	Need bike Lane on the avenue	1	6/4/2023	https://www.google.com/maps/place/51.51841549088846%2C-0.31936817964594244/@51.51841549088846,-0.31936817964594244,1	105 The Avenue, London, W13 8JT	West Ealing	Ealing Broadway	Request for cycle lane on the Avenue (part of Greenford - Ealing improvements)	1			1			1											1			1																		
0332			6/4/2023	https://www.google.com/maps/place/51.52021330 2466935%2C-0.3206095741154025/@51.52021330 2466935,-0.3206095741154025,17																																												
0333			6/4/2023	https://www.google.com/maps/place/51.51951900410666%2C-0.3195581481815646/@51.51951900410666,-0.3195581481815646,17																																												
0334			6/4/2023	https://www.google.com/maps/place/51.51079339780007%2C-0.3194623330381452/@51.51079339780007,-0.3194623330381452,17																																												
0335	PLEASE CONTINUE THE CYCLE PATH FROM WEST WALK TO EALING BROADWAY. THERE IS A CYCLE ROUTE ON WEST WALK AND THEN IS SUDDENLY STOPS AS YOU GO TOWARDS EALING BROADWAY.	1	6/4/2023	https://www.google.com/maps/place/51.51761297190229 5%2C-0.30026099828870834/@51.517612971902295,-0.30026099828870834,1	48F Mountfield Rd, London, W5 2NQ	Montpelier	Ealing Broadway / Hanger Hill	C85 improvements very limited indication of blue route	1			1			1											1			1																		

0336	VERY BUSY ROUTE IN CENTRAL EALING BROADWAY. NO CYCLE PATHS, CYCLE SYMBOLS OR CYCLE LANE. VERY DANGEROUS FOR CYCLIST AS THERE ARE LOADS OF BUSES PULLING IN AND OUT AND LOTS OF PEDESTRIANS ETC	1	6/4/2023	https://www.google.com/maps/place/51.51567347251754%2C-0.30227801946790755/@51.51567347251754,-0.30227801946790755,1	35 Haven Grn, London, W5 2NX	Ealing Broadway	Ealing Broadway	Lack of cycle infrastructure on approach to Ealing Broadway station. hotspot	1		
0337	PLEASE CONNECT UP THE CYCLE PATHS, WHY DO THEY NOT CONNECT ? MAKES NO SENSE, ESP AS THIS IS THE BUSIEST PART OF EALING.	1	6/4/2023	https://www.google.com/maps/place/51.51452471831133%2C-0.30222706663551424/@51.51452471831133,-0.30222706663551424,1	39 The Broadway, London, W5 2NP	Ealing Broadway	Ealing Broadway	Lack of cycle infrastructure heading south past Ealing Broadway station. hotspot	1		
0338	NO CYCLE LANES IN NORTHFIELDS, A VERY BUSY THROUGHFARE FOR CYCLIST BUT WE SEEM TO BE FORGOTTEN ABOUT HERE!	1	6/4/2023	https://www.google.com/maps/place/51.50150189268883%2C-0.315322833011428 8/@51.50150189268883,-0.315322833011428 8,17	164 Northfield Ave, London W13 9SB	Northfields	Walpole / Northfield	No cycle infrastructure on Northfield Avenue	1		
0339	A GREAT OPPORTUNITY TO OUT A CYCLE LANE IN HERE AND CONNECT UP THE CYCLEWAYS. WILL IT EVER HAPPEN ?	1	6/4/2023	https://www.google.com/maps/place/51.51377502740874%2C-0.30827334036789944/@51.51377502740874,-0.30827334036789944,1	Unit 31, Dickens Yard, Longfield Ave, London W5 2BF	Ealing Broadway	Ealing Broadway	No North / South link - use Longfield Avenue	1		
0340	It's very hard to cross the Uxbridge road to head up towards West Ealing station.	1	6/4/2023	https://www.google.com/maps/place/51.51056900973261%2C-0.31693009886495815/@51.51056900973261,-0.31693009886495815,1	12 Broomfield Rd, London, W13 9AP	West Ealing	West Ealing / Walpole	Minimal Uxbridge Road crossings and generally not adapted for cyclists	1		
0340.1		1			2 Broadway London, W13 0NG			Additional location for previous log	1		
0341			6/4/2023	https://www.google.com/maps/place/51.49882223231998%2C-0.3943914177063901/@51.49882223231998,-0.3943914177063901,17							
0342	I got knocked off on guru Nanak road the drivers do not check both directions at junctions. One way street for cars but not for bicycles	1	6/4/2023	https://www.google.com/maps/place/51.50083949846797%2C-0.3801256065577463/@51.50083949846797,-0.3801256065577463,17	Guru Nanak Rd, Southall UB2 4NP	Southall	Southall Green	The minimal cycle markings are very faded and there is likely to be a high rotation of cars parking and pulling out into the oncoming cyclists. Needs improvement	1	1	
0343	Speeding cars in Culmington road. Enforcement of action against drivers who blare their horns, rev their engines and generally intimidate cyclists.	1	6/4/2023	https://www.google.com/maps/place/51.50742714807584%2C-0.31016671613039337/@51.50742714807584,-0.31016671613039337,1	57 Culmington Rd, London,	Walpole	Walpole	Culmington Road - speeding and poor driver behaviour. Possible hotspot			
0344	Cycle lane along Uxbridge rd is badly maintained surface, grit,pot holes, stones, not regularly cleaned and dangerous to use	1	6/4/2023	https://www.google.com/maps/place/51.50838965992669%2C-0.2740108097127214/@51.50838965992669,-0.2740108097127214,17	235 High St, London, W3 9BY	Acton	North Acton / South Acton	Uxbridge Road Acton - street cleaning and highway (doesn't look too bad on Google)	1		
0345	The green surface and painted image of a bicycle are useless in combatting aggressive drivers. When is actual effective enforcement action going to be taken by police or council officials ?	1	6/4/2023	https://www.google.com/maps/place/51.501338372801264%2C-0.328910990603383 8/@51.501338372801264,-0.328910990603383 8,17	247 Boston Rd, London, W7 2AT	Boston Manor	Hanwell Broadway / Northfield	Poor driver behaviour in relation to (quite faded) cycle lanes and boxes	1		
0346	Moped parking outside Bens Scooters should be monitored daily. Petrol scooters are parked on yellow lines and within the pedestrian crossing zone. If they fail to comply the business should be closed down because their parking is a risk to not just cyclists but other road users.	1	6/4/2023	https://www.google.com/maps/place/51.50570564070876%2C-0.3361409137075455/@51.50570564070876,-0.3361409137075455,17	48 Lower Boston Rd, London, W7 2NP	Hanwell	Hanwell Broadway	Illegal parking on double yellow lines / zig zag / cycle lane at a dangerous point for cyclists	1	1	
0347	Confusing signage on road markings at approach to this crossing over Northfield avenue from Mattock Lane	1	6/4/2023	https://www.google.com/maps/place/51.509900042528535%2C-0.31856886272930707/@51.509900042528535,-0.31856886272930707,1	60-55 Mattock Ln, London, W13 9LA	Walpole	Walpole	hotspot - Mattock Lane road markings should be improved as outlined elsewhere	1		
0348	Ruislip road has parked cars.	1	6/4/2023	https://www.google.com/maps/place/51.53002846875112%2C-0.3639041485520278/@51.53002846875112,-0.3639041485520278,17	112 Ruislip Rd, Greenford UB6 9QH	Greenford	Lady Margaret / Greenford Broadway	Very faded road markings and parking in cycle lanes (pavement parking permitted but single yellow 7 - 7)	1		
0349			6/4/2023	https://www.google.com/maps/place/51.50641599250091%2C-0.26254350583495567/@51.50641599250091,-0.26254350583495567,1							
0350			6/4/2023	https://www.google.com/maps/place/51.51063790256809%2C-0.32109841593380706/@51.51063790256809,-0.32109841593380706,1							
0351			6/4/2023	https://www.google.com/maps/place/51.5090103059469%2C-0.33446733433508014/@51.5090103059469,-0.33446733433508014,1							
0352			6/4/2023	https://www.google.com/maps/place/51.499975135008725%2C-0.3239352761020031/@51.499975135008725,-0.3239352761020031,17							
0353			6/4/2023	https://www.google.com/maps/place/51.50911918731986%2C-0.31312413564607455/@51.50911918731986,-0.31312413564607455,1							
0354			6/4/2023	https://www.google.com/maps/place/51.52168457110578%2C-0.31955595559075567/@51.52168457110578,-0.31955595559075567,1							
0355			6/4/2023	https://www.google.com/maps/place/51.53994556690167%2C-0.3242766434569666/@51.53994556690167,-0.3242766434569666,17							
0356			6/4/2023	https://www.google.com/maps/place/51.513053837366556%2C-0.31002602523362066/@51.513053837366556,-0.31002602523362066,1							
0357			6/4/2023	https://www.google.com/maps/place/51.521652929898515%2C-0.29174408858811285/@51.521652929898515,-0.29174408858811285,1							
0358			6/4/2023	https://www.google.com/maps/place/51.50915433499422%2C-0.3397234434465113/@51.50915433499422,-0.3397234434465113,17							
0359			6/4/2023	https://www.google.com/maps/place/51.50623374776738%2C-0.2587510506371937/@51.50623374776738,-0.2587510506371937,17							
0360			6/4/2023	https://www.google.com/maps/place/51.50658068970238%2C-0.2678493511916291/@51.50658068970238,-0.2678493511916291,17							
0361			6/4/2023	https://www.google.com/maps/place/51.50844810030286%2C-0.28139931492998427/@51.50844810030286,-0.28139931492998427,1							
0362			6/4/2023	https://www.google.com/maps/place/51.513092343996675%2C-0.28098531416763217/@51.513092343996675,-0.28098531416763217,1							
0363			6/4/2023	https://www.google.com/maps/place/51.51042332598258%2C-0.3156602615448634/@51.51042332598258,-0.3156602615448634,17							
0364	This crossing is so dangerous for cyclists with no clear path to cycle. Cars drive very fast while it's a very steep road coming from Acton going to Ealing. Also, coming out of the roundabout, often UberEats mopeds and parked cars are in the way. Just like there are parked cars blocking the cyclist lane in between the roundabout and Ealing Common station. It really isn't a safe route for cyclists.	1	6/4/2023	https://www.google.com/maps/place/51.5083832236308%2C-0.27577187935531544/@51.5083832236308,-0.27577187935531544,1	272 High St, London, W3 9BH	Acton	North Acton / South Acton	Uxbridge Road / Gunnersbury Lane / Steyne Road junction / Roundabout in Acton. The junction with Gunnersbury heading West in particular is a little lacking in designated	1		1
0365	This crossing is so dangerous for cyclists with no clear path to cycle. Cars drive very fast while it's a very steep road coming from Acton going to Ealing. Also, coming out of the roundabout, often UberEats mopeds and parked cars are in the way. Just like there are parked cars blocking the cyclist lane in between the roundabout and Ealing Common station. It really isn't a safe route for cyclists.	1	6/4/2023	https://www.google.com/maps/place/51.5083148487155%2C-0.2745486896937366/@51.5083148487155,-0.2745486896937366,17	272 High St, London, W3 9BH	Acton	North Acton / South Acton	As previous but with pin on Roundabout rather than Gunnersbury Lane junction	1		1
0366	Parked cars blocking the cyclist lane.	1	6/4/2023	https://www.google.com/maps/place/51.508398319125334%2C-0.27727381405286744/@51.508398319125334,-0.27727381405286744,1	326 Uxbridge Rd, London, W3 9QP	Acton	North Acton / South Acton	Any loading or parking is likely to be illegal as no loading / parking most of the day (7 - 7 Mon -Fri)	1		
0367	Cars parked on double yellow at both corners, obstructing clear view to indicate if there's traffic coming from left of right.	1	6/4/2023	https://www.google.com/maps/place/51.509864034602224%2C-0.28649869012986606/@51.509864034602224,-0.28649869012986606,1	5, Grosvenor Parade, Uxbridge Rd, London, W5 3NN	Ealing Common	Ealing Common	Parking on double yellow lines (observed on Google Maps)	1		
0368			6/4/2023	https://www.google.com/maps/place/51.5241839618443 86%2C-0.37442659215341 4/@51.524183961844386,-0.374426592153414,17z							
0369			6/4/2023	https://www.google.com/maps/place/51.53709177818092%2C-0.3923870046611677/@51.53709177818092,-0.3923870046611677,17							
0370			6/4/2023	https://www.google.com/maps/place/51.53901537703626%2C-0.38823183397939776/@51.53901537703626,-0.38823183397939776,1							
0371			6/4/2023	https://www.google.com/maps/place/51.542286435423485%2C-0.3759181200916317/@51.542286435423485,-0.3759181200916317,17							
0372			6/4/2023	https://www.google.com/maps/place/51.512045092256464%2C-0.2714297162043766/@51.512045092256464,-0.2714297162043766,17							
0373	Often issues in underpass with flooding, broken glass etc.	1	6/4/2023	https://www.google.com/maps/place/51.535870113353546%2C-0.34607577158607405/@51.535870113353546,-0.34607577158607405,1	750-758 Greenford Rd, Greenford UB6 8QQ	Greenford	Central Greenford	Roundabout a40 / Greenford road. Underpass street cleaning	1		
0374	State of the road in this section is terrible.	1	6/4/2023	https://www.google.com/maps/place/51.509613608511124%2C-0.3358236411072135/@51.509613608511124,-0.3358236411072135,17	32 Cherington Rd, London, W7 3HJ	Hanwell	Hanwell Broadway	Likely to be Uxbridge Road but Cherington also appears to in in slightly poor condition	1		
0375			6/4/2023	https://www.google.com/maps/place/51.513375141512206%2C-0.2923819187270382/@51.513375141512206,-0.2923819187270382,17							
0376			6/4/2023	https://www.google.com/maps/place/51.51133481015629%2C-0.29255092551220496/@51.51133481015629,-0.29255092551220496,1							
0377	northfields ave and uxbridge rd jct is dangerous - already a death there	1	6/4/2023	https://www.google.com/maps/place/51.5109511432707%2C-0.31967111135759785/@51.5109511432707,-0.31967111135759785,1	6 Broadway Ealing, London, W13 0SR	West Ealing	Hanwell Broadway / Walpole	Uxbridge Road / Northfield / Drayton Bridge hotspot	1	1	
0378	The Uxbridge road from Ealing Broadway to Hanwell has a painted, unsegregated cycle lane most of the way. The road is congested, the cycle lane is continuously filled with parked cars and there is no enforcement. For example, every single day, there is a line of cars parked from Deans gardens all the way to Coldershaw Rd. This makes it dangerous for cyclists abbd pedestrians and holds up	1	6/4/2023	https://www.google.com/maps/place/51.51073609053387%2C-0.3278845533003705/@51.51073609053387,-0.3278845533003705,17	129 Broadway, London, W13 9BF	West Ealing / Hanwell	Hanwell Broadway / Walpole	Cycle lane parking; 'no parking' 8am - 6pm' but 'loading only' outside of peak times. The 'loading only' is seemingly being abused	1		
0379	Why o why did you not work with Hounslow and build a segregated cycle route from BM tube station northwards to the Uxbridge road? There is no reason why you couldn't apart from political will. The current lan northbound dumps cyclists onto the pavement outside the tube station and 10 yards from a busy bus stop. If you wanted to design something to discourage cycling, you couldn't have done	1	6/4/2023	https://www.google.com/maps/place/51.498448216094665%2C-0.32635390464194947/@51.498448216094665,-0.32635390464194947,1	Harvester Royal Hanwell, Royal Harvester, Boston Rd,	Bsoton Manor	Hanwell Broadway / Northfield	End of segregated cycle lane. Reference to Bus Stop north of the station	1	1	1
0380	There's a north/south hole in your already fragmented network around west Ealing station. It's such a pity that it's practically impossible to cycle safely to WE station from the south, especially given the extensive work done on it for crossrail. The traffic lights at Hastings Road should give proper priority to cyclists to allow them to get up the hill then on to the station. Also, frankly, I don't	1	6/4/2023	https://www.google.com/maps/place/51.514880377303186%2C-0.3189545278471284/@51.514880377303186,-0.3189545278471284,17	1, Castle Hill Parade, The Avenue, London, W13 8JP	West Ealing	Pitshanger / Ealing Broadway / Hanwell Broadway / Walpole	Lack of cycle infrastructure around West Ealing station preventing North / South travel - also concerns about volume of traffic and traffic behaviour on The Avenue as a	1	1	1
0381	Just now you can highlight the Uxbridge road in Acton as a 'safe' route beggars belief. Once again, cars park in the painted cycle lane, drivers are aggressive and there is no enforcement of any offences. Please enforce the rules that are already there, stop pandering to entitled motorists and build a PROPERLY SEGREGATED lane all along the Uxbridge road. Paint doesn't work. Go and look at	1	6/4/2023	https://www.google.com/maps/place/51.5083553429223%2C-0.27340140000586377/@51.5083553429223,-0.27340140000586377,1	235 High St, London, W3 9BY	Acton	North Acton / South Acton	Acton Uxbridge Road; Lack of segregation, parking in cycle lanes, lack of enforcement etc	1		
0382	Along Mattock lane and the Grove, you could have a quiet cycle route all the way from Ealing Common to West Ealing. All you need to do is build up a bit of courage and stop non-residents from driving along these roads. Simple really!!	1	6/4/2023	https://www.google.com/maps/place/51.51142358940666%2C-0.3081206333621589/@51.51142358940666,-0.3081206333621589,17	8 Mattock Ln, London, W5 5BG	Matock Lane	Walpole / Ealing Common	Request to stop rat running on Mattock / The Grove	1		
0383	Not a cycle path. It's a busy bus lane on a busy road with a poor road surface. I avoid it if I can	1	6/4/2023	https://www.google.com/maps/place/51.51288584378977%2C-0.3074403257172009/@51.51288584378977,-0.3074403257172009,17	Ealing Town Hall, New Broadway, London, W5 2BY	Ealing Broadway	Ealing Broadway	This section of Uxbridge Road / The Broadway is busy shared bus lane	1		
0384	It's just a normal road, with a poor surface. Not a designated or segregated lane. Only a bit safer because it's a bit quieter	1	6/4/2023	https://www.google.com/maps/place/51.52008137869955%2C-0.31920449445651977/@51.52008137869955,-0.31920449445651977,1	1 St Stephen's Ave, London W13 8ES	West Ealing / The Avenue	Ealing Broadway	Improvements needed to The Avenue	1		
0385	The cycling crossing has grit and stones on it. Not swept at all. Could cause a puncture	1	6/4/2023	https://www.google.com/maps/place/51.5248627512465%2C-0.3209693879883191/@51.5248627512465,-0.3209693879883191,17	53 Scotch Common, London, W13 8DL	Pitshanger	Pitshanger	Street cleaning	1		
0386	Not a proper segregated cycle path. Drivers virtually ignore it and swerve into it at times when crossing over the humps. Should be segregated. also, it's only in one direction.	1	6/4/2023	https://www.google.com/maps/place/51.53412159571284%2C-0.3239427368402503/@51.53412159571284,-0.3239427368402503,17	2 Dawlish Ave, Perivale, Greenford UB6 8AB	Perivale	Perivale	Horsenden Lane cycle path appears very faded. Request for 2 way cycle lane / segregation - might be possible if parking is fully removed on the west side and	1		1
0387	What use is a cycle path/route if it doesn't continue down along the whole road?	1	6/4/2023	https://www.google.com/maps/place/51.51482821469136%2C-0.3144220012891519/@51.51482821469136,-0.3144220012891519,17	99 Gordon Rd, London, W13 8PR	West Ealing / Ealing Broadway	Ealing Broadway	Lack of cycle infrastructure on these blue routes which form part of the new Greenford - Ealing	1		
0388			6/4/2023	https://www.google.com/maps/place/51.510943598372506%2C-0.3270157464124779/@51.510943598372506,-0.3270157464124779,17							
0389	Enforcemwnt of cycling lane is needed	1	6/4/2023	https://www.google.com/maps/place/51.51105528573554%2C-0.3281548470534901/@51.51105528573554,-0.3281548470534901,17	99 Gordon Rd, London, W13 8PR	West Ealing / Hanwell	Hanwell Broadway / Walpole	Assumed to be Uxbridge Road cycle lane parking west of Deans Garden	1		
0389.1		1			142 The Broadway, Ealing, London, W13 0TL			Additional location for previous log	1		
0390	Repaint of cycle lane needed	1	6/4/2023	https://www.google.com/maps/place/51.504999213462284%2C-0.3343089916831099/@51.504999213462284,-0.3343089916831099,17	149 Boston Rd, London, W7 3SA	Boston Manor	Hanwell Broadway / Northfield	Boston Road cycle lanes very faded	1		

0391	Fix the cycle lane under iron bridge	1	6/4/2023	https://www.google.com/maps/place/51.50979540394813%2C-0.35374252417218255/@51.50979540394813,-0.35374252417218255,1	Iron Bridge, Uxbridge Rd, Southall UB1 3EG	Iron Bridge	Dormers Wells / Southall Broadway / Norwood Green	Iron Bridge cycle infrastructure improvements	1		1		1			1		1									1	1			1																	
0392	Dangerous whem dark	1	6/4/2023	https://www.google.com/maps/place/51.497490583504714%2C-0.3021241526493412/@51.497490583504714,-0.3021241526493412,17	15 Chilton Ave, London W5 4RU	South Ealing	Northfield	C86 Clayponds Avenue street lighting, possibly personal safety	1			1			1								1																							
0393			6/4/2023	https://www.google.com/maps/place/51.504841680759576%2C-0.3277724712890584/@51.504841680759576,-0.3277724712890584,17																																								
0394	Doesn't feel safe.	1	6/4/2023	https://www.google.com/maps/place/51.52400111854227%2C-0.29225795466534255/@51.52400111854227,-0.29225795466534255,1	St Augustine's Priory School, Hillcrest Rd, London, W5	Hanger Lane	Hanger Hill	Hanger Lane / Hillcrest junction looks quite dangerous for cyclists and pedestrians heading North in particular as there is limited visibility at the junction -	1	1	1				1	1			1			1					1	1	1		1																	
0395			6/4/2023	https://www.google.com/maps/place/51.52846002708297%2C-0.2873656054221785/@51.52846002708297,-0.2873656054221785,17																																								
0396			6/4/2023	https://www.google.com/maps/place/51.522105282624935%2C-0.27414767939678786/@51.522105282624935,-0.27414767939678786,1																																								
0397			6/4/2023	https://www.google.com/maps/place/51.52103717129251%2C-0.26341884333721755/@51.52103717129251,-0.26341884333721755,1																																								
0398			6/4/2023	https://www.google.com/maps/place/51.51291870645044%2C-0.27595012385479567/@51.51291870645044,-0.27595012385479567,1																																								
0399			6/4/2023	https://www.google.com/maps/place/51.50800481914453%2C-0.3433450116437431/@51.50800481914453,-0.3433450116437431,17																																								
0400	cars parked in cycle lane	1	6/4/2023	https://www.google.com/maps/place/51.50971922072422%2C-0.3271543807931132/@51.50971922072422,-0.3271543807931132,17	129 Broadway, London, W13 9BF	West Ealing	Hanwell Broadway / Walpole	Uxbridge Road hotspot. Parking in cycle lane ('loading' permitted outside of peak hours)	1			1	1		1	1		1												1																		
0401	narrow road	1	6/4/2023	https://www.google.com/maps/place/51.508393254325256%2C-0.3408303688378389/@51.508393254325256,-0.3408303688378389,17	176 Uxbridge Rd, London, W7 3TB	Hanwell Broadway	Hanwell Broadway	Unsure of point - logged as road safety										1				1																										
0402	(from Acton towards Ealing) There's a nice little separated cycle lane to get around the roundabout however where it ends is where the road opens into two lanes with the left lane being a left-turn only lane, then traffic lights. I have never been able to navigate safely from end of cycle lane/left-turn lane into main traffic going straight on (not helped by it's a very short steep hill (need both	1	6/4/2023	https://www.google.com/maps/place/51.50740158767962%2C-0.2718636641900618/@51.50740158767962,-0.2718636641900618,17	253 High St, London, W3 9BY	Acton	North Acton / South Acton	All valid in relation to the end of the segregated cycle lane and the Gunnersbury Lane junction hotspot	1	1	1		1		1	1		1									1	1							1													
0403	The "Quiet" route that is signposted up Rusthall Avenue and into Southfield park diverts onto Carlton Road (via Bayham Rd & Somerset Road (I think)) and then into Southfield Park. The route marked on the map is a much more sensible route	1	6/4/2023	https://www.google.com/maps/place/51.50254562774833%2C-0.2628159956939924/@51.50254562774833,-0.2628159956939924,17	83 Carlton Rd, London, W4 5DY	Bedford Park	Southfield	Both routes appear to be sign posted, the existing c49 avoids all of Southfield Road whereas the blue alternative route is simpler. Much of a muchness but it could	1			1			1														1																			
0404	Scary junction	1	6/4/2023	https://www.google.com/maps/place/51.50699471748624%2C-0.2458236761542687/@51.50699471748624,-0.2458236761542687,17	8 The Vale Uxbridge Rd, London, W3 7SB	East Acton / Shepherds Bush	East Acton / Southfield	Borough boundary on Uxbridge Road / junction with Old Oak Road. Infrastructure and road condition are poor	1		1	1			1	1		1				1				1																						
0405	Cycle lane not sufficiently separate from the traffic	1	6/4/2023	https://www.google.com/maps/place/51.50657255086073%2C-0.25360914709650295/@51.50657255086073,-0.25360914709650295,1	117 The Vale, London, W3 7RQ	East Acton / Shepherds Bush	East Acton / Southfield	Cycle segregation ends to accommodate 'loading only' outside of peak hours. Concerns elsewhere on Uxbridge Road of this being abused are likely to be	1			1			1	1		1										1		1																		
0406			6/4/2023	https://www.google.com/maps/place/51.525273866053226%2C-0.33718027358476954/@51.525273866053226,-0.33718027358476954,1																																								
0407			6/4/2023	https://www.google.com/maps/place/51.50856485393257%2C-0.3436214095473078/@51.50856485393257,-0.3436214095473078,17																																								
0408			6/4/2023	https://www.google.com/maps/place/51.503436166764246%2C-0.3426772719740656/@51.503436166764246,-0.3426772719740656,17																																								
0409	Road is narrow through Southall and the surface has some big potholes & around drains which mean you have to pull out into traffic or risk damaging your wheels.	1	6/4/2023	https://www.google.com/maps/place/51.51188629265111%2C-0.37957323531548015/@51.51188629265111,-0.37957323531548015,1	70 The Broadway, Southall UB1 1QD	Southall	Southall Broadway	Likely to mean the cycle lane section near the town hall which is narrow, faded and road condition is poor in places	1			1			1			1					1																									
0409.1		1			9 High St, Southall UB1 3HA			Additional location for previous log	1			1			1			1					1																									
0410	This roundabout is a nightmare, it was much safer when there were traffic lights. Drivers are anxious to get across it and don't seem to see you or prefer to ignore cyclists. People also launch themselves onto the zebra crossing without looking. It's also bad if you're a driver.	1	6/4/2023	https://www.google.com/maps/place/51.50928659540648%2C-0.33451212386528484/@51.50928659540648,-0.33451212386528484,1	71 Uxbridge Rd, London, W7 3PX	Hanwell	Hanwell Broadway	General road safety and minimal cycle infrastructure at the cemetery roundabout. hotspot	1		1		1		1	1		1				1				1					1				1													
0411	The canal towpath is too narrow from Hanwell to Brentford for all the pedestrians + dogs, runners & cyclists, and the surface is inconsistent and very poor, muddy, rutted etc in places. Also the vegetation and bushes are not pruned so this narrows the path and pushes users towards the canal.	1	6/4/2023	https://www.google.com/maps/place/51.50402083059452%2C-0.34479240117571086/@51.50402083059452,-0.34479240117571086,1	62-60 Green Ln, London, W7 2PB	Hanwell Broadway / Boston Manor	Hanwell Broadway	General cycle path improvements	1			1			1	1					1																											
0412	This does not feel a safe route and it's narrow so difficult to pass people.	1	6/4/2023	https://www.google.com/maps/place/51.50466714617118%2C-0.365258633830865/@51.50466714617118,-0.365258633830865,17z	20 Feldspar Grove, Southall UB2 4QR	Southall	Southall Broadway / Norwood Green	Glade Lane - assumed to be a personal safety concern	1			1			1																	1									1							
0413	The bushes are encroaching on the road & need drastically cutting back so you don't have to swerve to avoid getting them in your face. There needs to be a cycle lane created on the Warren Farm side and a better footpath (to be shared by cyclists) on the western side to make this useful route to Osterley & retailers on A4 safer.	1	6/4/2023	https://www.google.com/maps/place/51.50076692594163%2C-0.3510965702322322/@51.50076692594163,-0.3510965702322322,17	Warren Farm Nature Reserve, Southall UB2 4NE	Windmill Lane / Warren Farm	Norwood Green	Windmill Lane in this section is narrow which makes improvements challenging although suggestion is otherwise valid	1		1	1			1	1								1		1																						
0414	I am not a fan of shared cycling+pedestrian paths	1	6/4/2023	https://www.google.com/maps/place/51.51244180652158%2C-0.2986027515523437/@51.51244180652158,-0.2986027515523437,17	39 The Mall Ealing, London, W5 3TJ	Ealing Common	Ealing Common	Assumed to be a reference to the cycle paths along Ealing Common - as noted elsewhere improvements could be made to designation but the respondent would like	1			1			1	1		1									1	1																				
0415	No route here	1	6/4/2023	https://www.google.com/maps/place/51.49784698182548%2C-0.3951115119644921/@51.49784698182548,-0.3951115119644921,17	280 Western Rd, Southall UB2 5JT	Southall Green	Southall Green	No designated routes in this area - western road is narrow and busy	1			1				1										1																						
0416	Remove the irrelevant bricked structure and replace with bus stop and cycle path	1	6/4/2023	https://www.google.com/maps/place/51.50504106500801%2C-0.3793553483184753/@51.50504106500801,-0.3793553483184753,17	Spiritualist Church, Hortus Rd, The Green, Southall UB2 4AL	Southall	Southall Green	Large planter on the western side of the roundabout just south of Southall station - if the footprint was reduced a segregated cycle lane could be added. If removed	1		1					1										1													1									
0417	Open this route to aid cyclists	1	6/4/2023	https://www.google.com/maps/place/51.50641391535218%2C-0.37869841202686993/@51.50641391535218,-0.37869841202686993,1	12 The Crescent, Southall UB1 1BE	Southall	Southall	Just North of the station there is a connection to 'The Straight' via The Crescent. Presumably this route is now open? If so cycle routes should be updated.	1			1		1																																		
0418	This route was never designed for cyclists	1	6/4/2023	https://www.google.com/maps/place/51.51133581309685%2C-0.3756389956644002/@51.51133581309685,-0.3756389956644002,17	4-6 The Broadway, Southall UB1 1PS	Southall	Southall Broadway / Dormers Wells	Entirely fair comment - c39 - cycle infrastructure does not appear to have been added as part of the redesign of the western section of Southall Broadway	1			1			1	1		1								1																						
0419	Tree roots pushing up tarmac now very hazardous in places.	1	6/4/2023	https://www.google.com/maps/place/51.52506091703176%2C-0.3370698446773712/@51.52506091703176,-0.3370698446773712,17	Cuckoo Ave, London, W7 1BW	Castle Bar Park	North Hanwell	Path down the centre of Cuckoo Avenue - highly likely that roots will be a problem over time - difficult to assess remotely how problematic it is at the moment	1			1			1								1																									
0420	Although wand have been placed here, they often show signs of damage from traffic. This part of the route does not feel safe to me.	1	6/4/2023	https://www.google.com/maps/place/51.50846338496651%2C-0.34327111191980286/@51.50846338496651,-0.34327111191980286,1	343-345 Uxbridge Rd, Hanwell Southall UB1 3ED	The Viaduct, Hanwell	Hanwell Broadway / Norwood Green	Still feels dangerous even with increased segregation - not sure what further steps could be taken while maintaining traffic flow.								1		1										1																				
0421	This part of Boston Road does not feel safe to me, and I always avoid by going via old Hanwell. Very busy most of the day and exacerbated by large commercial vehicles going to/from Trumper's Way. In contrast with the Hounslow segregated scheme going south from Boston Manor Station, this is a nightmare.	1	6/4/2023	https://www.google.com/maps/place/51.50364189030519%2C-0.3327139372371857/@51.50364189030519,-0.3327139372371857,17	Boundary House, Boston Rd, London, W7 2QE	Boston Manor	Hanwell Broadway / Northfield	Boston Road - lack of segregation	1			1	1			1				1		1						1																				
0422	Not used this part of the towpath for 6 months, but when I was last down there, this section of the route had become very rough and eroded.	1	6/4/2023	https://www.google.com/maps/place/51.50318651797077%2C-0.34194073624841614/@51.50318651797077,-0.34194073624841614,1	Billetts Hart Cl, London, W7 2PY	Boston Manor (Canal)	Norwood Green / Hanwell Broadway	Canal towpath - this section remains dirt track	1			1				1					1																											
0423	Road in poor condition near HS2 works	1	6/4/2023	https://www.google.com/maps/place/51.5246619871421%2C-0.2567161063717194/@51.5246619871421,-0.2567161063717194,17	Studio 20 Studios,, Victoria Rd, Acton NW10 6ND	North Acton	North Acton	A4000 Victoria Road - Cycle markings very faded and road in poor condition around HS2 works	1			1			1	1							1				1																					
0424	This cycle route goes nowhere - it needs extending along Park Royal Road towards North Acton, as this is currently very unsafe to cycle alone with the parked cars and narrow lanes	1	6/4/2023	https://www.google.com/maps/place/51.52380048580068%2C-0.26516130092437473/@51.52380048580068,-0.26516130092437473,1	1a Park Royal Rd, London, W3 6XA	North Acton	North Acton	Park Royal ROad has long sections without any cycle infrastructure and nothing to indicate on the sections without a cycle lane that this is a blue cycle route	1			1			1											1			1																			
0425	Could a cycle lane between West Acton and North Ealing be built? Traffic regularly gives cyclists very little room on this rat run	1	6/4/2023	https://www.google.com/maps/place/51.517550978474475%2C-0.28558321989270885/@51.517550978474475,-0.28558321989270885,1	2 Thanet Court, Queens Drive, London, W3 0HW	North Ealing / West Acton	Hanger Hill	Queens Drive rat run - key route East / West that links various cycle routes. Should be considered for improvements	1			1	1		1	1										1			1																			
0426	The footbridge over the A40 regularly littered with broken glass, leading increased risk of puncture. It needs to be swept more regularly.	1	6/4/2023	https://www.google.com/maps/place/51.53353041246145%2C-0.3241148551190798/@51.53353041246145,-0.3241148551190798,17	5 Western Ave, Perivale, Greenford UB6 8TF	Perivale	Perivale	Foot / cycle bridge over A40 on C86 - street cleaning	1			1		1											1																							
0427	The steps up from the grand union canal prevent a smooth interchange between the grand union canal and going northbound on oldfield lane north	1	6/4/2023	https://www.google.com/maps/place/51.547791535775325%2C-0.3443335776914447/@51.547791535775325,-0.3443335776914447,17	425 Oldfield Ln N, Greenford UB6 0AS	Greenford	Central Greenford	Steps can be avoided but it's a long way round - a short section of cycle rail up to the road would help as would clearing a basic track alongside the steps on the	1			1		1							1																											
0428	Road is full of potholes or drains. It's a nightmare to cycle on	1	6/4/2023	https://www.google.com/maps/place/51.50916693688665%2C-0.28431940199659334/@51.50916693688665,-0.28431940199659334,1	370-356 Uxbridge Rd, London, W3 9SL	Ealing Common / Acton	Ealing Common / North Acton	Uxbridge Road between Ealing Common station and Twyford Gardens. Poor road surface. Mostly the junctions that appear to be struggling	1						1			1					1																									
0429	Sure, it's painted green, but the surface is awful. And it's only on one side of the road. It's a half-attempt at making it "cyclable".	1	6/4/2023	https://www.google.com/maps/place/51.50626517851006%2C-0.2706304421276928/@51.50626517851006,-0.2706304421276928,17	20 Church Ln, London, W3 8PP	Acton	South Action	The cycle lane on Church Road is in poor condition - could do with attention	1			1				1							1																									
0430	There's no separate cycle lane, it's a normal road so no idea how or why this is labeled as a cycle route. What's the benefit or difference to any other road?	1	6/4/2023	https://www.google.com/maps/place/51.50840877258357%2C-0.26932152412842525/@51.50840877258357,-0.26932152412842525,1	104a Churchfield Rd, London, W3 6BY	Acton Central	South Acton	C41 - Churchfield Road. No cycle infrastructure or cycle route designation	1			1			1											1			1																			
0431	Cycling around Ealing Broadway station feels very unsafe. Cars don't care.	1	6/4/2023	https://www.google.com/maps/place/51.513840414970375%2C-0.30320830170187385/@51.513840414970375,-0.30320830170187385,1	Haart Estate Agents, 17 The Broadway, London, W5 2NH	Ealing Broadway	Ealing Broadway	General Road safety around Ealing Broadway (hotspot)	1				1		1	1						1																										
0432	Potholes, drains and speed bumps make this road difficult for less confident people to cycle on. And there's no separately between you and vehicle traffic making it feel unsafe.	1	6/4/2023	https://www.google.com/maps/place/51.49581839871857%2C-0.26206454248635325/@51.49581839871857,-0.26206454248635325,1	The Bedford Park Surgery, 55 S Parade, Chiswick, London, W4	Bedford Park	Southfield	South Parade - general road condition including speed bumps and lack of cycle lane (blue routes here are through the park not on street)	1			1			1							1	1						1																			
0433			6/4/2023	https://www.google.com/maps/place/51.52899139778755%2C-0.327054136284759/@51.52899139778755,-0.327054136284759,17z																																								
0434	Cycle lanes down Ealing part of the Boston Manor road never enforced. Parking is endemic particularly near Elthorne Park.. And it feels unsafe dodging in and out of lane for this reason	1	6/4/2023	https://www.google.com/maps/place/51.503923104971506%2C-0.3339487166018218/@51.503923104971506,-0.3339487166018218,17	128 Boston Rd, London, W7 2HJ	Boston Manor	Hanwell Broadway / Northfield	Parking in cycle lane	1			1	1		1					1										1																		
0435	Road surface on Uxbridge road cycle lane appalling. No safe separation from traffic on a major road. Very difficult to turn right onto road.	1	6/4/2023	https://www.google.com/maps/place/51.51114019129685%2C-0.3272168963130939/@51.51114019129685,-0.3272168963130939,17	142 The Broadway, Ealing, London, W13 0TL	Hanwell / West Ealing	Hanwell Broadway / Walpole	Uxbridge Road between cemetery and deans garden hotspot. General road surface and lack of infrastructure	1		1		1		1	1		1					1			1		1																				
0436	Can be dangerous going down hill. Had someone drive into me once opposite the garage as lanes are too small.	1	6/4/2023	https://www.google.com/maps/place/51.50845962066205%2C-0.3406290416067126/@51.50845962066205,-0.3406290416067126,17	201 Uxbridge Rd, London, W7 3TB	Hanwell	Hanwell Broadway	Cycle lane (and the main carriageway) are narrow and lines are faded.	1			1	1		1	1		1									1																					
0437	this is not really a cycle route IMO	1	6/4/2023	https://www.google.com/maps/place/51.50852185703604%2C-0.3522538079773829/@51.50852185703604,-0.3522538079773829,17	2 Alderson Pl, Southall UB2 4UH	Ealing Hospital	Norwood Green	Odd comment - lacking cycle designation but otherwise useful to the residents of the area																																								
0438	Got punctures cycling down here, even though it is a lovely route, the ground is just not designed for cyclists on the way to Brentford.	1	6/4/2023	https://www.google.com/maps/place/51.50087070692401%2C-0.3382311590759368/@51.50087070692401,-0.3382311590759368,17	41 Dock Meadow Reach, London, W7 2QN	Boston Manor (Canal)	Hanwell Broadway	Canal path currently just dirt track	1			1				1					1																											
0439	Needs to be cycle storage here.	1	6/4/2023	https://www.google.com/maps/place/51.50797327669467%2C-0.35018807669635166/@51.50797327669467,-0.35018807669635166,1	28 W Park Rd, Southall UB2 4UL	Ealing Hospital	Norwood Green	Cycle storage request (lots of driveways and on-street parking). A cycle hanger was recently installed nearby but is already full.	1			1			1																		1															
0440	Would be nice to have protected cycle storage like we have in the shopping centre outside of ealing town centre near the co-working space areas. Makes sense as more people are working outside of the office than ever before.	1	6/4/2023	https://www.google.com/maps/place/51.512701506449055%2C-0.3095280834900027/@51.512701506449055,-0.3095280834900027,17	Longfield House, 18-20 Uxbridge Rd, London, W5 2SR	Ealing Broadway	Ealing Broadway	Request for a cycle hub essentially	1		1					1		1															1															
0441	Surface and drainage needs improving. Proper segregation from pedestrian pavement as well	1	6/4/2023	https://www.google.com/maps/place/51.527739523759514%2C-0.292907743468207/@51.527739523759514,-0.292907743468207,17z	Garrick Cl, London, W5 1AS	Hanger Hill	Hanger Hill	A406 cycle lane condition - appears fine on Google but designation could be improved	1			1			1				1				1				1	1																				
0442	Road is used as a rat run, not safe for cyclists as vehicles squeeze past at speeds above limit.	1	6/4/2023	https://www.google.com/maps/place/51.543382547115975%2C-0.32578089715473046/@51.543382547115975,-0.32578089715473046,1	Unit 1, C Canal Wharf, Horsenden Ln N, Horsenden,	Horsenden Hill	North Greenford / Perivale	C86 runs adjacent to Horsenden Lane not on the highway - it may be helpful to improve road markings around the entrance and exit points near the bridge and to	1			1			1												1		1																			
0443	Needs to be replaced / supplemented by a direct safe route on the A312	1	6/4/2023	https://www.google.com/maps/place/51.55533809264573%2C-0.35307505609027734/@51.55533809264573,-0.35307505609027734,1	12 Russell Rd, Northolt UB5 4QR	Northolt Park	North Greenford	Suggested improvement to A312 Northolt Road is Harrow not Ealing																																								
0443.1		1			Unit 20, Station Parade, Northolt Rd, South Harrow,			Additional location for previous log																																								
0444	Segregated route with parking enforcement needed	1	6/4/2023	https://www.google.com/maps/place/51.50984756802082%2C-0.34964182855121484/@51.50984756802082,-0.34964182855121484,1	Unit 6-7, Triangle Centre, Uxbridge Rd, Southall UB1 3EJ	Ealing Hospital	Norwood Green	Cycle lane on North Side very faded and could be segregated. South side could also be segregated potentially but is less faded. Parking concern unlikely to be	1			1			1	1		1									1	1		1				1														
0445	Route needs to be cleaned regularly, needs to be continuous and parking enforcement applied	1	6/4/2023	https://www.google.com/maps/place/51.50685871667545%2C-0.2691649459194667/@51.50685871667545,-0.2691649459194667,17	106-112 High St, London, W3 6QX	Acton	South Acton	Uxbridge Road in Acton around the town hall. Cycle lanes are patchy and faded and some sections have permitted 'loading'	1		1	1	1		1	1		1							1	1				1																		

0502			6/4/2023	https://www.google.com/maps/place/51.50891443337662%2C-0.2562370010417703/@51.50891443337662,-0.2562370010417703,17																																										
0503			6/4/2023	https://www.google.com/maps/place/51.512020633436876%2C-0.3811785479270613/@51.512020633436876,-0.3811785479270613,17																																										
0504			6/4/2023	https://www.google.com/maps/place/51.511219374899625%2C-0.374569584914366/@51.511219374899625,-0.374569584914366,17z																																										
0505			6/4/2023	https://www.google.com/maps/place/51.50228988492689%2C-0.32935687586473694/@51.50228988492689,-0.32935687586473694,1																																										
0506	Path broken up. Not enough space for cyclists and pedestrians	1	6/4/2023	https://www.google.com/maps/place/51.503077298075766%2C-0.3394210700744704/@51.503077298075766,-0.3394210700744704,17	110 St Margaret's Rd, London, W7 2HF	Boston Manor (canal)	Hanwell Broadway	Assumed to be canal path which is poor in this section	1			1				1					1																										
0507	Dangerous. Too much traffic not enough space. Polluted. Illegally parked cars blocking route	1	6/4/2023	https://www.google.com/maps/place/51.5105477459958%2C-0.32234710010688783/@51.5105477459958,-0.32234710010688783,1	50 Broadway, Ealing, London, W13 0SU	West Ealing	Hanwell Broadway / Walpole	Uxbridge Road West Ealing Deans Garden - Cemetery. hotspot. Parking in cycle lanes etc	1			1	1		1	1		1								1				1																1	Air Quality concern
0508			6/4/2023	https://www.google.com/maps/place/51.507187803159134%2C-0.3103095229942876/@51.507187803159134,-0.3103095229942876,17																																										
0509	This cycle lane does not join up with any other cycle route so is of no benefit. In addition the way the Cycle lane intrudes into St Stephen's Road makes turning off Castlebar Road into St Stephen's Road hazardous as vehicles have to swing out on busy Castlebar Road when going up the hill to negotiate round the end of the cycle lane.	1	6/4/2023	https://www.google.com/maps/place/51.52012599165078%2C-0.3108409171825599/@51.52012599165078,-0.3108409171825599,17	74 Castlebar Rd, London, W5 2DD	Castlebar Hill	Ealing Broadway	The benefit of this section is clearly slow cyclists heading up hill however the junction with St Stephens Road does look dangerous and should be reviewed - certainly road	1	1		1			1							1						1																			
0510	This cycle lane does not join up with any other. It effectively reduces traffic on a wide thoroughfare and forces it onto narrower side streets. By doing this people are less likely to cycle as off the cycle routes it becomes more dangerous. It also becomes more dangerous for pedestrians and drivers. I would not cycle as any accident could be catastrophic for me. Forcing traffic off roads that	1	6/4/2023	https://www.google.com/maps/place/51.51567663715035%2C-0.307193112922306/@51.51567663715035,-0.307193112922306,17z	18 Gordon Rd, London, W5 2AD	Ealing Broadway Haven Green	Ealing Broadway	Assumed to be new cycle lane on Gordon Road which is part of the new Greenford - Ealing route and links to c85. There are concerns here in relation to cycle / pedestrian safety	1	1			1		1							1							1		1																
0511	There has not been consultation on this proposal. I use this route daily and have had no notice of proposed changes. No notices in situ. Changing roundabouts as proposed has been shown to be confusing, leading to accidents. Where are the statistics to support the proposal?	1	6/4/2023	https://www.google.com/maps/place/51.520844787455275%2C-0.3186911320214181/@51.520844787455275,-0.3186911320214181,17	14 North Ave, London W13 8AP	Montpelier	Ealing Broadway	St Stephens Roundabout complaint - consultation has been completed. No actions indicated																																							St Stephens roundabout complaint
0512	Cars park across the bus lanes when they aren't in use so you can't cycle safely in my opinion.	1	6/4/2023	https://www.google.com/maps/place/51.51241131765237%2C-0.3115458077558708/@51.51241131765237,-0.3115458077558708,17	111 Arc Tower, 32 Uxbridge Road, London, W5 2SN	Ealing Broadway / Walpole	Ealing Broadway / Walpole	Uxbridge Road Walpole section. This section is 'No loading 7am - 7pm' - could potentially be extended to later in the evening as there is no obvious reason to be	1			1			1			1									1			1																	
0513	Culmington road narrow but busy by Lammas park. Far better when an oLTN	1	6/4/2023	https://www.google.com/maps/place/51.501191490251344%2C-0.30992078697887004/@51.501191490251344,-0.30992078697887004,1	57 Culmington Rd, London,	Walpole	Walpole	Walpole / Lammas hotspot know rat run	1			1				1																								1							
0514	Mattock Lane very congested with parked cars. Cars don't always allow bikes room to pass. Can this be made one-.way	1	6/4/2023	https://www.google.com/maps/place/51.50950791717671%2C-0.3186755224421689/@51.50950791717671,-0.3186755224421689,17	64A Mattock Ln, London, W13 9LJ	Walpole	Walpole	Parking even with limited hours is clearly unhelpful here and should be reconsidered. One way not practical owing to lack of route in opposite direction	1			1			1							1							1			1															
0515	Dangerous junction particularly when cycling under Iron Bridge in both directions	1	6/4/2023	https://www.google.com/maps/place/51.50888178314984%2C-0.35428027850042954/@51.50888178314984,-0.35428027850042954,1	Ironbridge house, Southall UB2 4NJ	Iron Bridge	Dormers Wells / Southall Broadway / Norwood Green	Iron Bridge hotspot	1			1			1	1						1				1	1				1																
0516	Clearer priority for bikes, better road markings/signage. Segregation would be better	1	6/4/2023	https://www.google.com/maps/place/51.52848997621442%2C-0.3269804282104949/@51.52848997621442,-0.3269804282104949,17	3 Ruislip Rd E, London, W13 0AZ	Pitshanger	Pitshanger	Roundabout previously flagged. Advised route is a long way round and not overly helpful if traveling North on Argyle Road. On highway cycle lanes might be	1		1				1	1											1	1	1																		
0517	Widen footpath over Horseden Hill. Make connection with canal bridge clearer & safer	1	6/4/2023	https://www.google.com/maps/place/51.54281597626647%2C-0.3245813984268864/@51.54281597626647,-0.3245813984268864,17	Ballot Box Bridge, Horsenden Ln N, Perivale, Horsenden,	Horsenden Hill	North Greenford / Perivale	Very difficult to make footpath wider along the roadside. Heading Northbound it may be helpful to add road markings to indicate cyclists turning right	1		1				1						1						1		1																		
0518	Boston/manor Road needs consistent cycle lane, it's patchy. Cyclists on pavement nr Boston Manor tube is dangerous, please get them their own track on the road. Pavements are for pedestrians.	1	6/4/2023	https://www.google.com/maps/place/51.500678822343396%2C-0.32886598817068347/@51.500678822343396,-0.32886598817068347,1	St Thomas Church Hall 182 Boston Road, Hanwell W7 2AZ	Boston Manor	Hanwell Broadway / Northfield	Boston Manor - hot spot lack of segregation and also the bus stop	1	1		1	1		1	1												1											1								
0519	Canal towpath near Osterley lock needs attention. Very poor surface. Also make it clear on towpath that pedestrians have priority, bikes go too fast and All do not have bells. More general education of the borough residents re give and take re cycling.	1	6/4/2023	https://www.google.com/maps/place/51.49804599612172%2C-0.33447912620360176/@51.49804599612172,-0.33447912620360176,1	Osterley Lock Weir, Grand Union Canal Walk, London, W7	Boston Manor	Hanwell Broadway / Hounslow	Canal hotspot - just a dirt track here	1		1		1			1					1															1											
0520			6/4/2023	https://www.google.com/maps/place/51.5089211146604%2C-0.2793774940589011/@51.5089211146604,-0.2793774940589011,17																																										
0521	The road and cycle path quality is shocking, pot holes everywhere, lots of debris on path leading to punctures	1	6/4/2023	https://www.google.com/maps/place/51.50133478629798%2C-0.2739701606848777/@51.50133478629798,-0.2739701606848777,17	School House, 172 Bollo Bridge Rd, London, W3 8DG	South Acton	South Acton	Condition of Bollo Bridge Road is poor - likely owing to HGV use during developments. The path referenced is likely to be the footpath between Rosenberg Road and Stirling	1		1			1	1	1							1		1	1			1																		
0522			6/4/2023	https://www.google.com/maps/place/51.51405697870085%2C-0.26931028108516886/@51.51405697870085,-0.26931028108516886,1																																										
0523			6/4/2023	https://www.google.com/maps/place/51.508474834178834%2C-0.27759294252315714/@51.508474834178834,-0.27759294252315714,1																																										
0524			6/4/2023	https://www.google.com/maps/place/51.506992096837855%2C-0.2668476178776502/@51.506992096837855,-0.2668476178776502,17																																										
0525			6/4/2023	https://www.google.com/maps/place/51.51886772711597%2C-0.26545069076672423/@51.51886772711597,-0.26545069076672423,1																																										
0526	There is no protected cycle-lane on Uxbridge read, through Hanwell and leading up to Ealing Hospital.	1	6/4/2023	https://www.google.com/maps/place/51.508725379994125%2C-0.33753364283672926/@51.508725379994125,-0.33753364283672926,1	114 Uxbridge Rd, London, W7 3SU	Hanwell	Hanwell Broadway	Uxbridge Road Hanwell hotspot - lack of segregation	1			1				1		1										1																			
0527	Rat-running down Elthorne Park Road, Seward Road, Leighton Road and Haslemere Avenue make Boston Manor Road unsafe and unappealing to cycle on. There is also no protected cycle-lane. Paint is not infrastructure. White paint does no stop cars, vans or other vehicles hitting someone on a bike.	1	6/4/2023	https://www.google.com/maps/place/51.50259733870197%2C-0.3311040149522615/@51.50259733870197,-0.3311040149522615,17	205 Boston Rd, London,	Hanwell	Hanwell Broadway / Northfield	Rat running through Hanwell, lack of of cycle segregation on Boston Road	1			1				1				1								1									1										
0528	There is no official, protected cycle-lane upto Ealing Broadway. The West Ealing part of Uxbridge Road is horrible to cycle on. It is not true to suggest that Uxbridge Road, at this part of the Borough of Ealing, actually has any cycle-lane or infrastructure specific to bicycles.	1	6/4/2023	https://www.google.com/maps/place/51.514002749574175%2C-0.30239364965685134/@51.514002749574175,-0.30239364965685134,1	28b The Broadway, London, NW7 3LL	Ealing	Ealing Broadway / Walpole / Hanwell Broadway / Pitshanger /	Lack of segregated cycle route anywhere on Uxbridge Road from West Ealing to Ealing Broadway	1			1	1			1		1										1																			
0529	Cycling along this section of the main road is horrible and very unappealing/dangerous.	1	6/4/2023	https://www.google.com/maps/place/51.509988855560465%2C-0.3581253576521659/@51.509988855560465,-0.3581253576521659,17	Bridge Garage, Uxbridge Rd, Southall UB1 3DD	Southall	Southall Broadway / Dormers Wells	Already segregated where possible or shared bus lane. Improved physical segregation and designation such as tarmac colour etc may help to improve	1			1			1	1		1									1	1																			
0530	The wands here are brilliant and effective at making cycling on this section of the road feel much safer. They are not long enough. Before you know it, riding through Acton High Street on this A road becomes horribly dangerous and unsafe. Cars are parked in the "cycle-lane" throughout the Borough. Paint	1	6/4/2023	https://www.google.com/maps/place/51.507718485184746%2C-0.27295985701129677/@51.507718485184746,-0.27295985701129677,1	Provident House, 214 High St, London, W3 9NX	Acton	South Acton	Lack of segregation through Acton	1			1			1	1		1										1																			
0531	The hump is badly surfaced/finished. Where the bricks meet the tarmac it is lumpy across most of the road. Only one point to cycle smoothly over the hump without being badly jolted	1	6/4/2023	https://www.google.com/maps/place/51.50504374536489%2C-0.3090584800121987/@51.50504374536489,-0.3090584800121987,17	2 Beaconsfield Rd, London, W5 5JE	Walpole	Walpole	Culmington / Beaconsfield / Church Lane junction - the speed hump appears to be in poor condition for a cycle route.	1			1			1								1						1																		
0532	Tree branches extending out into road at cyclists height. Extra dangerous when there is to foliage on the branches, as it is now	1	6/4/2023	https://www.google.com/maps/place/51.50435301628748%2C-0.3086489191785513/@51.50435301628748,-0.3086489191785513,17	19 Church Ln, London, W5 5HD	Walpole	Walpole	Unsure of tree or trees in question	1			1		1										1																							
0533	Hump is not finished smoothly. I have to cross the hump in the middle of the road, often to the annoyance of other traffic	1	6/4/2023	https://www.google.com/maps/place/51.505712831047816%2C-0.30955264822424944/@51.505712831047816,-0.30955264822424944,1	57 Culmington Rd, London,	Walpole	Walpole	Also a reference to the speed bumps on Culmington alongside Lammas Park being in poor condition	1			1			1								1						1									1									
0534	Lack of connectivity is a major issue plus vehicles parking in cycle lanes	1	6/4/2023	https://www.google.com/maps/place/51.50139305087388%2C-0.2606483806572091/@51.50139305087388,-0.2606483806572091,17	27 Speldhurst Rd, London, W4 1BX	Bedford Park	Southfield	Issues possibly not referencing pin which is essentially on c49. Likely to be referencing Uxbridge Road in Acton	1			1			1	1		1								1				1																	
0535			6/4/2023	https://www.google.com/maps/place/51.50834417866485%2C-0.28992567425220495/@51.50834417866485,-0.28992567425220495,1																																										
0536			6/4/2023	https://www.google.com/maps/place/51.533326894733946%2C-0.28747862292621384/@51.533326894733946,-0.28747862292621384,1																																										
0537			6/4/2023	https://www.google.com/maps/place/51.52423277273346%2C-0.29560091008998146/@51.52423277273346,-0.29560091008998146,1																																										
0538			6/4/2023	https://www.google.com/maps/place/51.514611810386846%2C-0.3063390380932063/@51.514611810386846,-0.3063390380932063,17																																										
0539			6/4/2023	https://www.google.com/maps/place/51.517794164795205%2C-0.2662833882583038/@51.517794164795205,-0.2662833882583038,17																																										
0540			6/4/2023	https://www.google.com/maps/place/51.51376203284176%2C-0.3029614306967354/@51.51376203284176,-0.3029614306967354,17																																										
0541	Very bad state of road. Cycle lane bearly visible and drivers on daily basics ride cars on cycle lane especially when dark or bad weather	1	6/4/2023	https://www.google.com/maps/place/51.50508803595868%2C-0.33541132690389386/@51.50508803595868,-0.33541132690389386,1	145-147 Boston Rd, London, W7 3SA	Boston Manor	Hanwell Broadway / Northfield	Poor condition of cycle lane on Boston Road	1			1			1					1							1								1												
0542			6/4/2023	https://www.google.com/maps/place/51.50993669939772%2C-0.32540207960616074/@51.50993669939772,-0.32540207960616074,1																																										
0543			6/4/2023	https://www.google.com/maps/place/51.50849460396062%2C-0.259747793855416/@51.50849460396062,-0.259747793855416,17z																																										
0544	Need segregated cycle route all along Uxbridge road to the Broadway for me to cycle.	1	6/4/2023	https://www.google.com/maps/place/51.50955347022187%2C-0.3331596222721833/@51.50955347022187,-0.3331596222721833,17	Clare House, 49 Uxbridge Rd, London, W7 3PX	Hanwell	Hanwell Broadway / Walpole / Ealing Broadway	Uxbridge Road Ealing	1			1	1			1		1										1																			
0545	The cycle route needs to extend along church road so it joins the main Uxbridge road. Church road has wide enough space but it's taken up by parking. Parking should be removed on main roads to create segregated cycle route.	1	6/4/2023	https://www.google.com/maps/place/51.51232486819236%2C-0.33691817666809953/@51.51232486819236,-0.33691817666809953,1	25 Church Rd, London, W7 3BD	Hanwell	North Hanwell / Hanwell Broadway	Request to remove parking and install segregated path. Unlikely to be viable. In may be possible to generally improve road markings and general c87 designation	1			1	1		1	1										1		1															1				
0546	Need a large area for parking bikes which is monitored by CCTV as I'm concerned by bike will be stolen if I wanted to cycle.	1	6/4/2023	https://www.google.com/maps/place/51.51306916137885%2C-0.30708631326860525/@51.51306916137885,-0.30708631326860525,1	Ealing Town Hall, New Broadway, London, W5 2BY	Ealing Broadway	Ealing Broadway	Request for a cycle hub essentially (no reference to existing hub in Ealing Broadway)	1			1			1	1																	1														
0547	Remove parking on this road and put it on side roads and add segregated cycle or ban cars on this road to allow for cycling. Would be good to ban cars to create a village feel in Hanwell.	1	6/4/2023	https://www.google.com/maps/place/51.5076239832814%2C-0.33773094996116804/@51.5076239832814,-0.33773094996116804,1	16 Boston Rd, London, W7 3TR	Hanwell	Hanwell Broadway	Removing short stay parking unlikely to be popular with businesses and there is minimal parking available in the side streets. Improvements to road	1		1				1	1				1							1	1																			
0548	Segregated cycle route along the mall for cycling.	1	6/4/2023	https://www.google.com/maps/place/51.51321603251295%2C-0.29636311721217945/@51.51321603251295,-0.29636311721217945,1	6 N Common Rd London, W5 2QA	Ealing Broadway / Ealing Common	Ealing Broadway / Ealing Common	Difficult to establish exactly where they are referring to but general increase in segregation for the sections not currently segregated	1			1				1		1										1																			
0549	The cycle lane outside Ealing Hospital severely restricts access to emergency care by ambulances - causes dreadful restrictions and delays - which aggravates and encourages speeding by boy racers…	1	6/4/2023	https://www.google.com/maps/place/51.509206163126144%2C-0.34744708735577223/@51.509206163126144,-0.34744708735577223,1	431 Uxbridge Rd, Southall UB1 3EW	Ealing Hospital	Norwood Green	This section is mainly shared bus lane or narrow sections of painted cycle lane. Extremely unlikely to be bikes causing ambulance delays and encouraging boy racers.	1																																	1					
0550	Completely inappropirate as a 'Cycleway' - Bikes are vastly outnumbered by both Cars and Pedestrians here and it is full of Potholes anyway. I should know just how this is really not a Cycleway - I live on this road - do you? I thought not…	1	6/4/2023	https://www.google.com/maps/place/51.50081859837401%2C-0.26116459646057244/@51.50081859837401,-0.26116459646057244,1	9 Bayham Rd, London, W4 1BJ	Bedford Park	Southfields	c49 - indicates that improvements are needed but that may not be their intent. Road condition does appear poor in places	1			1			1								1						1																		
0551	Narrow one-way street (Boston Road, heading southwards) that opens up to be almost immediately confronted with a bus stop (opposite Rosebank Road) that can be tempting to overtake, but the sightline is not good.	1	6/4/2023	https://www.google.com/maps/place/51.506748773814344%2C-0.33920734126202223/@51.506748773814344,-0.33920734126202223,1	117 Boston Rd, London, W7 3SB	Hanwell	Hanwell Broadway	Boston Road but difficult to know exactly which section.	1			1				1				1		1																									
0552			6/4/2023	https://www.google.com/maps/place/51.51035155084053%2C-0.32323625795385835/@51.51035155084053,-0.32323625795385835,1																																										
0553			6/4/2023	https://www.google.com/maps/place/51.507193729743136%2C-0.3374624378177482/@51.507193729743136,-0.3374624378177482,17																																										
0554			6/4/2023	https://www.google.com/maps/place/51.50688592461902%2C-0.3337786870298798/@51.50688592461902,-0.3337786870298798,17																																										
0555			6/4/2023	https://www.google.com/maps/place/51.51479409594927%2C-0.3128523459406929/@51.51479409594927,-0.3128523459406929,17																																										
0556			6/4/2023	https://www.google.com/maps/place/51.50574573935098%2C-0.2904584805347188/@51.50574573935098,-0.2904584805347188,17																																										
0557	Is this being delivered?	1	6/4/2023	https://www.google.com/maps/place/51.510412745009106%2C-0.35406017660270184/@51.510412745009106,-0.35406017660270184,1	8 Greenford Rd, London, Southall UB1 3EB	Iron Bridge	Dormers Wells / Southall Broadway / Norwood Green	Unsure																																						
0558			6/4/2023	https://www.google.com/maps/place/51.512244457589674%2C-0.31234646200309246/@51.512244457589674,-0.31234646200309246,1																																										

0615	It is quite tricky when I take my bike out of Ealing Broadway cycle parking. I have 2 bad choices - either meet the heavy traffic in front of Ealing Broadway or go around buses in Haven Green.	1	6/4/2023	https://www.google.com/maps/place/51.51485768837223%2C-0.3029851550200213/@51.51485768837223,-0.3029851550200213,17	24 The Broadway, London, W5 2NP	Ealing Broadway	Ealing Broadway	Ealing Broadway hotspot - in particular lack of connection to cycle parking	1			1	1		1	1										1																				
0616	Pope's lane	1	6/4/2023	https://www.google.com/maps/place/51.50169761700661%2C-0.29483310326534173/@51.50169761700661,-0.29483310326534173,1	138 Popes Ln, London, W5 4NP	South Ealing	Ealing Common	Generally poor / limited cycle infrastructure on Popes Lane	1			1			1											1																				
0617	From A4 to Ealing Broadway (South Ealing Road/St Mary's Road)	1	6/4/2023	https://www.google.com/maps/place/51.50902099039806%2C-0.30461064963085427/@51.50902099039806,-0.30461064963085427,1	Glaston Court, Grange Rd, London, W5 5QR	South Ealing	Walpole / Ealing Common / Northfield	C86 and Lionel Road North both provide some coverage for this journey but there is a lack of East / West link for example Popes Lane	1			1			1											1			1																		
0618	Northfields area	1	6/4/2023	https://www.google.com/maps/place/51.50606860579768%2C-0.3182065923935573/@51.50606860579768,-0.3182065923935573,17	60 Glenfield Rd, London, W13 9JZ	Northfields	Hanwell Broadway / Walpole / Northfield	Lack of cycle infrastructure N/S or E/W in former LTNs	1			1				1										1																				
0619	Avoiding the junction of popes lane and North circular lights	1	6/4/2023	https://www.google.com/maps/place/51.50333061875502%2C-0.2840159891336591/@51.50333061875502,-0.2840159891336591,17	Unit A, 23 Gunnersbury Gardens, London, W3 9AF	Gunnersbury Park	Ealing Common	Popes Lane junction is frustrating because it only accommodates cyclists travleling North / South on the west side of the road. If you are on this section of cycle	1		1		1			1			1							1					1																	
0619.1		1			4 Park Parade, London, W3 9BD			Additional location for previous log	1		1		1			1			1							1					1																	
0620	Canal path is needs improving in most places, surface and width	1	6/4/2023	https://www.google.com/maps/place/51.50305989299764%2C-0.3410317320119738/@51.503059899299764,-0.3410317320119738,17	20 Billetts Hart Cl, London, W7 2PY	Boston Manor (Canal)	Hanwell Broadway	Canal towpath mainly dirt track through this southern section	1			1				1					1																									
0621	Separate cycling lane on busy roads like Uxbridge road	1	6/4/2023	https://www.google.com/maps/place/51.51028462392278%2C-0.323860708828847/@51.51028462392278,-0.323860708828847,17z	12A Broadway, Ealing, London, W13 0SR	West Ealing / Hanwell	Hanwell Broadway / Walpole	Lack of segregation on Uxbridge Road West Ealing	1			1	1			1		1										1																				
0622	Make the entire canal path fit for cycling	1	6/4/2023	https://www.google.com/maps/place/51.50308597569119%2C-0.3603494911837335/@51.50308597569119,-0.3603494911837335,17	91 Grand Union Canal Walk, London,, Southall UB2 4PG	Three Bridges	Norwood Green	Canal towpath west of Three Bridges is a dirt track	1			1				1					1																									
0623	Difficult and dangerous to make any right turn at this crossroads	1	6/4/2023	https://www.google.com/maps/place/51.51171183561151%2C-0.2919878680075638/@51.51171183561151,-0.2919878680075638,17	2-8 Hanger Ln, London, W5 3HN	Ealing Common	Ealing Common	Uxbridge / A406 hotspot - difficult to turn right or continue straight	1			1	1			1		1	1							1	1	1			1																	
0624	Limited space here for cyclists to make any manoeuvres	1	6/4/2023	https://www.google.com/maps/place/51.517463451403984%2C-0.2916993140836688/@51.517463451403984,-0.2916993140836688,17	56 Hanger Ln, London, W5 2JH	Ealing Common	Ealing Common	Madeley / A406 hotspot - difficult to navigate junction and connect to the North / South cycle path	1			1	1			1			1							1	1	1			1																	
0625	This cycleway needs connecting to the wider network, it's no use when anything that is safe(r) is not connected.	1	6/4/2023	https://www.google.com/maps/place/51.50447913679207%2C-0.28869209421732434/@51.50447913679207,-0.28869209421732434,1	52 Gunnersbury Ave, London, W5 4HA	Ealing Common	Ealing Common	Mainly an issue in relation to lack of East / West routes. Further South eventually connects to the Great West Road and North connects to c41 but in between there are	1			1			1	1			1							1																				
0626	Difficult to turn here	1	6/4/2023	https://www.google.com/maps/place/51.51335895997806%2C-0.30452436722317566/@51.51335895997806,-0.30452436722317566,1	Christ the Saviour Church, Ealing Grn, London, W5 2XA	Ealing Broadway	Ealing Broadway	CtS / McDonalds / M&S hotspot junction. Very poor for cycling	1			1	1			1		1								1	1				1																	
0627	Many parked cars make this area dangerous	1	6/4/2023	https://www.google.com/maps/place/51.51403825111213%2C-0.2997142533264241/@51.51403825111213,-0.2997142533264241,17	13c The Mall, Ealing, London, W5 2PJ	Ealing Broadway	Ealing Broadway	Uxbridge Road between The Broadway and the segregated path - parking permitted on the North Side with no cycle lane. The south side shared bus lane is no loading 6am -	1			1				1						1																								
0628	It is not uncommon in the roads around North Acton Playing Fields for drivers to go way over the speed limit of 20 mph. There needs to be serious enforcement of the speed limit and more visible reminders that these roads are being used by cyclists.	1	6/4/2023	https://www.google.com/maps/place/51.522607458496736%2C-0.27428948932488817/@51.522607458496736,-0.27428948932488817,1	Bridge Cafe. Westfields Rd, West Acton, London, W3 0AP	North Acton	North Acton	Improve blue route designation and speed enforcement	1			1			1	1													1					1	1													
0629	Cyclists need to be able to use Horn Lane safely. It would help to not allow cars to simply stop and block the left-hand side of the road. This causes cyclists to have to merge with traffic to keep going, which endangers them. Additionally, it would help if there were clear and frequent signs that this is a road used by cyclists, even if dedicated cycle lanes are not installed.	1	6/4/2023	https://www.google.com/maps/place/51.521037769191864%2C-0.26424590176128415/@51.521037769191864,-0.26424590176128415,1	328 Horn Ln, London, W3 6TH	Acton Main Line	North Acton	Limited infrastructure throughout Horn Lane - the Northern section on approach to the A40 is shared bus lane during peak hours. These hours could be extended -	1			1		1	1	1																														
0630	We need better surfaces around the canal, because during winter months it is very slippery. It would be ideal if there could be a separated part for cyclists so they don't have to navigate around pedestrians.	1	6/4/2023	https://www.google.com/maps/place/51.52960865637893%2C-0.2508992297031787/@51.52960865637893,-0.2508992297031787,17	Unit c, Nash House, Old Oak Ln, London, NW10 6FF	North Acton / Willesden Junction	North Acton	Canal - short section in North Acton. Currently paved path but looks very overgrown.	1			1			1	1					1																									
0631	All car parking should be removed in this area. There should be a continuous and uninterruptible cycle lane except, of course, for bus stops. It is however unacceptable that car parking, even short term, is allowed on this main road, which causes cyclists to have to merge with traffic and endanger themselves.	1	6/4/2023	https://www.google.com/maps/place/51.506716952407274%2C-0.2660009957457099/@51.506716952407274,-0.2660009957457099,17	Jeffries House, High St, London, W3 6LG	Acton Central	South Acton	Uxbridge Road Acton - mostly double yellow lines through this section but sections further west appear to have issues with parking	1			1	1		1			1								1				1																		
0632	cycle lanes both directions cause a serious hazard for cars eastbound turning left into Greenford Road and having to swerve past a bus stop westbound.	1	6/4/2023	https://www.google.com/maps/place/51.509945406823185%2C-0.35617472694370766/@51.509945406823185,-0.35617472694370766,1	Unit 3, 220 Uxbridge Rd, Southall UB1 3DZ	Iron Bridge	Southall Broadway / Dormers Wells	Westbound comment isn't quite the case - the cycle lane starts after the bus stop however buses will have to move back into the traffic which isn't ideal for any of	1		1				1			1				1					1	1			1										1							
0633	Constantly blocked by cars from nearby Garage's	1	6/4/2023	https://www.google.com/maps/place/51.52820441610304%2C-0.2788317841613708/@51.52820441610304,-0.2788317841613708,17	838 Coronation Rd, London, NW10 7QE	Park Royal	North Acton	Flagged as priority as there is a clear issue of persistent parking on double yellow / cycle lane. Evidence on Google of ticketing but likely to be a cause of conflict with	1	1		1		1	1															1				1														
0634	There very broad pavements which could be used as safe cycle lanes and used by pedestrians	1	6/4/2023	https://www.google.com/maps/place/51.51080334790334%2C-0.3268332695655052/@51.51080334790334,-0.3268332695655052,17	Wigmore Court, Singapore Rd, London,	West Ealing	Hanwell Broadway / Walpole	Assumed to be Uxbridge Road hotspot Deans Garden - Cemetery. Pavements do not appear wide enough																																								
0635	No provision for cyclists to change the traffic lights from the cycle lane at Boston manor station when travelling towards Hanwell. All cycle lanes have to give way to traffic crossing their path or when rejoining the carriageway	1	6/4/2023	https://www.google.com/maps/place/51.49702387256453%2C-0.3258533078925363/@51.49702387256453,-0.3258533078925363,17	Boston Manor Station, Boston Manor Rd, TW8 9LQ	Boston Manor	Northfield	Believed to be a Hounslow concern but also unsure exactly what the respondent is trying to do or why they would need to control the lights. Possibly heading North			1				1																1																	
0636	This is one of the most dangerous stretches of cycle lane I've ever come across and after the first time I've never used it again. It seems to have been designed for school children turning left to little Ealing so if you're going straight on towards Gunnersbury at a normal cycling speed you suddenly find your path has run out and there's no easy way of continuing along the main road. Drivers get	1	6/4/2023	https://www.google.com/maps/place/51.498028223381795%2C-0.3096352482530662/@51.498028223381795,-0.3096352482530662,17	58 Little Ealing Ln, London, W5 4EA	Northfield	Northfield	Good infrastructure meets no infrastructure. Clear signage and road markings needed to ensure that both cyclists and drivers are aware of cyclists having to rejoin the	1	1		1			1							1				1																						
0637	Really hair-rasing turning right off the Mall into Windsor road (which also appears to be a cycle lane/quiet through road for cyclists). The Mall is particularly narrow at that point and the road is busy with large vehicles making a cyclist waiting in the middle of the road vulnerable	1	6/4/2023	https://www.google.com/maps/place/51.5141534169459%2C-0.3009443469980866/@51.5141534169459,-0.3009443469980866,17	4 The Mall, Ealing, London, W5 2PJ	Ealing Broadway	Ealing Broadway	Agreed - horrible and this is a key connection North / South. Difficult to solve but needs looking at.	1	1	1				1			1								1																						
0638			6/4/2023	https://www.google.com/maps/place/51.548519238386206%2C-0.3298194903509155/@51.548519238386206,-0.3298194903509155,17																																										
0639			6/4/2023	https://www.google.com/maps/place/51.549864160417556%2C-0.33983077587997235/@51.549864160417556,-0.33983077587997235,1																																										
0640			6/4/2023	https://www.google.com/maps/place/51.545258304664294%2C-0.3416706823860438/@51.545258304664294,-0.3416706823860438,17																																										
0641			6/4/2023	https://www.google.com/maps/place/51.54075922343234%2C-0.3439534006051326/@51.54075922343234,-0.3439534006051326,17																																										
0642			6/4/2023	https://www.google.com/maps/place/51.55050014933428%2C-0.36284402465130317/@51.55050014933428,-0.36284402465130317,1																																										
0643			6/4/2023	https://www.google.com/maps/place/51.50883860600481%2C-0.33730903430529535/@51.50883860600481,-0.33730903430529535,1																																										
0644			6/4/2023	https://www.google.com/maps/place/51.508194105434406%2C-0.3377596454197973/@51.508194105434406,-0.3377596454197973,17																																										
0645			6/4/2023	https://www.google.com/maps/place/51.49741554290947%2C-0.3263595969427402/@51.49741554290947,-0.3263595969427402,17																																										
0646			6/4/2023	https://www.google.com/maps/place/51.506533489558926%2C-0.3372295921183266/@51.506533489558926,-0.3372295921183266,17																																										
0647			6/4/2023	https://www.google.com/maps/place/51.502574843524044%2C-0.3312890743150354/@51.502574843524044,-0.3312890743150354,17																																										
0648			6/4/2023	https://www.google.com/maps/place/51.51289199858614%2C-0.2818724413596785/@51.51289199858614,-0.2818724413596785,17																																										
0649			6/4/2023	https://www.google.com/maps/place/51.50049786023756%2C-0.2612730761253035/@51.50049786023756,-0.2612730761253035,17																																										
0650	Would be great if this went down Gunnersbury lane	1	6/4/2023	https://www.google.com/maps/place/51.50868693295442%2C-0.27492863791765965/@51.50868693295442,-0.27492863791765965,1	250 High St, London, W3 9BH	Acton	South Acton	Gunnersbury / Uxbridge / Styne hotspot. Request for Gunnersbury Lane infrastructure	1			1				1		1										1																				
0651	I wasn't aware this went all the way through the borough, but I still wouldn't feel confident as it's a busy road	1	6/4/2023	https://www.google.com/maps/place/51.51117515257244%2C-0.3244426736722028/@51.51117515257244,-0.3244426736722028,17	12A Broadway, Ealing, London, W13 0SR	Ealing	Various	Assumed to be Uxbridge Road				1										1																								
0652	too many parked cars	1	6/4/2023	https://www.google.com/maps/place/51.516573622206586%2C-0.2969286380714209/@51.516573622206586,-0.2969286380714209,17	31 Madeley Rd, London, W5 2LS	Ealing Broadway / Hanger Hill	Hanger Hill	Madeley Road is narrow and very busy during peak hours. It may be appropriate to extend parking restrictions to residents only throughout the day and certainly to cover the	1			1			1																												1					
0653	Very bumpy, not smooth	1	6/4/2023	https://www.google.com/maps/place/51.52089974234797%2C-0.2918143100350701/@51.52089974234797,-0.2918143100350701,17	2 Audley Rd, London, W5 3ET	Hanger Hill	Hanger Hill	A406 cycle lane south of Hanger Lane Station. Likely to be issues as a result of the construction work	1			1	1		1				1				1																									
0654	too many parked cars blocking the cycle path	1	6/4/2023	https://www.google.com/maps/place/51.513699506520176%2C-0.2968867597774483/@51.513699506520176,-0.2968867597774483,17	3A N Common Rd London, W5 2QA	Ealing Common	Ealing Common	Referenced location unclear - seems unlikely to be the segregated path																																								
0655	A cycle lane is needed along the South Ealing road all the way to Ealing Broadway as I end up being pushed into the uneven gutter on my cycle into the Broadway from the New Inn to the crossroads near The Grove Pub.	1	6/4/2023	https://www.google.com/maps/place/51.50300825349485%2C-0.3069421964064012/@51.50300825349485,-0.3069421964064012,17	62 St Mary's Rd, London, W5 5EX	South Ealing	Ealing Common / Walpole	No infrastructure on South Ealing / St Marys.	1			1	1		1											1																						
0656	Bike lane desperately needed here.	1	6/4/2023	https://www.google.com/maps/place/51.50623189895053%2C-0.3046455855517105/@51.50623189895053,-0.3046455855517105,17	29 St Mary's Rd, London, W5 5PR	South Ealing	Ealing Common / Walpole	Pin could be South Ealing / St Marys or Warwick Road which should also be considered for improvement / designation	1			1	1		1											1																						
0657	Bike lane needed here.	1	6/4/2023	https://www.google.com/maps/place/51.509750373828226%2C-0.3053468118028957/@51.509750373828226,-0.3053468118028957,17	Ealing Studios, Ealing Grn, London, W5 5EP	South Ealing	Ealing Common / Walpole	No infrastructure on South Ealing / St Marys.	1			1	1		1											1																						
0658	Cycle lane stops which is very dangerous. Worse to have to swap sides of the road to be on a cycle lane and then have it stop than having jo cycle lane and cycling on the road	1	6/4/2023	https://www.google.com/maps/place/51.495882950281526%2C-0.32459216446830474/@51.495882950281526,-0.32459216446830474,1	Boundary House Business Centre, Boston Rd, London, W7	Boston Manor	Northfield / Hanwell Broadway	Boston Road cycle lane (lack of)	1			1	1			1				1								1																				
0659	No cycle lane at all from Uxbridge Road all the way down Northfields Avenue. Lots of children cycle to parks, unsafe.	1	6/4/2023	https://www.google.com/maps/place/51.50238274969064%2C-0.31621989825937336/@51.50238274969064,-0.31621989825937336,1	135-161 B452, London, W13 9QT	Northfield	Northfield / Walpole	No cycle infrastructure on Northfield (or parallel)	1			1				1										1																						
0660			6/4/2023	https://www.google.com/maps/place/51.50882263919808%2C-0.33700610843250933/@51.50882263919808,-0.33700610843250933,1																																										
0661			6/4/2023	https://www.google.com/maps/place/51.5140266386486%2C-0.3010792687778552/@51.5140266386486,-0.3010792687778552,17																																										
0662			6/4/2023	https://www.google.com/maps/place/51.508174957331015%2C-0.27354322285059185/@51.508174957331015,-0.27354322285059185,1																																										
0663			6/4/2023	https://www.google.com/maps/place/51.50695913709118%2C-0.2699370447981586/@51.50695913709118,-0.2699370447981586,17																																										
0664			6/4/2023	https://www.google.com/maps/place/51.50667476749378%2C-0.25237373832681875/@51.50667476749378,-0.25237373832681875,1																																										
0665			6/4/2023	https://www.google.com/maps/place/51.51154746756997%2C-0.3784114990957965/@51.51154746756997,-0.3784114990957965,17																																										
0666			6/4/2023	https://www.google.com/maps/place/51.50557045144808%2C-0.3956441076054218/@51.50557045144808,-0.3956441076054218,17																																										
0667			6/4/2023	https://www.google.com/maps/place/51.50325024752995%2C-0.3741292113165584/@51.50325024752995,-0.3741292113165584,17																																										
0668			6/4/2023	https://www.google.com/maps/place/51.527124804708095%2C-0.3724794605275994/@51.527124804708095,-0.3724794605275994,17																																										
0669			6/4/2023	https://www.google.com/maps/place/51.53607462352403%2C-0.36502445309254394/@51.53607462352403,-0.36502445309254394,1																																										
0670	Whole of Uxbridge Road between West Ealing to Kensington	1	7/4/2023	https://www.google.com/maps/place/51.51251022347728%2C-0.3122067522440908/@51.51251022347728,-0.3122067522440908,17	Craven House, London,, W5 2TH	West London,	Various	Uxbridge Road	1			1	1			1		1																														

0671			7/4/2023	https://www.google.com/maps/place/51.51313433376652%2C-0.3037449429626027/@51.51313433376652,-0.3037449429626027,17																																										
0672			7/4/2023	https://www.google.com/maps/place/51.51091120713649%2C-0.29087655182984173/@51.51091120713649,-0.29087655182984173,1																																										
0673			7/4/2023	https://www.google.com/maps/place/51.50835626884813%2C-0.27630453095262464/@51.50835626884813,-0.27630453095262464,1																																										
0674			7/4/2023	https://www.google.com/maps/place/51.50650645504502%2C-0.25650112408244885/@51.50650645504502,-0.25650112408244885,1																																										
0675			7/4/2023	https://www.google.com/maps/place/51.50921167527188%2C-0.3357280195712242/@51.50921167527188,-0.3357280195712242,17																																										
0676			7/4/2023	https://www.google.com/maps/place/51.51033538089048%2C-0.32585749039641954/@51.51033538089048,-0.32585749039641954,1																																										
0677			7/4/2023	https://www.google.com/maps/place/51.51268781368939%2C-0.30887752086828923/@51.51268781368939,-0.30887752086828923,1																																										
0678			7/4/2023	https://www.google.com/maps/place/51.50952355950674%2C-0.284679026704846/@51.50952355950674,-0.284679026704846,17z																																										
0679			7/4/2023	https://www.google.com/maps/place/51.506762852580195%2C-0.2645941476151581/@51.506762852580195,-0.2645941476151581,17																																										
0680	Connect up to the Hounslow segregated lanes please.	1	7/4/2023	https://www.google.com/maps/place/51.50198517850664%2C-0.3300013719382866/@51.50198517850664,-0.3300013719382866,17	229 Boston Rd, London, W7 2AA	Boston Manor	Northfield / Hanwell Broadway	Boston Road lack of segregated cycle lane	1			1	1			1				1								1																		
0681			7/4/2023	https://www.google.com/maps/place/51.5132377813255%2C-0.29732332194110755/@51.5132377813255,-0.29732332194110755,1																																										
0682	The whole of Uxbridge Road is treacherous, full of pot holes and temporary bollards, and illegal parking. I'd love to be able to cycle along it with the family. Ealing Broadway to Shepherds Bush is the worst as there not easy back roads to use.	1	7/4/2023	https://www.google.com/maps/place/51.51300805792526%2C-0.2966195873378763/@51.51300805792526,-0.2966195873378763,17	4 The Common, London, W5 3TR	West London,	Various	Whole of Uxbridge Road mainly parking and road condition	1			1			1	1		1					1							1																
0683	It would be great to have some more north to south bike routes that provide safe family cycling. Most routes from Northfields to, say, Horseden require intimate knowledge of the back streets and parks to be considered safe.	1	7/4/2023	https://www.google.com/maps/place/51.519378680372995%2C-0.32167029390986146/@51.519378680372995,-0.32167029390986146,1	23 St Stephen's Ave, London W13 8ES	Ealing	Various	General improve blue routes	1			1			1														1																	
0684	West Ealing Uxbridge Road is a disaster with regular traffic jams, illegal parking, the air thick with fumes on a summers day.	1	7/4/2023	https://www.google.com/maps/place/51.510311439634194%2C-0.33019680319484435/@51.510311439634194,-0.33019680319484435,1	15 Uxbridge Rd, London, W7 3PX	West Ealing	Hanwell Broadway / Walpole	Uxbridge road west ealing hotspot including air quality	1			1	1		1	1		1												1				1											1	Air Quality concern
0685			7/4/2023	https://www.google.com/maps/place/51.49671587611785%2C-0.29905781803106324/@51.49671587611785,-0.29905781803106324,1																																										
0686	Cycle lane not clear, didn't know there was one here	1	7/4/2023	https://www.google.com/maps/place/51.498888345724566%2C-0.3094591517314016/@51.498888345724566,-0.3094591517314016,17	71 Little Ealing Ln, London, W5 4ED	South Ealing	Northfield	Presumably cycle lane along the schools. The lane itself is clear but it's not connected to anything else																																						
0687	No clear cycle lane, cycling past parked cars	1	7/4/2023	https://www.google.com/maps/place/51.507811593015006%2C-0.31289085369337943/@51.507811593015006,-0.31289085369337943,1	32 Churchfield Rd, London, W13 9NH	Walpole	Walpole	C86 Culmington Road poorly designated - no infrastructure or markings	1			1			1														1																	
0688	Parked cars mean you're always cycling in the road. Scary sharing with buses	1	7/4/2023	https://www.google.com/maps/place/51.50978815308788%2C-0.33022865276564506/@51.50978815308788,-0.33022865276564506,1	21-23 Uxbridge Rd, London, W7 3PX	West Ealing	Hanwell Broadway / Walpole	Uxbridge road west ealing hotspot	1			1	1		1	1		1												1																
0689	Would never cycle along here as no designated space away from cars	1	7/4/2023	https://www.google.com/maps/place/51.51250298294449%2C-0.30983419445805627/@51.51250298294449,-0.30983419445805627,1	24-22 Uxbridge Rd, London, W5 5SA	Ealing Broadway	Ealing Broadway / Walpole	Uxbridge Road hotspot - past all the hotels. No segregation (and no need for the parking)	1			1	1		1	1		1									1	1		1																
0690			7/4/2023	https://www.google.com/maps/place/51.49992893170927%2C-0.30457129795527615/@51.49992893170927,-0.30457129795527615,1																																										
0691	The Uxbridge Road from Ealing Broadway heading east is a great cycling route as its seperated. Heading West from Ealing Broadway on the Uxbridge Road towards West Ealing is unsafe even with the marked cycle lane. I have had many near misses with vehicles overtaking when cycling along this stretch of road. I recently got knocked off my bike and broke a rib when a lorry was parked inside	1	7/4/2023	https://www.google.com/maps/place/51.51264325877051%2C-0.31126224982277684/@51.51264325877051,-0.31126224982277684,1	Ground Floor, 32 Uxbridge Rd, London, W5 2SN	Ealing Broadway	Ealing Broadway / Walpole	Uxbridge Road hotspot - past all the hotels. No segregation (and no need for the parking)	1			1	1		1	1		1										1		1																
0692	Broomfield Road should be a one way street. It is extremely narrow and have encountered many cars speeding down here when cycling along it. Large hgv lorries use it as a cut through and often get stuck, resulting in a backlog of traffic and cyclists having to use the pavement.	1	7/4/2023	https://www.google.com/maps/place/51.510651552834865%2C-0.31668119918205395/@51.510651552834865,-0.31668119918205395,1	10 Broomfield Rd, London, W13 9AP	Walpole	Walpole	Agreed - it would be sensible for Chapel / Broomfield / Dane Roads too all be one way streets with counter flow (currently only Dane)	1			1			1							1																								
0693	Cycling wrong way down a one street. On coming traffic often unaware. Joining mini roundabout at the high street - other traffic unaware	1	7/4/2023	https://www.google.com/maps/place/51.507720600236816%2C-0.2710557533843261/@51.507720600236816,-0.2710557533843261,17	6 Market Pl, Acton, London, W3	Acton	South Acton	Agreed - currently dangerous - needs a clearly marked cycle lane on the east side to make traffic fully aware. Turning left from the roundabout onto Market place the sign high on	1	1		1			1												1		1																	
0694	Big potholes along westbound Uxbridge road	1	7/4/2023	https://www.google.com/maps/place/51.5123236074376%2C-0.31087099065233437/@51.5123236074376,-0.31087099065233437,1	Ground Floor, 32 Uxbridge Rd, London, W5 2SN	Ealing Broadway	Ealing Broadway	Agreed - road surface in cycle lane appears poor here (probably not helped by lack of parking restrictions)	1			1	1		1			1					1																							
0695	Leaves collect here making the cycle lane slippery. They never seem to be swept unlike the roads	1	7/4/2023	https://www.google.com/maps/place/51.510159876269114%2C-0.29145871415241054/@51.510159876269114,-0.29145871415241054,1	1 Leopold Rd, London, W5 3PB	Ealing Common	Ealing Common	Street cleaning of segregated cycle lane with lots of tree cover	1			1		1											1																						
0696	The cycle lane suddenly stops, leaving you at the mercy of narrow road and traffic	1	7/4/2023	https://www.google.com/maps/place/51.506498813761404%2C-0.2908312635713184/@51.506498813761404,-0.2908312635713184,17	19 Gunnersbury Ave, London, W5 3XD	Ealing Common	Ealing Common	A406 hotspot south of Ealing Common - rejoining the carriageway is unclear for cyclists and drivers.	1	1		1	1		1				1								1	1																		
0697	Travelling north there is often a queue of cars and cycle lane here would be useful to protect cyclists	1	7/4/2023	https://www.google.com/maps/place/51.504703586574635%2C-0.2671621921992817/@51.504703586574635,-0.2671621921992817,17	357 Acton Ln, Acton, London W3 8NR	Acton	South Acton	Point in question is a crossroad of blue routes which would connect to Uxbridge Road in either direction - this shows lack of awareness of the residential	1			1			1											1			1																	
0698	Uxbridge Road is not a safe route. Littered with parked cars and drivers frustrated by the traffic so over hanging junctions and not leaving space for cyclists in junction boxes.	1	7/4/2023	https://www.google.com/maps/place/51.51004028360877%2C-0.3255430368377077/@51.51004028360877,-0.3255430368377077,17	104 Broadway, London, W13 0SY	West Ealing	Hanwell Broadway / Walpole	Uxbridge Road west ealing hotspot.	1			1	1		1	1		1												1				1	1											
0699	The junction crossing Walpole and Lammas is a nightmare. Large cars make this terrifying experience taking my small child to school and clubs.	1	7/4/2023	https://www.google.com/maps/place/51.506289537220525%2C-0.3103674705544779/@51.506289537220525,-0.3103674705544779,17	57 Culmington Rd, London,	Walpole	Walpole	Culmington / Lammas hotspot. key cycle route and rat run	1			1	1		1	1										1			1																	
0700	This could be a lovely safe route to Bunny Park and up to the Indian grocery shops in Greenford but I find it difficult as cars do not give safe distance and they often take last minute decisions to cut through roads such as Erlesmere Gardens and Leighton/Elthorne.	1	7/4/2023	https://www.google.com/maps/place/51.50530751246363%2C-0.33396674832141926/@51.50530751246363,-0.33396674832141926,1	1 Cambridge Rd, London, W7 3PA	Hanwell	Hanwell Broadway / Walpole / Northfield	General rat running and poor driver behaviour in Hanwell	1			1				1																			1		1									
0701	This is polluted and full of parked cars. Almost impossible to cycle to Acton library and swimming pool. This facility should have safe and easy active travel options.	1	7/4/2023	https://www.google.com/maps/place/51.50664380469242%2C-0.2611053805011565/@51.50664380469242,-0.2611053805011565,17	Bryant Court, 278 The Vale, London, W3 7QB	Acton	South Acton / East Acton / Southfield	Uxbridge Road Acton - parking in cycle lanes and air quality	1			1			1	1		1												1															1	Air Quality concern
0702	Although some improvements here are welcomed, there are still too many close passes and cars stopping dangerously to drop off passengers for station and schools.	1	7/4/2023	https://www.google.com/maps/place/51.51576641352234%2C-0.3084949659858971/@51.51576641352234,-0.3084949659858971,17	Immax Ltd, 7 Longfield Rd, London, W5 2DH	Ealing Broadway	Ealing Broadway	Exact location unclear. General road safety / poor driver behaviour				1										1														1												
0703	Parked cars, buses and traffic make cycling through West Ealing unpleasant	1	7/4/2023	https://www.google.com/maps/place/51.511152943505266%2C-0.31882070541135565/@51.511152943505266,-0.31882070541135565,1	154 Uxbridge Rd, London, W13 8SB	West Ealing	Hanwell Broadway / Walpole	Uxbridge Road West ealing hotspot.	1			1	1		1	1		1				1								1																
0704	Lots of parked cars along Uxbridge Road mean difficult to cycle through traffic. Should be red route.	1	7/4/2023	https://www.google.com/maps/place/51.51200818816595%2C-0.31189040761363973/@51.51200818816595,-0.31189040761363973,1	89B Uxbridge Rd, London, W7 3ST	Ealing Broadway	Ealing Broadway	Uxbridge Road Ealing hotspot parking not needed	1			1			1			1												1																
0705	Lido junction needs better infrastructure. Advance stop lines often have cars in. 2 lanes of traffic heading West means no room for cyclists. Suggest priority lights for bikes and a protected cycle lane.	1	7/4/2023	https://www.google.com/maps/place/51.511272977621715%2C-0.3169625944117116/@51.511272977621715,-0.3169625944117116,17	2 Broadway London, W13 0NG	Lido West Ealing	Hanwell Broadway / Walpole	Uxbridge Road Lido hotspot	1			1	1			1		1								1																						
0706	Poor road surface, stones, pot holes makes cycling difficult especially at night when visibility is worse and I can't see the pot holes	1	7/4/2023	https://www.google.com/maps/place/51.508475693661346%2C-0.3433881714953957/@51.508475693661346,-0.3433881714953957,17	310-312 Uxbridge Rd, Southall UB1 3EP	Viaduct	Dormers Wells / Southall Broadway / Norwood Green	Not 100% on exact location. But lighting and poor highway - most likely the cycle land on the northern side based on original pin and condition of the bus lane into the cycle	1			1			1			1				1	1		1																						
0707	Some cars use this road as a short cut from the Uxbridge Road and can be VERY aggressive, one tried to physically push me off my bicycle. They then turn left into St Leonard's Road at speed, sometimes narrowly avoiding a crash with oncoming traffic.	1	7/4/2023	https://www.google.com/maps/place/51.51302243418138%2C-0.31774979711631346/@51.51302243418138,-0.31774979711631346,1	35 Hastings Rd, London, W13 8QH	West Ealing	Hanwell Broadway / Walpole	Rat running on Hastings Road	1			1			1	1																		1	1		1										
0708	Pitshanger Park is not appropriate to cycle at night, there are too many people having bags snatched and antisocial behaviour. This area needs to be patrolled to eradicate this and allow safe cycling at night. During the day it is good.	1	7/4/2023	https://www.google.com/maps/place/51.52838691708025%2C-0.31979988376383606/@51.52838691708025,-0.31979988376383606,1	Park Sports Pitshanger Park, The Lodge, Woodbury Park Rd,	Pitshanger park	Pitshanger / Perivale	Personal safety on cycle route through Pitshanger Park	1			1			1	1													1					1							1						
0709	Scarily dark at night down the alleyway going from Tesla garage down to Acton. I don't feel safe going there after dark. There is also often broken glass. This area needs better lighting. Generally cycle lanes are not swept and pieces of glass, nails, screws, stones etc are not removed, leading to punctures.	1	7/4/2023	https://www.google.com/maps/place/51.52618085917681%2C-0.28355887238704414/@51.52618085917681,-0.28355887238704414,1	152 Dukes Rd, London, W3 0SL	Park Royal / West Acton	Hanger Hill / North Acton	Mason's Green Lane - Dark + Street Cleaning	1			1			1								1		1																1						
0710	Lighting poor, sometimes antisocial behaviour (drug dealing) along the route, unsafe at night	1	7/4/2023	https://www.google.com/maps/place/51.50740710614774%2C-0.3661349994990193/@51.50740710614774,-0.3661349994990193,17	12 Collett Way, Southall UB2 4SE	Southall	Southall Broadway / Norwood Green	Park Avenue to Glade Lane lighting / personal safety																										1							1						
0711	Potholes along cycle route, sharing with buses sometimes dangerous	1	7/4/2023	https://www.google.com/maps/place/51.51070365080353%2C-0.3617597961563179/@51.51070365080353,-0.3617597961563179,17	176 Uxbridge Rd, Southall UB1 3DX	Southall	Dormers Wells / Southall Broadway	Uxbridge Road condition / shared bus lane concerns	1			1			1			1					1					1																		
0712	often delivery lorries meaning need to pull out into main traffic, dangerous	1	7/4/2023	https://www.google.com/maps/place/51.510223537919416%2C-0.3252807020250148/@51.510223537919416,-0.3252807020250148,17	176 Uxbridge Rd, Southall UB1 3DX	Southall	Dormers Wells / Southall Broadway	Uxbridge Road - deliveries to residential properties - there is parking therefore difficult to do anything further				1										1																								
0713	It would be good to make part of the path in Southall Broadway towards Hayes dedicated to bicycles as it can be a bit scary on the road. On the south side the path is wide and would allow for access on a bike without inconveniencing pedestrians too much	1	7/4/2023	https://www.google.com/maps/place/51.51196574902644%2C-0.3816098747278973/@51.51196574902644,-0.3816098747278973,17	124 The Broadway, Southall UB1 1QF	Southall	Southall West / Southall Broadway	There does appear to be plenty of width through the western section of Southall Uxbridge Road but it has been recently redeveloped. There may still be space to retrofit	1		1	1			1			1								1																						
0714	It is a little tricky cycling from the clocktower to the roundabout due to buses and sometimes, inconsiderate drivers! Not sure what you could do here!	1	7/4/2023	https://www.google.com/maps/place/51.50876236180821%2C-0.33584207593555737/@51.50876236180821,-0.33584207593555737,1	58-88 Uxbridge Rd, London,	Ealing Clock Tower	Hanwell Broadway	Uxbridge Road West Ealing / Hanwell Hotspot	1			1	1			1		1									1			1					1												
0715	This area towards Ealing Broadway becomes really congested on both sides of the road. Cyclists can feel vulnerable around the traffic lights and beyond as cars are often parked along the road too.	1	7/4/2023	https://www.google.com/maps/place/51.511753816439494%2C-0.316101017585948/@51.511753816439494,-0.316101017585948,17z	120 Uxbridge Rd, London, W13 8RA	Ealing Broadway	Walpole / Ealing Broadway	Uxbridge Road hotspot West Ealing - Ealing Broadway. Parking in cycle lane. Route could be segregated if parking is removed - businesses have their own parking	1			1	1		1	1		1										1		1																
0716	Some of the canal paths are becoming hazardous. Spme parts are quite narrow or rough and need attention. Overhanging branches need to be cut back better as there have been people falling off their bikes.	1	7/4/2023	https://www.google.com/maps/place/51.52264959727259%2C-0.3781566053545027/@51.52264959727259,-0.3781566053545027,17	58 Kingsbridge Cres, Southall UB1 2DL	Southall (Canal)	Lady Margaret	Canal is simple dirt track through Southall West / Lady Margaret	1			1			1	1					1			1																						
0717	Some of the canal paths here and beyond are a bit unstable	1	7/4/2023	https://www.google.com/maps/place/51.53407668385832%2C-0.28305620252247143/@51.53407668385832,-0.28305620252247143,1	9, Verde House, 189 Twyford Abbey Rd, London, NW10 7DQ	Hanger Hill borough boundary (Canal)	Hanger Hill	Canal path here is Tarmac but basic	1			1				1					1																									
0718	The tow path is too narrow and is dangerous for pedestrians and cyclists in places. It needs better maintenance to remove undergrowth and improve the surface	1	7/4/2023	https://www.google.com/maps/place/51.50104028952522%2C-0.33755868450650706/@51.50104028952522,-0.33755868450650706,1	41 Dock Meadow Reach, Ealing, London W7 2QN	Boston Manor (Canal)	Hanwell Broadway	Canal path narrow dirt track.	1			1			1	1					1			1																						
0719	Castlebay Road is Very unsafe. It is narrow and crowded with buses and cars. There is only a small stretch of the road with cycling lane (and a good one) but if it is unsafe to get there then, that stretch there is insufficient. I would not dare cycling in Uxbridge Rd either. It needs cycling lanes with physical barriers.	1	7/4/2023	https://www.google.com/maps/place/51.520744003796125%2C-0.3109679470221671/@51.520744003796125,-0.3109679470221671,17	76 Castlebar Rd, London, W5 2DD	Montpelier	Ealing Broadway / Pitshanger	Castlebar Park segregated path isn't well connected, no connection at all at the southern end - Charlbury / Blakesley could possibly be used as a residential	1			1			1	1		1				1				1		1																		
0719.1		1			22-24 Uxbridge Rd, London, W5 2RJ			Additional location for previous log	1			1			1	1		1				1				1		1																		
0720	Having to cross over to the other side of the road when going towards Brentford is not great so tend to stay on the road	1	7/4/2023	https://www.google.com/maps/place/51.49792839914144%2C-0.3263339949944588/@51.49792839914144,-0.3263339949944588,17	Byron Court 13 Boston Rd, London, W7 2AY	Boston Manor	Northfield	Consider a smoother connection to Hounslow's cycle lane. Safely using the crossing is a little awkward.	1			1				1				1												1																
0721	Very muddy in winter so not so practical	1	7/4/2023	https://www.google.com/maps/place/51.49643760825196%2C-0.3313519100692752/@51.49643760825196,-0.3313519100692752,17	Osterley Lock Weir, Grand Union Canal Walk, London, W7	Boston Manor (Canal)	Hanwell Broadway	Canal path mainly narrow dirt track connecting to tarmac at bridge	1			1				1					1																									
0722	What we need is a cycle path through Lammas Park which is without cars and safe. Also it should not be closed so early in winter, forcing us on the road.	1	7/4/2023	https://www.google.com/maps/place/51.50483063685871%2C-0.30764308557036824/@51.50483063685871,-0.30764308557036824,1	2 Beaconsfield Rd, London, W5 5JE	Lammas Park	Walpole	Keep park open later with improved cycle paths. Considering the tricky politics of increasing cycle infrastructure in Walpole this may help	1		1	1			1											1		1																		Improved routes though park
0723	Bring back the LTNs! Or more one way streets would be great e.g. in Elthorne Park Road as the confrontations between cars passing each other / causing gridlocks and road rage are a big problem for cyclists.	1	7/4/2023	https://www.google.com/maps/place/51.506918707650186%2C-0.32590561623845105/@51.506918707650186,-0.32590561623845105,1	77 Coldershaw Rd, London, W13 9DU	Hanwell	Hanwell Broadway / Walpole / Northfield	Reinstate LTN 21 or more one way streets (one way streets should potentially be considered even if they won't prevent rat running which is a big part of the problem)	1		1				1	1										1									1				1							
0724			7/4/2023	https://www.google.com/maps/place/51.500529826611896%2C-0.37087225173534577/@51.500529826611896,-0.37087225173534577,1																																										
0725			7/4/2023	https://www.google.com/maps/place/51.50189147627895%2C-0.376581853724427/@51.50189147627895,-0.376581853724427,17z																																										
0726			7/4/2023	https://www.google.com/maps/place/51.5074801577457%2C-0.3782114173932105/@51.5074801577457,-0.3782114173932105,17																																										

0727			7/4/2023	https://www.google.com/maps/place/51.5121755086727%2C-0.38087936985922166/@51.5121755086727,-0.38087936985922166,1																																										
0728			7/4/2023	https://www.google.com/maps/place/51.50311362104889%2C-0.35540659318848533/@51.50311362104889,-0.35540659318848533,1																																										
0729	ealing broadway is really bad, bad road markings no clear cycle lanes westbound on the Broadway when coming from station - even where there are bus lanes that is equally bad as no segregation of cyclists around the broadway westbound; and always scooters parked along the kerb anyway which forces cyclists to move off any cycle lanes	1	7/4/2023	https://www.google.com/maps/place/51.51397632789852%2C-0.30219285685650465/@51.51397632789852,-0.30219285685650465,1	29 The Broadway, London, W5 2NP	Ealing Broadway	Ealing Broadway / Walpole	Uxbridge Road west of Ealing Broadway - cycle infrastructure limited even without the parking in cycle lanes with or without restrictions	1			1	1		1	1		1									1	1		1				1													
0730	very dangerous stretch as when cycling westbound often cars overtake with very little space between me and cars as they don't want to stay behind me and often have lots of oncoming traffic; we need a separated cycle lane at least for the wider part of the road and at least clearer markings on the road	1	7/4/2023	https://www.google.com/maps/place/51.5169153645296%2C-0.29373853404156325/@51.5169153645296,-0.29373853404156325,1	82 Madeley Rd, London, W5 2LX	Ealing Common	Hanger Hill	Better East / West connections are needed and Madeley / Queens Drive would be the most useful even if Madeley will be limited in terms of possible	1			1			1	1										1									1												
0731	very bad road markings or non existent; very bad management with regards to how cyclists could approach junction when coming from Horne Lane, in particular no markings from end of bus lane to traffic lights which is very dangerous and not everyone wants to cross the junction on the path marked in the middle of the junction, for example cyclists going towards park royal road	1	7/4/2023	https://www.google.com/maps/place/51.52128150665891%2C-0.2637192507468855/@51.52128150665891,-0.2637192507468855,17	328 Horn Ln, London, W3 6TH	Gipsy Corner North Acton	North Acton	Difficult to assess remotely owing to age of Google Maps data however Horn Lane potential improvements have been noted elsewhere	1			1			1											1	1																				
0732	It's really busy at peak times and doesn't feel safe to cycle in.	1	7/4/2023	https://www.google.com/maps/place/51.51107487926961%2C-0.3194523531742499/@51.51107487926961,-0.3194523531742499,17	2 Broadway London, W13 0NG	West Ealing	Hanwell Broadway / Walpole	Lido junction hotspot. Busy and feels unsafe	1			1	1			1		1				1				1																				
0733	The canal path is a horribly uneven surface, too narrow in parts, and sometimes tilts into the canal. It needs resurfacing with something smooth.	1	7/4/2023	https://www.google.com/maps/place/51.50324715998734%2C-0.34139085090078014/@51.50324715998734,-0.34139085090078014,1	Billetts Hart Cl, London, W7 2PY	Boston Manor (Canal)	Hanwell Broadway	Canal - dirt track through this section	1			1				1					1																										
0734			7/4/2023	https://www.google.com/maps/place/51.51742746423756%2C-0.3251506764484491/@51.51742746423756,-0.3251506764484491,17																																										
0735			7/4/2023	https://www.google.com/maps/place/51.514115897448555%2C-0.3143360097004022/@51.514115897448555,-0.3143360097004022,17																																										
0736			7/4/2023	https://www.google.com/maps/place/51.514756864649186%2C-0.3036071736408319/@51.514756864649186,-0.3036071736408319,17																																										
0737			7/4/2023	https://www.google.com/maps/place/51.51513075801778%2C-0.2866126973224725/@51.51513075801778,-0.2866126973224725,17																																										
0738			7/4/2023	https://www.google.com/maps/place/51.51016137977343%2C-0.31820923495166964/@51.51016137977343,-0.31820923495166964,1																																										
0739			7/4/2023	https://www.google.com/maps/place/51.514708769646795%2C-0.2921946614198978/@51.514708769646795,-0.2921946614198978,17																																										
0740			7/4/2023	https://www.google.com/maps/place/51.521204738585006%2C-0.29164572713578973/@51.521204738585006,-0.29164572713578973,1																																										
0741	Cycle lanes are often ignored and occupied by pedestrians and traffic	1	7/4/2023	https://www.google.com/maps/place/51.52950861383992%2C-0.29280444143022333/@51.52950861383992,-0.29280444143022333,1	5 Royal Parade, Hanger Ln, London, W5 1ET	Hanger Lane Gyratory	Hanger Hill	Appears to be a reference to the Royal Parade Lanes and those through the underpass. Highway could be better indicated with a lane but it is an area where all road users	1			1			1												1																				
0742	Pedestrians and dog-walkers are often in the cycle lanes	1	7/4/2023	https://www.google.com/maps/place/51.520697378792896%2C-0.29889842031205927/@51.520697378792896,-0.29889842031205927,1	59 Hillcroft Cres, London, W5 2SL	Montpelier	Hanger Hill / Ealing Broadway	West Walk - essentially shared path even if designated - cyclists need to be polite and communicate with pedestrians.				1			1																																Poor pedestrian behaviour
0743	Cycle lanes need to be safely separated from traffic	1	7/4/2023	https://www.google.com/maps/place/51.51324654988071%2C-0.30529280660356317/@51.51324654988071,-0.30529280660356317,1	8 New Broadway, London, W5 2XA	Ealing Broadway	Ealing Broadway	Uxbridge Road Ealing Broadway - limited infrastructure.	1			1	1			1		1										1																			
0744	full of potholes, trees overgrown	1	7/4/2023	https://www.google.com/maps/place/51.525631220724904%2C-0.33725534885956643/@51.525631220724904,-0.33725534885956643,1	25 Cuckoo Ave, London W7 1BP	Perivale	North Hanwell	Cuckoo Lane - path is likely to be impacted by surrounding trees	1			1			1								1	1																							
0745	Very busy road with lots of parked cars. No enforcement of parking infringements.	1	7/4/2023	https://www.google.com/maps/place/51.51190339453882%2C-0.3155116653159018/@51.51190339453882,-0.3155116653159018,17	The Castelbar, 84 Uxbridge Rd, London, W13 8RA	West Ealing	Walpole	Uxbridge Road West Ealing hotspot. Parking in cycle lanes	1			1			1			1												1				1													
0746			7/4/2023	https://www.google.com/maps/place/51.50284873175354%2C-0.2724310656272566/@51.50284873175354,-0.2724310656272566,17																																										
0747			7/4/2023	https://www.google.com/maps/place/51.506267964750705%2C-0.28444736201397536/@51.506267964750705,-0.28444736201397536,1																																										
0748			7/4/2023	https://www.google.com/maps/place/51.50690904237477%2C-0.2580115099631941/@51.50690904237477,-0.2580115099631941,17																																										
0749			7/4/2023	https://www.google.com/maps/place/51.51460127033573%2C-0.25492160517803786/@51.51460127033573,-0.25492160517803786,1																																										
0750			7/4/2023	https://www.google.com/maps/place/51.51460127033573%2C-0.28856723506085036/@51.51460127033573,-0.28856723506085036,1																																										
0751	Inconsistent bicycle lane separation.	1	7/4/2023	https://www.google.com/maps/place/51.50874720257847%2C-0.28210352869052935/@51.50874720257847,-0.28210352869052935,1	373-375 Uxbridge Rd, London, W3 9RH	Acton	Ealing Common / North Acton / South Acton	Uxbridge Road, Ealing Common to Acton some sections are segregated, remaining sections appear to have parking except during peak hours	1			1			1			1										1																			
0752	Would be good to be able to cycle around the park	1	7/4/2023	https://www.google.com/maps/place/51.50925775997958%2C-0.2933677039651572/@51.50925775997958,-0.2933677039651572,17	Ealing Common	Ealing Common	Ealing Common	Ealing Common - not a huge number of paths therefore difficult to cycle in / around the park except on the highway	1			1			1																																Request for more cycle path in the park
0753	Muddy and dirty bicycle lane. No clear separation with pedestrians. Inconsistent signals. Suddenly the lane starts. Suddenly it stops.	1	7/4/2023	https://www.google.com/maps/place/51.52185096325855%2C-0.29219372982028036/@51.52185096325855,-0.29219372982028036,1	70 Hanger Ln, London, W5 2JH	North Circular	Hanger Hill	A406 cycle lane Madeley Road - Hanger Lane - presumably also referring to sections further south.	1			1			1	1			1						1		1	1			1																
0754	Unsafe water leakage in winter causing my bicycle accidents. Also the bicycle lanes are very dirty and have a lot of gravel.	1	7/4/2023	https://www.google.com/maps/place/51.506537780244614%2C-0.26463955821669716/@51.506537780244614,-0.26463955821669716,1	11 The Vale, London, W3 6NG	Acton	South Acton	Uxbridge Road / Acton High Street.	1			1			1			1							1																						Water leak
0755	Not enough bicycle stalls for commuters or for people coming to Ealing broadway area.	1	7/4/2023	https://www.google.com/maps/place/51.51352397226449%2C-0.30418407883552767/@51.51352397226449,-0.30418407883552767,1	1 The Broadway, London, W5 2ND	Ealing Broadway	Ealing Broadway	Uxbridge Road Ealing - lack of cycle parking	1			1		1				1															1														
0756	the road surface is awful full of potholes caused by buses and no separate bike lane	1	7/4/2023	https://www.google.com/maps/place/51.50871536787694%2C-0.34543534457491143/@51.50871536787694,-0.34543534457491143,1	471 Uxbridge Rd, Southall UB1 3ET	Ealing Hospital	Norwood Green	Uxbridge Road - there does appear to be poor highway condition in shared bus lane	1	1		1			1			1					1					1																			
0757			7/4/2023	https://www.google.com/maps/place/51.51028872101202%2C-0.360834890064623/@51.51028872101202,-0.360834890064623,17																																										
0758	nears regular sweeping bike lane is covered in grit and stones	1	7/4/2023	https://www.google.com/maps/place/51.507902069557055%2C-0.36005567672395156/@51.507902069557055,-0.36005567672395156,1	12 Collett Way, Southall UB2 4SE	Southall Park	Southall Broadway / Norwood Green	Assumed to be Glade Lane in need of street cleaning	1			1		1											1																						
0759			7/4/2023	https://www.google.com/maps/place/51.50195675719512%2C-0.3304209560161686/@51.50195675719512,-0.3304209560161686,17																																										
0760	Uxbridge road between hanwell and Ealing is unpleasant and often dangerous to cycle. The 20 mile speed limit helps when enforced, but is still on a major road with lorries. Creating a new path through the Kensington cemetery by connecting Holly Park Road with Felix Road would transform cycling on the east / west main route.	1	7/4/2023	https://www.google.com/maps/place/51.51006721664075%2C-0.33060298678202926/@51.51006721664075,-0.33060298678202926,1	27B Shirley Gardens, London, W7 3PT	Hanwell	Hanwell Broadway	Uxbridge Road West Ealing / Hanwell. Suggestion of a new East-West route though Kensington Cemetery which would help but might be challending to implement	1		1					1		1										1																			
0761	The section of Uxbridge road between the clock tower and Hanwell cemetery is the most frightening, I avoid this section at all costs, I have already been knocked off my bike here by a parked car opening its door. I would like to commute from Ealing to southall but this section puts me off.	1	7/4/2023	https://www.google.com/maps/place/51.50879968655434%2C-0.3367057606041013/@51.50879968655434,-0.3367057606041013,17	129 Uxbridge Rd, London, W7 3ST	Hanwell	Hanwell Broadway	Uxbridge Road West Ealing / Hanwell - hotspot. Poor road safety / parking in cycle lanes etc	1			1	1		1	1		1				1				1		1		1					1												
0762	This junction is so dangerous, I've had so many near misses here and seen many other cyclists at risk. It's also an important intersection for cyclists trying to access Northfields avenue but the adjoining Northfields avenue is too dangerous, it's too narrow and traffic is uncompromising. A number of safe north south routes across Uxbridge road around	1	7/4/2023	https://www.google.com/maps/place/51.51093657407748%2C-0.31941410749094956/@51.51093657407748,-0.31941410749094956,1	2 Broadway London, W13 0NG	West Ealing	Hanwell Broadway / Walpole	Lido Uxbridge / Northfield / Drayton Bridge hotspot and lack of North - South options	1			1	1			1		1								1					1																
0763	The approaches and section under the bridge is terrifying.	1	7/4/2023	https://www.google.com/maps/place/51.50937845005695%2C-0.35424026131478437/@51.50937845005695,-0.35424026131478437,1	Iron Bridge, Uxbridge Rd, Southall UB1 3EG	Iron bridge	Southall Green / Norwood Green / Dormers Wells	Iron Bridge general poor infrastructure.	1			1	1			1		1				1					1	1			1																
0764	Going up this hill is dangerous due to parked vehicles and buses that force you to pull out into uncompromising traffic	1	7/4/2023	https://www.google.com/maps/place/51.508501072286535%2C-0.34097963209627213/@51.508501072286535,-0.34097963209627213,1	207A Uxbridge Rd, London, W7 3TH	Hanwell	Hanwell Broadway	Uxbridge Road Hanwell hotspot. Parking in cycle lane and tricky general conditions	1			1			1	1		1				1								1																	
0765	Fell off here due to large pot hole. This downhill section is badly rutted with numerous pot holes, very dangerous	1	7/4/2023	https://www.google.com/maps/place/51.50861769230643%2C-0.34472512071027195/@51.50861769230643,-0.34472512071027195,1	483 Uxbridge Rd, Southall UB1 3ET	Ealing Hospital	Norwood Green	Increasingly appears to be a problem hotspot. Poor road condition Eastbound Uxbridge Road around the hospital	1	1		1	1		1			1					1																								
0766	I don't feel safe as a cyclist or pedestrian on the joint pathway for cyclists and pedestrians. I was nearly hit the other day by an oncoming electric bike going really fast on the downhill section from the station heading to Hanwell.	1	7/4/2023	https://www.google.com/maps/place/51.49627335645733%2C-0.3248654885872426/@51.49627335645733,-0.3248654885872426,17	Boundary House Business Centre, Boston Rd, London, W7	Boston Manor	Northfield	The shared pavements North of Boston Manor station are poorly designated at present and do not appear to be safe	1	1		1	1		1	1				1								1								1											
0767	Cycle lanes on Bollo Bridge Road, Acton Lane and Cunnington Street would be useful	1	7/4/2023	https://www.google.com/maps/place/51.501900237094354%2C-0.27121938949053126/@51.501900237094354,-0.27121938949053126,1	98 Bollo Bridge Rd, London, W3 8TJ	South Acton	South Acton / Southfield	Bollo Bridge Road and Acton Lane could help provide additional East-West routes as well as a bypass of Uxbridge Road hotspots. Cunnington Street could be	1		1				1										1																					
0768			7/4/2023	https://www.google.com/maps/place/51.49920576995132%2C-0.26451493685912375/@51.49920576995132,-0.26451493685912375,1																																										
0769			7/4/2023	https://www.google.com/maps/place/51.50391137433141%2C-0.26673733575359737/@51.50391137433141,-0.26673733575359737,1																																										
0770	Also Bollo Lane	1	7/4/2023	https://www.google.com/maps/place/51.501571544708725%2C-0.2780706237062658/@51.501571544708725,-0.2780706237062658,17	96 Osborne Rd, London, W3 8RB	South Acton	South Acton / Southfield	Assumed to be connected to previous comment and therefore a request for a cycle lane on Bollo Lane	1			1			1											1																					
0771	Fletcher Road to join up S Acton overground station	1	7/4/2023	https://www.google.com/maps/place/51.50134513001413%2C-0.26708042337648896/@51.50134513001413,-0.26708042337648896,1	48-24 Fletcher Rd, London,	South Acton	Southfield	This would complete a potentially useful connection to C49 / Southfield Road (via Kingswood Terrace too)	1			1			1											1			1																		
0772	Cycle path crosses pedestrian areas without warning also passes through a bus stop.	1	7/4/2023	https://www.google.com/maps/place/51.50017727745301%2C-0.3376623888694441/@51.50017727745301,-0.3376623888694441,17	Boston Manor Station, Boston Manor Rd, Brentford	Boston Manor	Northfield	Assumed to be the bus stop North of Boston Manor station which needs attention	1	1		1	1		1							1																	1								
0773	Cyclists including school children use extensively bu they have to mix with cars that use it as a rat-run. Also some of the cars have a tendency to speed up on the road. Measures that would calm or prevent traffic would be beneficial	1	7/4/2023	https://www.google.com/maps/place/51.51778473632395%2C-0.31167939035411374/@51.51778473632395,-0.31167939035411374,1	15 Amherst Rd, London, W13 8LU	Montpelier	Ealing Broadway	Conceivable rat run.	1			1			1																				1		1							1			
0774			7/4/2023	https://www.google.com/maps/place/51.513105661062355%2C-0.384182622023741/@51.513105661062355,-0.384182622023741,17																																										
0775			7/4/2023	https://www.google.com/maps/place/51.504772081884205%2C-0.3766295214378035/@51.504772081884205,-0.3766295214378035,17																																										
0776			7/4/2023	https://www.google.com/maps/place/51.50904590264586%2C-0.34126727778545973/@51.50904590264586,-0.34126727778545973,1																																										
0777			7/4/2023	https://www.google.com/maps/place/51.50968694118463%2C-0.3532835741721785/@51.50968694118463,-0.3532835741721785,17																																										
0778			7/4/2023	https://www.google.com/maps/place/51.52133090440629%2C-0.29680698115460036/@51.52133090440629,-0.29680698115460036,1																																										
0779	inconvenient - no way to get to ealing broadway centre on bike without being in massive danferous traffic, totally insufficient and hidden away, inconveniently places bike racks	1	7/4/2023	https://www.google.com/maps/place/51.510728609573164%2C-0.3049608965598738/@51.510728609573164,-0.3049608965598738,17	Central Studios Ealing, 1 The Grove, London, W5 5BL	Ealing Broadway	Ealing Broadway	At the rear of these student homes there are two large double tiered bike racks which are presumably for resident use rather than shoppers. Appear to be poorly			|1|																																			
0780	really difficult to cross the road here as there is just a traffic island and the traffic is pretty continuous - needs a zebra	1	7/4/2023	https://www.google.com/maps/place/51.51008758569112%2C-0.2919146319114363/@51.51008758569112,-0.2919146319114363,17	1 Leopold Rd, London, W5 3PB	Ealing Common	Ealing Common	Appears to be an incorrect location - this location is a Pelican crossing																																						
0781	need bike priority at front of lights on popes lane and gunnersbury lane,	1	7/4/2023	https://www.google.com/maps/place/51.50187511989698%2C-0.2854490189512493/@51.50187511989698,-0.2854490189512493,17	144 Gunnersbury Ave, London, W3 8LA	Gunnersbury Park	Ealing Common / South Acton	Agreed - although more is need at this junction than just bike priority - this junction is only adapted for cyclists heading north - south on the Western side of the A406	1			1			1	1			1							1					1																
0782	access from the park back on the road is dangerous because a) there is no light for traffic from park and b) there is a lot of jumping of red light for traffic coming out of lionel road north - needs a camera here	1	7/4/2023	https://www.google.com/maps/place/51.49984478553431%2C-0.29952525186140555/@51.49984478553431,-0.29952525186140555,1	94 Popes Ln London, W5 4NS	Gunnersbury Park	Northfield / Ealing Common / Hounslow				1											1									1			1	1													
0783			7/4/2023	https://www.google.com/maps/place/51.5099963582626%2C-0.3290497145999738/@51.5099963582626,-0.3290497145999738,17																																										

0838	Junction and two way traffic	1	7/4/2023	https://www.google.com/maps/place/51.50405476325537%2C-0.33339628000089716/@51.50405476325537,-0.33339628000089716,1	173 Boston Rd, London, W7 3QJ	Boston Manor	Hanwell Broadway / Walpole	C41 joins Boston Road which lith limited cycle infrastructure. This junction should be reviewed as there is contraflow cycle traffic on Oaklands and the cycle route	1		1				1	1				1						1			1																		
0839	Narrow road spilts into 2 lanes	1	7/4/2023	https://www.google.com/maps/place/51.507986755128215%2C-0.34181913237102846/@51.507986755128215,-0.34181913237102846,1	Salvation Army Hall, Lower Boston Rd, London, W7 3UA	Hanwell / Viaduct	Hanwell Broadway	There is no support for cyclists where the road widens and becomes two (narrow lanes) particularly in relation to moving across to the cycle lane in the middle of	1			1			1	1		1		1							1	1			1																
0840	Cars parked on side of the road, car doors opened without care. No cycle lane	1	7/4/2023	https://www.google.com/maps/place/51.50893260104672%2C-0.33675137952358325/@51.50893260104672,-0.33675137952358325,1	127 Uxbridge Rd, London, W7 3ST	Hanwell Clock Tower	Hanwell Broadway	West Ealing - Hanwell hotspot. Mainly a parking in cycle lanes issue	1			1	1		1			1								1				1					1												
0841	Bus lane surface full of potholes	1	7/4/2023	https://www.google.com/maps/place/51.50925667387573%2C-0.3475047530643405/@51.50925667387573,-0.3475047530643405,17	429 Uxbridge Rd, Southall UB1 3EW	Ealing Hospital	Norwood Green	Increasingly appearing to be a hotspot for poor highway way concerns	1	1		1	1		1			1					1																								
0842	Canal towpath is poorly surfaced, and litter (eg. cans and bottles) presents a hazard to cycling.	1	7/4/2023	https://www.google.com/maps/place/51.50547996114736%2C-0.35178510729072077/@51.50547996114736,-0.35178510729072077,1	Hanwell Lock No 93, Grand Union Canal, Windmill	Ealing Hospital (Canal)	Norwood Green	This section of the canal path has been improved therefore likely to be a general comment on the cycle path network	1			1			1	1					1		1		1																						
0843			7/4/2023	https://www.google.com/maps/place/51.5088722864894%2C-0.3378555079185164/@51.5088722864894,-0.3378555079185164,17																																										
0844			7/4/2023	https://www.google.com/maps/place/51.50900463264714%2C-0.33427110880287714/@51.50900463264714,-0.33427110880287714,1																																										
0845			7/4/2023	https://www.google.com/maps/place/51.51325388485241%2C-0.304279470036406/@51.51325388485241,-0.304279470036406,17z																																										
0846			7/4/2023	https://www.google.com/maps/place/51.50796718881503%2C-0.2733687838346599/@51.50796718881503,-0.2733687838346599,17																																										
0847			7/4/2023	https://www.google.com/maps/place/51.511653124510424%2C-0.29142399536248753/@51.511653124510424,-0.29142399536248753,1																																										
0848			7/4/2023	https://www.google.com/maps/place/51.499107878336744%2C-0.3028783576468763/@51.499107878336744,-0.3028783576468763,17																																										
0849			7/4/2023	https://www.google.com/maps/place/51.50776302510856%2C-0.31309220957558725/@51.50776302510856,-0.31309220957558725,1																																										
0850			7/4/2023	https://www.google.com/maps/place/51.513478794680374%2C-0.30691240000527475/@51.513478794680374,-0.30691240000527475,1																																										
0851	This cycle lane only exists for a short section of Castlebar Rd. It then peters out. For cycle lanes to be useful they need to be continuous and joined up. This a perfect example of an almost useless cycle lane. And there is no cycle lane in the other direction.	1	7/4/2023	https://www.google.com/maps/place/51.520080927618324%2C-0.3110676634430276/@51.520080927618324,-0.3110676634430276,17	74 Castlebar Rd, London, W5 2DD	Castlebar Hill	Ealing Broadway	Generally agreed - this cycle lane provides support for slow moving cyclists on an uphill section which does therefore have a place. Suggests for improving	1			1			1	1										1			1																		
0852	Kent avenue, North Avenue, The Avenue. These are not cycle lanes. It would be useful if these were proper segregated cycle lanes. Just labelling a road a cycle lane is not enough.	1	7/4/2023	https://www.google.com/maps/place/51.520312065799146%2C-0.31722447338877524/@51.520312065799146,-0.31722447338877524,1	12 North Ave, London W13 8AP	Montpelier	Pitshanger / Ealing Broadway	General blue route improvements	1			1			1	1												1	1																		
0853			7/4/2023	https://www.google.com/maps/place/51.51662111320469%2C-0.2958342561551519/@51.51662111320469,-0.2958342561551519,17																																										
0854	This not a proper cycle lane. Needs to be segregated to be safe.	1	7/4/2023	https://www.google.com/maps/place/51.51654099607697%2C-0.2957913408109136/@51.51654099607697,-0.2957913408109136,17	60 Madeley Rd, London, W5 2LU	Ealing Broadway / Hanger Hill	Ealing Broadway / Hanger Hill	Improvement to Madeley should be considered as a key East - West route	1			1			1	1										1		1																			
0855			7/4/2023	https://www.google.com/maps/place/51.49958030687676%2C-0.2603674329188954/@51.49958030687676,-0.2603674329188954,17																																										
0856			7/4/2023	https://www.google.com/maps/place/51.50209963778544%2C-0.25338420162707154/@51.50209963778544,-0.25338420162707154,1																																										
0857			7/4/2023	https://www.google.com/maps/place/51.49539388049965%2C-0.2605510641148645/@51.49539388049965,-0.2605510641148645,17																																										
0858			7/4/2023	https://www.google.com/maps/place/51.51310411568453%2C-0.31129873723602763/@51.51310411568453,-0.31129873723602763,1																																										
0859			7/4/2023	https://www.google.com/maps/place/51.51139360099101%2C-0.35480228676806114/@51.51139360099101,-0.35480228676806114,1																																										
0860			7/4/2023	https://www.google.com/maps/place/51.52441924774586%2C-0.2580499785944945/@51.52441924774586,-0.2580499785944945,17																																										
0861			7/4/2023	https://www.google.com/maps/place/51.52106198619151%2C-0.2623846799292684/@51.52106198619151,-0.2623846799292684,17																																										
0862			7/4/2023	https://www.google.com/maps/place/51.515802446636606%2C-0.2518234184140189/@51.515802446636606,-0.2518234184140189,17																																										
0863	1 argyle road, turning west into felix road - very scary on a bike: narrow lanes, unforgiving cars. I normally use the pavement instead (illegal but safe) 2 Tentelow lane/windmill road - lovely route in lockdown now full of white vans and aggressive car drivers who enjoy intimidating cyclists (I am also a car driver, I know how you're meant to behave	1	7/4/2023	https://www.google.com/maps/place/51.51368600908837%2C-0.31950870434224177/@51.51368600908837,-0.31950870434224177,1	1, Castle Hill Parade, The Avenue, London, W13 8JP	West Ealing / Three Bridges	Norwood Green / Pitshanger / Ealing Broadway / Hanwell	Argyle / Felix is the West Ealing station hotspot - lack of clear cycle infrastructure connecting north - south across the railway.	1			1			1	1										1																					
0836.1		1			230 Tentelow Ln, Southall UB2 4LR			Additional location for previous log	1			1			1	1										1																					
0864	Full of rat runners	1	7/4/2023	https://www.google.com/maps/place/51.50370488244288%2C-0.35631596835499435/@51.50370488244288,-0.35631596835499435,1	228 Tentelow Ln, Southall UB2 4LR	Norwood Green	Norwood Green	Difficult to class this traffic as Rat Running as this is an A road.	1			1																									1											
0865	Very infrequent protected space and very frequent illegal parking that gets in the way - needs protected lanes throughout	1	7/4/2023	https://www.google.com/maps/place/51.50924989055857%2C-0.27935233041972873/@51.50924989055857,-0.27935233041972873,1	335 Uxbridge Rd, London, W3 9RA	Acton	North Acton / South Acton	Uxbridge Road Acton - parking in cycle lanes and request for increased segregation	1			1			1	1		1										1		1				1	1												
0866	Awful road surface and cycling in the bus lane does not make me feel safe	1	7/4/2023	https://www.google.com/maps/place/51.51306658648473%2C-0.3103937873706841/@51.51306658648473,-0.3103937873706841,17	26-30 Uxbridge Rd, London, W5 2AU	West of Ealing Broadway	Ealing Broadway / Walpole	Uxbridge Road hotspot - lack of segregation / road condition	1			1	1		1	1		1					1					1																			
0867	Big and busy junction with no protected lanes	1	7/4/2023	https://www.google.com/maps/place/51.51163999685041%2C-0.2917230784371938/@51.51163999685041,-0.2917230784371938,17	2-8 Hanger Ln, London, W5 3HN	Ealing Common	Ealing Common	hotspot junction A406 / Uxbridge	1			1	1			1		1	1							1					1																
0868	Very infrequent protection that often gives up right when you need it	1	7/4/2023	https://www.google.com/maps/place/51.50715256501057%2C-0.25391473080254245/@51.50715256501057,-0.25391473080254245,1	131 The Vale, London, W3 7RQ	Acton Park	East Acton / Southfield	Uxbridge Road Acton	1			1			1	1		1										1																			
0869	No way of getting to the station from the broadway - major incovencience. Needs a contra flow to the station.	1	7/4/2023	https://www.google.com/maps/place/51.514122195633625%2C-0.301889267007025/@51.514122195633625,-0.301889267007025,17z	35 The Broadway, London, NW7 3DG	Ealing Broadway	Ealing Broadway	Ealing Broadway Hotspot - no cycle infrastructure to and from the station	1			1	1			1										1																					
0870	Needs to be a pedestrian and cycle crossing to link parks	1	7/4/2023	https://www.google.com/maps/place/51.506727405470635%2C-0.3107713992527672/@51.506727405470635,-0.3107713992527672,17	55A Culmington Rd, London, W13 9NJ	Walpole / Lammas	Walpole	hotspot junction Walpole / Lammas / Culmington / Elers junction there is a crossing already but it would be improved if a Zebra	1			1			1														1																		Improve crossings
0871	Needs light phasing for bikes	1	7/4/2023	https://www.google.com/maps/place/51.504358601772864%2C-0.3064119522421649/@51.504358601772864,-0.3064119522421649,17	84A St Mary's Rd, London, W5 5EX	South Ealing	Walpole / Ealing Broadway	This is a key junction for c86 and potentially any additional north - south infrastructure on St Marys. At present there is no infrastructure to make this	1		1					1										1			1		1																
0872	Speeding cars. Needs speed cameras as danger to cyclists and pedestrians	1	7/4/2023	https://www.google.com/maps/place/51.50550348455464%2C-0.30937897416305704/@51.50550348455464,-0.30937897416305704,1	Park Sports Lammas Park, Ealing Culmington Rd, Greater, London,	Walpole / Lammas	Walpole	Known rat run so speed could be a concern despite speed humps at start and end of this section	1			1			1																			1	1		1										
0873	Junction is congested not quiet. Needs light phasing, segregation or alternative route	1	7/4/2023	https://www.google.com/maps/place/51.511059354747196%2C-0.30558053593984/@51.511059354747196,-0.30558053593984,17z	14 The Grn, London, W5 5DA	Ealing Green	Ealing Broadway / Ealing Common / Walpole	Agreed - improvements strongly advised and outlined in suggestions	1			1			1	1										1			1																		
0874	It's very messy at the station where cyclists and pedestrians share the pavement and then the new cycle lane starts in Hounslow	1	7/4/2023	https://www.google.com/maps/place/51.49581557940986%2C-0.3248122376070972/@51.49581557940986,-0.3248122376070972,17	Boston Manor Underground Station, Boston Manor Rd,	Boston Manor	Northfield	Boston Road concerns around the pavement north of the station	1	1		1	1		1	1				1							1	1			1																
0875			7/4/2023	https://www.google.com/maps/place/51.50613886995916%2C-0.26430442511041097/@51.50613886995916,-0.26430442511041097,1																																										
0876			7/4/2023	https://www.google.com/maps/place/51.50669179177077%2C-0.24905994806616372/@51.50669179177077,-0.24905994806616372,1																																										
0877			7/4/2023	https://www.google.com/maps/place/51.50807816264994%2C-0.2779708565510486/@51.50807816264994,-0.2779708565510486,17																																										
0878			7/4/2023	https://www.google.com/maps/place/51.50984103437259%2C-0.2859531105793689/@51.50984103437259,-0.2859531105793689,17																																										
0879			7/4/2023	https://www.google.com/maps/place/51.50791789820191%2C-0.2939353646076892/@51.50791789820191,-0.2939353646076892,17																																										
0880	Turning right into Montpelier Ave is very awkward and potentially dangerous as drivers don't expect cyclists to join the road at the zebra crossing. When signalling right, it confuses oncoming drivers thinking the cyclist intends to cross the road.	1	7/4/2023	https://www.google.com/maps/place/51.52031027273303%2C-0.3111279408975154/@51.52031027273303,-0.3111279408975154,17	76 Castlebar Rd, London, W5 2DD	Montpelier	Ealing Broadway	Appears to be a valid concern additional road markings are required to make it clear to drivers that cyclists are turning right.	1			1			1												1																				Crossing concern
0881	Cycleway not clearly signed	1	7/4/2023	https://www.google.com/maps/place/51.52366801597099%2C-0.2656275655258633/@51.52366801597099,-0.2656275655258633,17	283 Western Ave, London W3 0PP	North Acton	North Acton	This could be referring to the link between the segregated path on the southern side of Western Avenue and Park Royal Road which is a poorly designated blue route and	1			1		1	1											1			1																		Signage
0882	Turning from the A406 into Queen's Drive is very awkward	1	7/4/2023	https://www.google.com/maps/place/51.51703039056971%2C-0.2912882011206164/@51.51703039056971,-0.2912882011206164,17	20 Queen's Dr, London, W5 3HU	North Ealing	Hanger Hill	Madeley / Queens / A406 hotspot junction. Needs improvement - no support other than north - south on the western side of the road	1			1	1		1	1			1							1					1																
0883	No clear way to get to Ealing Broadway station from The Broadway	1	7/4/2023	https://www.google.com/maps/place/51.51401668528822%2C-0.30180312212579663/@51.51401668528822,-0.30180312212579663,1	53 The Broadway, London, W5 5JS	Ealing Broadway	Ealing Broadway	Ealing Broadway hotspot - no cycle infrastructure	1			1	1		1	1		1								1																					
0884	Difficult to turn right into the A406 coming from Ealing Broadway	1	7/4/2023	https://www.google.com/maps/place/51.51145605995418%2C-0.2920233331988076/@51.51145605995418,-0.2920233331988076,17	2-8 Hanger Ln, London, W5 3HN	Ealing Common	Ealing Common	hotspot junction A406 / Uxbridge - very difficult to continue straight or turn right	1			1	1			1		1	1							1					1																
0885	Dangerous due to no cycle Lane in either direction	1	7/4/2023	https://www.google.com/maps/place/51.508379512041884%2C-0.2756438051156618/@51.508379512041884,-0.2756438051156618,17	272 High St, London, W3 9BH	Acton	North Acton / South Acton	hotspot section between the roundabout and Gunnersbury Lane - improvements have been outlined.	1			1	1		1	1		1								1	1	1			1																
0886	Separate cycle Lane needed westbound. Traffic doesn't leave enough room for cycles to get past	1	7/4/2023	https://www.google.com/maps/place/51.507589200523455%2C-0.27254361332379906/@51.507589200523455,-0.27254361332379906,1	197 High St, London, W3 9DD	Acton	South Acton	Relatively narrow section of Uxbridge Road in Acton - presumably too narrow to add segregation but the 'no loading' could be extended to 24 hours to ensure the route	1			1			1			1										1		1					1												
0887	There is no safe cycleway on this road, it is just paint. Cars park in it. Lots of close passes.	1	7/4/2023	https://www.google.com/maps/place/51.50961359327719%2C-0.3277080079185768/@51.50961359327719,-0.3277080079185768,17	146 Broadway, London,, W13 9BE	West Ealing	Hanwell Broadway / Walpole	Deans Garden - Cemetery hotspot in West Ealing. Parking in cycle lane and lack of segregation	1			1	1		1	1		1												1					1												
0888	As previous comment	1	7/4/2023	https://www.google.com/maps/place/51.50925316463844%2C-0.3312523622023855/@51.50925316463844,-0.3312523622023855,17	Cherry House, 30 Uxbridge Rd, London, W7 3PP	West Ealing	Hanwell Broadway / Walpole	Deans Garden - Cemetery hotspot in West Ealing. Parking in cycle lane and lack of segregation	1			1	1		1	1		1												1																	
0889	Drivers speed on this road. Needs closing to rat runners.	1	7/4/2023	https://www.google.com/maps/place/51.50834356325465%2C-0.3137144229568456/@51.50834356325465,-0.3137144229568456,17	24 Churchfield Rd, London, W13 9NH	Walpole	Walpole	Culmington / Churchfield is a known rat run. 'Closing' to rat runners will be politically challenging but speed enforcement should be considered.	1		1	1			1	1													1					1	1												
0890	This is the North Circular, it is not a quietway! If its not suitable for a 10yo then its not a good cycle route.	1	7/4/2023	https://www.google.com/maps/place/51.502758702924275%2C-0.2879547517577552/@51.502758702924275,-0.2879547517577552,17	80 Gunnersbury Ave, London, W5 4HA	Ealing Common / Gunnersbury Park	Ealing Common	This route includes sections on the main carriageway	1			1	1		1	1			1								1	1																			
0891	No safe cycle route here, it's a busy main road.	1	7/4/2023	https://www.google.com/maps/place/51.51210853424132%2C-0.3105739936678886/@51.51210853424132,-0.3105739936678886,17	71 Uxbridge Rd, London, W5 5SL	Ealing Broadway	Ealing Broadway / Walpole	hotspot section of Uxbridge Road west of Ealing Broadway which lacks segregation etc. Suggestions for improvements have been made	1			1	1		1	1		1										1		1																	
0892	Uxbridge Road is a very horrible cycling environment with a current lack of provision, but in particular the number of illegally parked	1	7/4/2023	https://www.google.com/maps/place/51.51099937684958%2C-0.31886254029187544/@51.51099937684958,-0.31886254029187544,1	209 Uxbridge Rd, London, W13 9AA	West Ealing	Hanwell Broadway / Walpole	hotspot section of Uxbridge Road west of Ealing Broadway which lacks segregation etc and only has short periods of no loading restrictions	1			1			1			1								1				1																	
0893			7/4/2023	https://www.google.com/maps/place/51.50818805353338%2C-0.3419188588984645/@51.50818805353338,-0.3419188588984645,17																																										

0894	Next to busy road and street furniture is within the cycle way too	1	7/4/2023	https://www.google.com/maps/place/51.53244015301896%2C-0.3154050619819815/@51.53244015301896,-0.3154050619819815,17	24 Langdale Gardens, Perivale, Greenford UB6 8DG	A40 Perivale	Perivale	Pin originally on the southern side. Unable to identify any overly problematic items of street furniture other than some signage which is required and does not overly																																							
0895	So many motorists speed and close pass here	1	7/4/2023	https://www.google.com/maps/place/51.506967856086234%2C-0.31121744341894964/@51.506967856086234,-0.31121744341894964,1	39-55 Culmington Rd, London, W13 9NB	Walpole	Walpole	Culmington / Churchfield is a known rat run. 'Closing' to rat runners will be politically challenging but speed enforcement should be considered.	1		1	1			1	1													1					1	1											
0896	Road marking not visible enough	1	7/4/2023	https://www.google.com/maps/place/51.50237763209068%2C-0.33052693116116805/@51.50237763209068,-0.33052693116116805,1	211 Boston Rd, London, W7 2AA	Hanwell Broadway	Hanwell Broadway	Markings north of Elmers Park do appear faded - particularly across the junctions	1			1			1					1							1																			
0897	Road markings not visible enough	1	7/4/2023	https://www.google.com/maps/place/51.505936970439734%2C-0.3364671479084591/@51.505936970439734,-0.3364671479084591,17	75-109 Boston Rd, London, W7 3SA	Hanwell Broadway	Hanwell Broadway	Markings appear faded between lower boston road and Trumpers Way	1			1			1					1							1																			
0898	Abandon all hope ye who enter here	1	7/4/2023	https://www.google.com/maps/place/51.51318404843684%2C-0.30877045750907106/@51.51318404843684,-0.30877045750907106,1	14 Uxbridge Rd, London, W5 2HL	Ealing Broadway	Ealing Broadway	Noted. May not be intended to be a comment on Uxbridge Road but logged accordingly all the same										1				1																									
0899	Here be dragons	1	7/4/2023	https://www.google.com/maps/place/51.53112988382092%2C-0.24792532547478263/@51.53112988382092,-0.24792532547478263,1	72 Old Oak Ln, London, NW10 6UB	North Acton / Willesden Junction	North Acton	Borough boundary - lack of cycle infrastructure.	1			1			1	1										1																					
0900	Lacking the vistas that cyclists like. Needs more cricket pitches.	1	7/4/2023	https://www.google.com/maps/place/51.512728269680785%2C-0.38246298406055423/@51.512728269680785,-0.38246298406055423,1	8 Dane Rd, Southall UB1 2EA	Southall	Southall Broadway	Unable to determine a definite action but assumed to be Uxbridge Road Southall which lacks segregation										1				1																									
0901	Too middle class.	1	7/4/2023	https://www.google.com/maps/place/51.50677091772827%2C-0.33838120462792/@51.50677091772827,-0.33838120462792,17z	23A Lower Boston Rd, London, W7 3TP	Hanwell Viaduct	Hanwell Broadway	Known to be a hotspot but no definite action																																							
0902	Not enough high rises. Needs more elevated parking options for flying bicycles.	1	7/4/2023	https://www.google.com/maps/place/51.51825512845059%2C-0.26123955611461636/@51.51825512845059,-0.26123955611461636,1	216 Western Ave, London W3 6YW	A40 East Acton	East Acton	No clear action																																							
0903			7/4/2023	https://www.google.com/maps/place/51.51293888758637%2C-0.32568597997289617/@51.51293888758637,-0.32568597997289617,1																																												
0904			8/4/2023	https://www.google.com/maps/place/51.506328149767874%2C-0.2512800038299079/@51.506328149767874,-0.2512800038299079,17																																												
0905			8/4/2023	https://www.google.com/maps/place/51.50650247666852%2C-0.2608930409392829/@51.50650247666852,-0.2608930409392829,17																																												
0906			8/4/2023	https://www.google.com/maps/place/51.4947574124149%2C-0.2672972171066368/@51.4947574124149,-0.2672972171066368,17																																												
0907			8/4/2023	https://www.google.com/maps/place/51.50679132211692%2C-0.25718080415543243/@51.50679132211692,-0.25718080415543243,1																																												
0908			8/4/2023	https://www.google.com/maps/place/51.509085198687245%2C-0.2627860034780416/@51.509085198687245,-0.2627860034780416,17																																												
0909	The junction to turn into oaklands rise from old oak common lane is very difficult to navigate especially when coming from wormwood scrub's direction. Better road markings which give space for bike to pause and turn is needed	1	8/4/2023	https://www.google.com/maps/place/51.527293672515654%2C-0.2503630439450455/@51.527293672515654,-0.2503630439450455,17	Oaklands Rise, 2 Green St, Old Oak Common Ln, London,	North Acton / Willsden Junction	North Acton	Borough boundary - the new housing is outside but the junction is inside. Old Oak Common generally lacks road markings but cycle markings will certainly support cyclists	1			1			1											1																					
0910	A cycle lane or shared pedestrian/ bike path is needed on old oak common lane. With the HS2 works going on it for many more years yet, it makes it dangerous and intimidating for cyclists faced with massive lorries constantly on route. This would also help families get their children to the local schools by bike without using cars	1	8/4/2023	https://www.google.com/maps/place/51.52397388608606%2C-0.25285197699556505/@51.52397388608606,-0.25285197699556505,1	11 Wells House Rd, London, NW10 6ED	North Acton / Willsden Junction	North Acton	Old Oak Common Lane connects cycle routes around East Acton station to the south and the canal / Victoria Road to the north. A cycle lane should be provided however	1			1			1											1																					
0911	Partitioned Cycle lane on old oak common lane/ old oak lane would be safer	1	8/4/2023	https://www.google.com/maps/place/51.512699429371224%2C-0.24797105958270338/@51.512699429371224,-0.24797105958270338,1	156 Old Oak Rd, London, W3 7HE	East Acton	East Acton	No existing cycle infrastructure on Old Oak Road. Various bits of blue route in the area but no complete and obvious north - south	1			1			1	1										1		1																			
0912	Partitioned cycle path on victoria rd would be safer	1	8/4/2023	https://www.google.com/maps/place/51.52500978095944%2C-0.2565671549267412/@51.52500978095944,-0.2565671549267412,17	LEWIS HOUSE, 3 School Rd, London, NW10 6TD	North Acton	North Acton	Victoria Road North Acton (designated blue route). In general the existing cycle path is very faded. The road appears wide enough in at least some of the sections to	1			1			1	1										1		1																			
0913			8/4/2023	https://www.google.com/maps/place/51.512363092481486%2C-0.29489279732603624/@51.512363092481486,-0.29489279732603624,1																																												
0914			8/4/2023	https://www.google.com/maps/place/51.51285840725487%2C-0.3071951303785281/@51.51285840725487,-0.3071951303785281,17																																												
0915			8/4/2023	https://www.google.com/maps/place/51.50605389280907%2C-0.2783784537745415/@51.50605389280907,-0.2783784537745415,17																																												
0916			8/4/2023	https://www.google.com/maps/place/51.50844715245444%2C-0.29122562584173783/@51.50844715245444,-0.29122562584173783,1																																												
0917			8/4/2023	https://www.google.com/maps/place/51.50218742717694%2C-0.28351025092007154/@51.50218742717694,-0.28351025092007154,1																																												
0918			8/4/2023	https://www.google.com/maps/place/51.51532416752654%2C-0.3022737286171928/@51.51532416752654,-0.3022737286171928,17																																												
0919	The improvements are welcome but something more joined up would be better. There's lots of parked cars so some sections are scary to navigate. Because traffic can be so bad here, we really need a way for bikes to avoid getting stuck in traffic queues	1	8/4/2023	https://www.google.com/maps/place/51.50569228174294%2C-0.2525906976880954/@51.50569228174294,-0.2525906976880954,17	115a The Vale, London, W3 7RQ	Acton	South Acton / East Acton / Southfield	Uxbridge Road - continue to increase segregation, remove parking in cycle lanes particularly during busy times.	1			1			1	1		1										1		1																		
0920	Please can you make Warple way 2 way for bikes. Coming out of Valetta road one wants to be able to turn right, left, right to join the Uxbridge road without going all the way round by the sewers where there are often lorries. Or just right to go to Acton park	1	8/4/2023	https://www.google.com/maps/place/51.504704750042784%2C-0.2556280466130678/@51.504704750042784,-0.2556280466130678,17	37 Warple Way, London, W3 0RX	East Acton / Southfield	Southfield	The blue route in this area uses Larden Road which is essentially parallel to Warpole but lacks signage etc. Contraflow could be considered for the north	1		1				1	1										1		1	1																		Consider contraflow
0921	Don't know how you're going to do it but really need a way to get cyclists to avoid traffic in Acton high street. The improvements help but not enough for more vulnerable road users	1	8/4/2023	https://www.google.com/maps/place/51.50695298331235%2C-0.2702032031427226/@51.50695298331235,-0.2702032031427226,17	149 High St, London, W3 6LP	Acton	South Acton / East Acton / Southfield	Uxbridge Road in Acton - continue to increase segregation (and improve other east - west options)	1			1			1	1		1										1		1																		
0922	Please make this 2 way for bikes so one can come from the SW and join Valetta road. Cyclists do this anyway, so would be safer to make it official	1	8/4/2023	https://www.google.com/maps/place/51.503650133316825%2C-0.2560360931561423/@51.503650133316825,-0.2560360931561423,17	24 Canham Rd, London, W3 7SR	East Acton / Southfield	Southfield	Canham Road is a connection into Bedford park therefore it is unsurprising that cyclists traveling SW - NE would be looking to use this route therefore a contra flow could	1		1				1	1										1		1	1																		
0923	This whole area has been immensely improved by closure to cars. Unfortunately cars often still flout the restrictions. If buses could be re-routed and the underpass closed to traffic that would be great. Also needs better joining up to Chiswick High Road C9 at end of Fisher's lane. And widening of pedestrian walkway under railway bridge	1	8/4/2023	https://www.google.com/maps/place/51.4949690489662%2C-0.2603785193225905/@51.4949690489662,-0.2603785193225905,17	73 Fisher's Ln, London, W4 5LG	Chiswick	Southfield	Improvements to underpass - increase enforcement and widen pedestrian path would be Ealing - Improvements at Chiswick High Road are Hounslow. Re-routing bus	1			1			1													1						1	1												
0924	Poorly marked, never noticed it	1	8/4/2023	https://www.google.com/maps/place/51.49918713601982%2C-0.27275180604831917/@51.49918713601982,-0.27275180604831917,1	6, 8 Colville Rd, London, W3 8BL	South Acton	South Acton	Assumed to be the cycle path linking Colville Road / Staley Road. Essentially an improve designation / residential routes issue as it is quite discrete	1			1			1												1		1																		
0925	Road is quite busy and narrow due to parked cars.	1	8/4/2023	https://www.google.com/maps/place/51.49996497009744%2C-0.26032882370912613/@51.49996497009744,-0.26032882370912613,1	126 Rusthall Ave, London W4 1BS	Bedford Park	Southfield	Agreed - but difficult to resolve as the street is narrow, kinked and two way. One way traffic with St Albans parallel might improve this area (both cyclists and motor	1			1			1														1																		
0926	Narrow bike lane, not separated from traffic, poor surface.	1	8/4/2023	https://www.google.com/maps/place/51.506574530529086%2C-0.26573732136530026/@51.506574530529086,-0.26573732136530026,1	39 High St, London, W3 6ND	Acton	South Acton	This section of Uxbridge Road in acton lacks segregation . There does appear to be a pothole westbound approching the junction as of September 2022	1			1			1	1		1					1					1																			
0927	Poor surface, bike lane in one direction only, busy road for other side.	1	8/4/2023	https://www.google.com/maps/place/51.50579568740038%2C-0.270206205270469/@51.50579568740038,-0.270206205270469,17z	58-70 Church Rd, London, W3 8PP	Acton	South Acton	Church Road surface (particularly the cycle lane) is generally poor. Designated cycle lane is uphill only but southbound cyclists should be able to maintain a good	1			1			1								1				1		1																		
0928	This road is scary to cycle along. The stretch from Sainsburys to Ealing Broadway is unavoidably busy but the cars/scooters in the cycle lanes and aggressive driving make it worse.	1	8/4/2023	https://www.google.com/maps/place/51.51308538012907%2C-0.3184992433928313/@51.51308538012907,-0.3184992433928313,17	148 Uxbridge Rd, London, W13 8SB	Hanwell to Ealing Broadway	Hawell Broadway / Walpole / Ealing Broadway	Appears to be an Uxbridge Road Ealing comment in general	1			1	1		1	1		1												1					1												
0929			8/4/2023	https://www.google.com/maps/place/51.511042190763334%2C-0.31768385185230397/@51.511042190763334,-0.31768385185230397,1																																												
0930	Nasty junction with cars half overtaking you and then turning left over you	1	8/4/2023	https://www.google.com/maps/place/51.51331824778319%2C-0.3051664179354119/@51.51331824778319,-0.3051664179354119,17	Units 1/3/22C, The Arcadia Centre, 50/52 The Broadway,	Ealing Broadway	Ealing Broadway	Ealing M&S / McDonalds / Christ the Saviour hotspot junction	1			1	1		1	1		1								1					1																
0931	Cars often turn left across the cycle lane without checking for cyclist, even if they have just overtaken a cyclist	1	8/4/2023	https://www.google.com/maps/place/51.511196009615%2C-0.29091039755476444/@51.511196009615,-0.29091039755476444,1	2-8 Hanger Ln, London, W5 3HN	Ealing Common	Ealing Common	Uxbridge Road / A406 hotspot junction	1			1	1		1	1		1	1							1					1				1												
0932	Cars often pull out from side roads without checking for cyclists	1	8/4/2023	https://www.google.com/maps/place/51.51119096509682%2C-0.30019151056907/@51.51119096509682,-0.30019151056907,17z	94A The Grove, London, W5 3SH	Ealing Common	Ealing Common / Ealing Broadway	Poor driver behaviour on blue route	1			1			1														1						1												
0933	The cycle lane ends into a car lane. Cars often cross the solid white line without checking for cyclist.	1	8/4/2023	https://www.google.com/maps/place/51.508381835007924%2C-0.27548124979727584/@51.508381835007924,-0.27548124979727584,1	267A High St, London, W3 9BY	Acton	South Acton	Acton hotspot. Styne / Uxbridge / Gunnersbury	1	1		1	1		1	1		1										1		1					1												
0934	It's not clear who has priority at the bus stop. The cycle lane and car lane seem to have merged suggesting that cyclists should be able to overtake a parked bus but I've had quite a few cars almost crash into the back of me.	1	8/4/2023	https://www.google.com/maps/place/51.50760493577684%2C-0.27257589630184986/@51.50760493577684,-0.27257589630184986,1	199 Mount Pl, London, W3 9DD	Acton	South Acton	Road markings are very poor heading east from the end of the segregated lane prior to King Street through to the restart of the segregated lane. Additional markings to make	1	1		1	1		1			1									1				1								1								
0935	The quality of the road needs improving along the whole of the Uxbridge Road. It makes risk of punctures very high and discourages cycling and comfort.	1	8/4/2023	https://www.google.com/maps/place/51.50919623775143%2C-0.28017347780895374/@51.50919623775143,-0.28017347780895374,1	347 Uxbridge Rd, London, W3 9RH	Acton	Various	General road quality	1			1			1			1					1																								
0936	Poor/bad/illegal parking causes obstruction at the top of of Coronation Road.	1	8/4/2023	https://www.google.com/maps/place/51.52857941962422%2C-0.27543805091580387/@51.52857941962422,-0.27543805091580387,1	61 Coronation Rd, London, NW10 7PT	Park Royal	North Acton	Coronation Road hotspot of parking in cycle lane	1			1	1		1															1				1													
0937	There is no secure cycling options, a few railings would be good. I often struggle to find somewhere to leave my bike with confidence in this area.	1	8/4/2023	https://www.google.com/maps/place/51.5292972808044%2C-0.2702595679795805/@51.5292972808044,-0.2702595679795805,17	857 Coronation Rd, London, NW10 7PP	North Acton	North Acton	General cycle parking - there are a few but sparse on street stands and there is cycle parking at the hospital. Cycle parking at Asda is of a poor quality (butterfly only)	1			1		1																			1														
0938	Very heavy traffic, very poor quality road/pavement, lack of markings, signage.	1	8/4/2023	https://www.google.com/maps/place/51.52720255644807%2C-0.257207569633926/@51.52720255644807,-0.257207569633926,17z	The Old Torpedo Factory, St Leonards Way, London,	North Acton	North Acton	Very badly faded / designated contraflow in an industrial area. Needs improving.		1		1			1								1				1		1																		
0939	Should be a safer way to get across from the common to the protected cycle track on Uxbridge road. Lots of children could then use this to get to school in Acton / people commute to work. Currently you have to cross three lanes of traffic from the cycle track to turn right onto the main road, then are not well protected crossing the north circular / Uxbridge road junction.	1	8/4/2023	https://www.google.com/maps/place/51.511672123031126%2C-0.29203101521435126/@51.511672123031126,-0.29203101521435126,1	2-8 Hanger Ln, London, W5 3HN	Ealing Common	Ealing Common	Uxbridge / A406 hotspot junction.	1			1	1		1	1		1	1							1					1																
0940	Cycle route needs to be extended along church road which connects to uxbridge road for me to be able to cycle safely. At the moment I don't cycle because of this, there is car parking on church road for a few cars which should be removed I think because parking should not be on a main road. Then this would give room for segregated cycling. Church road is busy and people don't abide by the 20mph	1	8/4/2023	https://www.google.com/maps/place/51.5124481699629%2C-0.3371004665901567/@51.5124481699629,-0.3371004665901567,17	78 Church Rd, London, W7 1LB	Hanwell	North Hanwell / Hanwell Broadway	Church Road (C87) crossing the railway east of Hanwell station - no cycle infrastructure through this section which is narrow - has on street parking with limited	1			1			1	1										1			1					1	1								1				
0941	There should be cycle parking in Hanwell which is protected by CV and monitored as there is no where to park bikes.	1	8/4/2023	https://www.google.com/maps/place/51.5088424294026%2C-0.33602758298419966/@51.5088424294026,-0.33602758298419966,1	107 Uxbridge Rd, London, W7 3ST	Hanwell	Hanwell Broadway	Cycle hub / secure cycle parking in Hanwell Broadway	1			1			1			1															1														
0942	There needs to be segregated cycle routes all along Uxbridge road to enable travel to Ealing Broadway where the shops are and where I would travel for leisure.	1	8/4/2023	https://www.google.com/maps/place/51.50972385900454%2C-0.32941861997150435/@51.50972385900454,-0.32941861997150435,1	3-5 Uxbridge Rd, London, W7 3PX	Hanwell / West Ealing	Hanwell Broadway / Walpole	Uxbridge Road (Ealing) segregation	1			1	1		1	1		1										1																			
0943	There needs to be segregated cycling all along uxbridge road and parking facilities in Ealing Broadway which are monitored by CCTV so bike's wont be stolen.	1	8/4/2023	https://www.google.com/maps/place/51.51330282218156%2C-0.3041414822151567/@51.51330282218156,-0.3041414822151567,17	Units 1/3/22C, The Arcadia Centre, 50/52 The Broadway,	Ealing Broadway	Ealing Broadway	Uxbridge Road (Ealing) segregation and Ealing Broadway cycle parking	1			1	1		1	1		1										1					1														
0944	cycle route should be extended up to Uxbridge road, its very busy on Argyle road, speed bumps to reduce cars speeding and places to park your bike.	1	8/4/2023	https://www.google.com/maps/place/51.51493195855812%2C-0.31948371778034224/@51.51493195855812,-0.31948371778034224,1	1, Castle Hill Parade, The Avenue, London, W13 8JP	West Ealing	Walpole / Hanwell Broadway / Pitshanger / Ealing Broadway	Agreed - this is the West Ealing / Drayton Green Road Bridge hotspot + cycle parking and speed enforcement on Argyle Road	1			1	1		1	1										1							1	1	1									1			
0945	Cycle route needs to be extended along church road, I don't feel safe cycling along church road. It's busy with cars and parking should be removed to allow for space for cycling.	1	8/4/2023	https://www.google.com/maps/place/51.51251808684139%2C-0.3371813944019286/@51.51251808684139,-0.3371813944019286,17	Birchdale 79 church road, London, W7 3BH	Hanwell	North Hanwell / Hanwell Broadway	Agreed - church road lack of north - south infrastructure - parking should be reviewed.	1			1	1		1	1										1																	1				
0946	It would be good if there was cycle parking in Hanwell, there isn't any at the moment. It would be great if it was protected to deter bike theifs.	1	8/4/2023	https://www.google.com/maps/place/51.508770048426946%2C-0.33761054784431144/@51.508770048426946,-0.33761054784431144,1	Sycamore House, 36 Uxbridge Rd, London, W7 3PP	Hanwell	Hanwell Broadway / Walpole	Straight forward - cycle parking in Hanwell,	1			1		1		1																	1														
0947	Drayton Bridge road is busy and deters me from cycling, it would be good if this was looked at with segregated cycling, stopping cars from going along this road.	1	8/4/2023	https://www.google.com/maps/place/51.51656878517735%2C-0.3308728387989013/@51.51656878517735,-0.3308728387989013,17	Drayton Green Station, London, W13 0JX	Drayton Green	North Hanwell / Pitshanger	Drayton Bridge Road has been highlighter as the only existing east - west crossing. Difficult to close the road to traffic completely and segregation may lights for one	1			1	1		1	1										1		1																			
0948	Need segregated cycling that goes up to Uxbridge road	1	8/4/2023	https://www.google.com/maps/place/51.51410603602902%2C-0.31956168950314057/@51.51410603602902,-0.31956168950314057,1	5a The Avenue, London, W13 8JP	West Ealing	Walpole / Hanwell Broadway / Pitshanger / Ealing Broadway	West Ealing station hotspot connecting The Avenue with Uxbridge Road	1			1	1		1	1										1		1																			
0949	Uxbridge road needs to be priortised all the way along to acton with segregated cycling and wands.	1	8/4/2023	https://www.google.com/maps/place/51.50931300313313%2C-0.33388583857647536/@51.50931300313313,-0.33388583857647536,1	Wicklow Court, 61 Uxbridge Rd, London, W7 3PZ	Ealing / Acton	Various	Uxbridge Road Ealing - Acton segregation.	1			1	1		1	1		1										1																			
0950	This route needs to be extended along church road which is very busy and traffic measures put in place to slow down cars. We need segregated cycle routes and to remove the parking on church road with double yellow lines.	1	8/4/2023	https://www.google.com/maps/place/51.5126783351078%2C-0.3368040819846785/@51.5126783351078,-0.3368040819846785,17	Kipling Court, Greenford Ave, London W7 1LZ	Hanwell	North Hanwell / Hanwell Broadway	Agreed - church road lack of north - south infrastructure - parking should be reviewed.	1			1	1		1	1										1		1																1	1			

0951	Greenford avenue remove parking on main road and add segregated cycle route.	1	8/4/2023	https://www.google.com/maps/place/51.51460127 0335746%2C-0.3372332354270613/@51.514601270335746,-0.3372332354270613,17	67B Greenford Ave, London W7 1LL	North Hanwell	North Hanwell / Pitshanger	Tricky but the request is straight forward	1		
0952	Safe cycle parking in Ealing Broadway.	1	8/4/2023	https://www.google.com/maps/place/51.51380005 718893%2C-0.304531743117491/@51.51380005718893,-0.304531743117491,17z	Haven House, 2 Spring Bridge Rd, London, W5 2AA	Ealing Broadway	Ealing Broadway	Clear - but pin location suggests the wider area rather than the station (existing hub in the shopping centre)	1		
0953	Drayton Bridge road remove the parking on this road, it stops buses and there isn't enough space for cycling. Need a segregated cycle route.	1	8/4/2023	https://www.google.com/maps/place/51.51695141 426875%2C-0.327877690383116/@51.51695141426875,-0.327877690383116,17z	191 Drayton Bridge Rd, London, W13 0JH	Drayton Green	North Hanwell / Pitshanger	Agreed - improvements recommended for this key east - west connection	1		
0954	Church Road does not feel safe, lots of traffic, parking on main road. I want segregated cycling.	1	8/4/2023	https://www.google.com/maps/place/51.51126709 991283%2C-0.33513625704240546/@51.51126709991283,-0.33513625704240546,1	50A Church Rd, London, W7 1LB	Hanwell	North Hanwell / Hanwell Broadway	Agreed - church road lack of north - south infrastructure - parking should be reviewed.	1		
0955	Drayton Bridge road, get rid of the parking and slow down traffic. People don't obey the speed limit. Add a speed camera and remove parking.	1	8/4/2023	https://www.google.com/maps/place/51.51690231 3381216%2C-0.32646735750627265/@51.516902313381216,-0.32646735750627265,1	221 Drayton Bridge Rd, London, W13 0JH	Drayton Green	North Hanwell / Pitshanger	Agreed - improvements recommended for this key east - west connection	1		
0956			8/4/2023	https://www.google.com/maps/place/51.51004002 6046156%2C-0.3346775437477967/@51.510040026046156,-0.3346775437477967,17							
0957	Church road does not feel safe and I do not cycle there because of the traffic. Would be good to add some measures for cycling, e.g. segregated cycling and also parking to be moved to the side roads.	1	8/4/2023	https://www.google.com/maps/place/51.51113706 381485%2C-0.33560179798657996/@51.51113706381485,-0.33560179798657996,1	15 Church Rd, London, W7 3BB	Hanwell	North Hanwell / Hanwell Broadway	Agreed - church road lack of north - south infrastructure - parking should be reviewed.	1		
0958	Drayton Bridge road is very difficult to navigate with the busses and traffic, consider remove the parking and add speed camera where the road curves next to Drayton Green station.	1	8/4/2023	https://www.google.com/maps/place/51.51583758 787903%2C-0.33543013660962684/@51.51583758787903,-0.33543013660962684,1	36 Drayton Bridge Rd, London, W7 1EX	Drayton Green	North Hanwell / Pitshanger	Agreed - improvements recommended for this key east - west connection	1		
0959	Church Road is horrible, needs to be segregated. I hate the bloody parking on the main road, add double yellow lines and stop parking on this road at all times.	1	8/4/2023	https://www.google.com/maps/place/51.51177025 414462%2C-0.3360316057883894/@51.51177025414462,-0.3360316057883894,17	78a Church Rd, London, W7 1LB	Hanwell	North Hanwell / Hanwell Broadway	Agreed - church road lack of north - south infrastructure - parking should be reviewed.	1		
0960	Greenford avenue needs segregated cycling and remove parking on this main road and slow down traffic with speed camera as people don't obey.	1	8/4/2023	https://www.google.com/maps/place/51.51652412 4390926%2C-0.3376623888694441/@51.516524124390926,-0.3376623888694441,17	72-138 Greenford Ave, London W7 1HA	North Hanwell	North Hanwell	Tricky to remove parking as it is short stay for businesses or residential. But equally there is a lack of cycle infrastructure on this key north - south route	1		
0961	Drayton Bridge road at the corner is horrible for cyclists, speeding cars need to be deterred. I almost got hit by a car one day.	1	8/4/2023	https://www.google.com/maps/place/51.51636388 9653306%2C-0.3307959337913191/@51.516363889653306,-0.3307959337913191,17	191 Drayton Bridge Rd, London,	Drayton Green	North Hanwell / Pitshanger	Agreed - improvements recommended for this key east - west connection	1		
0962	Requires improvement on church road with Wands for cycists to seperate from traffic, no parking should be on church road its ridiculous.	1	8/4/2023	https://www.google.com/maps/place/51.51116064 370206%2C-0.3352197568939186/@51.51116064370206,-0.3352197568939186,17	7-15 Church Rd, London, W7 1LB	Hanwell	North Hanwell / Hanwell Broadway	Agreed - church road lack of north - south infrastructure - parking should be reviewed.	1		
0963	Drayton Bridge road is busy, deters me from wanting to cycle.	1	8/4/2023	https://www.google.com/maps/place/51.51655180 227404%2C-0.3307036635884808/@51.51655180227404,-0.3307036635884808,17	120 Drayton Bridge Rd, London, W7 1EP	Drayton Green	North Hanwell / Pitshanger	Agreed - improvements recommended for this key east - west connection	1		
0964	Cycle lanes constantly taken over by parking cars	1	8/4/2023	https://www.google.com/maps/place/51.51538841 36071%2C-0.3137049687365989/@51.5153884136071,-0.3137049687365989,17	1 St Leonard's Rd, London, W13 8PN	Ealing Broadway	Ealing Broadway	Location unclear - no cycle infrastructure at pin	0		
0965	Another one where cars park freely on cycle lanes with no repercussion	1	8/4/2023	https://www.google.com/maps/place/51.50855002 901481%2C-0.2575075551012529/@51.50855002901481,-0.2575075551012529,17	Acton Park Childrens Centre, E Acton Ln, London, W3 7LJ	Acton Park	East Acton	Also location unclear - no cycle infrastructure at pin (likely to be Uxbridge Road in East Acton)	0		
0966	Uxbridge Road, cars parked on cycle lanes with no repercussion	1	8/4/2023	https://www.google.com/maps/place/51.51189132 14867%2C-0.3134690697666809/@51.5118913214867,-0.3134690697666809,17	68 Uxbridge Rd, London, W13 8RA	Ealing Broadway	Walpole / Ealing Broadway	Agreed - and parking isn't needed in this location	1		
0967			8/4/2023	https://www.google.com/maps/place/51.51108571 3995236%2C-0.3007873736275646/@51.511085713995236,-0.3007873736275646,17							
0968			8/4/2023	https://www.google.com/maps/place/51.50615722 0531186%2C-0.3026722583941921/@51.506157220531186,-0.3026722583941921,17							
0969			8/4/2023	https://www.google.com/maps/place/51.49552972 3291014%2C-0.30176395115762755/@51.495529723291014,-0.30176395115762755,1							
0970	Lots of parked cars on cycle paths make this road very unattractive to cycle on. Where's the enforcement? Would be great if cycle paths are kept clear as it means better and safer access to the high street.	1	8/4/2023	https://www.google.com/maps/place/51.51111750 705788%2C-0.318221743390914/@51.51111750705788,-0.318221743390914,17z	140-144 Uxbridge Rd, London, W13 8SB	West Ealing	Hanwell Broadway / Walpole	Uxbridge Road west ealing hotspot parking in cycle lane	1		
0971	Difficult to signal intent when turning right into Montpelier Ave as the cycle route goes into a zebra crossing	1	8/4/2023	https://www.google.com/maps/place/51.52032887 947408%2C-0.31107058513249797/@51.52032887947408,-0.31107058513249797,1	74 Castlebar Rd, London, W5 2DD	Montpelier	Ealing Broadway	Noted and added to suggestions	1		Awkward to signal intent
0972	Ealing Broadway cycle parking is amazing but difficult to get to as it's surrounded by very busy roads with limited cycling infrastructure	1	8/4/2023	https://www.google.com/maps/place/51.51503038 8027256%2C-0.30279218971612565/@51.515030388027256,-0.30279218971612565,1	9-10, Central Buildings, The Broadway, London, W5	Ealing Broadway	Ealing Broadway	Ealing Broadway cycle parking hotspot	1		
0973	Difficult junction to cycle in, especially when turning and having to cross the flow of traffic	1	8/4/2023	https://www.google.com/maps/place/51.51702897 7708264%2C-0.2913704239974835/@51.517028977708264,-0.2913704239974835,17	85 Madeley Rd, London, W5 2LT	Hanger Hill	Hanger Hill	Madeley A406 hotspot junction - lack of infrastructure	1		
0974	Awkward cycle lane as cyclists have to turn into the crossing to reach the station	1	8/4/2023	https://www.google.com/maps/place/51.51518959 189297%2C-0.3046429283562069/@51.51518959189297,-0.3046429283562069,17	5 Haven Grn, London, W5 2UU	Ealing Broadway	Ealing Broadway	Agreed - Gordon Road / Haven Green priority issue junction	1	1	
0975	The part of Boston Manor road in Hounslow (I think?) is wonderful with a separated cycle lane. North of this it goes into the road with the usual contention with parked cars, and it's a busy road so this can feel quite pushed!	1	8/4/2023	https://www.google.com/maps/place/51.49715390 429426%2C-0.3261260876343508/@51.49715390429426,-0.3261260876343508,17	21 Boston Gardens, London, W7 2DG	Boston Manor	Northfield / Hanwell Broadway	Boston Road lack of segregation	1		
0976	Uxbridge road here is marked as a cycle lane but I feel like I need to be super cautious along here, it makes me very uncomfortable and I only cycle along here if I can't avoid it	1	8/4/2023	https://www.google.com/maps/place/51.51305268 739961%2C-0.3058981825777729/@51.51305268739961,-0.3058981825777729,17	17-31 New Broadway, London, W5 2XA	Ealing Broadway	Ealing Broadway	Very unfriendly section of Uxbridge Road	1		
0977	The bridge crossing the canal needs replacing, before lockdown during Covid this bridge was the route through the fields which is better than riding along the A40	1	8/4/2023	https://www.google.com/maps/place/51.53841678 601836%2C-0.36575626002279815/@51.53841678601836,-0.36575626002279815,1	7 Old Bridge Cl, Northolt UB5 6UA	Northolt	Greenford Broadway	Unable to verify condition of bridge remotely - bridge between Smiths Farm and Marnham Fields	1		Bridge replacement
0978			8/4/2023	https://www.google.com/maps/place/51.51449444 2730374%2C-0.29955356318585036/@51.514494442730374,-0.29955356318585036,1							
0979			8/4/2023	https://www.google.com/maps/place/51.50915274 302868%2C-0.33869235713116286/@51.50915274302868,-0.33869235713116286,1							
0980			8/4/2023	https://www.google.com/maps/place/51.50851169 697357%2C-0.27140109736553786/@51.50851169697357,-0.27140109736553786,1							
0981			8/4/2023	https://www.google.com/maps/place/51.50701588 776854%2C-0.2456518908225691/@51.50701588776854,-0.2456518908225691,17							
0982			8/4/2023	https://www.google.com/maps/place/51.51193050 5041654%2C-0.36753146845928786/@51.511930505041654,-0.36753146845928786,1							
0983	I saw that there was a proposed route across Drayton Green. Would be good to have a better route from Poets Corner/Browning/Framfield/Homefarm to the existing connections just south of W Ealing stn for access to Ealing Broadway.	1	8/4/2023	https://www.google.com/maps/place/51.51665765 290835%2C-0.3301092882835066/@51.51665765290835,-0.3301092882835066,17	Drayton Bridge Station, London, W13 0JX	Drayton Green	North Hanwell / Pitshanger	Agreed and included in suggestions to improve east - west connection as well as general blue routes in the area	1		
0984	Uxbridge Road junction with Northfields Ave/Drayton Green Rd - just yuk for cyclists east and westbound.	1	8/4/2023	https://www.google.com/maps/place/51.51092892 768662%2C-0.31943409640423415/@51.51092892768662,-0.31943409640423415,1	2 Broadway Ealing, London, W13 0SR	West Ealing	Pitshanger / Ealing Broadway / Walpole / Hanwell Broadway	Agreed - hotspot lido junction	1		
0985	There's a nice cycle entrance at the "wrong end" of Balfour Road that avoids the nightmare of Church Road southbound approaching Cherington Road, but it's not shown on the cycle maps.	1	8/4/2023	https://www.google.com/maps/place/51.51119710 67456%2C-0.33718790604015725/@51.5111971067456,-0.33718790604015725,1	10 York Ave, London, W7 3HT	Hanwell	Hanwell Broadway	Agreed - York Avenue (which is a cycle access only / school street) and Balfour (which has contraflow) should be designated for connection to Boston Manor Road	1		
0986	The eastbound cycle lane past the RBKC cemetery gets pretty scary - there's no way the buses and lorries leave 1.5m. Needs bollards and not just paint. (Lots of parking in the cycle lane too).	1	8/4/2023	https://www.google.com/maps/place/51.50916854 6843064%2C-0.3328513157476731/@51.509168546843064,-0.3328513157476731,17	Clare House, 49 Uxbridge Rd, London, W7 3PX	Hanwell Broadway	Hanwell Broadway	Agreed - no obvious reason why parking is needed or why segregation can't be considered. On suggestion list	1		
0987	Boston Road cycle path (what cycle path?) is not segregated and basically useless	1	8/4/2023	https://www.google.com/maps/place/51.50049801 5407864%2C-0.32800730019098223/@51.500498015407864,-0.32800730019098223,1	210 Boston Rd, London, W7 2AD	Boston Manor	Hanwell Broadway / Northfield	Boston Road segregation	1		
0988	Towpath surface is hopelessly bumpy and dangerous	1	8/4/2023	https://www.google.com/maps/place/51.50172689 5187254%2C-0.3390794590044588/@51.501726895187254,-0.3390794590044588,17	8 Dock Meadow Reach, London, W7 2QN	Boston Manor (Canal)	Hanwell Broadway	Canal path is dirt track through this section	1		
0989	Northfield Avenue desperately needs cycle infrastructure	1	8/4/2023	https://www.google.com/maps/place/51.50351566 9192375%2C-0.3169648834778682/@51.503515669192375,-0.3169648834778682,17	Northfield Court, 101-103 Northfield Ave, London W13 9QR	Northfield	Northfield / Walpole	Clear	1		
0990	This section can barely be described as a cycle path, but is at least on a relatively quiet road	1	8/4/2023	https://www.google.com/maps/place/51.51056745 291999%2C-0.31164338079232135/@51.51056745291999,-0.31164338079232135,1	26 Mattock Ln, London, W5 5BH	Walpole	Walpole	Improve blue routes	1		
0991	Cycling on these roads is terribly stressful due to the large volume of motor traffic driving down these narrow streets	1	8/4/2023	https://www.google.com/maps/place/51.50241617 118605%2C-0.3229895848339881/@51.50241617118605,-0.3229895848339881,17	99 Midhurst Rd, Ealing, London, W13 9UF	Hanwell	Hanwell Broadway / Northfield	Lack of cycle infrastructure in the area and known rat runs	1		
0992	No safe cycle route from Northfields side to West Ealing Station and beyond. It doesn't exist. Bedford Rd filter is blocked by vehicles every single time I've attempted to use it. Cycling around them takes you into the path of oncoming vehicles taking the corner quickly and not expecting to see bikes on that 1 way section. Hill outside station very narrow. If there is already traffic queuing	1	8/4/2023	https://www.google.com/maps/place/51.51408788 0329456%2C-0.3191444150678757/@51.514087880329456,-0.3191444150678757,17	Drayton Court, 2 The Avenue, London, W13 8PH	West Ealing	Pitshanger / Ealing Broadway / Walpole / Hanwell Broadway	Bedford Road filter does appear to be a parking issue and potentially dangerous / West Ealing Station hotspot	1	1	
0993	Seems crazy that these roads are even considered cycle routes. The painted bike lanes offer no protection and majority hidden beneath a long lines of parked cars (risk of dooring added to other dangers) Navigating the roundabout at Church Rd is difficult for and with children (I also know adults who are scared to cycle it) Road surface awful in many places.	1	8/4/2023	https://www.google.com/maps/place/51.51081942 049343%2C-0.32255634952989665/@51.51081942049343,-0.32255634952989665,1	64a The Broadway, London, W13 0SU	West Ealing	Hanwell Broadway / Walpole	Uxbridge Road hot spots.	1		
0994	Have been purposely driven into here. With lots of vehicles cutting through there's a tendency for speeding cars, too much traffic, lack of patience/care shown to cyclists (or pedestrians). Speed bumps nr Park are hindrance to cars but make for a bumpy, uncomfortable cycle. Mini roundabout at sth ealing Rd junction not cycle friendly. Broomfield Rd is narrow and has speeding issues. Not easy to	1	8/4/2023	https://www.google.com/maps/place/51.50576660 663824%2C-0.3095190631148359/@51.50576660663824,-0.3095190631148359,17	Park Sports Lammas Park, Ealing Culmington Rd, Greater, London,	Walpole	Walpole / Ealing Common	Various issues - Culmington Lammas hotspot / South Ealing Mini Roundabout likely to be busy and lacks cycle markings but otherwise appears okay - it could be	1		
0994.1		1			2 S Ealing Rd, London, W5 4QA			Additional location of above	1		
0994.2		1			15 Broomfield Rd, London, W13 9AP			Additional location of above	1		
0995	Entering Grove Rd from Ealing Green, most cyclists would be continuing straight through the modal filter which puts them in the dangerous path of motorists entering and exiting the busy Ealing Broadway multi storey car park. There are no give ways/road markings to protect cyclists or pedestrians here.	1	8/4/2023	https://www.google.com/maps/place/51.51061405 3593834%2C-0.30427121444631444/@51.510614053593834,-0.30427121444631444,1	10 The Grove, London, W5 5LH	Ealing Broadway	Ealing Broadway / Ealing Common	Agreed - this junction should be reviewed.	1	1	
0996	Weymouth is not a safe route. Too many crossroad junctions to stop and give way at but visibility usually hindered by parked cars. At school run times it is particularly bad. Narrow, risk of dooring/close passing.	1	8/4/2023	https://www.google.com/maps/place/51.49885566 0234504%2C-0.3084683636435881/@51.498855660234504,-0.3084683636435881,17	72 Weymouth Ave, London W5 4SB	South Ealing	Northfield	Lacks signage and clear designation - but possibly should have as an alternative to South Ealing Road and the only Piccadilly line crossing. If designated the junctions	1		
0997			8/4/2023	https://www.google.com/maps/place/51.50885106 100906%2C-0.33411621295400984/@51.50885106100906,-0.33411621295400984,1							
0998	always cars parked around here	1	8/4/2023	https://www.google.com/maps/place/51.51084834 323981%2C-0.3199626379997844/@51.51084834323981,-0.3199626379997844,17	10 Broadway, Ealing, London, W13 0SR	West Ealing	Hanwell Broadway / Walpole	West Ealing parking in cycle lane hotspot	1		
0999	nothing has really changed on gordon road apart from some paint to show it is a cycle lane, quite bumpy on this part, lovely junction at the end though	1	8/4/2023	https://www.google.com/maps/place/51.51523265 44115%2C-0.3066056782413673/@51.5152326544115,-0.3066056782413673,17	10 Gordon Rd, London, W5 2AD	Ealing Broadway	Ealing Broadway		1		
1000	many cars parked on the side going towards west ealing	1	8/4/2023	https://www.google.com/maps/place/51.51240204 013049%2C-0.3101253391577852/@51.51240204013049,-0.3101253391577852,17	28-26 Uxbridge Rd, London,	Ealing Broadway	Ealing Broadway	Uxbridge road parking in cycle lane hotspot - parking not needed here	1		
1001	massive puddles on both sides	1	8/4/2023	https://www.google.com/maps/place/51.50929384 4155756%2C-0.33137480632078997/@51.509293844155756,-0.33137480632078997,1	Cherry House, 30 Uxbridge Rd, London, W7 3PP	West Ealing	West Ealing	Highways / street cleaning issue	1		
1002	Eastbound isn't nice to ride. West feels a lot safer.	1	8/4/2023	https://www.google.com/maps/place/51.50692796 1033234%2C-0.26913322278656615/@51.506927961033234,-0.26913322278656615,1	106-112 High St, London, W3 6QX	Acton	South Acton	No obvious reason for the preference other than roundabout segregation at Styne			
1003	Cycle lane disappears, cars pass dangerously	1	9/4/2023	https://www.google.com/maps/place/51.50312869 3503925%2C-0.3317714720087861/@51.503128693503925,-0.3317714720087861,17	The Beeches, 193 Boston Rd, London, W7 2JU	Boston Manor	Hanwell Broadway	No obvious reason why cycle lane on the east side stops for a short stretch North of Elthorne Avenue opposite Townholm Avenue	1		
1004	The entire stretch between Ealing Broadway and the cemeteries is treacherous, road surface is dangerous, no feasible cycle lanes	1	9/4/2023	https://www.google.com/maps/place/51.51217749 482117%2C-0.31213400051309126/@51.51217749482117,-0.31213400051309126,1	Craven House, 40-44 Uxbridge Rd, London, W5 2BS	Ealing Broadway / West Ealing	Hanwell Broadway / Walpole / Ealing Broadway	Uxbridge Road Ealing hot spots	1		
1005	This is not usable in the dark or in bad weather	1	9/4/2023	https://www.google.com/maps/place/51.51576181 522052%2C-0.343173502436267/@51.51576181522052,-0.343173502436267.17z	174 Church Rd, London, W7 3BW	North Hanwell	North Hanwell	High Lane - unable to verify condition of route remotely but additional lighting and maintenance could be considered.	1		

1063			9/4/2023	https://www.google.com/maps/place/51.50679763151787%2C-0.25897541728781226/@51.50679763151787,-0.25897541728781226,1																																										
1064			9/4/2023	https://www.google.com/maps/place/51.50700466493342%2C-0.266884525794413/@51.50700466493342,-0.266884525794413,17z																																										
1065			9/4/2023	https://www.google.com/maps/place/51.50760949435322%2C-0.27168349290854765/@51.50760949435322,-0.27168349290854765,1																																										
1066			9/4/2023	https://www.google.com/maps/place/51.537029517227865%2C-0.35860507685772536/@51.537029517227865,-0.35860507685772536,1																																										
1067			9/4/2023	https://www.google.com/maps/place/51.535321087199385%2C-0.32564609248272536/@51.535321087199385,-0.32564609248272536,1																																										
1068			9/4/2023	https://www.google.com/maps/place/51.531049731576026%2C-0.2985235949241316/@51.531049731576026,-0.2985235949241316,17																																										
1069			9/4/2023	https://www.google.com/maps/place/51.5126783351078%2C-0.3266760607444441/@51.5126783351078,-0.3266760607444441,17																																										
1070			9/4/2023	https://www.google.com/maps/place/51.510541645205926%2C-0.3706213732444441/@51.510541645205926,-0.3706213732444441,17																																										
1071	Appalling orbital connectivity to Hounslow and Richmond for example.	1	9/4/2023	https://www.google.com/maps/place/51.49877491429097%2C-0.30042598860118064/@51.49877491429097,-0.30042598860118064,1	The Pavement, Popes Ln, London, W5 4NG	South Ealing	Ealing Common / Northfield	The most obvious missing link is Popes Lane / Little Ealing Lane.	1			1			1	1										1																			
1072	Council has abandoned cycle route in Windsor to Elderberry and connection to Lionel Road north. This is TfL LCN+ cycle route with vital connectivity of South Ealing to Ealing Broadway.	1	9/4/2023	https://www.google.com/maps/place/51.508445133814014%2C-0.2975077451929775/@51.508445133814014,-0.2975077451929775,17	24 Kenilworth Rd, London, W5 3UH	Ealing Common	Ealing Common / Ealing Broadway	Route is designated but poorly signalled and poor junction at the top with Uxbridge Road	1			1			1	1											1		1																
1073	Void in west/southwest ealing.	1	9/4/2023	https://www.google.com/maps/place/51.50205038618411%2C-0.3231951123126442/@51.50205038618411,-0.3231951123126442,17	1 Woodstock Ave, London W13 9UF	Boston Manor / Northfield	Northfield / Hanwell Broadway / Walpole	Agreed - lack of designated routes	1			1			1	1										1																			
1074	Popes Lane traffic management is very poor. This has been forgotten despite previous speed Management proposals. Poor cross boundary working with Hounslow.	1	9/4/2023	https://www.google.com/maps/place/51.502023671948294%2C-0.29097603039690556/@51.502023671948294,-0.29097603039690556,1	192 Popes Ln, London, W5 4NJ	Gunnersbury Park	Northfield / Ealing Common	Agreed - lack of cycle infrastructure on Popes Lane	1			1	1		1	1										1																			
1075	What are you supposed to do at this roundabout to join from Madeley Road to the cycle lane across the green? Run the gauntlet on the roundabout with all the cars, buses and delivery scooters?	1	9/4/2023	https://www.google.com/maps/place/51.51595065418686%2C-0.30151781586913673/@51.51595065418686,-0.30151781586913673,1	2A Madeley Rd, London, W5 2LH	Ealing Broadway	Ealing Broadway	Agreed - part of the general lack of cycle infrastructure around Haven Green / Ealing Broadway. Designated but nothing to support cyclists apart from a few Roundalls	1			1	1		1	1										1																			
1076	Road surface terrible as usual.	1	9/4/2023	https://www.google.com/maps/place/51.51514409876512%2C-0.3086392885312317/@51.51514409876512,-0.3086392885312317,17	32B Gordon Rd, London, W5 2AH	Ealing Broadway	Ealing Broadway	Road condition does appear poor in some sections - mainly related to utilities	1			1			1								1																						
1077	Road surface terrible	1	9/4/2023	https://www.google.com/maps/place/51.51303209598339%2C-0.3199965263403781/@51.51303209598339,-0.3199965263403781,17	36 Drayton Green Rd, London, W13 8RY	West Ealing	Hanwell Broadway	Nothing obvious via Google	1			1			1								1																						
1078	Very dangerous junction and terrible road surface for remainder of Gordon Road with added speed bumps which make it hard to turn right off the main road and then cut left down Arlington Road.	1	9/4/2023	https://www.google.com/maps/place/51.51472596347457%2C-0.31416277103434975/@51.51472596347457,-0.31416277103434975,1	99 Gordon Rd, London, W13 8PR	West Ealing	Ealing Broadway	As a key link this junction should be improved	1			1			1	1										1			1																
1079	I don't cycle and didn't know that any these routes were cycle routes. There is no demand for cycling in the borough.	1	9/4/2023	https://www.google.com/maps/place/51.50959822436016%2C-0.28891408863169543/@51.50959822436016,-0.28891408863169543,1	12C Leopold Rd, London, W5 3PB	Ealing Common	Ealing Common	Thousands of responses would suggest there is demand. Lack of clear designation on blue routes	1			1			1												1		1																
1080	Poor quality roads. No cycle lanes	1	9/4/2023	https://www.google.com/maps/place/51.52118542292434%2C-0.33058293083208845/@51.52118542292434,-0.33058293083208845,1	524 Copley Cl, London, W7 1QP	Castle Bar Park	North Hanwell / Pitshanger	Agreed - lack of cycle infrastructure in the area. Copley Close could be designated and linked to Drayton Bridge Road via Whitstone Ave for example	1			1			1	1										1																			
1081	Cycle lanes not connected.	1	9/4/2023	https://www.google.com/maps/place/51.51539063709418%2C-0.3170623485121915/@51.51539063709418,-0.3170623485121915,17	112 Gordon Rd, London, W13 8PJ	West Ealing	Ealing Broadway	Agreed - Gordon Road designation should continue to The Avenue for journeys towards West Ealing station or West towards Drayton Green	1			1			1	1										1			1																
1082	No defined or separate cycle lane. Space is shared with cars which is scary and risky.	1	9/4/2023	https://www.google.com/maps/place/51.511173317858436%2C-0.31812625841550757/@51.511173317858436,-0.31812625841550757,1	13 Hartington Rd, London, W13 8QL	West Ealing	Walpole / Ealing Broadway	West Ealing Uxbridge Road hotspot - lack of segregation	1			1	1		1	1		1								1		1																	
1083	Junction of Drayton bridge road feels unsafe, traffic needs to slow down and cycling lane needs to be extended.	1	9/4/2023	https://www.google.com/maps/place/51.51620365435203%2C-0.3313109179221785/@51.51620365435203,-0.3313109179221785,17	11 Browning Ave, London W7 1EW	Drayton Green	North Hanwell / Pitshanger	Busy roundabout including busses and bend on the road heading towards Drayton Green station - lack of cycle infrastructure to navigate this area	1			1			1	1										1																	1			
1084	Cycle lane should be extended along church road, deters me from wanting to cycle as its busy and not segregated from the traffic. there is lots of parking on church road which is unnecessary and could be moved to side streets.	1	9/4/2023	https://www.google.com/maps/place/51.51216654490626%2C-0.33679809046615716/@51.51216654490626,-0.33679809046615716,1	5 Greenford Ave, London W7 1LD	Hanwell	North Hanwell / Hanwell Broadway	Agreed - church road lack of north - south infrastructure - parking should be reviewed.	1			1	1		1	1										1		1															1				
1085	Add segregated cycling all along bridge road, wands or raised kerbs.	1	9/4/2023	https://www.google.com/maps/place/51.50885459563379%2C-0.33589686823715326/@51.50885459563379,-0.33589686823715326,1	58-88 Uxbridge Rd, London,	West Ealing	Hanwell Broadway / Walpole	Uxbridge Road hotspot - increase segregation	1			1	1		1	1		1										1																	
1086	Traffic goes too fast as cut through from Argyle Rd to Castlebar Hill	1	10/4/2023	https://www.google.com/maps/place/51.51976466246118%2C-0.32019431596667536/@51.51976466246118,-0.32019431596667536,1	2 St Stephen's Ave, London W13 8ES	Pitshanger / St Stevens	Ealing Broadway	Hopefully planned improvements will help	1			1			1	1																			1										1			
1087	New crossing arrangement is terrifying for cyclists, pedestrians and car drivers- terrible as most cyclists come up St Leonard's Rd and don't use the cycle/ paedestrian crossings; cars accelerate south to get over Gordon Rd and then meet a paedestrian crossing and end up with their back sticking out on Gordon rd; no adequate cycle provisions from the Uxbridge Rd along St Leonard's rd ti get to this	1	10/4/2023	https://www.google.com/maps/place/51.51487153577363%2C-0.3145812864555486/@51.51487153577363,-0.3145812864555486,17	86 Gordon Rd, London, W13 8PT	Ealing Broadway	Ealing Broadway	Junction is understandably difficult for all road users. Key link in routes	1			1			1	1						1							1																
1088	Narrow rd with no provision for cyclists as cars use this as a cut through route	1	10/4/2023	https://www.google.com/maps/place/51.50142272164641%2C-0.3101545118239679/@51.50142272164641,-0.3101545118239679,17	11 Weymouth Ave, London W5 4SA	South Ealing	Northfield	Weymouth Ave - lack of cycle infrastructure and known rat run	1			1			1	1										1											1										
1089	Lack of designated cycle paths between Boston Manor Rd and Northfields Av on the south section. Since Swyncombe Av was closed the traffic levels travelling at speed through these streets coupled with the narrower nature of them, makes this section very hazardous fir cycling. Please instigate some sort of LTN or one way system or increase speed tables. Crossing Midhurst rd is	1	10/4/2023	https://www.google.com/maps/place/51.50095098905207%2C-0.3291584136618453/@51.50095098905207,-0.3291584136618453,17	11 Weymouth Ave, London W5 4SA	Boston Manor / Northfield	Northfield / Walpole	Agreed - but politically challenging lack of designated routes particularly in the southern section	1		1	1			1	1										1									1					1				1			
1090			10/4/2023	https://www.google.com/maps/place/51.5079722619592%2C-0.3378163312603588/@51.5079722619592,-0.3378163312603588,17																																										
1091			10/4/2023	https://www.google.com/maps/place/51.51041934206988%2C-0.3231355448447859/@51.51041934206988,-0.3231355448447859,17																																										
1092			10/4/2023	https://www.google.com/maps/place/51.51116719694281%2C-0.31841485697857497/@51.51116719694281,-0.31841485697857497,1																																										
1093			10/4/2023	https://www.google.com/maps/place/51.509778313836364%2C-0.32714194451804346/@51.509778313836364,-0.32714194451804346,1																																										
1094			10/4/2023	https://www.google.com/maps/place/51.5087900443051%2C-0.3357250133656997/@51.5087900443051,-0.3357250133656997,17																																										
1095			10/4/2023	https://www.google.com/maps/place/51.508763334020244%2C-0.3387720028066177/@51.508763334020244,-0.3387720028066177,17																																										
1096			10/4/2023	https://www.google.com/maps/place/51.508301731704286%2C-0.3401991286645667/@51.508301731704286,-0.3401991286645667,17																																										
1097			10/4/2023	https://www.google.com/maps/place/51.49784276733354%2C-0.3355286693334869/@51.49784276733354,-0.3355286693334869,17																																										
1098			10/4/2023	https://www.google.com/maps/place/51.51202514404899%2C-0.3159855029883407/@51.51202514404899,-0.3159855029883407,17																																										
1099			10/4/2023	https://www.google.com/maps/place/51.51356912103236%2C-0.3021027040623947/@51.51356912103236,-0.3021027040623947,17																																										
1100			10/4/2023	https://www.google.com/maps/place/51.50503063943239%2C-0.28937282441933165/@51.50503063943239,-0.28937282441933165,1																																										
1101			10/4/2023	https://www.google.com/maps/place/51.5149515601949%2C-0.3473181184426033/@51.5149515601949,-0.3473181184426033,17																																										
1102			10/4/2023	https://www.google.com/maps/place/51.519758506169616%2C-0.32637543045432205/@51.519758506169616,-0.32637543045432205,1																																										
1103			10/4/2023	https://www.google.com/maps/place/51.51776595664789%2C-0.33328313093358153/@51.51776595664789,-0.33328313093358153,1																																										
1104			10/4/2023	https://www.google.com/maps/place/51.51012295112651%2C-0.319145857668095/@51.51012295112651,-0.319145857668095,17z																																										
1105			10/4/2023	https://www.google.com/maps/place/51.50877410163209%2C-0.3219353550435833/@51.50877410163209,-0.3219353550435833,17																																										
1106			10/4/2023	https://www.google.com/maps/place/51.50964217766916%2C-0.3226434582235149/@51.50964217766916,-0.3226434582235149,17																																										
1107			10/4/2023	https://www.google.com/maps/place/51.506732652162185%2C-0.31089047592612884/@51.506732652162185,-0.31089047592612884,1																																										
1108			10/4/2023	https://www.google.com/maps/place/51.498909891341455%2C-0.30339133996348133/@51.498909891341455,-0.30339133996348133,1																																										
1109			10/4/2023	https://www.google.com/maps/place/51.50976707036778%2C-0.3268906374656355/@51.50976707036778,-0.3268906374656355,17																																										
1110			10/4/2023	https://www.google.com/maps/place/51.51142304193376%2C-0.31882255274883864/@51.51142304193376,-0.31882255274883864,1																																										
1111			10/4/2023	https://www.google.com/maps/place/51.51347828626077%2C-0.3046666678131471/@51.51347828626077,-0.3046666678131471,17																																										
1112			10/4/2023	https://www.google.com/maps/place/51.50898826967572%2C-0.3368826675454373/@51.50898826967572,-0.3368826675454373,17																																										
1113			10/4/2023	https://www.google.com/maps/place/51.51026954233091%2C-0.28751763116623197/@51.51026954233091,-0.28751763116623197,1																																										
1114			10/4/2023	https://www.google.com/maps/place/51.50353171205255%2C-0.308936545879408/@51.50353171205255,-0.308936545879408,17z																																										
1115			10/4/2023	https://www.google.com/maps/place/51.500486287295956%2C-0.30953736069874394/@51.500486287295956,-0.30953736069874394,1																																										
1116			10/4/2023	https://www.google.com/maps/place/51.506790625389826%2C-0.31039566758350956/@51.506790625389826,-0.31039566758350956,1																																										
1117			10/4/2023	https://www.google.com/maps/place/51.51101083890257%2C-0.3108248210258924/@51.51101083890257,-0.3108248210258924,17																																										
1118			10/4/2023	https://www.google.com/maps/place/51.504600233910324%2C-0.30515999558643925/@51.504600233910324,-0.30515999558643925,1																																										
1119	Cycling in this park is not practical in darkness, making it only viable in summer	1	10/4/2023	https://www.google.com/maps/place/51.52152083595257%2C-0.351267887970248/@51.52152083595257,-0.351267887970248,17z	Greenford Island, London,, Greenford W7 3RT	Brent Valley Park	Dormers Wells / North Hanwell	Unable to entirely verify but seemingly lack of / poor lighting on connection between Greenford ROad and c87 - improvement may be helpful as an alternative to	1		1												1																						

1120	Cycling on pavement route here put you in conflict with pedestrians and is not a continuous route	1	10/4/2023	https://www.google.com/maps/place/51.52856983292706%2C-0.34817798318509174/@51.52856983292706,-0.34817798318509174,1	48 Costons Ln, Greenford UB6 8RP	Greenford	Greenford Broadway / Central Greenford / North Hanwell	Location not entirely clear - could be Coston Road which is not shared path therefore more likely to be Ruislip Road shared path ending at Greenford				1			1	1										1		1																			
1121	Wherever way I try to cross the A40 it is a deeply unpleasant environment, filled with blind corners, lack of continuous cycle routes or routes which are in conflict with pedestrians	1	10/4/2023	https://www.google.com/maps/place/51.53780663885624%2C-0.34886462869290424/@51.53780663885624,-0.34886462869290424,1	250 Oldfield Ln N, Greenford UB6 8PR	Greenford	Central Greenford	This particular connection is a subway. Difficult to see what else could be provided at this location as a bridge would likely have similar concerns	1		1					1																															
1122	There's no segregated way to cross from Boston Manor Road towards Greenford. It feels unsafe. Segregated cycle routes are only as good as their weakest points. Hanwell town centre is the weakest point	1	10/4/2023	https://www.google.com/maps/place/51.50909491364652%2C-0.3399901594197585/@51.50909491364652,-0.3399901594197585,17	192 Uxbridge Rd, London, W7 3TB	Hanwell	Hanwell Broadway	Lack of segregated crossing in Hanwell town centre	1			1	1		1	1		1								1					1																	
1123	I work at Brompton and unsurprisingly cycle to work. The stretch of road immediately in front of our plant is some of the least cycle friendly road in all of London,	1	10/4/2023	https://www.google.com/maps/place/51.54412606749087%2C-0.34534598308424425/@51.54412606749087,-0.34534598308424425,1	1 Ockham Dr, Greenford UB6 0FD	Greenford	Central Greenford	C87 but total lack of clear infrastructure or clear designation	1		1	1			1	1										1																					
1124			10/4/2023	https://www.google.com/maps/place/51.51641730129512%2C-0.31671970088116286/@51.51641730129512,-0.31671970088116286,1																																											
1125	The cycle lane along Uxbridge Road doesn't protect cyclists. Drivers take no notice when a bike painted on the road is the only indication of a cycle lane.	1	10/4/2023	https://www.google.com/maps/place/51.50900954493848%2C-0.33903516388108956/@51.50900954493848,-0.33903516388108956,1	167B Uxbridge Rd, London, W7 3TH	Hanwell	Hanwell Broadway	Uxbridge Road hotspot - lack of segregation	1			1	1		1	1		1										1																		
1126	The image of a bike painted on the road is not sufficient to identify a cycle lane.	1	10/4/2023	https://www.google.com/maps/place/51.50657162247445%2C-0.32693410060298467/@51.50657162247445,-0.32693410060298467,1	125 Oaklands Rd, London, W7 2DT	Hanwell	Hanwell Broadway / Walpole	Blue route indication	1			1			1												1		1																		
1127	This is a really dangerous junction for cyclists. There should be a physical barrier to protect cyclists from vehicles.	1	10/4/2023	https://www.google.com/maps/place/51.51111647494909%2C-0.31869198929319165/@51.51111647494909,-0.31869198929319165,1	150 Uxbridge Rd, London, W13 8SB	West Ealing	Hanwell Broadway / Walpole	Deans Garden / Lido junction hotspot	1			1	1			1		1								1		1			1																	
1128	This is a busy road where a barrier of some sort is needed to protect cyclists from vehicles.	1	10/4/2023	https://www.google.com/maps/place/51.50028729097958%2C-0.30426241420627775/@51.50028729097958,-0.30426241420627775,1	26a Olive Rd, London, W5 4JH	South Ealing	Northfield	Could be Olive Road c86 which is a known rat run or could be South Ealing / Popes Lane. Either way lack of segregation	1			1			1	1												1																			
1129	Again, a physical barrier is needed to designate safe cycling lanes.	1	10/4/2023	https://www.google.com/maps/place/51.50795595778209%2C-0.31312883360433696/@51.50795595778209,-0.31312883360433696,1	30 Churchfield Rd, London, W13 9NH	Walpole	Walpole	Culmington / Lammas hotspot junction / routes	1			1	1		1	1										1		1	1																		
1130			10/4/2023	https://www.google.com/maps/place/51.511599004277706%2C-0.29233722949132623/@51.511599004277706,-0.29233722949132623,1																																											
1131			10/4/2023	https://www.google.com/maps/place/51.5149371276665%2C-0.30254287980501005/@51.5149371276665,-0.30254287980501005,1																																											
1132			10/4/2023	https://www.google.com/maps/place/51.510962293803495%2C-0.3195790883440086/@51.510962293803495,-0.3195790883440086,17																																											
1133			10/4/2023	https://www.google.com/maps/place/51.50881216828433%2C-0.33456864543185194/@51.50881216828433,-0.33456864543185194,1																																											
1134			10/4/2023	https://www.google.com/maps/place/51.531803620146846%2C-0.3492709894858992/@51.531803620146846,-0.3492709894858992,17																																											
1135			10/4/2023	https://www.google.com/maps/place/51.50841366616689%2C-0.2914838423148214/@51.50841366616689,-0.2914838423148214,17																																											
1136			10/4/2023	https://www.google.com/maps/place/51.51677328490309%2C-0.30783458846960654/@51.51677328490309,-0.30783458846960654,1																																											
1137			10/4/2023	https://www.google.com/maps/place/51.50699798779679%2C-0.277235948027712/@51.50699798779679,-0.277235948027712,17z																																											
1138			10/4/2023	https://www.google.com/maps/place/51.51971080579203%2C-0.26479049819861045/@51.51971080579203,-0.26479049819861045,1																																											
1139			10/4/2023	https://www.google.com/maps/place/51.514743614345306%2C-0.2695111860648214/@51.514743614345306,-0.2695111860648214,17																																											
1140	Film units here are often bullying, wanting us to divert onto pavement and not use the road section. Cyclists often wish to cross to another section at junction with NCRoad in order to hook up with creffield road route. Means crossing over with pedestrians. Not thought through.	1	10/4/2023	https://www.google.com/maps/place/51.51004209696648%2C-0.29220757759552685/@51.51004209696648,-0.29220757759552685,1	Warwick Rd, London, W5 3NH	Ealing Common	Ealing Common	No clear action and generally disagree with the comments. The crossing is segregated from pedestrians and no need to use routes other than Leopold to connect to																																							
1141	Very busy junction, narrowed by parked vehicles. Drivers delivering kids to school drive aggressively here.	1	10/4/2023	https://www.google.com/maps/place/51.51201127609758%2C-0.29082028476081767/@51.51201127609758,-0.29082028476081767,1	1A Creffield Rd, London, W5 3HP	Ealing Common	Ealing Common	Alongside the hotspot junction of A406 / Uxbridge but additionally this Hanger Lane spur is a rat run and cyclists are likely to use this junction if joining Uxbridge			1		1		1	1		1								1			1		1				1												
1142	Excellent facility, but watch out for tired pedestrians wanting to walk on the cycling section. Often have to give way along here.	1	10/4/2023	https://www.google.com/maps/place/51.51611368672275%2C-0.2593275600449063/@51.51611368672275,-0.2593275600449063,17	129 Western Ave, London W3 6RN	East Acton	East Acton	No clear action																																							
1143	Needs a safer cycle crossing from Haslemere to Southdown Ave	1	10/4/2023	https://www.google.com/maps/place/51.4984699411398%2C-0.3271695212097536/@51.4984699411398,-0.3271695212097536,17	311A Boston Rd, London, W7 2AT	Boston Manor	Northfield	There is a zebra crossing at this junction but it could be better designated as a cycle crossing too with potential improvement to the start of Haslemere	1			1			1					1							1																			
1144	CArs speed on Haslemere and don't leave enough space when passing cyclists	1	10/4/2023	https://www.google.com/maps/place/51.499112798220025%2C-0.3252544239731203/@51.499112798220025,-0.3252544239731203,17	72-80 Haslemere Ave, London W13 9UL	Boston Manor	Northfield	Known rat run (potentially worse since swyncombe avenue closure)				1																							1												
1145	The cycle lane through Hanwell village is almost non-existent and ignored by parking cars/trucks/deliveries. Paint has faded almost completely and is disregarded by most motorists. The same applies on both sides of the road going in both directions all the way towards Ealing Broadway and Southall.	1	10/4/2023	https://www.google.com/maps/place/51.50879806809266%2C-0.33562391001812575/@51.50879806809266,-0.33562391001812575,1	58-88 Uxbridge Rd, London,	Hanwell	Hanwell Broadway	Agreed Hanwell Uxbridge Road hotspot - poor cycle lanes and cycle lane parking	1			1	1		1	1		1									1			1					1												
1146	Bike lane has be neglected, paint faded and especially around Hanwell square. Much the case towards Boston manor station. This route should be an encouraged cycle route for those commuting towards Boston Manor station.	1	10/4/2023	https://www.google.com/maps/place/51.50767622284394%2C-0.33764093119732497/@51.50767622284394,-0.33764093119732497,1	16 Boston Rd, London, W7 3TR	Hanwell	Hanwell Broadway	Agreed Boston Road markings are very faded	1	1		1	1		1												1																			
1147	On Station Approach side of station there is oddly only 4 bike locking stations, whereas on the other side there is many. There is plenty of space for more, and this problem will only get worse once developments nearby are complete.	1	10/4/2023	https://www.google.com/maps/place/51.51186964586459%2C-0.3385421534263289/@51.51186964586459,-0.3385421534263289,17	Hanwell Station Forecourt, Station Approach, London, W7	Hanwell	Hanwell Broadway / North Hanwell	Hanwell Station lack of cycle stands on the south side of the station	1			1		1																			1														
1148	There used to be a cycle lane, but it's so faded than cars are not following the lanes and they park on them. That makes it dangerous for cyclists as we need to get around the parked cars into the main car lane. Cycle lanes on most of Uxbridge Road have similar issues, where	1	10/4/2023	https://www.google.com/maps/place/51.50887358613465%2C-0.3369324926299755/@51.50887358613465,-0.3369324926299755,17	135 Uxbridge Rd, London, W7 3ST	Hanwell	Hanwell Broadway	Uxbridge Road hotspot Hanwell - poor cycle lane designation and parking in cycle lanes	1			1	1		1			1									1			1																	
1149	The cycle Lanes on Boston Road are very faded and cars are not following the lanes and sometimes park on them. Also the road is in very bad shape, with a lot of bumps and holes, which means that cyclists need to go around. This is dangerous.	1	10/4/2023	https://www.google.com/maps/place/51.506532271340454%2C-0.33728801490911176/@51.506532271340454,-0.33728801490911176,1	62 Boston Rd, London, W7 3TR	Hanwell	Hanwell Broadway	Boston Road poor surface and faded lines	1	1		1	1		1					1			1				1																			
1150	Lack of clearly signed cycle lanes all the way to Boston Manor, it's dangerous for cyclists.	1	10/4/2023	https://www.google.com/maps/place/51.503136612098196%2C-0.3321764358251067/@51.503136612098196,-0.3321764358251067,17	174-168 Boston Rd, London,	Boston Manor	Hanwell Broadway / Northfield	Boston Road poor infrastructure	1			1	1		1					1							1																			
1151	This route terminates in a residential street. Would be better if cycle route from South Ealing can be extended up to Ealing Broadway	1	11/4/2023	https://www.google.com/maps/place/51.506405692399056%2C-0.30249514542074474/@51.506405692399056,-0.30249514542074474,1	174-168 Boston Rd, London,	South Ealing	Walpole / Ealing Common	Location is a little odd but the fundamental of St Mary's lacking cycle infrastructure through to Ealing Broadway is valid	1			1	1		1	1										1																					
1152			11/4/2023	https://www.google.com/maps/place/51.498972157981115%2C-0.3429089531599816/@51.498972157981115,-0.3429089531599816,17																																											
1153			11/4/2023	https://www.google.com/maps/place/51.51227028949026%2C-0.3116282410715443/@51.51227028949026,-0.3116282410715443,17																																											
1154			11/4/2023	https://www.google.com/maps/place/51.507943349676786%2C-0.32458867503150524/@51.507943349676786,-0.32458867503150524,1																																											
1155			11/4/2023	https://www.google.com/maps/place/51.50464502889872%2C-0.2886196605097724/@51.50464502889872,-0.2886196605097724,17																																											
1156			11/4/2023	https://www.google.com/maps/place/51.51112127218707%2C-0.29197511489347905/@51.51112127218707,-0.29197511489347905,1																																											
1157			11/4/2023	https://www.google.com/maps/place/51.52426592072478%2C-0.2932259744738741/@51.52426592072478,-0.2932259744738741,17																																											
1158			11/4/2023	https://www.google.com/maps/place/51.51736313656063%2C-0.28818342152587606/@51.51736313656063,-0.28818342152587606,1																																											
1159			11/4/2023	https://www.google.com/maps/place/51.515282522802906%2C-0.30231200247919254/@51.515282522802906,-0.30231200247919254,1																																											
1160			11/4/2023	https://www.google.com/maps/place/51.51249284006773%2C-0.30467203685232036/@51.51249284006773,-0.30467203685232036,1																																											
1161	The bollards placed on cycle lanes have made driving hazardous when cars overtake on Acton High Street. Time to stop all this pro cycling at the cost of everything else	1	11/4/2023	https://www.google.com/maps/place/51.50957241007764%2C-0.28324140676175613/@51.50957241007764,-0.28324140676175613,1	358 Uxbridge Rd, London, W3 9SL	Acton	Ealing Common	Remove cycle infrastructure etc	1			1			1	1																										1					
1162	At Hangar Lane the cycle path is unsafe, not clear where cyclists have to go and the end of cycle lane (Eastbound joins the main road where cars and buses take a left turn on to the north circular	1	11/4/2023	https://www.google.com/maps/place/51.51192698837308%2C-0.2932842647266587/@51.51192698837308,-0.2932842647266587,17	38 N Common Rd London, W5 2QB	Ealing Common	Ealing Common	Ultimately this is the hotspot junction of Uxbridge / A406 this eastbound merge is tricky for cyclists and difficult to improve without major works possibly increased cycle lane	1			1	1		1	1		1	1								1				1																	
1163	This route used to be a traffic restricted LTN, but is now busy with cars making it not a safe route for cycling. If Ealing wants this to be a quiet safe cycling route, the LTN traffic restriction should be put back in	1	11/4/2023	https://www.google.com/maps/place/51.5083143068032%2C-0.31326466135138675/@51.5083143068032,-0.31326466135138675,1	24 Culmington Rd, London, W13 9NR	Walpole	Walpole	Culmington / churchfield rat run. Reinstate LTNs will be politically challenging	1			1	1		1	1						1																	1							
1164	The Uxbridge cycle lane is not up to standard. While there are parts with physical separation, the cycle lane often ends unexpectedly, with cyclists then having to dangerously mix with traffic when there are parked cars or a bus stop. The road should have a fully separated cycle lane for its entire length, with car parking bays removed and diversions around bus stops. An example of how this	1	11/4/2023	https://www.google.com/maps/place/51.509528622532585%2C-0.2848415729145781/@51.509528622532585,-0.2848415729145781,17	Sacred Hearts Community, 372 Uxbridge Rd, London,	Ealing Common / Acton	Various	Uxbridge Road fully segregated like C9	1			1	1			1		1								1		1																		
1165	The cycle/walking path on Occupation Lane just ends on South Ealing Road with no way to cross the busy junction for pedestrians and cyclists. This could be addressed by including a pedestrian and cycle crossing at this junction, allowing a cycle route to continue through to the cycle infrastructure on Northfields Ave/Weymouth Ave as well as further on on Boston Manor Park.	1	11/4/2023	https://www.google.com/maps/place/51.49629791532839%2C-0.30578307785368075/@51.49629791532839,-0.30578307785368075,1	199 S Ealing Rd, London, W5 4RH	South Ealing	Northfield	Agreed - but slightly tricky owing to borough boundary if a programme of improvements are made to the are in general then a crossing at this location would provide	1			1				1										1																					
1166	There is currently no safe way to get to Ealing Broadway from South Ealing. South Ealing Road needs protected cycle infrastructure, or we need LTNs to allow safe cycling on back streets.	1	11/4/2023	https://www.google.com/maps/place/51.50908177999982%2C-0.3052057176882439/@51.50908177999982,-0.3052057176882439,17	8 Grange Rd, London, W5 5BX	South Ealing	Northfield / Ealing Common / Walpole	The main missing link is from c86 directly north to Ealing Green. On emerging suggestions	1			1			1	1										1														1							
1167	This cycle lane just ends on Northfields Ave. It should continue up through Northfields Avenue to provide a north/south link to West Ealing and the Elizabeth line station. There is enough space for the same high quality separation for a cycle lane the length of Northfields Ave if parking was removed. This would allow for the planting of more trees and a nicer public realm for the restaurants	1	11/4/2023	https://www.google.com/maps/place/51.49751483611296%2C-0.3106559664065056/@51.49751483611296,-0.3106559664065056,17	12 Little Ealing Ln, London, W5 4EA	Northfield	Northfield / Walpole	Agreed - lack of cycle infrastructure on Northfield which would be much easier to install if car parking was reduced or switched to the east side only providing	1			1			1	1										1		1																			
1168			11/4/2023	https://www.google.com/maps/place/51.510741964141445%2C-0.3206893702232039/@51.510741964141445,-0.3206893702232039,17																																											
1169			11/4/2023	https://www.google.com/maps/place/51.51384119016144%2C-0.3198096056663191/@51.51384119016144,-0.3198096056663191,17																																											
1170			11/4/2023	https://www.google.com/maps/place/51.509647344555376%2C-0.2850484767348149/@51.509647344555376,-0.2850484767348149,17																																											
1171			11/4/2023	https://www.google.com/maps/place/51.49852136527107%2C-0.3059191554833851/@51.49852136527107,-0.3059191554833851,17																																											
1172			11/4/2023	https://www.google.com/maps/place/51.49797367789875%2C-0.32679747045530894/@51.49797367789875,-0.32679747045530894,1																																											
1173	Lots of confusing traffic here.	1	11/4/2023	https://www.google.com/maps/place/51.50891066591494%2C-0.338864018508116/@51.50891066591494,-0.338864018508116,17z	165 Uxbridge Rd, London, W7 3TH	Hanwell	Hanwell Broadway	Clearer markings would be helpful for all users but it is a complicated junction	1			1			1	1											1				1																	
1174	Northbound you end a nice segregated cycle way, into a confusion, and then into a busy road.	1	11/4/2023	https://www.google.com/maps/place/51.49627164687896%2C-0.3252598543845808/@51.49627164687896,-0.3252598543845808,17	Boundary House Business Centre, Boston Rd, London, W7	Boston Manor	Northfield / Hanwell Broadway	Agreed - this infrastructure should be clearer - particularly to account for pedestrians exiting the station and potentially not giving the street their full	1			1	1		1	1				1							1				1																	
1175			11/4/2023	https://www.google.com/maps/place/51.52326786969386%2C-0.3206363220371/@51.52326786969386,-0.3206363220371,17z																																											
1176			11/4/2023	https://www.google.com/maps/place/51.5282125087551%2C-0.3152002869561654/@51.5282125087551,-0.3152002869561654,17																																											

1177			11/4/2023	https://www.google.com/maps/place/51.51526199537481%2C-0.3041417468114216/@51.51526199537481,-0.3041417468114216,17																																												
1178			11/4/2023	https://www.google.com/maps/place/51.5078337042606 9%2C-0.27412511563798647/@51.50783370426069,-0.27412511563798647,1																																												
1179			12/4/2023	https://www.google.com/maps/place/51.54027733696702%2C-0.3670261082480697/@51.54027733696702,-0.3670261082480697,17																																												
1180			12/4/2023	https://www.google.com/maps/place/51.5481569082499 7%2C-0.36756137141214174/@51.54815690824997,-0.36756137141214174,1																																												
1181	This cycle lane says it only applies part of the day, what happens the rest of the time - cars can drive in the cycle lane / don't need to leave space for cyclists?	1	12/4/2023	https://www.google.com/maps/place/51.50967857946505%2C-0.3299279782883091/@51.50967857946505,-0.3299279782883091,17	11 Barchester Cl, Uxbridge Rd, London, W7 3XA	West Ealing	Hanwell Broadway / Walpole	Agreed - no obvious reason why this cycle lane / parking restrictions can't be 24 hours. Residents have off street parking or side roads.	1			1	1		1	1		1									1			1																	
1182	I don't want to cycle on a main road where the cycle lane has to dodge parked cars, buses pulling in and out, I would much prefer to cycle on the back streets, but thereisnt one north of uxbridge road	1	12/4/2023	https://www.google.com/maps/place/51.51131823124568%2C-0.3247022426983759/@51.51131823124568,-0.3247022426983759,17	88a Broadway, London, W13 0SG	West Ealing	Hanwell Broadway / Walpole	Hotspot section in West Ealing - lack of alternative routes and poor infrastructure on Uxbridge itself.	1			1			1	1		1								1				1																	
1183	Why doesn't this cycle lane continue West?	1	12/4/2023	https://www.google.com/maps/place/51.514959013856114%2C-0.3150917030560141/@51.514959013856114,-0.3150917030560141,17	90A Gordon Rd, London, W13 8PT	West Ealing / Ealing Broadway	Ealing Broadway	Agreed - it would be helpful if Gordon Road route also continued west towards West Ealing station and Drayton Green Station	1			1			1	1										1			1																		
1184	I wouldn't cycle along this route with kids	1	12/4/2023	https://www.google.com/maps/place/51.50830154149722 5%2C-0.3425856642171854/@51.508301541497225,-0.3425856642171854,17	343-345 Uxbridge Rd, Hanwell Southall UB1 3ED	Viaduct	Hanwell Broadway / Norwood Green	Improvements have been made to provide some additional segregation but more would be helpful	1			1			1	1						1						1																			
1185			12/4/2023	https://www.google.com/maps/place/51.50922659239317%2C-0.35510349918700834/@51.50922659239317,-0.35510349918700834,1																																												
1186			12/4/2023	https://www.google.com/maps/place/51.51130992640399%2C-0.31776714969970365/@51.51130992640399,-0.31776714969970365,1																																												
1187			12/4/2023	https://www.google.com/maps/place/51.53154761023507%2C-0.349590043099568/@51.53154761023507,-0.349590043099568,17z																																												
1188			12/4/2023	https://www.google.com/maps/place/51.52798897378937%2C-0.3143317621787278/@51.52798897378937,-0.3143317621787278,17																																												
1189			12/4/2023	https://www.google.com/maps/place/51.51157891527446%2C-0.37932695750581447/@51.51157891527446,-0.37932695750581447,1																																												
1190			12/4/2023	https://www.google.com/maps/place/51.501465593235146%2C-0.2890757757267681/@51.501465593235146,-0.2890757757267681,17																																												
1191			12/4/2023	https://www.google.com/maps/place/51.512438686463085%2C-0.3193354710614815/@51.512438686463085,-0.3193354710614815,17																																												
1192	The new route between Southfield Rec and Fishers Lane is crazy. No body would seriously try to follow this route. Much better simply to route this along St Albans Avenue which is the route most people will take in practice. If necessary some cycle priority could be added on St Albans Ave.	1	12/4/2023	https://www.google.com/maps/place/51.49869394587928%2C-0.2610069419761052/@51.49869394587928,-0.2610069419761052,17	94 Rusthall Ave, London W4 1BS	Bedford Park	Southfield	Arguably less likely to encounter rat running traffic on Rusthall than St Albans but additional signage and designation in the whole area would be advisable	1			1			1												1		1																			
1193			12/4/2023	https://www.google.com/maps/place/51.5311978826844%2C-0.3290957655777449/@51.5311978826844,-0.3290957655777449,17																																												
1194			12/4/2023	https://www.google.com/maps/place/51.507550110979075%2C-0.33457248408428786/@51.507550110979075,-0.33457248408428786,1																																												
1195			12/4/2023	https://www.google.com/maps/place/51.51203733865988%2C-0.33800571162335036/@51.51203733865988,-0.33800571162335036,1																																												
1196			12/4/2023	https://www.google.com/maps/place/51.51054164520592 6%2C-0.3204962511741316/@51.510541645205926,-0.3204962511741316,17																																												
1197			12/4/2023	https://www.google.com/maps/place/51.51908780353129%2C-0.3184363146506941/@51.51908780353129,-0.3184363146506941,17																																												
1198			12/4/2023	https://www.google.com/maps/place/51.51225100514468 4%2C-0.3026434679710066/@51.512251005144684,-0.3026434679710066,17																																												
1199	Poorly laid out, with traffic forcing you into the ketb under the iron bridge	1	13/4/2023	https://www.google.com/maps/place/51.50946117672355 5%2C-0.3546489494393068/@51.509461176723555,-0.3546489494393068,17	Iron Bridge, Uxbridge Rd, Southall UB1 3EG	Iron Bridge	Norwood Green / Southall Broadway / Dormers Wells	Iron Bridge hotspot - westbound in particular is difficult (eastbound the path is shared).	1			1	1		1	1		1								1					1				1													
1200	When the cycle lane goes onto the pavement, please mark the cycle lane on the pavement as a shared space with pedestrians. Ther is currently a gap from when the cycle lane transitions from the orad.	1	13/4/2023	https://www.google.com/maps/place/51.5134301239492 7%2C-0.297010358253841 9/@51.51343012394927,-0.297010358253841 9,17	3 N Common Rd London, W5 2QA	Ealing Common	Ealing Common	Agreed - markings needed on pavement. - on emerging suggestions sheet	1	1		1			1			1									1																				
1201	Please create a way to join the cycle route that runs along Crown Street. At present it is dangerous to turn into Crown Street from Uxbridge Road an the cycle lane is entirely separate to any other markings. It is also often blocked by vehicles.	1	13/4/2023	https://www.google.com/maps/place/51.50755408254297 4%2C-0.27199071256292395/@51.507554082542974,-0.27199071256292395,1	Queensland College, 3 The Mount, London, W3 9NW	Acton	South Acton	The connection is the mini roundabout not ideal but difficult to improve without a completely new junction	1			1				1		1								1	1																				
1202	I would cycle along church road if it was safe and speed of traffic was reduced, cars are often speeding. There is ridiculous parking on church road which should be removed and allocated to cyclists and a speed camera introduced. I would only cycle if it was segregated along church road an uxbridge road.	1	13/4/2023	https://www.google.com/maps/place/51.5117568998777 74%2C-0.3359362091584339/@51.511756899877774,-0.3359362091584339,17	78a Church Rd, London, W7 1LB	Hanwell	North Hanwell / Hanwell Broadway	Agreed - church road lack of north - south infrastructure - parking should be reviewed.	1			1	1		1	1										1		1							1	1									1	1				
1203	Drayton Bridge Road is horrible with people speeding and the curve at the road over the bridge with the train station and junction stop sme from cycling. its the main route from west ealing to ealing broadway, please improve it! or I won't be cycling.	1	13/4/2023	https://www.google.com/maps/place/51.5169035639603%2C-0.32944821448178674/@51.5169035639603,-0.32944821448178674,1	195 Drayton Bridge Rd, London, W13 0JH	Drayton Green	North Hanwell / Pitshanger	Agreed - improvements recommended for this key east - west connection	1			1	1		1	1										1								1	1													
1204	Uxbridge road needs fully segregated cycle route, I won't cycle unless this is done. Its far too dangerous and I don't feel safe.	1	13/4/2023	https://www.google.com/maps/place/51.5104403695762 94%2C-0.32348298163266564/@51.510440369576294,-0.32348298163266564,1	72 Broadway, London, W13 0SY	West Ealing	Hanwell Broadway / Walpole	West Ealing Uxbridge Road - lack of segregation	1			1	1			1		1										1																			
1205	This route needs to be connected to Uxbridge road, needs to be segregated, its far to busy.	1	13/4/2023	https://www.google.com/maps/place/51.51399256924614%2C-0.31962060065122033/@51.51399256924614,-0.31962060065122033,1	1 The Avenue, London, W13 8JP	West Ealing	Pitshanger / Ealing Broadway / Walpole / Hanwell Broadway	West Ealing station hotspot. Lack of infrastructure	1			1	1		1	1										1																					
1206	Adding parking near the shops for bikes its silly this is not avaiable!	1	13/4/2023	https://www.google.com/maps/place/51.51337743999737%2C-0.306210847864834/@51.51337743999737,-0.306210847864834,17z	16 New Broadway, London, W5 2XA	Ealing Broadway	Ealing Broadway	There are some Sheffield stands in this area and utilsation on Google maps shows reasonable levels of availability at present but there is seemingly space	1			1			1																		1															
1207			13/4/2023	https://www.google.com/maps/place/51.54523069973019%2C-0.3548082719029888/@51.54523069973019,-0.3548082719029888,17																																												
1208			13/4/2023	https://www.google.com/maps/place/51.546591342201864%2C-0.3881453309999783/@51.546591342201864,-0.3881453309999783,17																																												
1209			13/4/2023	https://www.google.com/maps/place/51.51717068031057%2C-0.3437598086821203/@51.51717068031057,-0.3437598086821203,17																																												
1210			13/4/2023	https://www.google.com/maps/place/51.503004246761556%2C-0.3540761853804453/@51.503004246761556,-0.3540761853804453,17																																												
1211			13/4/2023	https://www.google.com/maps/place/51.50540841353588%2C-0.3547628308882578/@51.50540841353588,-0.3547628308882578,17																																												
1212			13/4/2023	https://www.google.com/maps/place/51.52927016830347%2C-0.3268487145986576/@51.52927016830347,-0.3268487145986576,17																																												
1213			13/4/2023	https://www.google.com/maps/place/51.53260489439347%2C-0.32262892669909116/@51.53260489439347,-0.32262892669909116,1																																												
1214			13/4/2023	https://www.google.com/maps/place/51.511027140204234%2C-0.3193010375643279/@51.511027140204234,-0.3193010375643279,17																																												
1215			13/4/2023	https://www.google.com/maps/place/51.52882518797236 6%2C-0.3558833888755175/@51.528825187972366,-0.3558833888755175,17																																												
1216	Very poor quality cycling. Very dangerous with delivery drivers stopping in the bus lane forcing cyclists into dangerous situations	1	13/4/2023	https://www.google.com/maps/place/51.5128948628484%2C-0.3108400765512753/@51.5128948628484,-0.3108400765512753,17	26-30 Uxbridge Rd, London, W5 2AU	Ealing Broadway	Ealing Broadway / Walpole	hotspot Ealing Broadway - West Ealing. Parking in cycle lane - parking doesn't appear needed owing to off street availability	1			1	1		1	1		1												1																		
1217	Very poor provision	1	13/4/2023	https://www.google.com/maps/place/51.50811177620011%2C-0.27339503497442186/@51.50811177620011,-0.27339503497442186,1	216 High St, London, W3 9NX	Acton	South Acton	Seemingly a general comment some segregated sections mixed with general lack of infrastructure	1			1			1	1		1				1				1	1	1		1																		
1218	Dangerous area as you enter the Ealing Broadway are	1	13/4/2023	https://www.google.com/maps/place/51.51618925789255%2C-0.30052973177553177/@51.51618925789255,-0.30052973177553177,1	16 Haven Ln, London, W5 2HN	Ealing Broadway	Ealing Broadway	Lack of cycle infrastructure at this roundabout / junction particularly joining from the c85 routes to the north	1			1			1	1						1				1																					
1219	Cycle provision is non existent. Goes from well maintained divided area (Hounslow) to nothing	1	13/4/2023	https://www.google.com/maps/place/51.49615571669168%2C-0.3255367416115673/@51.49615571669168,-0.3255367416115673,17	Wyndham Court, Boston Rd, London, W7 2AS	Boston Manor	Northfield / Hanwell Broadway	Boston Road end of cycle segregation hotspot	1			1	1		1	1				1								1																			
1220	Does not link to anything	1	13/4/2023	https://www.google.com/maps/place/51.49771210951783 5%2C-0.3098417116940899/@51.497712109517835,-0.3098417116940899,17	52 Little Ealing Ln, London, W5 4EA	South Ealing	Northfield	Agreed - lack of cycle infrastructure on Northfield or Popes	1			1			1	1										1																					
1221	Going under the roundabout at the white heart is not safe for a female lone cyclist. It is too isolated.	1	13/4/2023	https://www.google.com/maps/place/51.53634882232335%2C-0.39081104413269063/@51.53634882232335,-0.39081104413269063,1	White Hart Roundabout, Northolt	Rectory Park	Northolt West End	General personal safety. Difficult to assess remotely	1			1			1								1																		1							
1222	The target roundabout underpass is dirty and dark and has men lurking there drinking. I don't feel safe going under here.	1	13/4/2023	https://www.google.com/maps/place/51.54294179177253%2C-0.3784728826641848/@51.54294179177253,-0.3784728826641848,17	256 Church Rd, Northolt UB5 5AW	Northolt	Northolt West End / Northolt Mandeville	General personal safety. Difficult to assess remotely	1			1			1								1																		1							
1223	This route to the station is dark and isolated, there are often men standing around drinking. I don't feel safe using this route.	1	13/4/2023	https://www.google.com/maps/place/51.54245524758251%2C-0.37280805722473165/@51.54245524758251,-0.37280805722473165,1	30 Rectory Gardens, Northolt UB5 5DN	Northolt	Northolt Mandeville	General person safety - and not clear on route being referred to but could be Ealing Road	1			1			1																										1							
1224	As far as I know there is nowhere safe to leave my bike during the day if I go into London, on the tube.	1	13/4/2023	https://www.google.com/maps/place/51.54835347374317%2C-0.36868818417785665/@51.54835347374317,-0.36868818417785665,1	Underground Ltd, Northolt Underground Station, London,,	Northolt station	Northolt Mandeville	Plentiful on street cycle parking at the station but no secure facility	1			1				1																	1															
1225	This is really dark in the winter months. I dont feel safe cycling here and so go on the main roads which feels really dangerous.	1	13/4/2023	https://www.google.com/maps/place/51.539866191 9435%2C-0.37830122128723165/@51.5398661919435,-0.37830122128723165,1	Northala Fields, Westway Cl, Northolt UB5 6UR	Northolt	Northolt Mandeville	Personal safety in Northala Fields. Church Road is shared Bus Lane but only 7 - 10am and 4 - 7pm. 24 hour bus lane would significantly improve segregation	1			1			1													1														1							
1226	Priority for cyclists on Northfields Avenue (whole street).	1	13/4/2023	https://www.google.com/maps/place/51.50423799174867%2C-0.3181427288024019/@51.50423799174867,-0.3181427288024019,17	58 Northfield Ave, London W13 9RR	Northfield	Northfield / Walpole	Lack of cycle infrastructure on Northfield Ave	1			1	1		1	1										1																					
1227	Priority lights for cyclists only at traffic lights at junctions on Uxbridge Road (for each direction).	1	13/4/2023	https://www.google.com/maps/place/51.51091459329014 6%2C-0.318187288739602/@51.510914593290146,-0.318187288739602,17z	215 Uxbridge Rd, London, W13 9LD	West Ealing	Hanwell Broadway / Walpole	Deans Garden / Lido hotspot junction	1			1	1		1	1		1								1					1																	
1228	Shared path with pedestrians on Ealing side of Boston Manor station. Could easily have painted cycle lane(s). This is especially a problem around the bus stop, as people get off the bus and don't look.	1	13/4/2023	https://www.google.com/maps/place/51.49598373660422%2C-0.3249720788074928/@51.49598373660422,-0.3249720788074928,17	Boston Manor Station (Stop U), London, W7 2AS	Boston Manor	Northfield	Complete agree. This needs to be unmissably clear and at present it is not	1	1		1	1	1	1					1							1																				
1229	Anywhere there is a gap in the cycle route/lane is dangerous for cyclists, particularly where they are forced back into the traffic. If you want to encourage more cycling, cyclists have to be the priority not cars. So you can't just have cycle lanes where it's convenient. There should be no gaps in the route.	1	13/4/2023	https://www.google.com/maps/place/51.51327360382076 4%2C-0.31932356877206747/@51.513273603820764,-0.31932356877206747,1	42 Hastings Rd, London, W13 8QH	West Ealing	Pitshanger / Ealing Broadway / Hanwell Broadway / Walpole	West Ealing station hotspot lack of cycle infrastructure	1			1	1		1	1										1																					
1230			13/4/2023	https://www.google.com/maps/place/51.53374889256924%2C-0.34936009179702854/@51.53374889256924,-0.34936009179702854,1																																												
1231			13/4/2023	https://www.google.com/maps/place/51.52604048096275 6%2C-0.3529786921491507/@51.526040480962756,-0.3529786921491507,17																																												
1232			13/4/2023	https://www.google.com/maps/place/51.54003245172403%2C-0.3440253065063059/@51.54003245172403,-0.3440253065063059,17																																												
1233			13/4/2023	https://www.google.com/maps/place/51.51713865924434 5%2C-0.34564139047031706/@51.517138659244345,-0.34564139047031706,1																																												

1234			13/4/2023	https://www.google.com/maps/place/51.54565408526025%2C-0.34224276768565653/@51.54565408526025,-0.34224276768565653,1																																												
1235			13/4/2023	https://www.google.com/maps/place/51.505696453322855%2C-0.29064332682849026/@51.505696453322855,-0.29064332682849026,1																																												
1236	Vehicles speed cutting up cycles switching lanes, buses are the worst offenders they use their size and weight to intimidate cycles!!	1	13/4/2023	https://www.google.com/maps/place/51.50884640600566%2C-0.3382938602314445/@51.50884640600566,-0.3382938602314445,17	128A Uxbridge Rd, London, W7 3SL	Hanwell	Hanwell Broadway	Hanwell Town Centre hotspot tricky as lots of vehicles will need to change lane. Logging as lack of cycle infrastructure as difficult to suggest a solution	1			1	1		1	1		1				1				1									1													
1237	This area is very dangerous for cyclists as vehicles chop and change lanes without correct indication, I have been knocked off twice this year 2023. Car drivers break test/check cycles it's so dangerous at this junction for cycling	1	13/4/2023	https://www.google.com/maps/place/51.50875403073379%2C-0.33457532076289986/@51.50875403073379,-0.33457532076289986,1	Adam's Roundabout, London, W7 3FE	Hanwell	Hanwell Broadway	Adams Roundabout generally lacking infrastructure and poor driver behaviour	1			1	1		1	1		1				1				1									1													
1238	Terrible junction for cycling as at night vehicles are double parked all the way along west Ealing, Red route definitely needs to be enforced here! Car drivers open their doors into cyclists,laughing at the cyclist having to swerve into on coming vehicles, extremely dangerous at night 10pm.	1	13/4/2023	https://www.google.com/maps/place/51.50958058962094%2C-0.3283677641207472/@51.50958058962094,-0.3283677641207472,17	160 Broadway, London, W13 0TL	West Ealing / Hanwell	Hanwell Broadway / Walpole	Parking permitted in cycle lanes despite close proximity to the junction - should be reconsidered to keep approach to junction clear	1	1		1	1		1			1				1								1	1				1													
1239	Dangerous junction for cyclists as car drivers do not indicate correctly and do not care about parking restrictions. At night time this junction/area is horrendous for cyclist as drivers double park all along the Uxbridge Road, need red route at this junction. Uxbridge Road should have no parking allowed at all for the safety to cyclists	1	13/4/2023	https://www.google.com/maps/place/51.509614465306505%2C-0.32758195750483/@51.509614465306505,-0.32758195750483,17z	47-43 Uxbridge Rd, London, W7 3QA	West Ealing	Hanwell Broadway / Walpole	Visibility very poor heading westbound towards this junction owing to cycle lane parking. September 2022 on Google Maps is an excellent example owing to delivery	1	1		1	1		1			1				1								1					1													
1240	The parking of vehicles here is outrageous as they have zero consideration for cyclist, ihave been side swiped from vehicle doors opening of parked vehicles,there should be no parking along here as a cyclist view of the junctions is blocked especially by big suv's. This is another accident hotspot for cyclist because vehicles park	1	13/4/2023	https://www.google.com/maps/place/51.51110236639367%2C-0.31832318857414776/@51.51110236639367,-0.31832318857414776,1	207A Uxbridge Rd, London, W13 9AA	West Ealing	140 Uxbridge Rd, London, W13 8QJ	West Ealing hotspot uxbridge road parking in cycle lanes.	1	1		1	1		1			1				1								1					1													
1241	Cycle route needs to be extended along church road, church road is truly awful. Speeding cars which makes it doesn't feel safe and ridiculous parking on the road.	1	13/4/2023	https://www.google.com/maps/place/51.51177025414462%2C-0.33616035182110426/@51.51177025414462,-0.33616035182110426,1	21-27 Church Rd, London, W7 1LD	Hanwell	North Hanwell / Hanwell Broadway	Agreed - church road lack of north - south infrastructure - parking should be reviewed.	1			1	1		1	1										1		1						1	1								1					
1242			13/4/2023	https://www.google.com/maps/place/51.516924708768805%2C-0.32945384900009866/@51.516924708768805,-0.32945384900009866,1																																												
1243	Greenford avenue needs a segregated cycle route and parking should not be allowed on this main road.	1	13/4/2023	https://www.google.com/maps/place/51.51518569804234%2C-0.3374071258113531/@51.51518569804234,-0.3374071258113531,17	89 Greenford Ave, London W7 1HA	North Hanwell	North Hanwell	Greenford Avenue lack of cycle infrastructure	1			1			1	1										1		1																				
1244			14/4/2023	https://www.google.com/maps/place/51.550677689282004%2C-0.33901281150847673/@51.550677689282004,-0.33901281150847673,1																																												
1245			14/4/2023	https://www.google.com/maps/place/51.546438274914074%2C-0.3411708392182877/@51.546438274914074,-0.3411708392182877,17																																												
1246			14/4/2023	https://www.google.com/maps/place/51.5423967390025%2C-0.3395032720241975/@51.5423967390025,-0.3395032720241975,17																																												
1247			14/4/2023	https://www.google.com/maps/place/51.549397353864016%2C-0.34373256198158453/@51.549397353864016,-0.34373256198158453,1																																												
1248			14/4/2023	https://www.google.com/maps/place/51.5488026224822%2C-0.34000360984157485/@51.5488026224822,-0.34000360984157485,1																																												
1249	Uxbridge Road is terrifying to cycle on and needs both new surface and a truly protected route. I would not even call it a cycle route at present.	1	14/4/2023	https://www.google.com/maps/place/51.50870067271701%2C-0.34671720510797144/@51.50870067271701,-0.34671720510797144,1	Ealing Hospital, Uxbridge Rd, Southall UB1 3HW	Ealing Hospital	Norwood Green	Lack of cycle segregation and poor highway (westbound highway appears okay on Google Maps but eastbound has been flagged as a hotspot)	1			1	1		1	1		1					1					1																				
1250	Because these routes are not protected in any way they're terrifying to cycle on. The protected cycle lane that starts at Boston Manor (as soon as you leave Ealing borough) is much better and you should use that as a model please.	1	14/4/2023	https://www.google.com/maps/place/51.505981063362185%2C-0.33523497526242396/@51.505981063362185,-0.33523497526242396,1	84 Boston Rd, London, W7 2ES	Boston Manor	Hanwell Broadway / Northfield	Boston Road lack of segregation	1			1	1		1	1				1								1																				
1251	The canal towpath is not wide enough for cycling safely, and the surface is poor.	1	14/4/2023	https://www.google.com/maps/place/51.50162837886053%2C-0.340268137695956/@51.50162837886053,-0.340268137695956,17z	Unit 75, The Waterside Trading Centre, Trumpers Way,	Boston Manor (Canal)	Hanwell Broadway	Canal path is rough track in this section	1			1	1		1	1					1		1																									
1252	Hanwell High Street has no cycle lanes so I'm surprised it's even marked as a route. I don't feel safe cycling there.	1	14/4/2023	https://www.google.com/maps/place/51.50859783667054%2C-0.33759999861126433/@51.50859783667054,-0.33759999861126433,1	114 Uxbridge Rd, London, W7 3SU	Hanwell	Hanwell Broadway	There are cycle lanes - they just can't be seen as they are so faded and full of parked cars	1			1	1		1	1		1									1			1																		
1253	The route from Southall to Ealing Common should be entirely protected. I fear for my life when cycling through West Ealing in particular because the junctions are impossible to navigate safely on a bike.	1	14/4/2023	https://www.google.com/maps/place/51.510698334854716%2C-0.32238118339074306/@51.510698334854716,-0.32238118339074306,1	54 Broadway, Ealing, London, W13 0SU	Ealing	Various	Uxbridge road lack of segregation in Ealing - west ealing in particular	1			1	1		1	1		1										1			1																	
1254	Old Oak Common is a cycling hell - pot holes, no cycling lanes, speeding cars, too many HGVs, dust and grit on the road surfaces makes cycling lethal, traffic fumes from hs2 and other construction vehicles, no cycle rental stations, etc. but then Ealing doesn't care about the people who live around Old Oak Common.	1	14/4/2023	https://www.google.com/maps/place/51.52846764510218%2C-0.25339939833578295/@51.52846764510218,-0.25339939833578295,1	14 Victoria Rd, London, W3 6HU	Old Oak Common	North Acton	Agreed - poor infrastructure. The A4000 Victoria / Old Oak Lane is very faded if present at all.	1			1			1	1										1	1																					
1255	dangerous junction.	1	14/4/2023	https://www.google.com/maps/place/51.51143173997369%2C-0.29192178665481405/@51.51143173997369,-0.29192178665481405,1	2-8 Hanger Ln, London, W5 3HN	Ealing Common	Ealing Common	Uxbridge / A406 hotspot junction	1			1	1		1	1		1	1							1					1																	
1256	delivery motor bikes in bus / cycle lane	1	14/4/2023	https://www.google.com/maps/place/51.513501619390915%2C-0.30382006584487753/@51.513501619390915,-0.30382006584487753,1	2-4 Haven Pl, London, W5 2NR	Ealing Broadway	Ealing Broadway	hotspot for exactly this issue	1			1	1	1	1			1												1																		
1257	very dangerous junction for cyclists (and pedestrians)	1	14/4/2023	https://www.google.com/maps/place/51.510907727968714%2C-0.3194001211054798/@51.510907727968714,-0.3194001211054798,17	162 Uxbridge Rd, London, W13 8SB	West Ealing	Hanwell Broadway / Walpole	Deans Gardens / Lido hotspot	1			1	1		1	1		1	1			1				1																						
1258	narrow road and narrow pavement across bridge	1	14/4/2023	https://www.google.com/maps/place/51.514587054439644%2C-0.3044593149165342/@51.514587054439644,-0.3044593149165342,17	12b Spring Bridge Rd, Broadway W5 2AB	Ealing Broadway	Ealing Broadway	Spring Bridge hotspot	1			1	1		1	1										1																						
1259	parking in cycle lanes	1	14/4/2023	https://www.google.com/maps/place/51.51006707413876%2C-0.2868470071278906/@51.51006707413876,-0.2868470071278906,17	Station Parade, Uxbridge Rd, London, W5 3LD	Ealing Common	Ealing Common	Pavement parking in this location but there does also appear to be further parking in the cycle lane	1			1		1	1			1												1				1	1													
1260			14/4/2023	https://www.google.com/maps/place/51.533628193126304%2C-0.33804323918688706/@51.533628193126304,-0.33804323918688706,1																																												
1261			14/4/2023	https://www.google.com/maps/place/51.52952384572419%2C-0.29279004197061864/@51.52952384572419,-0.29279004197061864,1																																												
1262			14/4/2023	https://www.google.com/maps/place/51.51107944883663%2C-0.3740379723507159/@51.51107944883663,-0.3740379723507159,17																																												
1263			15/4/2023	https://www.google.com/maps/place/51.49840015164253%2C-0.2560436426846646/@51.49840015164253,-0.2560436426846646,17																																												
1264			15/4/2023	https://www.google.com/maps/place/51.52537569604636%2C-0.2705490290372037/@51.52537569604636,-0.2705490290372037,17																																												
1265			15/4/2023	https://www.google.com/maps/place/51.50629114256326%2C-0.2572561373902027/@51.50629114256326,-0.2572561373902027,17																																												
1266	The cycle ways on the Uxbridge road seem like joke: there are random pieces of cycle lanes and the whole road seems extremely unsafe for cyclists. Nothing serious seems to be done to give priority to cyclists (and pedestrians) and allow access to shops in a sustainable way.	1	15/4/2023	https://www.google.com/maps/place/51.51410027966534%2C-0.2993512997280279/@51.51410027966534,-0.2993512997280279,17	Carmelita House, 21-22 The Mall London, W5 2PJ	Ealing	Various	Uxbridge Road in general	1			1	1			1		1								1																						
1267	Doesn't seem particularly safe with cars driving fast with no consideration for cyclists	1	15/4/2023	https://www.google.com/maps/place/51.50067660052295%2C-0.29689136599337695/@51.50067660052295,-0.29689136599337695,1	175 Popes Ln, London, W5 4ND	Gunnersbury Park	Ealing Common	Popes Lane lacks cycle infrastructure	1			1			1	1										1									1													
1268	I used to cycle on this road everyday to work. Cars drove very fast and it seemed extremely dangerous.	1	15/4/2023	https://www.google.com/maps/place/51.49867119389113%2C-0.2748179930563466/@51.49867119389113,-0.2748179930563466,17	111 Bollo Ln, London, W3 8HW	South Acton / Southfield	South Acton / Southfield	Bollo Lane - lacks cycle infrastructure	1			1	1		1	1						1				1									1													
1269	No dedicated safe cycle lanes	1	15/4/2023	https://www.google.com/maps/place/51.51318633486789%2C-0.30932230209453904/@51.51318633486789,-0.30932230209453904,1	Perceval House, 14-16 Uxbridge Rd, London, W5 2SR	Ealing Broadway	Ealing Broadway / Walpole	Uxbridge Road Ealing hotels section - parking doesn't appear required.	1			1	1		1	1		1										1																				
1270	No safe dedicated cycle lanes	1	15/4/2023	https://www.google.com/maps/place/51.50818635850592%2C-0.31271713621627617/@51.50818635850592,-0.31271713621627617,1	23A Culmington Rd, London, W13 9NJ	Walpole	Walpole	hotspot section alongside Walpole / Lammas parks. Known rat run and key cycle link	1			1	1		1	1										1			1																			
1271	No safe cycle lanes and pitiful secure and minimal parking bays, especially by all the supermarkets	1	15/4/2023	https://www.google.com/maps/place/51.51112517878992%2C-0.31844074762100494/@51.51112517878992,-0.31844074762100494,1	146 Uxbridge Rd, London, W13 8SB	West Ealing	Walpole / Hanwell Broadway	hotspot section around Deens garden	1			1	1		1	1		1												1			1															
1272	Bicycle lane is shoddy (painted lane) and always dirty/full of leaves etc	1	15/4/2023	https://www.google.com/maps/place/51.503927270693836%2C-0.28928205520532657/@51.503927270693836,-0.28928205520532657,1	58 Gunnersbury Ave, London, W5 4HA	Ealing Common	Ealing Common	A406 Gunnersbury Lane; Partly shared path and partly basic cycle lane on highway.	1			1		1		1			1						1			1																				
1273	Carlton road is consistently full of dangerous potholes, especially at night or during dark winter days because of low lighting, potholes which have been there for YEARS	1	15/4/2023	https://www.google.com/maps/place/51.51649491725524%2C-0.3109958598546525/@51.51649491725524,-0.3109958598546525,17	17 Carlton Rd, London, W5 2AW	Montpelier	Ealing Broadway	There appears to be a notably poor section towards the south west of Carlton Road on Google Earth in Sept 2022	1	1		1		1	1								1																									
1274	The section of cycleway through Chiswick High Road is, in parts, dangerous to pedestrians. We have a green man signal to cross the main road but are then confronted with cyclists whizzing past in both directions before reaching the pavement on the other side - why do cyclists also get a Green light at the same time as pedestrians trying to cross the road ? I have seen many older	1	16/4/2023	https://www.google.com/maps/place/51.50787064189883%2C-0.2655646105491316/@51.50787064189883,-0.2655646105491316,17	Acton Park, The Vale, London, W3 7JX	Acton Park / Chiswick	East Acton	Chiswick comments are more in relation to cycle infrastructure alongside pedestrians in general but are also applied to shared paths in parks etc such as Acton	1			1			1																					1						1						
1275	Many cars are parked along the south side of the road here, meaning that cyclists need to pull out into the main traffic. There are a number of shops here so I can understand if there need to be bays for unloading goods, but almost all of the cars I see are private cars not trucks delivering goods. I would suggest a segregated cycle lane with assigned spaces for loading bays.	1	16/4/2023	https://www.google.com/maps/place/51.50679250981296%2C-0.2548357744895613/@51.50679250981296,-0.2548357744895613,17	143 The Vale, London, W3 7RH	East Acton	East Acton	Parking permitted in cycle lanes - suggestions for loading bays is understandable and monitoring of the 'loading only ' throughout Uxbridge	1			1			1			1										1		1																		
1276	Again cars parked on the north side of the road block some of the cycle lane on this route, I'm not sure if parking spaces are necessary/wise here.	1	16/4/2023	https://www.google.com/maps/place/51.5094902861986%2C-0.25998561579815505/@51.5094902861986,-0.25998561579815505,1	183 The Vale, London, W3 7RW	Acton Park	East Acton	Believed to be Uxbridge Road rather than Churchfield Road as there is a section of single yellow lines along the south side of the park. If this is being kept unsegregated	1		1	1		1	1			1												1	1																	
1277	Cycle lane quality is particularly poor around this area with a number of potholes. This means either going very slowly or pulling out into the main traffic, neither of which is ideal.	1	16/4/2023	https://www.google.com/maps/place/51.506819221253224%2C-0.24784057337872145/@51.506819221253224,-0.24784057337872145,1	19 The Vale, London, W3 7SH	East Acton	East Acton	The Eastbound cycle lane appears poor in the first section from Old Oak / Askew Road	1			1		1	1			1					1																									
1278	Proper crossing of A406 needed	1	16/4/2023	https://www.google.com/maps/place/51.51222963968236%2C-0.29198330065316913/@51.51222963968236,-0.29198330065316913,1	12 Gatcombe Mews, Hanger Ln, London, W5 3HF	Ealing Common	Ealing Common	Uxbridge / A406 hotspot junction lack of infrastructure	1			1	1			1		1	1							1																						
1279	Gordon Road needs resurfacing	1	16/4/2023	https://www.google.com/maps/place/51.51538110540586%2C-0.30820530077523944/@51.51538110540586,-0.30820530077523944,1	28 Gordon Rd, London, W5 2AH	Ealing Broadway	Ealing Broadway	Gordon Road does appear poor in general	1			1			1								1																									
1280	New cycle track on south side of A40 is right next to fast traffic. How could TfL build such a substandard facility?	1	16/4/2023	https://www.google.com/maps/place/51.51874598912431%2C-0.26220005175180194/@51.51874598912431,-0.26220005175180194,1	Erne House, Rosebank Way, London, W3 6TY	North Acton	North Acton	It's a busy road, can't change that.																																								
1281	Barriers make this subway impassable to disabled cyclists such as myself	1	16/4/2023	https://www.google.com/maps/place/51.52376614712206%2C-0.26580494066781757/@51.52376614712206,-0.26580494066781757,1	312 Western Ave, London W3 0PH	North Acton	North Acton	Unsuitable for recumbent / cargo bikes etc	1	1		1			1																	1																
1282	No way to get from Coronation Road to Masons Green Lane without having to ride through large roundabout	1	16/4/2023	https://www.google.com/maps/place/51.52794735956069%2C-0.2800156683905408/@51.52794735956069,-0.2800156683905408,17	1 Coronation Rd, London, NW10 7QE	Park Royal	North Acton	Agreed - easiest solution to improve connection would be a shared path on the southern pavement however that is in Brent	1		1	1			1													1																				
1283			16/4/2023	https://www.google.com/maps/place/51.5090228[illegible]																																												
1284			16/4/2023	[illegible]																																												
1285			16/4/2023	[illegible]																																												
1286			16/4/2023	[illegible]																																												
1287			16/4/2023	[illegible]																																												
1288			16/4/2023	[illegible]																																												
1289	NO NO NO! GET RID OF IT! NO NEED FOR CYCLE LANES, this is a narrow road!	1	17/4/2023	[illegible]	[illegible]	Bedford Park	Southfield	[illegible]	1			1			1																								1					
1290			18/4/2023	[illegible]																																												

1291			18/4/2023	https://www.google.com/maps/place/51.510743915697816%2C-0.320353661699464/@51.510743915697816,-0.320353661699464,17z																																											
1292			18/4/2023	https://www.google.com/maps/place/51.508840871166928%2C-0.33804961661936916/@51.50884087166928,-0.33804961661936916,1																																											
1293	a separate cycle lane would be useful	1	18/4/2023	https://www.google.com/maps/place/51.50945282114523%2C-0.3310826805563516/@51.50945282114523,-0.3310826805563516,17	31 Uxbridge Rd, London, W7 3PX	Hanwell Cemetaries	Hanwell Broadway	Agreed - might be achievable if parking is removed as outlined on suggestions	1			1	1		1	1		1										1																			
1294	Getting from Oaklands school to Hanwell community centre isn't easy- I would like to cycle with my children but that road is too busy	1	18/4/2023	https://www.google.com/maps/place/51.509763340910915%2C-0.3348027471952064/@51.509763340910915,-0.3348027471952064,17	St Mellitus Hall, Church Rd, London, W7 3BA	Hanwell	Hanwell Broadway	Church road busy and lacks infrastructure	1			1														1																					
1295	Getting past the railway is always busy and feels unsafe with children	1	18/4/2023	https://www.google.com/maps/place/51.516653555592536%2C-0.3307304593135596/@51.51665355592536,-0.3307304593135596,17	Drayton Green Station, Ealing, London, W13 0JX	Drayton Green	North Hanwell / Pitshanger	Key east - west link for all road users but no cycle infrastructure.	1			1	1		1	1										1																					
1296	The whole area around the Clocktower is a nightmare. If you're coming out of Station Road, you have to turn right not a busy Uxbridge Road or get off your bike and walk it over to Cherington Road. Then as you move down Boston Road it's basically a free for all as the the route is not free for cyclists as so much parking	1	18/4/2023	https://www.google.com/maps/place/51.508820998317%2C-0.33794602372252847/@51.508820998317,-0.33794602372252847,1	Hanwell Town Centre, London, W7 3SP	Hanwell	Hanwell Broadway	Agreed - hotspot for various reasons. With parking a key issue. The junction with Boston Road doesn't provide a safe crossing for cyclists and feeds you straight on a	1			1	1		1	1		1		1						1				1	1																	
1297	Very tight, often get almost squashed by buses/ lorries going down this road especially as you approach the railway bridge	1	18/4/2023	https://www.google.com/maps/place/51.510601165776555%2C-0.33463040098682173/@51.51060116577655,-0.33463040098682173,1	36a Church Rd, London, W7 1DL	Hanwell	Hanwell Broadway	Church road busy and lacks infrastructure	1			1	1		1	1										1																					
1298	Exceptionally tight around here and esp as you come into Trumpers Way junction and people pulling out of Esso garage - it's not well marked as a cycle way and so it's a free for all - have seen someone get knocked off their bike	1	18/4/2023	https://www.google.com/maps/place/51.50547656582226%2C-0.3359194784869657/@51.50547656582226,-0.3359194784869657,17	84 Boston Rd, London, W7 2ES	Boston Manor	Hanwell Broadway	Notably poor section of Boston Road - long sections without a cycle lane then, markings are very faded and there is parking in cycle lanes and finally the junction with	1			1	1		1	1				1		1				1	1			1																		
1299			18/4/2023	https://www.google.com/maps/place/51.53968236475615%2C-0.3653367971690069/@51.53968236475615,-0.3653367971690069,17																																											
1300			18/4/2023	https://www.google.com/maps/place/51.538920742 5408%2C-0.3631738634264958/@51.5389207425408,-0.3631738634264958,17																																											
1301			18/4/2023	https://www.google.com/maps/place/51.54035900945698%2C-0.37010462431639635/@51.54035900945698,-0.37010462431639635,1																																											
1302			18/4/2023	https://www.google.com/maps/place/51.542913593487%2C-0.3771581541486291/@51.5429135993487,-0.3771581541486291,17																																											
1303	I have devise over several years a circular cycle around Acton, Ealing, Hanwell, and Brentford, which is 95 per cent off road. This is an excellent route for the Ealing Marathon (which runs through too many streets). I am happy to email a map of the route to yourselves. Basically the route starts/end at any point: West Acton Station, Princes Gardens, Masons Green, Hanger Lane Roundabout	1	18/4/2023	https://www.google.com/maps/place/51.52577672426262%2C-0.3490564127647078/@51.52577672426262,-0.3490564127647078,17	Brentside Playing Fields, Ruislip Rd E Greenford UB6 9FH	Ealing	Various	Might be worth reviewing alongside cycle map improvements	1		1			1																																1	Off street marathon route
1304			19/4/2023	https://www.google.com/maps/place/51.50330852712493%2C-0.3411530894740533/@51.50330852712493,-0.3411530894740533,17																																											
1305	Holes and general bad quality cycle lanes	1	20/4/2023	https://www.google.com/maps/place/51.50844495609454%2C-0.2821377970210026/@51.50844495609454,-0.2821377970210026,17	373-375 Uxbridge Rd, London, W3 9RH	Ealing Common - Acton	Ealing Common / North Acton	Mostly segregated or bus lanes now - area around Hale Gardens appears a little poor	1			1			1			1					1																								
1306	No cycle lanes separated from traffic	1	20/4/2023	https://www.google.com/maps/place/51.506901185238675%2C-0.26809935001501195/@51.506901185238675,-0.26809935001501195,1	82 High St, London, W3 6QX	Acton	South Acton	Section of limited segregation around Acton Town Hall	1			1	1		1	1		1										1																			
1307	Cars park on the cycle lane all along Uxbridge road.	1	20/4/2023	https://www.google.com/maps/place/51.507364129636876%2C-0.24848263856977582/@51.507364129636876,-0.24848263856977582,1	27 The Vale, London, W3 7RR	East Acton	East Acton / Southfield	Multiple sections of cycle lane car parking. This particular section doesn't need the parking	1			1			1			1												1																	
1308	Should make this cycle friendly, currently a nightmare for cycles, and not safe at all, which is a shame as the area could be a great place to cycle with children	1	20/4/2023	https://www.google.com/maps/place/51.500769469 0071%2C-0.34941548343126794/@51.5007694690071,-0.34941548343126794,1	Warren Farm Nature Reserve, Southall UB2 4NE	Norwood Green	Norwood Green	Assuming Windmill Lane (rather than the nature reserve itself) - on suggestions tab	1			1			1	1										1																					
1309	No cycle lane on Northfield avenue	1	20/4/2023	https://www.google.com/maps/place/51.5016088963 20285%2C-0.31562274834435744/@51.501608896320285,-0.31562274834435744,1	160 Northfield Ave, London W13 9SB	Northfield	Northfield / Walpole	Agreed	1			1			1	1										1																					
1310			22/4/2023	https://www.google.com/maps/place/51.512141402725995%2C-0.31288625518302693/@51.512141402725995,-0.31288625518302693,1																																											
1311			22/4/2023	https://www.google.com/maps/place/51.50970909406432%2C-0.3274141001265929/@51.50970909406432,-0.3274141001265929,17																																											
1312			22/4/2023	https://www.google.com/maps/place/51.499558262933796%2C-0.32814366097864367/@51.499558262933796,-0.32814366097864367,1																																											
1313			22/4/2023	https://www.google.com/maps/place/51.5050253261037%2C-0.3342820672400548/@51.5050253261037,-0.3342820672400548,17																																											
1314	I haven't seen a cycle path on Meadvske or in Ealing broadway	1	24/4/2023	https://www.google.com/maps/place/51.52786820432495%2C-0.3162945201663869/@51.52786820432495,-0.3162945201663869,17	170 Meadvale Rd, London, W5 1LT	Pitshanger	Pitshanger / Hanger Hill	Meadvale Road is on the draft LBE maps but not cyclestreets but does provide alternative to the A40 track which is basic through this section. No signage / designation at	1			1			1											1			1																		
1314.1		1			Ealing Broadway Station, London, W5 2NU			Additional location for previous log	1			1			1											1			1																		
1315	This drag and drop thing isn't working for me	1	24/4/2023	https://www.google.com/maps/place/51.49792103387932%2C-0.31206554368702344/@51.49792103387932,-0.31206554368702344,1	6 Julien Rd, Ealing, London W5 4XA			Survey issue																																								1	**Survey issue**
1316	The whole of Radbourne ave, junction road is a dangerous death trap. Oncoming SUVs that don't slow down for bikes and others crossing Junction road with no care or duty for bikes	1	27/4/2023	https://www.google.com/maps/place/51.49646990142447%2C-0.3096634700493861/@51.49646990142447,-0.3096634700493861,17	28-2 Radbourne Ave, London	South Ealing	Northfield	hotspot junction road rat run	1			1	1		1	1										1									1		1										
1317			27/4/2023	https://www.google.com/maps/place/51.49427774265214%2C-0.3070947566213822/@51.49427774265214,-0.3070947566213822,17																																											
1318			27/4/2023	https://www.google.com/maps/place/51.49580531539108%2C-0.3089773327130785/@51.49580531539108,-0.3089773327130785,17																																											
1319			27/4/2023	https://www.google.com/maps/place/51.49486733331448%2C-0.30840934602307746/@51.49486733331448,-0.30840934602307746,1																																											
1320			27/4/2023	https://www.google.com/maps/place/51.49416025697855%2C-0.3080079974142502/@51.49416025697855,-0.3080079974142502,17																																											
1321	These do not work for families or kids, with bus stops, loading, parking to navigate it requires frequent moves into the run of traffic	1	27/4/2023	https://www.google.com/maps/place/51.511671641040486%2C-0.31109333143320095/@51.511671641040486,-0.31109333143320095,1	85 Uxbridge Rd, London, W5 5BW	West Ealing	Ealing Broadway / Walpole	Lack of segregation on Uxbridge, Ealing Broadway - West Acton, hotel section which doesn't need parking	1			1	1		1	1		1										1																			
1322	As per previous comments, these routes do not work for families. Smaller rods adjacent are better for families and younger children, but more awareness/education of drivers required about how to pass and how close to be when following behind.	1	27/4/2023	https://www.google.com/maps/place/51.50677950209284%2C-0.31241490311045395/@51.50677950209284,-0.31241490311045395,1	43 Waldemar Ave, London W13 9PZ	Walpole	Walpole	General poor driver behaviour				1																							1												
1323			27/4/2023	https://www.google.com/maps/place/51.51153621954839%2C-0.304864934461766/@51.51153621954839,-0.304864934461766,17z																																											
1324			27/4/2023	https://www.google.com/maps/place/51.50876770906272%2C-0.319258906395814/@51.50876770906272,-0.319258906395814,17z																																											
1325			27/4/2023	https://www.google.com/maps/place/51.51159869323035%2C-0.31564577981842534/@51.51159869323035,-0.31564577981842534,1																																											
1326	Turning vehicles regularly block pedestrian/cycle crossing or driving when there is a green light for pedestrians.	1	27/4/2023	https://www.google.com/maps/place/51.513856483691306%2C-0.24883422504796693/@51.513856483691306,-0.24883422504796693,1	10 Westway, London, W3 7EL	East Acton	East Acton	Old Oak Common / A40 junction. Poor driver behaviour and surprisingly no yellow boxes. TfL issue	1			1			1	1										1					1			1	1												
1327	This bridge is not cycling-friendly you have to dismount or otherwise run into pedestrians or rowdy mobility scooters. Grange School just next to it is another hazard point for obvious reasons. Without mentioning the poles which makes for a very awkward passage.	1	27/4/2023	https://www.google.com/maps/place/51.50200808462836%2C-0.30529266696400326/@51.50200808462836,-0.30529266696400326,1	Roberts Alley, London, W5 4HL	South Ealing	South Ealing	The Bollards at Church Gardens looks difficult for regular bikes and certainly are not passable with recumbents or cargo	1			1			1												1		1			1															
1328	The whole stretch next to llamas park is a death trap where cars already struggle to pass next to parked vehicles. Sidewalks are too damaged to find a safe haven upon even if they are unused by pedestrians.	1	27/4/2023	https://www.google.com/maps/place/51.505801350644305%2C-0.30992752414173763/@51.505801350644305,-0.30992752414173763,1	Park Sports Lammas Park, Ealing Culmington Rd, Greater, London,	Walpole	Walpole	Culmington Road hotspot - the parking should be reviewed in the knowledge this is a key link for all road users	1			1	1		1	1										1																					
1329	Uxbridge road is a hazard where buses and taxis compete to have runover cyclist's marks added to their kill score.	1	27/4/2023	https://www.google.com/maps/place/51.51205153 6742845%2C-0.3130174289268939/@51.512051536742845,-0.3130174289268939,17	58 Uxbridge Rd, London, W5 2ST	West Ealing	Ealing Broadway / Walpole	Lack of segregation on Uxbridge, Ealing Broadway - West Acton, hotel section which doesn't need parking	1			1	1		1	1		1				1						1		1																	
1330	Bond Street is neither safe to cycle or park a bike, the same could be said of the whole broadway area to be fair.	1	27/4/2023	https://www.google.com/maps/place/51.51226520316106%2C-0.3058934817833392/@51.51226520316106,-0.3058934817833392,17	14 Bond St, London, W5 5AA	Ealing Broadway	Ealing Broadway	Agreed - partly why Barnes Pikle connection would be beneficial	1			1	1		1	1										1							1														
1331	Legend has it the red lights of the crossing of Pope's lane and Lionel road is painted red with the blood of cyclists. this whole area is a hazard for all vehicles.	1	27/4/2023	https://www.google.com/maps/place/51.49987089429231%2C-0.29984241824574154/@51.49987089429231,-0.29984241824574154,1	90 Popes Ln London, W5 4NS	Gunnesbury Park	Northfield / Ealing Common	This crossing is tricky and this area is on emerging suggestions	1			1			1	1						1				1					1																
1332	Need route to Asda from here	1	28/4/2023	https://www.google.com/maps/place/51.523895347851855%2C-0.2650528157709142/@51.523895347851855,-0.2650528157709142,17	322 Park Royal Rd, London, W3 0PH	North Acton	North Acton	Park Royal Road lack of cycle infrastructure - on suggestions tab	1			1			1	1										1																					
1333	This junction a bit dangerous with cars coming from 5 directions	1	28/4/2023	https://www.google.com/maps/place/51.522219802888635%2C-0.27343203673343863/@51.522219802888635,-0.27343203673343863,1	3 Westfields Rd, London, W3 0AP	North Acton	North Acton	This junction has been referenced a few time now - adding to suggestions - needs clear priorities for all road users - most likely those continuing straight between	1			1			1							1					1		1																		
1334	Need safe route South along Noel Road and over the bridge to Twyford Avenue	1	28/4/2023	https://www.google.com/maps/place/51.51774012691744%2C-0.28009699835646273/@51.51774012691744,-0.28009699835646273,1	119 Saxon Dr, West Acton, London, W3 0NT	West Acton	Hanger Hill / North Acton	Agreed this is a missing link and on suggestions	1			1			1	1										1			1																		
1335	Dangerous on road crossing, need to be able to cross with pedestrians on the Pelican crossing.	1	28/4/2023	https://www.google.com/maps/place/51.51141059513619%2C-0.2918558026777518/@51.51141059513619,-0.2918558026777518,17	2-8 Hanger Ln, London, W5 3HN	Ealing Common	Ealing Common	Agreed - Uxbridge / A406 hotspot junction. Lack of cycle infrastructure	1			1	1			1		1	1							1				1																	
1336			28/4/2023	https://www.google.com/maps/place/51.51481761795754%2C-0.3018199281047451/@51.51481761795754,-0.3018199281047451,17																																											
1337			28/4/2023	https://www.google.com/maps/place/51.51168049685549%2C-0.316448659460955/@51.51168049685549,-0.316448659460955,17z																																											
1338			28/4/2023	https://www.google.com/maps/place/51.50884929914527%2C-0.2761940665654472/@51.50884929914527,-0.2761940665654472,17																																											
1339			28/4/2023	https://www.google.com/maps/place/51.50692612111235%2C-0.25731131510060345/@51.50692612111235,-0.25731131510060345,1																																											
1340	The bike lanes stops and starts along this stretch of road - why is that? There are wands in the road leading up to here but when you get to the part where you need the lane which is near the traffic lights the lane disappears to a ridiculous dashed lane and it full of people parked. All along the stretch of road from Shepherds Bush to Acton	1	28/4/2023	https://www.google.com/maps/place/51.506677405 8988%2C-0.25529922145452577/@51.5066774058988,-0.25529922145452577,1	143-159 The Vale, London, W3 7RH	Acton Park - Shepherds Bush	East Acton / Southfield	Agreed - much more of this section could be either segregated or double yellow lines than is currently in place. Some sections of highway are poor but are	1			1			1	1		1					1			1		1		1	1														1		
1341	no proper cycle lane to go towards ealing broadway station	1	28/4/2023	https://www.google.com/maps/place/51.51496639089925%2C-0.3111063898783062/@51.51496639089925,-0.3111063898783062,17	54 Gordon Rd, London, W5 2AR	West Ealing Ealing Broadway	Ealing Broadway	General lack of signage and clear designation on Gordon Road	1			1			1												1		1																		
1342	Cycle lanes taken up by parked mopeds	1	28/4/2023	https://www.google.com/maps/place/51.51414130890861%2C-0.3004334732439262/@51.51414130890861,-0.3004334732439262,17	7A The Mall Ealing, London, W5 2PJ	Ealing Broadway	Ealing Broadway	Probably a reference to a different section in this area as there is no cycle lane here.																						1																	
1343			28/4/2023	https://www.google.com/maps/place/51.514702995441496%2C-0.30106588236441745/@51.514702995441496,-0.30106588236441745,1																																											
1344	We need a cycle track and a running track	1	28/4/2023	https://www.google.com/maps/place/51.556550082131615%2C-0.3543940200918949/@51.556550082131615,-0.3543940200918949,17	35 Russell Rd, London,, Northolt UB5 4QS	Northolt Park	North Greenford	One for the parks team	1		1				1																															1	Park infrastructure
1345	A cycle track on the main roads would be helpful, together with bike storage	1	28/4/2023	https://www.google.com/maps/place/51.55382812843586%2C-0.3550195331258643/@51.55382812843586,-0.3550195331258643,17	156-154 Wood End Ln, Northolt	Northolt Park	North Greenford	Agreed and on suggestions. Needs to connect with c88 and c87. There are no cycle hangers in this area and no previous requests suggestion awareness of the cycle hanger	1			1			1	1										1							1														
1346	It's crazy that at the busiest part of Ealing, all cycling lanes, signage etc disappear. It seems its a case of cycling isnt important when it come to busy areas becasue there are too many cars and it might inconvenience cars.	1	28/4/2023	https://www.google.com/maps/place/51.51581726945815%2C-0.3021056558534463/@51.51581726945815,-0.3021056558534463,17	33 The Broadway, London, W5 2NX	Ealing Broadway	Ealing Broadway	Ealing Broadway / Haven Green hotspot - lack of cycle infrastructure	1			1	1			1										1																					

1347	Please connect these 2 cycle ways. a very obvious place to do it.	1	28/4/2023	https://www.google.com/ maps/place/51.5176213 40821%2C- 0.3002594634028699/@ 51.5176213740821,- 0.3002594634028699,17	48F Mountfield Rd, London, W5 2NQ	Montpelier	Ealing Broadway / Hanger Hill	This is displayed on Cyclestreets as C85 but not shown on the provisional LBE map. Lacks clear signage and designation though. On suggestions tab	1			1			1											1	1		1																	
1348			28/4/2023	https://www.google.com/ maps/place/51.5157920 804542%2C- 0.30455099782669803/ @51.51579203804542,- 0.30455099782669803,1																																										
1349			28/4/2023	https://www.google.com/ maps/place/51.51438994 244364%2C- 0.3019331618281629/@ 51.51438994244364,- 0.3019331618281629,17																																										
1350			28/4/2023	https://www.google.com/ maps/place/51.5143231 490992%2C- 0.30446516713822147/ @51.51432317490992,- 0.30446516713822147,1																																										
1351			28/4/2023	https://www.google.com/ maps/place/51.5201300 4348344%2C- 0.28631447211606265/ @51.520130074348344,- 0.28631447211606265,1																																										
1352			28/4/2023	https://www.google.com/ maps/place/51.5104311 358619%2C- 0.33472075882031715/ @51.51043110358619,- 0.33472075882031715,1																																										
1353			28/4/2023	https://www.google.com/ maps/place/51.5161131 5963154%2C- 0.3046800178535203/@ 51.516113155963154,- 0.3046800178535203,17																																										
1354	Considerable traffic at the T-Junction. It would be better with a roundabout.	1	28/4/2023	https://www.google.com/ maps/place/51.5007516 334269%2C- 0.2774706222186518/@ 51.50075165334269,- 0.2774706222186518,17	231 Bollo Ln, London, W3 8RB	South Acton	South Acton	Junction of Bollo Lane and Bollo Bridge Road								1						1																								1	Preference for a roundabout
1355	Dangerous mini-roundabout for cyclists, as cars don't stop for them.	1	28/4/2023	https://www.google.com/ maps/place/51.5073566 7373146%2C- 0.2712513712027498/@ 51.507356677373146,- 0.2712513712027498,17	172 High St, Acton, London, W3 9NN	Acton	South Acton	Poor driver behaviour and tricky connection to the cycle route on church road - priority unclear arriving north on the cycle path	1			1			1			1									1								1											
1356	You leave the lovely Hounslow path to the dangerous mess of Ealing	1	28/4/2023	https://www.google.com/ maps/place/51.4977579 943285%2C- 0.32676402700174245/ @51.49775792943285,- 0.32676402700174245,1	18 Boston Gardens, London, W7 2AN	Boston Manor	Northfield / Hanwell Broadway	Boston Road in general	1			1	1		1	1				1								1																		
1357			28/4/2023	https://www.google.com/ maps/place/51.5011781 9097724%2C- 0.3200656044949346/@ 51.501178129097724,- 0.3200656044949346,17																																										
1358			28/4/2023	https://www.google.com/ maps/place/51.4974761 6259864%2C- 0.3372317421902471/@ 51.497476156259864,- 0.3372317421902471,17																																										
1359			28/4/2023	https://www.google.com/ maps/place/51.50447544 901694%2C- 0.3239709008206182/@ 51.50447544901694,- 0.3239709008206182,17																																										
1360			28/4/2023	https://www.google.com/ maps/place/51.5047095 4453585%2C- 0.32067035505562336/ @51.504709574453585,- 0.32067035505562336,1																																										
1361	This section of Uxbridge Road needs a segregated cycle lane to feel safe	1	28/4/2023	https://www.google.com/ maps/place/51.5114890 0342915%2C- 0.31624994255320615/ @51.511489030342915,- 0.31624994255320615,1	Lovelace House, 96-122 Uxbridge Rd, London, W13 8RD	West Ealing	Walpole	hotspot section of Uxbridge Road which lacks segregation	1			1	1		1	1		1										1																		
1362	Going straight (east to west or west to east) across this roundabout is intimidating and needs better cycle infrastructure	1	28/4/2023	https://www.google.com/ maps/place/51.5084692 120282%2C- 0.2744145347266813/@ 51.50846922120282,- 0.2744145347266813,17	255 High St, London, W3 9BY	Acton	North Acton / South Acton	Styne / Uxbridge hotspot roundabout. Westbound issues are cycle lane parking and end of segregation. Eastbound the segregated route is a significant	1			1	1		1	1		1									1	1																		
1363	The cycle lane on the south side of Uxbridge road disappears here for several hundred metres and makes you feel unsafe as cars and lorries get very close	1	28/4/2023	https://www.google.com/ maps/place/51.5068111 330997%2C- 0.26875110124036095/ @51.50681116330997,- 0.26875110124036095,1	100 High St, London, W3 6QX	Acton	South Acton	Unsegregated sections in Acton	1			1	1		1	1		1										1																		
1364	The cycle lane on the north side of Uxbridge Road disappears for several hundred metres here and leaves you feeling exposed to close passes by large lorries and cars	1	28/4/2023	https://www.google.com/ maps/place/51.5067388 110122%2C- 0.26501045137408363/ @51.50673886110122,- 0.26501045137408363,1	20-24 High St, London, W3 8QX	Acton	South Acton	Unsegregated sections in Acton	1			1	1		1	1		1										1																		
1365	The markings of the cycle lane are now very faint here. Some infrastructure e.g. flexible polls would be great to create some segregation from the motor traffic on a large piece of road	1	28/4/2023	https://www.google.com/ maps/place/51.5092510 742988%2C- 0.3490221566607543/@ 51.50925102742988,- 0.3490221566607543,17	401 Uxbridge Rd, Southall UB1 3EW	Ealing Hospital	Norwood Green	Agreed and on suggestions	1			1	1		1	1		1					1					1																		
1366	Please can we have a proper cycle lane like in Chiswick?	1	28/4/2023	https://www.google.com/ maps/place/51.50888564 1601864%2C- 0.28006999690167067/ @51.508885641601864,- 0.28006999690167067,1	347 Uxbridge Rd, London, W3 9RH	Ealing Common - Acton	Ealing Common / North Acton	Full segregation	1			1				1		1										1																		
1367	Cars often park on the bike lane, forcing cyclists to go onto the main lane. Posts like on the way from Acton to Shepherd's Bush or some sort of barrier would really really help.	1	28/4/2023	https://www.google.com/ maps/place/51.5146044 005493%2C- 0.3020588752124653/@ 51.51460442005493,- 0.3020588752124653,17	Ealing Broadway Station, The Broadway, London, W5 2NU	Ealing Broadway	Ealing Broadway	Lack of segregation	1			1	1		1	1		1								1		1																		
1368	Cars often park on the bike lane, forcing cyclists to go onto the main lane. Posts like on the way from Acton to Shepherd's Bush or some sort of barrier would really really help.	1	28/4/2023	https://www.google.com/ maps/place/51.5125990 977242%2C- 0.31437172448862905/ @51.51259909977242,- 0.31437172448862905,1	68 Uxbridge Rd, London, W13 8RA	West Ealing	Walpole	Lack of segregation / parking in cycle lanes	1			1	1		1	1		1										1		1																
1369	Cars often park on the bike lane, forcing cyclists to go onto the main lane. Posts like on the way from Acton to Shepherd's Bush or some sort of barrier would really really help.	1	28/4/2023	https://www.google.com/ maps/place/51.5105228 650788%2C- 0.3228280423390273/@ 51.51052282650788,- 0.3228280423390273,17	64a The Broadway, London, W13 0SU	West Ealing	Hanwell Broadway / Walpole	Lack of segregation / parking in cycle lanes	1			1	1		1	1		1										1		1																
1370	Around Horsenden and along the canals, pedestrians don't seem to be aware that cyclists are allowed there too and seem irritated by their presence. Signage definitely needs improvement	1	28/4/2023	https://www.google.com/ maps/place/51.5429765 203926%2C- 0.32645799610016235/ @51.54297652203926,- 0.32645799610016235,1	Unit 1, C Canal Wharf, Horsenden Ln N, Horsenden,	Horsenden	Perivale / North Greenford	Poor signage / designation	1			1			1						1						1																			
1371	Along Argyle road there doesn't seem to be much space or obvious route for cyclists. I was driving along it today snd a female cyclist got cut up by another driver and then ended up having to use the footpath	1	28/4/2023	https://www.google.com/ maps/place/51.5297430 802656%2C- 0.32855922592581743/ @51.52974308802656,- 0.32855922592581743,1	2 Peal Gardens, London, W13 0BA	Pitshanger	Pitshanger / Perivale	North section of Argyle - not a designated route but it is an inevitable one connecting north into Perivale (particularly at night / winter when people will be less	1			1			1	1										1																				
1372	People park at the entrance of cycle lanes making access impossible. Also the lanes are not segregated, making them less secure.	1	28/4/2023	https://www.google.com/ maps/place/51.5089608 5093256%2C- 0.28271213626964276/ @51.508960845093256,- 0.28271213626964276,1	387 Uxbridge Rd, London, W3 9SA	Ealing Common - Acton	Ealing Common / North Acton	hotspot section along Twyford Gardens - lack of segregation and parking in cycle lanes	1			1	1		1	1		1										1		1																
1373	People park at the entrance of cycle lanes making access impossible. Also the lanes are not segregated, making them less secure.	1	28/4/2023	https://www.google.com/ maps/place/51.5066102 8894805%2C- 0.2599670038233537/@ 51.506610288894805,- 0.2599670038233537,17	120 The Vale, London, W3 7JT	Acton Park	East Acton / Southfield	Uxbridge Road East Acton patchy segregation and parking in cycle lanes	1			1	1		1	1		1										1		1																
1374	People park at the entrance of cycle lanes making access impossible. Also the lanes are not segregated, making them less secure.	1	28/4/2023	https://www.google.com/ maps/place/51.5068774 366082%2C- 0.2501393899927873/@ 51.50687740366082,- 0.2501393899927873,17	55 The Vale, London, W3 7RR	East Acton	East Acton / Southfield	Uxbridge Road East Acton patchy segregation and parking in cycle lanes	1			1	1		1	1		1										1		1																
1375	People park at the entrance of cycle lanes making access impossible. Also the lanes are not segregated, making them less secure. Also joining this big-ish roundabout is a bit of a weird maneuver, especially if travelling towards Acton.	1	28/4/2023	https://www.google.com/ maps/place/51.5084681 172323%2C- 0.2746093184092646/@ 51.50846812172323,- 0.2746093184092646,17	257 High St, London, W3 9BY	Acton	North Acton / South Acton	hotspot styne / Uxbridge roundabout. Cycle lane parking and infrastructure concerns	1			1	1		1	1		1									1	1		1																
1376			28/4/2023	https://www.google.com/ maps/place/51.5065434 5791566%2C- 0.3048878217369211/@ 51.506543465791566,- 0.3048878217369211,17																																										
1377			28/4/2023	https://www.google.com/ maps/place/51.5139853 01772%2C- 0.30442018888549915/ @51.5139853801772,- 0.30442018888549915,1																																										
1378			28/4/2023	https://www.google.com/ maps/place/51.5144936 099492%2C- 0.30204465311182815/ @51.51449365099492,- 0.30204465311182815,1																																										
1379			28/4/2023	https://www.google.com/ maps/place/51.5011617 35364%2C- 0.3069408237407001/@ 51.5011617335364,- 0.3069408237407001,17																																										
1380			28/4/2023	https://www.google.com/ maps/place/51.4994519 7533054%2C- 0.30084684485886415/ @51.499451957533054,- 0.30084684485886415,1																																										
1381			28/4/2023	https://www.google.com/ maps/place/51.5111970 494793%2C- 0.3184525594187049/@ 51.51119709494793,- 0.3184525594187049,17																																										
1382			28/4/2023	https://www.google.com/ maps/place/51.5083643 872456%2C- 0.34076715593796436/ @51.50836439872456,- 0.34076715593796436,1																																										
1383			28/4/2023	https://www.google.com/ maps/place/51.5132673 901498%2C- 0.30413289411990174/ @51.51326735901498,- 0.30413289411990174,1																																										
1384			28/4/2023	https://www.google.com/ maps/place/51.5119319 683739%2C- 0.29357571943728455/ @51.51193195683739,- 0.29357571943728455,1																																										
1385			28/4/2023	https://www.google.com/ maps/place/51.5084463 273092%2C- 0.2770533119055463/@ 51.50844637273092,- 0.2770533119055463,17																																										
1386	Busy road - could do with separate cycle option	1	28/4/2023	https://www.google.com/ maps/place/51.5034598 282406%2C- 0.3328621397024456/@ 51.50345983282406,- 0.3328621397024456,17	164 Boston Rd, London, W7 2HP	Boston Manor	Northfield / Hanwell Broadway	Boston Road lack of segregation	1			1	1			1				1								1																		
1387	Would not consider cycling on Uxbridge Road but can usually get around using side roads	1	28/4/2023	https://www.google.com/ maps/place/51.5099774 670651%2C- 0.3271973142629925/@ 51.50997743670651,- 0.3271973142629925,17	136 Broadway, Ealing, London, W13 0TL	West Ealing	Hanwell Broadway / Walpole	General Uxbridge Road										1				1																								
1388	Decent cycle lane here going from west to east, though when cycling in west direction need to watch parked cars just moving off, that don't always keep a lookout for bikes	1	28/4/2023	https://www.google.com/ maps/place/51.5110524 46536%2C- 0.3101599226003948/@ 51.5110524846536,- 0.3101599226003948,17	18 Mattock Ln, London, W5 5BG	Walpole	Walpole	Poor driver behaviour																											1											
1389	No cycle lane or suitable markings here	1	28/4/2023	https://www.google.com/ maps/place/51.5288810 180494%2C- 0.3482287070418666/@ 51.52888103180494,- 0.3482287070418666,17	85 Costons Ln, Greenford UB6 8RR	Greenford	Central Greenford	C87 - this is a very useful link to avoid Greenford Broadway entirely yet there is no signage at all where it crosses Greenford Road or at any point heading along this route	1			1			1											1	1		1																	
1390	No usable cycle lane here, this is just a normal road.	1	28/4/2023	https://www.google.com/ maps/place/51.5386879 010837%2C- 0.3491541891631256/@ 51.53868799010837,- 0.3491541891631256,17	266 Oldfield Ln N, Greenford UB6 8PS	Greenford	Central Greenford	C87 - as previous lack of infrastructure and signage	1			1			1											1	1		1																	
1391	Surface of the entire canal path can be quite poor	1	28/4/2023	https://www.google.com/ maps/place/51.5427089 124651%2C- 0.3345194900980286/@ 51.54270897124651,- 0.3345194900980286,17	Ballot Box Bridge, Horsenden Ln N, Perivale, Horsenden,	Horsenden (Canal)	Central Greenford / North Greenford / Perivale	Basic gravel track in this section	1			1				1					1																									
1392			28/4/2023	https://www.google.com/ maps/place/51.5131550 551621%2C- 0.3113457345390769/@ 51.51315500551621,- 0.3113457345390769,17																																										
1393	No separation here between bikes and traffic, road surface often potholed. Ludicrous to call this a cycleway, given it only has a thin marking, which often is blocked by parked vehicles	1	28/4/2023	https://www.google.com/ maps/place/51.5136462 176651%2C- 0.30489724044325595/ @51.51364622176651,- 0.30489724044325595,1	2 Spring Bridge Rd, London, W5 2AB	Ealing Broadway	Ealing Broadway	Springbridge Road lack of cycle infrastructure alongside the whole area	1			1	1		1	1		1					1			1		1		1																
1394	Lots of potholes, bumps, and the start and end of the cycle road is difficult to get on and off and leaves you in busy fast traffic and unsafe roads	1	28/4/2023	https://www.google.com/ maps/place/51.5022695 165563%2C- 0.37665607238558385/ @51.50226954165563,- 0.37665607238558385,1	8 Merrick Rd, Southall UB2 4AT	Southall	Southall Green / Norwood Green	Unable to verify general condition remotely but the start / end / general signage and designation are poor. On suggestion tab	1			1			1	1							1				1																			
1395	Busy, not at all quiet or safe, fast traffic feels dangerous	1	28/4/2023	https://www.google.com/ maps/place/51.5085682 897604%2C- 0.3476551292607155/@ 51.50856821897604,- 0.3476551292607155,17	Ealing Hospital (Stop Q), Southall, UB2 4FY	Ealing Hospital	Norwood Green	This is the uphill unsegregated section following the hospital. May need to designated the path as shared as cycle speeds will be low and traffic speeds high	1			1			1	1		1				1						1																		
1396	Not at all a quiet road. Car drivers do not give cyclists room round here at all	1	28/4/2023	https://www.google.com/ maps/place/51.5122614 774556%2C- 0.3822040921512837/@ 51.51226146774556,- 0.3822040921512837,17	136 The Broadway, Southall UB1 1QN	Southall Broadway	Southall West / Southall Broadway	C39 - lack of infrastructure or designation despite new layout and surfacing	1			1			1	1		1								1																				
1397	Very difficult at the traffic lights not to be knocked off by traffic. Clear signage to indicate cycle lane are needed in particular when cycling from Acton to Ealing Bdy	1	28/4/2023	https://www.google.com/ maps/place/51.5083766 325452%2C- 0.27606232748792037/ @51.50837665325452,- 0.27606232748792037,1	The Red Back Tavern, High St, London, W3 9BH	Acton	North Acton / South Acton	hotspot Gunnersbury / Uxbridge junction - poor infrastructure. On suggestions sheet.	1			1	1		1	1		1								1	1	1			1															
1398			28/4/2023	https://www.google.com/ maps/place/51.5076492 725536%2C- 0.27260727009867036/ @51.50764923725536,- 0.27260727009867036,1																																										
1399	All along Acton high street the cycling lanes are full of car parked illegally on a daily basis. Traffic wardens should patrol more frequently to ensure cycling lanes are not blocked. It is very dangerous given the number of bus routes in that area.	1	28/4/2023	https://www.google.com/ maps/place/51.5068179 6976395%2C- 0.26893820658853596/ @51.506817916976395,- 0.26893820658853596,1	106-112 High St, London, W3 6QX	Acton	South Acton	Cycle lane parking in Acton	1			1	1		1			1												1				1	1											
1400	There should definitely be a cycling lane here as it is the main road to go to Ealing Broadway.	1	28/4/2023	https://www.google.com/ maps/place/51.5074979 4321946%2C- 0.30515177215124645/ @51.507497924321946,- 0.30515177215124645,1	12 St Mary's Rd, London, W5 5ES	South Ealing	Walpole / Ealing Common	Lack of / poor cycle infrastructure on St Marys / South Ealing most of which could accommodate a cycle lane and then there are options along Ealing Green	1			1	1		1	1										1	1	1																		
1401	This is not a cycling lane! There isn't even signage anywhere...	1	28/4/2023	https://www.google.com/ maps/place/51.5002215 859392%2C- 0.3091932864882607/@ 51.50022158859392,- 0.3091932864882607,17	51 Weymouth Ave, London W5 4SB	South Ealing	Northfield	Lack of clear signage and designation on Weymouth Avenue	1			1			1											1	1		1																	
1402	Very tricky to see traffic coming around the Mcdonalds corner when trying to cross U	1	28/4/2023	https://www.google.com/ maps/place/51.5092796 565788%2C- 0.35408823687664626/ @51.50927961565788,- 0.35408823687664626,1	Iron Bridge, Uxbridge Rd, Southall UB1 3EG	Iron Bridge	Norwood Green / Southall Broadway / Dormers Wells /	Not entirely clear where this specific issue is in terms of sight lines etc	1			1	1		1	1						1																								
1403	Make it clear that that canal path is a cycle route as sometimes pedestrians can be abusive	1	28/4/2023	https://www.google.com/ maps/place/51.5056033 4901396%2C- 0.3500485889766969/@ 51.505603354901396,- 0.3500485889766969,17	Hanwell Lock No 93, Grand Union Canal, Windmill	Hanwell (Canal)	Norwood Green / Hanwell Broadway	Additional markings on the track would be helpful particularly at the entrance and exit points	1			1			1						1																									

1461	All of North Circular would benefit from a more continuous, clearly marked and separated cycle lane	1	29/4/2023	https://www.google.com/maps/place/51.52121073 8064916%2C-0.2916045458607197/@51.521210738064916,-0.2916045458607197,17	55 Hanger Ln, London, W5 3HL	A406	Hanger Hill / Ealing Common	Improve North Circular route	1	
1462			29/4/2023	https://www.google.com/maps/place/51.5119705 64653446%2C-0.3138346941761494/@51.511970564653446,-0.3138346941761494,17						
1463			29/4/2023	https://www.google.com/maps/place/51.5057346 0112506%2C-0.30364886047369755/@51.50573460112506,-0.30364886047369755,1						
1464	A40 cycle lane is quite bad, it's narrow, uneven and hard to navigate	1	29/4/2023	https://www.google.com/maps/place/51.5360690 7963562%2C-0.3440032267537396/@51.53606907963562,-0.3440032267537396,17	74 Runnymede Gardens, Greenford UB6 8SU	A40	Various	(This section is side streets) but in general the path west of Park Royal station is basic	1	
1465	Bad stretch of cycle lane here, very uneven and unsafe, subway crossing has many blind spots	1	29/4/2023	https://www.google.com/maps/place/51.5392008 7313029%2C-0.3608578210404412/@51.53920087313029,-0.3608578210404412,17	Aladdin Building, Western Ave, Greenford UB6 8UY	A40	Greenford Broadway / Central Greenford	Basic cycle lane through this section but no obvious major cause for concern	1	
1466	Awful subway, very badly signposted, unsafe, always amazed bottles, blind spots, dirty, very unsafe cycling and scooting here with kids. Drain covers never in place. One on the worst subways in Ealing, such a shame. Subway is triangulated by several schools all of which are used by kids to scoot and cycle, however it is very unsafe, I avoid using this subway with my kids to scoot or cycle.	1	29/4/2023	https://www.google.com/maps/place/51.5361962 5151691%2C-0.34658914201737945/@51.53619625151691,-0.34658914201737945,1	750-758 Greenford Rd, Greenford UB6 8QQ	Greenford Roundabout	Central Greenford	Various concerns - difficult to verify remotely.	1	
1467	Poor, narrow, uneven, prone to flooding cycle lane, not suitable for any road bike	1	29/4/2023	https://www.google.com/maps/place/51.5331411 9917791%2C-0.3216007917996544/@51.53314119917791,-0.3216007917996544,17	Premier Inn, Western Ave, Perivale, Greenford UB6 8TE	A40 Perivale	Perivale	Basic cycle lane through this section but no obvious major cause for concern	1	
1468	Entire stretch of cycle lane here is poor and extremely outdated, subway crossings are also poor, outdated and unsafe	1	29/4/2023	https://www.google.com/maps/place/51.5323448 5009739%2C-0.31332069164986764/@51.53234485009739,-0.31332069164986764,1	42 Western Ave, Perivale, Greenford, UB6 8DQ	A40 Perivale	Perivale	Basic cycle lane through this section. Junctions are generally poor	1	
1469	Cycle lanes often collect all grease and dirt and are not cleaned. My bike has slipped in such conditions and I fell off. Cycle lanes need maintaining e.g iron bridge Greenford and by Ealing hospital	1	29/4/2023	https://www.google.com/maps/place/51.5426820 7852234%2C-0.3881858514490943 4/@51.542682077852234,-0.3881858514490943 4,1	Iron Bridge, Uxbridge Rd, Southall UB1 3EG	Iron Bridge / Ealing Hospital	Norwood Green	Street cleaning of cycle lanes	1	
1468.1		1			483 Uxbridge Rd, Southall UB1 3ET			Additional location for previous log	1	
1470	Lady Margaret Rd: most of the paint has worn away. So there's barely any indication that there is Cycling infrastructure there. And it's paint. Which is not infrastructure. It's not segregated. The little islands are good. But need to be cleaned more regularly as some of them just get clogged with leaves and have to be cycled round. There needs to be more little islands and more speed cameras	1	30/4/2023	https://www.google.com/maps/place/51.5247190 320716%2C-0.37419653622996263/@51.5247190320716,-0.37419653622996263,1	350-320 Lady Margaret Rd, Southall UB1 2NH	Southall	Lady Margaret	In the short term the lines are badly faded and should be repainted. Wand segregation is difficult owing to pavement parking but in the long term there is clearly plentiful	1	
1471	Cars coming from Southall and heading towards Ealing that are going to turn right into Ealing Hospital should have there own change of lights. At the moment, a lot of cars just go and don't care if there is a bike coming. Make them wait for the lights to turn green to turn into Ealing hospital.	1	30/4/2023	https://www.google.com/maps/place/51.5086906 80022276%2C-0.34655611333824776/@51.508690680022276,-0.34655611333824776,1	431 Uxbridge Rd, Southall UB1 3EW	Ealing Hospital	North Hanwell	This may improve road safety for all users - at present there is a green light for all traffic and an additional right turn filter (presumably depending on traffic volume). This could	1	
1472	You call that a cycle lane?? Try cycling along here at rush hour from Southall towards Ealing. It's clogged with park cars, a lot of traffic and is generally awful. Paint is not infrastructure. It's not the same as holding a yellow helmet in a park in Ealing.	1	30/4/2023	https://www.google.com/maps/place/51.5088185 9273337%2C-0.3370875295422038/@51.50881859273337,-0.3370875295422038,17	137 Uxbridge Rd, London, W7 3ST	Hanwell	Hanwell Broadway	Uxbridge Road hotspot - cycle lane parking.	1	
1473	Elthorne Park Road / Leighton Road are traffic sewers. Something needs to be done. Especially as the council has not replaced the bollard. Put large concrete width restrictions in. That will make drivers think twice. At the moment it's awful down here. Especially at school pick up times and rush hour.	1	30/4/2023	https://www.google.com/maps/place/51.5035244 8728158%2C-0.32778266541694023/@51.50352448728158,-0.32778266541694023,1	81 Elthorne Park Rd., London, W7 2JH	Hanwell	Hanwell Broadway	Elthorne / Leighton rat run.	1	
1474	If this is the junction just past the medical place the paint needs adjusting. Cars left hook cyclists where the cycle path ends. And they pull out of the side road into the cycle lane. Please can you make this junction and the next one (which is slightly better) like the "new" cycle lanes in Southall (which were just old ones upgraded and not new). Those junctions have been laid out to give	1	30/4/2023	https://www.google.com/maps/place/51.5138095 6164356%2C-0.2986373727753322/@51.51380956164356,-0.2986373727753322,17	46-47 The Mall, Ealing, London, W5 3TJ	Ealing Common	Ealing Common	Uxbridge / Hamilton Road junction. Presumably the request is for a raised junction table but in the short term the markings could be reviewed to make priority	1	
1475			30/4/2023	https://www.google.com/maps/place/51.5164645 7561344%2C-0.33372035694675617/@51.51646457561344,-0.33372035694675617,1						
1476			30/4/2023	https://www.google.com/maps/place/51.5153617 1804976%2C-0.3102247035664263/@51.51536171804976,-0.3102247035664263,17						
1477			30/4/2023	https://www.google.com/maps/place/51.5104400 28204684%2C-0.3273803938699671/@51.510440028204684,-0.3273803938699671,17						
1478			30/4/2023	https://www.google.com/maps/place/51.5035342 90931654%2C-0.3184608390298016/@51.503534290931654,-0.3184608390298016,17						
1479	This isn't a cycle route. There is no infrastructure for cyclists through the centre of Broadway at all, meaning that cyclists have to join cars and weave across lanes to get in the right area.	1	30/4/2023	https://www.google.com/maps/place/51.5137757 41360526%2C-0.30393565031001657/@51.513775741360526,-0.30393565031001657,1	The Waterglade Centre, 1 The Broadway, London, W5	Ealing Broadway	Ealing Broadway	Ealing Broadway lack of cycle infrastructure	1	
1480	There is a very good cycle path that lets you skip the Morrisons roundabout from High Street to Uxbridge Road. Unfortunately, there is almost always a car parked across the entrance and/or exit to the slip path, so it becomes dangerous trying to use it. Then by the Red Lion, bikes have to join the main traffic and move	1	30/4/2023	https://www.google.com/maps/place/51.5084558 60623314%2C-0.2745384496625536/@51.508455860623314,-0.2745384496625536,17	251 High St, Acton, London W3 9BY	Acton	South Acton	hotspot cycle lane parking at the Styne / Uxbridge roundabout	1	
1481	The cycle path along High Street would be quite good if cars didn't constantly park in it...	1	30/4/2023	https://www.google.com/maps/place/51.5067104 31616256%2C-0.2644695416874021/@51.506710431616256,-0.2644695416874021,17	10A High St, London, W3 6LJ	Acton	South Acton	Acton cycle lane parking in sections which aren't segregated	1	
1482	There is no infrastructure here, bikes have to weave in between the cars	1	30/4/2023	https://www.google.com/maps/place/51.5088015 4748001%2C-0.26591662326302945/@51.50880154748001,-0.26591662326302945,1	Poets Court, 52 Churchfield Rd, London, W3 6DA	Acton Central	South Acton	Agreed	1	
1483	There is no easy way to get from the Gordon Road exit to Haven Green as it is dependent on lights which aren't positioned for cyclists to turn red. It's also not clear that you're allowed to do that or not, though it would certainly make sense for cyclists. The turn into Gordon Road is far too small with the blocks that have been put out -- I have crashed more than once trying to turn into the	1	30/4/2023	https://www.google.com/maps/place/51.5153599 4860453%2C-0.3053147716876947/@51.51535994860453,-0.3053147716876947,17	1 Gordon Rd, London, W5 2AD	Ealing Broadway	Ealing Broadway	Agreed - Gordon Road junction with Haven Green needs adjusting	1	1
1484	Cycle route needs to be extended along church road, traffic needs to be slowed down as they speed and remove the parking on church road to give more space.	1	30/4/2023	https://www.google.com/maps/place/51.5115229 5903335%2C-0.33608052532928756/@51.51152295903335,-0.33608052532928756,1	21 Church Rd, London, W7 3BB	Hanwell	North Hanwell / Hanwell Broadway	Agreed - church road lack of north - south infrastructure - parking should be reviewed.	1	
1485	Sharp bend on Drayton green road, need traffic to be slowed down. The roundabout junction doesn't feel safe. Need an ambitious scheme which removes only allows buses, cyclists and taxis.	1	30/4/2023	https://www.google.com/maps/place/51.5164682 17680675%2C-0.3305882117735126/@51.516468217680675,-0.3305882117735126,17	144 Shakespeare Rd, London, W7 1LX	Drayton Green	North Hanwell / Pitshanger	As the only link north of Uxbridge stopping all private vehicles would be incredibly ambitious and highly unlikely. This route however should be improved for	1	
1486			30/4/2023	https://www.google.com/maps/place/51.5098433 15501115%2C-0.32079473353707755/@51.509843315501115,-0.32079473353707755,1						
1487	Junction is very difficult and lacks clear cycle lanes. Especially if turning.	1	30/4/2023	https://www.google.com/maps/place/51.5115954 5490652%2C-0.292004956194829/@51.51159545490652,-0.292004956194829,17z	2-8 Hanger Ln, London, W5 3HN	Ealing Common	Ealing Common	hotspot A406 / Uxbridge junction	1	
1488	Lacks clear signage or lanes	1	30/4/2023	https://www.google.com/maps/place/51.5097532 9451646%2C-0.32024404159469055/@51.50975329451646,-0.32024404159469055,1	1 Tawny Cl, London, W13 9LX	Dean Gardens	Walpole	Believed to be the C41 connection between Mattock and Leeland Terrace via Dean Gardens. There are signs at the entrances both ends but it would be beneficial to add	1	
1489	Lacks clear signage or lanes	1	30/4/2023	https://www.google.com/maps/place/51.5106230 7601101%2C-0.30565569823582717/@51.51062307601101,-0.30565569823582717,1	25 The Grn, Ealing, London, W5 5DA	Ealing Broadway	Walpole / Ealing Broadway / Ealing Common	C41 Mattock to The Grove should be improved to generally avoid the roundabout but as cyclists may be continuing North on Bond Street a cycle lane	1	
1490	Too many buses and/or bike lanes	1	30/4/2023	https://www.google.com/maps/place/51.5115053 1629026%2C-0.315445843398805/@51.51150531629026,-0.315445843398805,17z	133 Uxbridge Rd, London, W13 9AU	West Ealing	Walpole / Hanwell Broadway	Presumed to mean remove the bus and cycle lanes on Uxbridge Road in Ealing	1	
1491			30/4/2023	https://www.google.com/maps/place/51.5112694 9280907%2C-0.29196940781576863/@51.51126949280907,-0.29196940781576863,1						
1492	Needs wands to be installed to stop cars parking in the cycle lane	1	30/4/2023	https://www.google.com/maps/place/51.5103593 08882485%2C-0.32346472876620735/@51.510359308882485,-0.32346472876620735,1	68 Broadway, Ealing, London, W13 0SY	West Ealing	Walpole	Parking / loading is permitted at various points in the day. West Ealing hotspot	1	
1493	Needs wands installing to stop cars parking in the cycle lane	1	30/4/2023	https://www.google.com/maps/place/51.5129410 8525083%2C-0.3080346658825639/@51.51294108525083,-0.3080346658825639,17	Ealing Town Hall, New Broadway, London, W5 2BY	West Ealing	Walpole / Ealing Broadway	Parking / loading is permitted at various points in the day. Parking / loading generally not required in this area	1	
1494	Remove one Westbound lane & convert to segregated cycle lane.	1	30/4/2023	https://www.google.com/maps/place/51.5138437 3793398%2C-0.3025525787879668/@51.51384373793398,-0.3025525787879668,17	26 The Broadway, London, W5 2NP	Ealing Broadway	Ealing Broadway	Entirely possible but would require strong political will.	1	
1495	Needs resurfacing & more wands	1	30/4/2023	https://www.google.com/maps/place/51.5066582 5312266%2C-0.24787175619469082/@51.50665825312266,-0.24787175619469082,1	19 The Vale, London, W3 7SH	East Acton	East Acton / Southfield	Surface poor across junctions - parking not required at this location therefore could be segregated	1	
1496	This whole junction is a mess for cyclists. Needs a complete rethink, but to start with remove one lane in each direction and change to cycle lane. It only goes up to 2 lanes for the junction then back down to 1 lane either side of the junction so no need for 2 lanes at the lights.	1	30/4/2023	https://www.google.com/maps/place/51.5113831 3653132%2C-0.29188176255675824/@51.51138313653132,-0.29188176255675824,1	10 Hanger Ln, London, W5 3HN	Ealing Common	Ealing Common	Valid observation that the roads are single lane except at the junction. Uxbridge / A406 hotspot lack of cycle infrastructure	1	
1497	To support safe cycling, there need to be continuous segregated cycle lanes along all major roads in the borough. Many of the cycle lanes marked on this map are not segregated - they are simply painted dotted lines on roads shared with cars, buses, lorries, etc. On main roads this is not safe enough. Worse, these cycle lanes are endlessly interrupted with gaps where cyclists need to join main	1	30/4/2023	https://www.google.com/maps/place/51.5134261 52897594%2C-0.288052250929991/@51.513426152897594,-0.288052250929991,17z	32 Inglis Rd London, W5 3RL	Ealing	Various	Segregate all main routes	1	
1498	Good quiet route to avoid Argyle Road is to use Lynton Road/ Kingsley Av up to Vallis Way. And in reverse too	1	30/4/2023	https://www.google.com/maps/place/51.5194004 2063446%2C-0.326793908112728/@51.51940042063446,-0.326793908112728,17z	74 Kingsley Ave, London W13 0EG	West Ealing	Pitshanger	General lack of designated routes in this area - this is clearly an option but Highview / Claremont would be straighter	1	
1499	Put a dedicated cycle traffic lights in with 10 seconds or so head start to enable cyclists to fully turn right and get into the bus lane.	1	30/4/2023	https://www.google.com/maps/place/51.5088428 2428324%2C-0.34213943697017246/@51.50884282428324,-0.34213943697017246,1	221 Uxbridge Rd, London, W7 3TD	Hanwell	Hanwell Broadway	A cycle filter at these lights would be very useful when a bike is present but would reduce traffic flow in a congested area when no bike is present therefore some	1	
1500	Make Poet's Corner a LTN for safe cycling	1	30/4/2023	https://www.google.com/maps/place/51.5149645 1735927%2C-0.33432265933188265/@51.51496451735927,-0.33432265933188265,1	53 Cowper Rd, Ealing, London, W7 1EL	Hanwell	North Hanwell	This would be beneficial but the main improvement would be a clear cycle lane designation running east - west on Drayton Bridge Road to include the school.	1	
1501			30/4/2023	https://www.google.com/maps/place/51.5200042 4009635%2C-0.32444165134619896/@51.52000424009635,-0.32444165134619896,1						
1502	Why not link Elthorne Park Road (currently a dangerous cut through read identical street) with the park and Elthorne High School? Hundreds of school kids and park goers would benefit.	1	30/4/2023	https://www.google.com/maps/place/51.5026564 2056286%2C-0.33013083635245577/@51.50265642056286,-0.33013083635245577,1	211 Boston Rd, London, W7 2AA	Boston Manor	Hanwell Broadway / Northfield	Adding a clear cycle route around the existing zebra crossing would improve this link and increase awareness for cyclists using Elthorne	1	
1503	Ideally, a cycle lane segregated from cars on Uxbridge road (or West/East parallel) would increase my confidence. I cycle with my kid on the back and always hesitate between this more direct but busy road or slower but possibly safer alternatives.	1	30/4/2023	https://www.google.com/maps/place/51.5101142 9519964%2C-0.3298517962180769/@51.51011429519964,-0.3298517962180769,17	11 Barchester Cl, Uxbridge Rd, London, W7 3XA	West Ealing Cemetaries	Hanwell Broadway	Uxbridge Road - this section looks like it could be segregated as the parking / loading isn't needed	1	
1504	I tend to leave my bike after school drop off at nursery at West Ealing station. There have been no bad surprise so far but I wonder if a room that would be unlock with Oyster or bank card (as used to open gate lines in the train station) could be considered?	1	30/4/2023	https://www.google.com/maps/place/51.5146546 8404453%2C-0.32037378518294357/@51.51465468404453,-0.32037378518294357,1	West Ealing Station, Manor Road, Ealing, Greater,	West Ealing	Pitshanger	Cycle hub request	1	
1505	The outside perimeter of Ealing Broadway/Hanwell is well covered but there is not much infrastructure in place in the middle. Most streets are relatively low traffic but that tend to lead to wild parking which can have dangerous consequences. Determining a more cycle friendly path would be great. Somewhere connecting Castlebar and Montpelier areas.	1	30/4/2023	https://www.google.com/maps/place/51.5217152 7195072%2C-0.322446022681/@51.52171527195072,-0.322446022681,17z	78A Cleveland Rd, London, W13 8AH	Drayton Green	North Hanwell / Pitshanger / Ealing Broadway	On suggestions - there is no west - east connection via Drayton Bridge Road basically	1	
1506	Each train/tube station should be served by a degree of cycle infrastructure to support a better mode combination.	1	30/4/2023	https://www.google.com/maps/place/51.5161080 5408677%2C-0.3339917615932131/@51.51610805408677,-0.3339917615932131,17	9 Dryden Ave, London W7 1ES	All stations	Various	Improve connections to stations	1	
1507			30/4/2023	https://www.google.com/maps/place/51.5168734 86977126%2C-0.32952974707842086/@51.516873486977126,-0.32952974707842086,1						
1508			30/4/2023	https://www.google.com/maps/place/51.5161435 7568158%2C-0.3310370607015578/@51.51614357568158,-0.3310370607015578,17						
1509			30/4/2023	https://www.google.com/maps/place/51.5190651 8710561%2C-0.32280811624595174/@51.51906518710561,-0.32280811624595174,1						
1510			30/4/2023	https://www.google.com/maps/place/51.5153542 3571485%2C-0.33590981249358/@51.51535423571485,-0.33590981249358,17z						
1511	This stretch of road going into hanwell from Southall is bumpy and uneven.	1	30/4/2023	https://www.google.com/maps/place/51.5105062 3861737%2C-0.3502206363658322/@51.51050623861737,-0.3502206363658322,17	Unit 6-7, Triangle Centre, Uxbridge Rd, Southall UB1 3EJ	Ealing Hospital	Norwood Green	Ealing hospital highway condition hotspot	1	
1512	The speed bumps on this road are not cycle friendly, especially when you have children in a bike seat.	1	30/4/2023	https://www.google.com/maps/place/51.5055677 93161205%2C-0.3166510367355735/@51.505567793161205,-0.3166510367355735,17	81-41 Dudley Gardens, London, W13 9LU	Walpole	Walpole	Full width speed humps	1	
1513	A lot of potholes on this road	1	30/4/2023	https://www.google.com/maps/place/51.5075602 4822738%2C-0.3260068998315435/@51.50756024822738,-0.3260068998315435,17	8a St Kilda Rd, London, W13 9DE	Hanwell	Walpole	No clear issues via Google	1	
1514	Potholes	1	30/4/2023	https://www.google.com/maps/place/51.5046047 1711118%2C-0.32437559501557356/@51.50460471711118,-0.32437559501557356,1	105-135 Leighton Rd., London, W13 9EJ	Hanwell	Walpole / Northfield	Junction with Midhurst is poor and the general condition east of Midhurst (ie Leighton Road) isn't great	1	
1515			30/4/2023	https://www.google.com/maps/place/51.5155630 20643626%2C-0.30176224876314217/@51.515563020643626,-0.30176224876314217,1						
1516			1/5/2023	https://www.google.com/maps/place/51.5140630 3793054%2C-0.30156422214228096/@51.51406303793054,-0.30156422214228096,1						

1517			1/5/2023	https://www.google.com/maps/place/51.514570471630314%2C-0.3099756296129841/@51.514570471630314,-0.3099756296129841,17																																
1518			1/5/2023	https://www.google.com/maps/place/51.509442460501376%2C-0.28369176759849957/@51.509442460501376,-0.28369176759849957,1																																
1519			1/5/2023	https://www.google.com/maps/place/51.51048882942856%2C-0.30607447923698405/@51.51048882942856,-0.30607447923698405,1																																
1520			1/5/2023	https://www.google.com/maps/place/51.506295188426826%2C-0.25674109353549746/@51.506295188426826,-0.25674109353549746,1																																
1521			1/5/2023	https://www.google.com/maps/place/51.50055153749671%2C-0.3914108187605936/@51.50055153749671,-0.3914108187605936,17																																
1522			1/5/2023	https://www.google.com/maps/place/51.51886328735483%2C-0.3366335815072219/@51.51886328735483,-0.3366335815072219,17																																
1523			1/5/2023	https://www.google.com/maps/place/51.503167106862676%2C-0.35940271869158824/@51.503167106862676,-0.35940271869158824,1																																
1524			1/5/2023	https://www.google.com/maps/place/51.498785870234094%2C-0.37107569232440074/@51.498785870234094,-0.37107569232440074,1																																
1525			1/5/2023	https://www.google.com/maps/place/51.4979384791635%2C-0.39295377502372997/@51.4979384791635,-0.39295377502372997,1																																
1526			1/5/2023	https://www.google.com/maps/place/51.51238679322837%2C-0.3107603050805463/@51.51238679322837,-0.3107603050805463,17																																
1527			1/5/2023	https://www.google.com/maps/place/51.51119940000735%2C-0.289284302447399/@51.51119940000735,-0.289284302447399,17z																																
1528	The road surface of the bus lane heading East along this stretch of West Ealing is pitted and rutted with potholes and suffers from subsidence. It feels more like an off road course than a sealed road The resurfacing of this stretch is long over due not just for cyclists but for all road users.	1	1/5/2023	https://www.google.com/maps/place/51.510231837659916%2C-0.32391746056643633/@51.510231837659916,-0.32391746056643633,1	Stop U, West Ealing Broadway, London, W13 0SA	West Ealing	Hanwell Broadway / Walpole	Agreed - there are a few issues with this section of Uxbridge Road	1			1			1			1					1													
1529	This part of Hanwell is always tough when heading East as cyclists are sometimes forced out of the leftmost lane into mainstream traffic due to parked cars. This is made more difficult because it's an up hill climb.	1	1/5/2023	https://www.google.com/maps/place/51.50855272913858%2C-0.3400429011639705/@51.50855272913858,-0.3400429011639705,17	191 Uxbridge Rd, London, W7 3TH	Hanwell	Hanwell Broadway	This section should probably be addressed as a priority as it is steeply inclined and only requires a short link to the 24 hour bus lane.	1	1		1	1		1			1				1						1								
1530	I'm always careful at this junction as it is narrow and often congested. I sometimes judge well ahead and decide to detour through Dean Gardens via Leeland Road providing opposing traffic is light enough to allow this right turn safely otherwise I stay put and negotiate the junction instead.	1	1/5/2023	https://www.google.com/maps/place/51.510858171320436%2C-0.3198486422279423/@51.510858171320436,-0.3198486422279423,17	6 Broadway Ealing, London, W13 0SR	West Ealing	Hanwell Broadway / Walpole	Dean Garden / Lido hotspot junction	1			1	1			1		1								1					1					
1531	When heading West under the Iron Bridge, it would be useful to have a green cyclists only light to provide a head start from the motorised vehicles to clear the junction and take the primary position in the narrow section directly under the bridge.	1	1/5/2023	https://www.google.com/maps/place/51.50924407545931%2C-0.3535499347461557/@51.50924407545931,-0.3535499347461557,17	Iron Bridge, Uxbridge Rd, Southall UB1 3EG	Iron Bridge	Norwood Green	This would be helpful if westbound in particular a cycle phase (possibly on request) could be established.	1		1	1	1			1		1										1			1					
1532	Connection from path from Gordon Road to railway station and then onto Uxbridge Road. Currently not sure if we can go on footpath or wrong way on one way street etc.	1	1/5/2023	https://www.google.com/maps/place/51.51491963824194%2C-0.30247252251457635/@51.51491963824194,-0.30247252251457635,1	Central Buildings, The Broadway, London, W5 2NT	Ealing Broadway	Ealing Broadway	Agreed - this is not clear and should be addressed alongside accessing the cycle parking. With the current (poor) infrastructure this will most likely require cyclists to	1	1		1	1		1							1				1										
1533	Make cycle and footpath please	1	1/5/2023	https://www.google.com/maps/place/51.513051443040354%2C-0.3387943190414977/@51.513051443040354,-0.3387943190414977,17	22 Greenford Ave, London W7 3QP	Hanwell	North Hanwell / Hanwell Broadway	Believed to be Greenford Ave / Church Road	1			1	1		1	1										1										
1534	Please can we connect Haven Green to Pitzhanger	1	1/5/2023	https://www.google.com/maps/place/51.51724021118695%2C-0.3077426948225148/@51.51724021118695,-0.3077426948225148,17	7 Blakesley Ave, London W5 2DN	Ealing Broadway	Ealing Broadway / Pitshanger	Lack of route - existing routes take you east or west of Pitshanger Lane. Eaton Rise would be the obvious link partly owing to the challenges related to Castlebar Hill	1			1			1	1										1										
1535	Good improvement here but all of Acton High Street is horrible to cycle as too many trucks park and block cycle path East. West has nothing through High Street.	1	1/5/2023	https://www.google.com/maps/place/51.50839517205883%2C-0.2749540675819939/@51.50839517205883,-0.2749540675819939,17	201 High St, London, W3 9DD	Acton	South Acton	Switched location to the high street area rather than the roundabout which they feel is better. Patchy segregation and cycle lane parking are the concerns	1			1				1										1		1								
1536	Road North /South is horrible to cycle.	1	1/5/2023	https://www.google.com/maps/place/51.53737263771453%2C-0.345724535721621/@51.53737263771453,-0.345724535721621,17z	1147-1149 Greenford Rd, Greenford UB6 0DP	Greenford Roundabout	Greenford	No infrastructure on Greenford Road north of Greenford Roundabout until the segregated section (c87 is broadly parallel but also lacks infrastructure). Heading	1			1				1										1										
1537	Unsafe with buses	1	1/5/2023	https://www.google.com/maps/place/51.51019932486023%2C-0.34640041289748735/@51.51019932486023,-0.34640041289748735,1	445A Uxbridge Rd, Southall UB1 3ET	Ealing Hospital	Norwood Green	Shared bus lanes.	1			1				1		1										1								
1538	I would dispute that many of the lines on the map are routes that make any concession for cyclists at all. Cycling along one "quiet residential street" is much like another, as motorised traffic behaves the same on all of them, making cyclists vulnerable to cars speeding, coming too close, pulling out in front of them etc. And our residential streets are being used more and more as	1	2/5/2023	https://www.google.com/maps/place/51.506632407814124%2C-0.3106901316865107/@51.506632407814124,-0.3106901316865107,17	57 Culmington Rd, London,	Ealing	Various	They have selected the Lammas / Culmington hotspot by way of example for the general point lack of cycle infrastructure / segregation owing to poor driver	1			1	1			1										1	1	1	1						1	
1539	What do you do at the end of it? Is there a safe transition?	1	2/5/2023	https://www.google.com/maps/place/51.50480414651428%2C-0.35566732079141294/@51.50480414651428,-0.35566732079141294,1	Three Bridges, Grand Union Canal, Windmill	Three Bridges	Norwood Green	No safe transition from the canal path to routes in any direction. On suggestions list.	1			1	1		1	1					1					1										
1540	I cycle along Madeley Road on my commute to work. I was unaware it is a designated cycle route. As far as I have experienced there are no particular provisions to make it safer for cycling. I can't understand how you can claim it as a cycle route.	1	2/5/2023	https://www.google.com/maps/place/51.51659053416286%2C-0.29668929892076257/@51.51659053416286,-0.29668929892076257,1	35b Madeley Rd, London, W5 2LS	Ealing Broadway - West Acton	Hanger Hill	Agreed - lack of cycle infrastructure on key route. On suggestions as part of improving this east - west route	1			1	1		1	1										1			1							
1541	For a safe journey, the cycle routes need to connect. So often it seems that a council does something great like putting in a segregated cycle lane, but then when it gets to a tricky bit, where maybe there isn't space, or there is a junction to navigate, the cyclist is left high and dry with no safe provision.	1	2/5/2023	https://www.google.com/maps/place/51.52379287487636%2C-0.29837525915362484/@51.52379287487636,-0.29837525915362484,1	16 West Rd, London, W5 2QL	Montpelier	Ealing Broadway / Hanger Hill	No real reason why the road section of West Road isn't included on the LB Ealing map (it is on cyclestreets). Infrastructure could be added to West Road as well as	1			1			1	1										1	1		1							
1542	Uxbridge Road is always unpleasant to cycle along. More segregation would help (with same rights of way as main carriageway so cyclists don't haev to stop at every side road). This map has shown me analternative route running south of Uxbridge Road which I might try now.	1	2/5/2023	https://www.google.com/maps/place/51.511766667794035%2C-0.3599189611346221/@51.511766667794035,-0.3599189611346221,17	Bridge Garage, Uxbridge Rd, Southall UB1 3DD	Dormers Wells	Dormers Wells / Southall Broadway / Norwood Green	Increase Uxbridge segregation	1			1			1	1		1										1								
1543	I often cycle to Park Royal, either from Ealing or from Chiswick. Crossing the A4 and getting through the traffic system around North Acton station is a bit of a nightmare, and takes a long time, and getting back again is confusing as one has to go a different way. Some kind of cycling and pedestrian overpass would probably be the ideal solution. A southwards cycle lane on Horn Lane would be	1	2/5/2023	https://www.google.com/maps/place/51.52237111295032%2C-0.26320615128268887/@51.52237111295032,-0.26320615128268887,1	1, Brett Villas, Park Royal Rd, North Acton London, W3 6XD	A40 North Acton	North Acton	General lack of infrastructure on Horn Lane as well as Park Royal & Victoria Roads - both of which are on suggestions tab.	1			1	1		1											1	1	1			1					
1544	I try to avoid cycling through Acton on the A4020 as it's narrow and busy and polluted - generally slow and unpleasant.	1	2/5/2023	https://www.google.com/maps/place/51.50923960076177%2C-0.27481266522103365/@51.50923960076177,-0.27481266522103365,1	227 High St, London, W3 9BY	Acton	South Acton	General Uxbridge Road in Acton. No clear action - it is likely to remain narrow / busy etc even with increased segregation										1																		
1545	St Leonard St at as cycling route to schools (NHEHS, St Bennedict)	1	2/5/2023	https://www.google.com/maps/place/51.51330472425485%2C-0.3141083508788478/@51.51330472425485,-0.3141083508788478,17	St Leonard's Rd, London, W5 2TU	Ealing Broadway	Ealing Broadway	hotspot lack of north - south connection across Uxbridge Road in Ealing and the mainline.	1			1	1		1	1		1								1										
1546			2/5/2023	https://www.google.com/maps/place/51.515147028159326%2C-0.3169221942239764/@51.515147028159326,-0.3169221942239764,17																																
1547	I have never noticed a cycle lane on The Avenue!	1	2/5/2023	https://www.google.com/maps/place/51.51709656459089%2C-0.31943274186191584/@51.51709656459089,-0.31943274186191584,1	74 The Avenue, London, W13 8LB	West Ealing	Ealing Broadway	Lack of clear signage / designation	1			1			1														1							
1548	Ealing Green is dangerous for cyclists. Cars driving very fast	1	2/5/2023	https://www.google.com/maps/place/51.50910345830505%2C-0.3052663512769338/@51.50910345830505,-0.3052663512769338,17	3 Ealing Grn, London, W5 5QS	Ealing Broadway	Ealing Broadway / Walpole / Ealing Common	Poor driver behaviour and lack of infrastructure on the main road.	1			1	1		1	1										1									1	
1549			2/5/2023	https://www.google.com/maps/place/51.516607731732144%2C-0.3076500668849347/@51.516607731732144,-0.3076500668849347,17																																
1550	Hard to avoid this main road when cycling around Ealing but quite dangerous due to overtakes on the hill section. I'd far sooner see cycling improvements here than St Stephen's where there isn't really a problem.	1	2/5/2023	https://www.google.com/maps/place/51.51840627487069%2C-0.31015439880459406/@51.51840627487069,-0.31015439880459406,1	62 Castlebar Rd, London, W5 2DD	Castlebar Hill	Ealing Broadway	Lack of cycle infrastructure linking Haven Green to the segregated section.	1			1				1						1				1										
1551	Very busy car junction where drivers aren't paying attention to cyclists	1	2/5/2023	https://www.google.com/maps/place/51.5149025324048%2C-0.3148066680069106/@51.5149025324048,-0.3148066680069106,17	86 Gordon Rd, London, W13 8PT	Ealing Broadway	Ealing Broadway / Walpole	Increasingly appears to be hotspot junction which should be reviewed alongside St Leonards Road (south) improvements.	1			1			1							1					1		1						1	
1552	With weaving path of road, and buses, it doesn't seem like a good place to have a cycle path compared to say woodville gardens.	1	2/5/2023	https://www.google.com/maps/place/51.51612381390869%2C-0.29887201173419475/@51.51612381390869,-0.29887201173419475,1	9 Madeley Rd, London, W5 2LA	Ealing Broadway	Hanger Hill	Woodville Gardens provides less clear east - west connectivity.	1			1														1										
1553	No way this is a safe cycle route. Why not divert more bikes along the grove and mattock?	1	2/5/2023	https://www.google.com/maps/place/51.51355545040523%2C-0.3033012501556076/@51.51355545040523,-0.3033012501556076,17	11 The Broadway, London, W5 2NH	Ealing Broadway	Ealing Broadway	Ideally both. (Both are displayed on LB Ealing map and cyclestreets map)	1			1	1			1		1								1										
1554	Cars speed up and down here, parked cars and bus stops on uphill, blind corner at top. Both end of that short cycle path on castlebar feel very unsafe. Would far sooner have better marked paths on side streets if proper infrastructure not possible on main road.	1	2/5/2023	https://www.google.com/maps/place/51.521847133394786%2C-0.31429613946319046/@51.521847133394786,-0.31429613946319046,1	12 Castlebar Hill, London, W5 1TD	Castlebar Hill	Ealing Broadway / Pitshanger	Existing double yellow lines at the top of the hill. Both ends of the cycle path are on the suggestions tab as are alternative side streets	1			1	1		1	1						1					1	1	1						1	
1555			2/5/2023	https://www.google.com/maps/place/51.50812502176363%2C-0.27435896652298286/@51.50812502176363,-0.27435896652298286,1																																
1556			2/5/2023	https://www.google.com/maps/place/51.50696940055114%2C-0.24555579342562917/@51.50696940055114,-0.24555579342562917,1																																
1557	Cycle lane combined with bus lane along route so lots of pollution behind buses and have to pull to go past buses. Also cars / vans parked across cycle lanes and yellow lines not policed.	1	2/5/2023	https://www.google.com/maps/place/51.51129922567713%2C-0.2912717617878613/@51.51129922567713,-0.2912717617878613,17	5 - 6, Station Buildings, 5 6 Uxbridge Rd, London, W5 3NU	Ealing Common	Ealing Common	Uxbridge Road cycle lane parking / shared with buses	1							1		1										1		1				1		
1558			2/5/2023	https://www.google.com/maps/place/51.52017621011503%2C-0.3099780756489978/@51.52017621011503,-0.3099780756489978,17																																
1559			2/5/2023	https://www.google.com/maps/place/51.51251210886048%2C-0.30897741329519945/@51.51251210886048,-0.30897741329519945,1																																
1560			2/5/2023	https://www.google.com/maps/place/51.52468144060411%2C-0.32341851732007765/@51.52468144060411,-0.32341851732007765,1																																
1561			2/5/2023	https://www.google.com/maps/place/51.5215867710887%2C-0.34530274673882033/@51.5215867710887,-0.34530274673882033,1																																
1562			2/5/2023	https://www.google.com/maps/place/51.51469693422491%2C-0.31440369888725783/@51.51469693422491,-0.31440369888725783,1																																
1563	castlebar road is very dangerous - the sidewalk is narrow and the cars do not respect the 20mph	1	2/5/2023	https://www.google.com/maps/place/51.518197990312544%2C-0.3101814270734371/@51.518197990312544,-0.3101814270734371,17	62 Castlebar Rd, Ealing, London, W5 2DD	Castlebar Hill	Ealing Broadway	Castlebar road lack of infrastructure	1			1				1						1				1									1	
1564	the potholes on Longfield Ave are very dangerous and make bikes unstable and difficult for children	1	2/5/2023	https://www.google.com/maps/place/51.514058564234716%2C-0.3083789826154293/@51.514058564234716,-0.3083789826154293,17	Longfield Ave, London W5 2TD	Ealing Broadway	Ealing Broadway	Beyond the newly paved section the general condition appears poor	1			1			1								1													
1565	the avenue is not safe in the current poor condition of the road - and cars do not respect bikes on the road -there's nothing to indicate to give space to bikes	1	2/5/2023	https://www.google.com/maps/place/51.51712978733832%2C-0.31966571815009726/@51.51712978733832,-0.31966571815009726,1	81 The Avenue, London, W13 8JS	West Ealing	Ealing Broadway	Increase signage / designation, no obvious cause for concern with road condition via Google Maps	1			1			1								1				1									
1566	A406 cycle lane is a great connection to Chiswick but its in a dreadful state - uneven and unpleasant - particularly for cargo bikes.	1	2/5/2023	https://www.google.com/maps/place/51.507552860151314%2C-0.29128925294150676/@51.507552860151314,-0.29128925294150676,1	10 Gunnersbury Ave, London, W5 3NJ	A406 Ealing Common	Ealing Common	The middle section north of the piccadilly line - appears poor in places mainly owing to utilities and tree routes	1			1			1								1													
1567	the B455 and Madeley road roundabout is very unsafe to take from any direction with a bike - needs a bike lane or signals for cars to respect bikes	1	2/5/2023	https://www.google.com/maps/place/51.516274280271396%2C-0.3031338879512724/@51.516274280271396,-0.3031338879512724,17	21 Haven Grn, London, W5 2UP	Ealing Broadway	Ealing Broadway	hotspot area around Ealing Broadway - generally lack of infrastructure and poor connectivity across this roundabout in all directions	1			1			1	1						1				1									1	
1568			3/5/2023	https://www.google.com/maps/place/51.51085001144735%2C-0.3025630274262614/@51.51085001144735,-0.3025630274262614,17																																
1569			3/5/2023	https://www.google.com/maps/place/51.507311405443275%2C-0.3116328062611906/@51.507311405443275,-0.3116328062611906,17																																
1570			3/5/2023	https://www.google.com/maps/place/51.502449717906295%2C-0.30991619249165936/@51.502449717906295,-0.30991619249165936,1																																
1571			3/5/2023	https://www.google.com/maps/place/51.50442651057943%2C-0.30214851518453045/@51.50442651057943,-0.30214851518453045,1																																
1572	The route is littered with broken glass and large vans are often parked on corners so you cannot see what is coming around the bend of Colville road	1	3/5/2023	https://www.google.com/maps/place/51.49912271221201%2C-0.2734422927786917/@51.49912271221201,-0.2734422927786917,17	3, 11 Colville Rd, London, W3 8BL	South Acton	South Acton	Street cleaning potentially (no clear cause for concern via Google. There are double yellow lines around all the corners therefore potentially an enforcement concern	1			1			1							1			1									1	1	
1573	Lack of cycle priority at traffic lights makes the junction unsettling during busy times	1	3/5/2023	https://www.google.com/maps/place/51.508901851591745%2C-0.27602317536501664/@51.508901851591745,-0.27602317536501664,1	281 High St, London, W3 9BP	Acton	North Acton / South Acton	Gunnersbury / Uxbridge junction hotspot	1			1	1			1		1								1					1					

1574	Uxbridge Road needs a proper segregated cycle lane across the borough, east to west. Just having sections isn't any use!	1	3/5/2023	https://www.google.com/maps/place/51.519503392238875%2C-0.3173395959020775/@51.519503392238875,-0.3173395959020775,17	143-145 Uxbridge Rd, London, W13 9AU	Uxbridge Road	Various	General Uxbridge Road segregation	1			1	1		1	1		1										1																			
1575	Cars ate parked continoisly in the cycle.lane they pull out without looking for cyclists oftenaking u turns	1	5/5/2023	https://www.google.com/maps/place/51.50662974480826%2C-0.25384656888525203/@51.50662974480826,-0.25384656888525203,1	123 The Vale, London, W3 7RQ	East Acton	East Acton / Southfield	Cycle lane parking / loading permitted at various times	1			1			1	1														1					1												
1576	Long sections along the Uxbridge Road need improving especially at Iron Bridge which is a major barrier to cycling	1	7/5/2023	https://www.google.com/maps/place/51.50974036065573 4%2C-0.354571034499326 9/@51.509740360655734,-0.3545710344993269,17	Iron Bridge, Uxbridge Rd, Southall UB1 3EG	Iron Bridge	Norwood Green / Southall Broadway / Dormers Wells	General Uxbridge Road improvements	1			1			1	1		1								1		1			1																
1577	There is a missing link in the cycle network here - a south to north route past Ealing Broadway station on the east side of Haven Green	1	7/5/2023	https://www.google.com/maps/place/51.5149217516 4855%2C-0.3019568224631941/@51.51492175164855,-0.3019568224631941,17	Ealing Broadway Station, London, W5 2NU	Ealing Broadway	Ealing Broadway	Ealing Broadway hotspot - lack of cycle infrastructure	1			1	1		1	1										1																					
1578	Lady Margaret Road is meant to be a cycle route, but the cycle lanes are dangerously close to parked vehicles and not wide enough. Given the level of traffic it should have proper segregated lanes.	1	7/5/2023	https://www.google.com/maps/place/51.52043929524858%2C-0.3749329429942305/@51.52043929524858,-0.3749329429942305,17	240-212 Lady Margaret Rd, Southall UB1 2RU	Lady Margaret	Lady Margaret / Dormers Wells	Lack of segregation on Lady Margaret which is wide and could accommodated segregation as well as parking	1			1				1												1																			
1579	Most of the "cycle route" alongside the A406 is sub-standard shared path and not wide enough for comfortable safe cycling. There is no phase at the traffic lights here for pedestrians and cyclists to cross the junction with Madeley Road.	1	7/5/2023	https://www.google.com/maps/place/51.5167540704 6587%2C-0.2912480217295821/@51.51675407046587,-0.2912480217295821,17	35 Hanger Ln, London, W5 3HJ	North Ealing	Ealing Common / Hanger Hill	Maddeley / A406 / Queens Drive hotspot - no cycle infrastructure except north - south on the west side of the A406	1			1	1			1			1							1					1																
1580	The tunnel under the railway here is too narrow for shared-use by pedestrians and cyclists. The railway through Southall is a big barrier to cycling in the area as there aren't any crossing points that most people would feel comfortable cycling on. The tunnel between the Straight and Dudley Road is currently closed, South Road is too busy with motor traffic and doesn't have any cycle	1	7/5/2023	https://www.google.com/maps/place/51.5077801023 5585%2C-0.3665215355235274/@51.50778010235585,-0.3665215355235274,17	200 Park Ave, Southall UB1 3AN	Southall	Southall Broadway / Norwood Green	Difficult to improve all of these routes.	1			1				1		1								1						1									1						
1581	I would like my children to be able to cycle down Elthorne Park Road on their way to school and the park. Leighton Road and EPR (they are dangerous at the moment due to the high volume of traffic) would be a great quiet way route between Northfields and Boston Manor.	1	9/5/2023	https://www.google.com/maps/place/51.5028490186 9466%2C-0.3300936367688023/@51.50284901869466,-0.3300936367688023,17	21 Elthorne Park Rd., London, W7 2JB	Hanwell	Hanwell Broadway / Northfield / Walpole	Elthorne / Leighton is a known rat run	1			1			1	1						1				1											1										
1582			9/5/2023	https://www.google.com/maps/place/51.5134063318 04404%2C-0.3041709417444727/@51.513406331804404,-0.3041709417444727,17																																											
1583			9/5/2023	https://www.google.com/maps/place/51.5166514083 64204%2C-0.3063832392908483/@51.516651408364204,-0.3063832392908483,17																																											
1584			9/5/2023	https://www.google.com/maps/place/51.5080497976 5655%2C-0.3054097091461294/@51.50804979765655,-0.3054097091461294,17																																											
1585			9/5/2023	https://www.google.com/maps/place/51.5115464477 17535%2C-0.31584167708399447/@51.511546447717535,-0.31584167708399447,1																																											
1586			9/5/2023	https://www.google.com/maps/place/51.5007983940 1192%2C-0.30621416674380564/@51.50079839401192,-0.30621416674380564,1																																											
1587			9/5/2023	https://www.google.com/maps/place/51.5126570046 4511%2C-0.336862600606167/@51.51265700464511,-0.336862600606167,17z																																											
1588			9/5/2023	https://www.google.com/maps/place/51.5132954383 4822%2C-0.3368707975529084/@51.51329543834822,-0.3368707975529084,17																																											
1589			9/5/2023	https://www.google.com/maps/place/51.5151083240 3473%2C-0.3372338624614257/@51.51510832403473,-0.3372338624614257,17																																											
1590			9/5/2023	https://www.google.com/maps/place/51.5159915547 7339%2C-0.33756527846080964/@51.51599155477339,-0.33756527846080964,1																																											
1591			9/5/2023	https://www.google.com/maps/place/51.5207845979 2267%2C-0.3393020531636637/@51.52078459792267,-0.3393020531636637,17																																											
1592	Need a cycle lane both directions up and down from Boston manor road To Uxbridge toad	1	9/5/2023	https://www.google.com/maps/place/51.5056336599 72204%2C-0.33601965535626555/@51.505633659972204,-0.33601965535626555,1	117 Boston Rd, London, W7 3SB	Boston Manor	Northfield / Hanwell Broadway	There is no cycle lane at all through this section.	1			1	1		1	1				1						1		1																			
1593	Feeling nervous at this roundabout. Always get off the bike	1	9/5/2023	https://www.google.com/maps/place/51.5088119302 1401%2C-0.3344598181082592/@51.50881193021401,-0.3344598181082592,17	Adam's Roundabout, London, W7 3FE	Hanwell	Hanwell Broadway	Nothing on this roundabout to support cyclists. hotspot	1			1	1		1	1		1								1																					
1594	Road surface, west bound in particular, is dreadful. And please get rid of the wands, again, westbound in particular. Just dangerous.	1	9/5/2023	https://www.google.com/maps/place/51.5073438933 2047%2C-0.2535409496584462/@51.50734389332047,-0.2535409496584462,17	115 The Vale, London, W3 7RQ	East Acton	East Acton / Southfield	No obvious westbound concerns through this section and most people have been requesting more wants rather than less	1			1			1			1					1																			1					
1595			9/5/2023	https://www.google.com/maps/place/51.5301492151 64656%2C-0.293378625575613 2/@51.530149215164656,-0.2933786255756132,17																																											
1596			9/5/2023	https://www.google.com/maps/place/51.5157034394 2201%2C-0.2586601120868437/@51.51570343942201,-0.2586601120868437,17																																											
1597			9/5/2023	https://www.google.com/maps/place/51.5118419545 9028%2C-0.2913769261595123/@51.51184195459028,-0.2913769261595123,17																																											
1598	Previously wide entrance for cycling lane is good. Recent roadwork blocked the cycling lane, forcing cyclists to use pedestrian walk which is only wide enough for one bicycle or one pedestrian, making more congestion at this busy corner with many users from both directions. The roadwork almost finished but I saw previous cycling lane becomes all width of a few metres paved for	1	9/5/2023	https://www.google.com/maps/place/51.5151251983 9777%2C-0.3051669621499453/@51.51512519839777,-0.3051669621499453,17	5 Haven Grn, London, W5 2UU	Ealing Broadway	Ealing Broadway	Gordon Road / Haven Green hotspot	1			1	1		1												1	1			1																
1599	There are always many cars parked on, and therefore blocked the cycle lane, at Uxbridge road from Ealing Common station to Twyford Gardens.	1	9/5/2023	https://www.google.com/maps/place/51.5100721249 0998%2C-0.2874506441642666/@51.51007212490998,-0.2874506441642666,17	437b Uxbridge Rd, London, W5 3NT	Ealing Common - Acton	Ealing Common / North Acton	There is a section West of Twyford Gardens which is unsegregated but the permitted cycle lane parking / loading does not appear to be needed.	1			1			1			1										1		1																	
1600	There are only 1 parking rail at the junction of Hereford Road/ Weymouth Avenue. This is far from enough for use for students for Little Ealing Primary School nearby. Students has to fight for parking rails every school. In order to secure a parking space there, they must arrive before 8am. For your information, the school gates open at 8:30am. If students arrive after 8am, it is very likely rail are	1	9/5/2023	https://www.google.com/maps/place/51.4988533886 22095%2C-0.30907912759821965/@51.498853388622095,-0.30907912759821965,1	41 Weymouth Ave, London W5 4SB	South Ealing	Northfield	Little Ealing School - lack of cycle parking hotspot	1			1	1	1		1																	1														
1601	There are only 1 parking rail at the junction of Temple Road/ Weymouth Avenue. This is far from enough for use for students for Little Ealing Primary School nearby. Students has to fight for parking rails every school. In order to secure a parking space there, they must arrive before 8am. For your information, the school gates open at 8:30am. If students arrive after 8am, it is very likely rail are	1	9/5/2023	https://www.google.com/maps/place/51.4984485292 9933%2C-0.30840608074732767/@51.49844852929933,-0.30840608074732767,1	35 Temple Rd, London, W5 4SL	South Ealing	Northfield	Little Ealing School - lack of cycle parking hotspot	1			1	1	1		1																	1														
1602			9/5/2023	https://www.google.com/maps/place/51.5411979992 8781%2C-0.3695488914288081/@51.54119799928781,-0.3695488914288081,17																																											
1603			9/5/2023	https://www.google.com/maps/place/51.5001234846 0234%2C-0.3183071240326707/@51.50012348460234,-0.3183071240326707,17																																											
1604			9/5/2023	https://www.google.com/maps/place/51.5260596616 9139%2C-0.3465748163020854/@51.52605966169139,-0.3465748163020854,17																																											
1605	Uxbridge road between Hanwell and Southall along Ealing hospital is a death trap. I work in Southall and would love to cycle to work but it is simply too dangerous. The short stretch of a cycle lane on one side of the iron bridge comes to an end very suddenly and in front of the hospital there is no protection at all. Cyclists compete for road space with busses and lorries and are very vulnerable.	1	9/5/2023	https://www.google.com/maps/place/51.5090993228 6856%2C-0.34883468523237315/@51.50909932286856,-0.34883468523237315,1	401 Uxbridge Rd, Southall UB1 3EW	Ealing Hospital	Norwood Green	Lack of cycle lanes and segregation	1			1	1		1	1		1										1																			
1606	Boston road needs to have safe cycle paths along the whole way.	1	9/5/2023	https://www.google.com/maps/place/51.5026172121 8381%2C-0.33149688616010753/@51.50261721218381,-0.33149688616010753,1	199 Boston Rd, London, W7 2AA	Boston Manor	Northfield / Hanwell Broadway	Boston Road segregation	1			1	1			1				1								1																			
1607	Argyle Road is not safe for cycling	1	9/5/2023	https://www.google.com/maps/place/51.5158609448 38515%2C-0.3211482251233799/@51.515860944838515,-0.3211482251233799,17	46 Argyle Rd, London, W13 8AA	West Ealing	Pitshanger / Ealing Broadway	Lack of cycle infrastructure	1			1			1	1						1				1																					
1608	Cycling along the Uxbridge Road in Ealing Broadway is not safe.	1	9/5/2023	https://www.google.com/maps/place/51.5140983060 5859%2C-0.3008921826429112/@51.51409830605859,-0.3008921826429112,17	5 The Mall, Ealing, London, W5 2PJ	Ealing Broadway	Ealing Broadway	Ealing Broadway - lack of cycle infrastructure	1			1	1		1	1		1								1																					
1609	Poor quality surfacing. Lane is narrow with bollards which prevent parking but also makes challenging for cycling.	1	9/5/2023	https://www.google.com/maps/place/51.5064739564 88385%2C-0.2704288583017611/@51.506473956488385,-0.2704288583017611,17	33 Church Rd, London, W3 8PU	Acton	South Acton	Church Road cycle path surface is poor in places.	1			1			1								1									1															
1610	Poor surfacing with pot holes.	1	9/5/2023	https://www.google.com/maps/place/51.5135136179 82944%2C-0.303475241603377/@51.513513617982944,-0.303475241603377,17z	11A The Broadway, London, W5 2NH	Ealing Broadway	Ealing Broadway	Road surface generally poor through this section	1			1	1		1			1					1																								
1611	More signage needed	1	9/5/2023	https://www.google.com/maps/place/51.5088273085 76215%2C-0.2683357181067314/@51.508827308576215,-0.2683357181067314,17	82 Churchfield Rd, London, W3 6DH	Acton Central	South Acton	C41 - General lack of signage / designation / infrastructure on Churchfield.	1			1			1	1										1			1																		
1612	More segregation required.	1	9/5/2023	https://www.google.com/maps/place/51.5082860909 63885%2C-0.27862699545645686/@51.508286090963885,-0.27862699545645686,1	327 Uxbridge Rd, London, W3 9RA	Ealing Common - Acton	Ealing Common / North Acton	Most eastbound sections east of the Ealing Common shops are now segregated or bus lane. Westbound difficult to segregated unless pavement is narrowed	1			1				1		1										1																			
1613	Can only be used in daylight hours.	1	9/5/2023	https://www.google.com/maps/place/51.4977398557 45024%2C-0.3341368795689692/@51.497739855745024,-0.3341368795689692,17	Osterley Lock Weir, Grand Union Canal Walk, London, W7	Boston Manor (Canal)	Hanwell Broadway	No lighting no canal path	1			1			1						1		1																								
1614	All along boston Road from the Uxbridge Road to Boston Manor Station - no cycle route, parked cars, dangerous	1	9/5/2023	https://www.google.com/maps/place/51.5002671116 64655%2C-0.3279283069603056/@51.500267111664655,-0.3279283069603056,17	271 Boston Rd, London, W7 2AT	Boston Manor	Northfield / Hanwell Broadway	Boston Road lack of segregation, parking in cycle lanes	1			1	1		1	1				1		1				1		1		1																	
1615	Cycling anywhere along the Uxbridge road but specifically from the clock tower to Ealing Broadway is treacherous. I drive a 15 min journey to work rather than die under a bus by bike	1	9/5/2023	https://www.google.com/maps/place/51.5124452300 17995%2C-0.3098166232430333/@51.512445230017995,-0.3098166232430333,17	24-22 Uxbridge Rd, London, W5 5SA	Uxbridge Road Hanwell - Ealing	Hanwell Broadway / Walpole / Ealing Broadway	General Uxbridge Road	1			1	1					1				1						1																			
1616	Bus lanes are really uneven	1	10/5/2023	https://www.google.com/maps/place/51.5112104032 1716%2C-0.31813310422636576/@51.51121040321716,-0.31813310422636576,1	199B Uxbridge Rd, London, W13 9AA	West Ealing	Walpole	Some sections on bus lane / bus stops in West Ealing are poor but not at this specific location	1			1			1			1					1																								
1617	Cycle lane ends ubruptly and is really uneven	1	10/5/2023	https://www.google.com/maps/place/51.5086169585 0908%2C-0.29135167899149605/@51.50861695850908,-0.29135167899149605,1	1 Gunnersbury Ave, London, W5 3NH	Ealing Common	Ealing Common	A406 - cycle lane on the west side of the road ends at Warwick Road (on suggestions). Cycle lane surface appears fine on google but is likely to be	1			1			1	1			1				1			1																					
1618	I caught flat tire here because of bumps and it is really narrow even though it is walking/cycling	1	10/5/2023	https://www.google.com/maps/place/51.5054929750 41875%2C-0.29024581485013634/@51.505492975041875,-0.29024581485013634,1	37 Gunnersbury Ave, London, W5 3XD	Ealing Common	Ealing Common	This section is narrow and impacted by tree roots	1			1			1	1			1				1									1															
1619	Loads of bumps and holes on cycling lane towards Hanwell	1	10/5/2023	https://www.google.com/maps/place/51.5129123686 9663%2C-0.3084434605320552/@51.51291236869663,-0.3084434605320552,17	14 Uxbridge Rd, London, W5 2HL	Ealing	Ealing Broadway / Hanwell	Issues appear to mainly be westbound and particularly across the drop kerbs	1			1			1			1					1																								
1620	Motorcycles parking on both the single yellow lines and (illegal parking) on the zigzag lines adjacent to the pedestrian crossing outside the motorcycle shop make cycling unsafe and block the cycle line. The single yellow lines section should become no parking.	1	10/5/2023	https://www.google.com/maps/place/51.5060636852 31936%2C-0.33729248592566874/@51.506063685231936,-0.33729248592566874,1	48 Lower Boston Rd, London, W7 2NP	Boston Manor	Hanwell Broadway	Agreed	1			1	1		1					1							1			1				1													
1621	Vehicles parking here, cause unsafe passing for cyclists.	1	10/5/2023	https://www.google.com/maps/place/51.5058072228 4084%2C-0.3368657742118253/@51.50580722284084,-0.3368657742118253,17	68 Lower Boston Rd, London, W7 2ET	Boston Manor	Hanwell Broadway	Single Yellow lines just south of the Lower Boston Road one way split should be reconsidered owing to the proximity to the junction and availability of a side road	1			1	1		1					1							1	1		1																	
1622	What was a bike lane is all broken and not fit for purpose. Not observed by motorists, and often results in motorist overtaking too close to cyclist.	1	10/5/2023	https://www.google.com/maps/place/51.5043349515 35945%2C-0.33387977188388707/@51.504334951535945,-0.33387977188388707,1	165 Boston Rd, London, W7 3QJ	Boston Manor	Hanwell Broadway	Poor markings on the northern section of Boston Road	1			1	1		1					1							1																				
1623	The whole section of cycling on Boston Manor Road, to the north of Boston Manor Station is very poor for cyclists, the mixed cycling with motorists section where cycle markings were relatively recently applied to the road do nothing to help cyclists, and have faded already. It does not seem well thought out. The relatively recent work to join the north of Boston Manor Station	1	10/5/2023	https://www.google.com/maps/place/51.5002993316 7586%2C-0.32846102282494627/@51.50029933167586,-0.32846102282494627,1	269 Boston Rd, London, W7 2AT	Boston Manor	Northfield / Hanwell Broadway	Lack of segregation essentially and a feeling that the cross over is confusing	1			1	1		1	1				1							1	1			1																
1624			10/5/2023	https://www.google.com/maps/place/51.5015448839 8205%2C-0.3048853417802211/@51.50154488398205,-0.3048853417802211,17																																											
1625			10/5/2023	https://www.google.com/maps/place/51.5125309468 41515%2C-0.3109566279080811/@51.512530946841515,-0.3109566279080811,17																																											
1626			10/5/2023	https://www.google.com/maps/place/51.5112956777 8664%2C-0.3191963740018311/@51.51129567778664,-0.3191963740018311,17																																											
1627	The Uxbridge Road cannot, in good faith, be considered a safe cycle route. Too many parked cars/obstructions - often the restrictions are approprirate but are not enforced.	1	10/5/2023	https://www.google.com/maps/place/51.5105595145 6387%2C-0.3235046682273457/@51.51055951456387,-0.3235046682273457,17	72 Broadway, London, W13 0SY	West Ealing	Hanwell Broadway / Walpole	hotspot section west of deans gardens. Cycle lane 'loading' permitted and parking outside of daylight hours - should be reconsidered and enforced	1			1	1		1			1												1																	
1628	This route is too narrow to be safe - far too many close passes, fast traffic	1	10/5/2023	https://www.google.com/maps/place/51.5060956190 4233%2C-0.3097990854641641/@51.50609561904233,-0.3097990854641641,17	Park Sports Lammas Park, Ealing Culmington Rd, Greater, London,	Walpole	Walpole	Culmington hotspot between Lammas and Walpole - parking restrictions should be considered.	1			1	1		1											1						1															
1629	This section is awful. Absolutely not safe and I avoid this section when I can (and I cycle 5000km a year in London,)	1	10/5/2023	https://www.google.com/maps/place/51.5076754791 5295%2C-0.2724969763891649/@51.50767547915295,-0.2724969763891649,17	201 High St, London, W3 9DD	Acton	South Acton	Bus stop pinch point and lack of segregation at Acton Market Place	1			1	1		1	1		1				1					1	1																			
1630	The cycle access to Ealing Broadway station from the Uxbridge Road is inadequate. You have to cycle all the way round the green - which is not a safe route. Such a missed opportunity to build a counterflow from the Uxbridge Road when that pavement was resurfaced.	1	10/5/2023	https://www.google.com/maps/place/51.5149481493 7213%2C-0.3024654336439858/@51.51494814937213,-0.3024654336439858,17	Ealing Broadway Station, The Broadway, London, W5 2NU	Ealing Broadway	Ealing Broadway	hotspot - lack of access to Ealing Broadway station	1			1	1		1	1										1																					

1631	This section is far too busy with cut through traffic coming through and going up Florence Road to miss the lights at the top of the common. I cycle this daily with a cycle trailer with children - Florence Road needs traffic management to support the nursery there.	1	10/5/2023	https://www.google.com/maps/place/51.51136993146471%2C-0.29806458860493823/@51.51136993146471,-0.29806458860493823,1	125 The Grove, London, W5 3SL	Ealing Common	Ealing Common / North Acton	Certainly conceivable as a rat run. Worth considering additional measures.	1		
1632	The cycle lane on South Side of Ruislip Rd is often full of parked cars around school finish times, even though it's within the hours of mandatory operation, causing me to have to cycle in the middle of the lane or dodge around the parked cars. Please enforce, this is a mandatory cycle lane at certain times	1	10/5/2023	https://www.google.com/maps/place/51.52719752419769%2C-0.3424275327544013/@51.52719752419769,-0.3424275327544013,17	Drayton Manor Playing Field, Ealing	North Hanwell	North Hanwell	Parking in cycle lane - there does not appear to be any yellow line signage of the restrictions therefore at present it may not be enforceable. Additionally in	1		
1633	Segregated cycle lanes here are short and constantly interrupted. You're constantly exposed and shunted into traffic using them.	1	10/5/2023	https://www.google.com/maps/place/51.50705187730073%2C-0.2545311699279673/@51.50705187730073,-0.2545311699279673,17	143 The Vale, London, W3 7RH	Acton Park	East Acton / Southfield	Parking permitted in cycle lane overnight. Loading permitted outside of peak hours. Lots of shops etc through this section hence the permitted loading	1		
1634	Cycle lanes here are not segregated, and are constantly filled with parked cars. This makes you move into traffic to get around them.	1	10/5/2023	https://www.google.com/maps/place/51.50975348570789%2C-0.2859844166851566/@51.50975348570789,-0.2859844166851566,17	3-1 Uxbridge Rd, London,	Ealing Common - Acton	Ealing Common / North Acton	Parking permitted in cycle lane overnight. Loading permitted outside of peak hours	1		
1635	Cycle lane here is not segregated, and is constantly filled with (illegally) parked cars and motorcycles.	1	10/5/2023	https://www.google.com/maps/place/51.51318970412964%2C-0.3047498851249286/@51.51318970412964,-0.3047498851249286,17	1 New Broadway, London, W5 5AW	Ealing Broadway	Ealing Broadway	hotspot junction and cycle lane parking	1		
1636	There's too much heavy traffic to feel safe. Would only cycle on this route if it was segregated.	1	10/5/2023	https://www.google.com/maps/place/51.50080795318108%2C-0.2662365094825425/@51.50080795318108,-0.2662365094825425,17	236 Acton Ln, London, W4 5DL	Southfield	South Acton / Southfield	Lack of cycle infrastructure on Acton Lane - the section through the bridge needs attention as this is a key east west link and the only railway crossing	1		
1637	There's a safer back street route to Acton Main Line via Cumberland Park and Messaline Avenue. Unfortunately there are no cycle storage provision at Acton Main Line even though there is plenty of space for a facility.	1	10/5/2023	https://www.google.com/maps/place/51.517368216363465%2C-0.2664510862037339/@51.517368216363465,-0.2664510862037339,17	Acton Mainline Station, Horn Ln, London, W3 9EH	Acton Main Line	North Acton / East Acton	Acton Mainline cycle parking?	1		
1638	Uxbridge Road has too much heavy traffic to feel safe. There needs to be segregation.	1	10/5/2023	https://www.google.com/maps/place/51.50692526756855%2C-0.2667514936134019/@51.50692526756855,-0.2667514936134019,17	64 High St, London, W3 6LE	Acton	South Acton	Uxbridge Road segregation	1		
1639			11/5/2023	https://www.google.com/maps/place/51.51574913528177%2C-0.3344850096746521/@51.51574913528177,-0.3344850096746521,17							
1640	The route from hanwell to ealing broadway via argyle road / pitshanger could be improved upon - especially as they are particularly busy areas with many cars	1	11/5/2023	https://www.google.com/maps/place/51.5199187299881%2C-0.32289417844533874/@51.5199187299881,-0.32289417844533874,1	132 Argyle Rd, London, W13 8ER	West Ealing	Pitshanger / Ealing Broadway	New route parallel but Argyle Road would benefit from single yellow restrictions becoming 24 hour loading only	1		
1641	Need to link the cycle routes	1	11/5/2023	https://www.google.com/maps/place/51.51756583513635%2C-0.33151474753298826/@51.51756583513635,-0.33151474753298826,1	27A Browning Ave, London W7 1EW	Drayton Green	North Hanwell / Pitshanger	Lack of connected routes in the area - on suggestions tab	1		
1642	Cars park in the cycle lane	1	11/5/2023	https://www.google.com/maps/place/51.51197507646033%2C-0.3133094956452842/@51.51197507646033,-0.3133094956452842,17	54-58 Uxbridge Rd, London, W5 2ST	West Ealing Ealing Broadway	Ealing Broadway / Walpole	hotspot cycle lane parking - parking not needed	1		
1643	Busy road in front of station. Need a cycle lane to join the road	1	11/5/2023	https://www.google.com/maps/place/51.51494779686609%2C-0.30229496171819026/@51.51494779686609,-0.30229496171819026,1	Ealing Broadway Station, The Broadway, London, W5 2NU	Ealing Broadway	Ealing Broadway	Ealing Broadway / Haven Green hotspot	1		
1644	Isolated cycle lane on pavement... road above and below is narrow with aggressive drivers.	1	11/5/2023	https://www.google.com/maps/place/51.51958976176621%2C-0.3107122120815431/@51.51958976176621,-0.3107122120815431,17	74 Castlebar Rd, London, W5 2DD	Castle Bar Hill	Ealing Broadway	hotspot isolated cycle lane	1		
1645	Too many pot holes and breaking up road surface opposite Ealing Hospital and when coming down from Hanwell Clock tower towards Brent river and Ealing hospital. Cycle lanes need to be maintained. It's so dangerous especially in the dark □	1	11/5/2023	https://www.google.com/maps/place/51.50787845882331%2C-0.3435727107544495/@51.50787845882331,-0.3435727107544495,17	483 Uxbridge Rd, Southall UB1 3ET	Ealing Hospital	Hanwell Broadway / Norwood Green	Ealing Hospital hotspot	1		
1646	I wouldn't feel safe cycling along Uxbridge Road through Ealing as the existing cycle paths are insufficiently separated from traffic	1	14/5/2023	https://www.google.com/maps/place/51.51348162135626%2C-0.29680335100659816/@51.51348162135626,-0.29680335100659816,1	3 N Common Rd, London, W5 2QA	Ealing Common	Ealing Common	Uxbridge Road - increase segregation	1		
1647	The junctions off this cycle path seem really dangerous as there is no infrastructure to protect cyclists crossing junctions	1	14/5/2023	https://www.google.com/maps/place/51.52104662251983%2C-0.2916848755895485/@51.52104662251983,-0.2916848755895485,17	70 Hanger Ln, London, W5 2JH	Hanger Hill	Hanger Hill	Agreed - poor junctions and lack of crossing points but also TfL red route so complicated	1		
1648	The round about here is really dangerous and existing cycle infrastructure doesn't seem sufficient to make it safe	1	14/5/2023	https://www.google.com/maps/place/51.508292356278346%2C-0.27500924906633584/@51.508292356278346,-0.27500924906633584,1	259 High St, London, W3 9BY	Acton	North Acton / South Acton	Styne / Uxbridge Road hotspot roundabout	1		
1649	Why is there no safe cycle route to Acton Main Line?	1	14/5/2023	https://www.google.com/maps/place/51.5146490281612%2C-0.2697735770692655/@51.5146490281612,-0.2697735770692655,17	181 Horn Ln, London, W3 6PW	Acton Main Line	North Acton / East Acton / South Acton	Horn Lane / Acton Mainline hotspot - lack of infrastructure	1		
1650	The Vale / Uxbridge Rd has many parked cars in an incomplete cycle lane and is dangerous to cross. It holds our family with two children back from cycling more	1	14/5/2023	https://www.google.com/maps/place/51.507000355202436%2C-0.2479693194114363/@51.507000355202436,-0.2479693194114363,17	19 The Vale, London, W3 7SH	East Acton	East Acton	Uxbridge Road in East Acton. Parking in cycle lanes - probably not needed on the westbound side between Elizabeth Gardens and Cowley Road. Might be too	1		
1651	Old Oak Rd could be an important cycling connection to the cycle lane at Westway but is too dangerous to cycle on	1	14/5/2023	https://www.google.com/maps/place/51.50803849536119%2C-0.24567046479656796/@51.50803849536119,-0.24567046479656796,1	15 Old Oak Rd, London, W3 7HN	East Acton / Shepherds Bush	East Acton / Shepherds Bush	An inevitable route rather than an good one - lack of cycle infrastructure but difficult to add	1		
1652	The cross between the Vale and Old Oak Rd is very dangerous. Can you do something to improve it please?	1	14/5/2023	https://www.google.com/maps/place/51.50688992002658%2C-0.24528422669842342/@51.50688992002658,-0.24528422669842342,1	4a The Vale, London, W3 7SB	East Acton / Shepherds Bush	East Acton / Shepherds Bush	Borough boundary. Road condition and cycle infrastructure is poor	1		
1653	East Acton Ln should be a safe road to get to Acton Park but instead is a race track for cars	1	14/5/2023	https://www.google.com/maps/place/51.507450855784%2C-0.25687136964275936/@51.507450855784,-0.25687136964275936,1	301 E Acton Ln, London, W3 7EH	Acton Park	East Acton	East Acton Lane provides the connection to C41 and c49 - particularly at night when the park is closed. If all of the parking was limited the east side of the road then an	1		
1654	This road is dangerous and needs cycling facilities urgently	1	14/5/2023	https://www.google.com/maps/place/51.50771796562229%2C-0.2510777981705914/@51.50771796562229,-0.2510777981705914,17	254 Bromyard Ave, London, W3 7BS	East Acton	East Acton	Marked on both Ealing and Cyclestreets maps but no clear designation or signage including in relation to the contraflow on Ashfield Road. This forms a clear Uxbridge	1		
1655	Please use proper protection all the way along the Uxbridge Road AND reduce junction movements with the side roads all the way along too (Low Traffic Neighbourhood safety wins are considerable in this context). The side road junctions are really unsafe at the moment, far too much other traffic. Your cycle network won't work unless you actively reduce motor traffic too and Ealing has the	1	16/5/2023	https://www.google.com/maps/place/51.51251808684136%2C-0.29543369013897536/@51.51251808684136,-0.29543369013897536,1	4 The Common, London, W5 3TR	Ealing Common	Ealing Common	All of Uxbridge Road therefore this junction is an example - poor cycle lane designation / segregation. General request for reducing road traffic considering	1		General reduction in traffic in favour of Active / Public transport
1656	Please complete the protection on this cycle route. It's direct and easy to use but not safe enough yet.	1	16/5/2023	https://www.google.com/maps/place/51.525122561789615%2C-0.35294025141827223/@51.525122561789615,-0.35294025141827223,1	137 Greenford Rd, Greenford UB6 9BD	Greenford	Dormer Wells / Greenford Broadway	Greenford Road lack of cycle infrastructure / segregation	1		
1657	Routes through parks don't count! they're not usable in darkness which puts afternoon school/work travel out of the question in the winter. Please do more on streets.	1	16/5/2023	https://www.google.com/maps/place/51.52052980963361%2C-0.34744708735577223/@51.52052980963361,-0.34744708735577223,1	Mayfield Primary School, High Ln, London, W7 3RT			C87 - Greenford Road link. Should be considered for an upgrade including lighting to provide a key east - west link. On emerging suggestions as Brent Valley Park Connection	1		
1658	Sort out junctions like this one at the lower end of Greenford Road. I appreciate that the rail bridge creates serious constraints, but you can do much better to create more direct routes, safer space, separated space OR movement to enable cycles to move safely through the junction in any direction.	1	16/5/2023	https://www.google.com/maps/place/51.51027455192177%2C-0.3541418810569441/@51.51027455192177,-0.3541418810569441,17	Iron Bridge, Uxbridge Rd, Southall UB1 3EG	Iron Bridge	Norwood Green / Southall Broadway / Dormers Wells	Iron Bridge hotspot and the junctions around it	1		
1659	The A40 route is unsafe and very poorly maintained. I actually thought this was in Hillingdon because it is so bad... links at Northolt are not good, barriers on the route under the Target roundabout are discriminatory.	1	16/5/2023	https://www.google.com/maps/place/51.54679836955006%2C-0.3848692675315535/@51.54679836955006,-0.3848692675315535,17	157 Islip Manor Rd, Northolt UB5 5EE	Northolt	Northolt West End / Northolt Mandeville	No obvious cause for concern with the A40 route here (basic but fine). Target Roundabout barriers should be assessed as likely to be too difficult for larger bikes	1	1	
1660	Quiet ways are not a huge problem - but segregated routes on busy roads /river pathways need improving	1	16/5/2023	https://www.google.com/maps/place/51.52248526404396%2C-0.3146500587782053/@51.52248526404396,-0.3146500587782053,17	12 Castlebar Hill, London, W5 1TE	Castle Bar Hill	Ealing Broadway	General request for canal improvements and increase segregation on busy roads	1		
1661			16/5/2023	https://www.google.com/maps/place/51.51432542266664%2C-0.32163303287468414/@51.51432542266664,-0.32163303287468414,1							
1662	Cars pass too close and too fast along here. Needs segregation	1	16/5/2023	https://www.google.com/maps/place/51.51690806016339%2C-0.29663108566013063/@51.51690806016339,-0.29663108566013063,1	35 Madeley Rd, London, W5 2LS	Ealing Broadway	Ealing Broadway	Madeley Road is on suggestions tab as a key connecting route currently lacking infrastructure.	1		
1663	This is a really dangerous junction	1	16/5/2023	https://www.google.com/maps/place/51.5224538291444%2C-0.2732547887765069/@51.5224538291444,-0.2732547887765069,17	1 Highfield Rd, London, W3 0AJ			Connecting route for cyclists but a tricky offset junction with 5 roads. A clear cycle lane along the junction continuing straight between Saxon Drive and Northfield	1		
1664	Does not feel safe here	1	16/5/2023	https://www.google.com/maps/place/51.52050624341532%2C-0.2642054355234036/@51.52050624341532,-0.2642054355234036,17	322 Horn Ln, London, W3 6TH	North Acton	North Acton	Cycle / Bus lane ends leaving cyclists just a narrow painted cycle lane to contend with the 5 lane junction ahead.	1	1	
1665			16/5/2023	https://www.google.com/maps/place/51.51263132286213%2C-0.2913573990691676/@51.51263132286213,-0.2913573990691676,17							
1666	Feels dangerous here	1	16/5/2023	https://www.google.com/maps/place/51.51357653585038%2C-0.3034852420161349/@51.51357653585038,-0.3034852420161349,17	11A The Broadway, London, W5 2NH	Ealing Broadway	Ealing Broadway	Uxbridge Road Ealing Broadway hotspot - generally poor or lacking cycle infrastructure	1		
1667	Parking along bicycle lane,	1	16/5/2023	https://www.google.com/maps/place/51.510213898289514%2C-0.28333156306378005/@51.510213898289514,-0.28333156306378005,1	364 Uxbridge Rd, London, W3 9SL	Ealing Common - Acton	Ealing Common / North Acton	Seemingly referring to the unsegregated section immediately following the bus stop which has presumably been kept clear owing to the post box (ie			
1668	Cycle lane moves on to path then abruptly stops at junction and back onto road. very disjointed and should probably form part of road the entire way	1	16/5/2023	https://www.google.com/maps/place/51.513581569666876%2C-0.29538291308265574/@51.513581569666876,-0.29538291308265574,1	7a N Common Rd, London, W5 2QA	Ealing Common	Ealing Common	Segregated path along North Side of Ealing Common confusion. On suggestions tab	1		
1669	road layout means single lane suddenly becomes 2 with cyclists typically penned in by left turning vehicles unless "lane is taken"	1	16/5/2023	https://www.google.com/maps/place/51.50340311156563%2C-0.2800363007148299/@51.50340311156563,-0.2800363007148299,17	3, Central Parade, Gunnersbury Ln, London, W3 8HL	Acton Town	South Acton	westbound towards Acton Town station. Very poor lane markings on approach to the roundabout and no cycle infrastructure	1		Poor lane markings for all users
1670			16/5/2023	https://www.google.com/maps/place/51.500952015322135%2C-0.27693717677227614/@51.500952015322135,-0.27693717677227614,1							
1671			16/5/2023	https://www.google.com/maps/place/51.50137945126749%2C-0.2910134096824324/@51.50137945126749,-0.2910134096824324,17							
1672			16/5/2023	https://www.google.com/maps/place/51.49646369585161%2C-0.2637192507468855/@51.49646369585161,-0.2637192507468855,17							
1673	This is one of the few nice places to cycle in Ealing as it's car free and quite quiet	1	16/5/2023	https://www.google.com/maps/place/51.49675718111137%2C-0.3020361088846424/@51.49675718111137,-0.3020361088846424,17	15 Chilton Ave, London, W5 4RU	South Ealing	Northfield	Positive			
1674	Ruislip Road East and Ruislip Road can be improved. Vehicular traffic is fast and there is not enough space on the road to feel safe. Uxbridge Road from Hanwell to Southall feels unsafe, particularly around the Iron Bridge. Greenford Road from Ealing Hospital to A40 and then to William Perkin HS could be improved.	1	16/5/2023	https://www.google.com/maps/place/51.528273135492796%2C-0.35860507685772536/@51.528273135492796,-0.35860507685772536,1	41 Ruislip Rd, Greenford UB6 9QD	Greenford	Dormers Wells / Greenford Broadway / Central Greenford	Ruislip Road - agreed and on Emerging suggestions. Iron Bridge hotspot. Link between William Perkin and Greenford Roundabout is poor and should be improved	1	1	
1674.1		1			William Perkin Church of England High School,			Additional location for previous log	1	1	
1675	Road surface is dangerously poor.	1	16/5/2023	https://www.google.com/maps/place/51.51079876189457%2C-0.31276101191554995/@51.51079876189457,-0.31276101191554995,1	32 Mattock Ln, London, W5 5BH	Walpole	Walpole	Agreed - Mattock appears poor on Google Maps in Jan 2021	1	1	
1676	Road surface is dangerously poor.	1	16/5/2023	https://www.google.com/maps/place/51.51565955864457%2C-0.3194558056167218/@51.51565955864457,-0.3194558056167218,17	49 The Avenue, London, W13 8JR	West Ealing	Ealing Broadway	Arlington - Gordon on The Avenue does appear poor owing to utilities	1		
1677	Road surface travelling East is extremely bad, so much so that I now choose other routes. Travelling west is just about ok but is getting worse.	1	16/5/2023	https://www.google.com/maps/place/51.516701090468466%2C-0.3208290966323468/@51.516701090468466,-0.3208290966323468,17	9 Sutherland Ave, London, W13 8LE	West Ealing	Ealing Broadway / Pitshanger	Agreed - some poor areas on this stretch (mainly around utilities)	1		
1678	Road surface is extremely poor - to the point of being unsafe to ride on, especially going east	1	16/5/2023	https://www.google.com/maps/place/51.515205550139825%2C-0.3068816097549054/@51.515205550139825,-0.3068816097549054,17	16 Gordon Rd, London, W5 2AD	Ealing Broadway / West Ealing	Ealing Broadway	Some sections of Gordon Road are poor	1		
1679	This is the missing link! This is crying out for a two-way route with a suface that is good enough to cycle on. Current road surface is dangerously potholed. This should be fixed now the station construction has been finished.	1	16/5/2023	https://www.google.com/maps/place/51.514698123514705%2C-0.3021609218886945/@51.514698123514705,-0.3021609218886945,17	Ealing Broadway Station, The Broadway, London, W5 2NU	Ealing Broadway	Ealing Broadway	Bus stop + through traffic + loading + two way segregated is challenging but clearly would be helpful	1		
1680			16/5/2023	https://www.google.com/maps/place/51.506222394252426%2C-0.26473826187782157/@51.506222394252426,-0.26473826187782157,1							
1681			16/5/2023	https://www.google.com/maps/place/51.510263828967304%2C-0.2903593372442015/@51.510263828967304,-0.2903593372442015,17							
1682			16/5/2023	https://www.google.com/maps/place/51.5150071096425%2C-0.30272514143407925/@51.5150071096425,-0.30272514143407925,1							
1683			16/5/2023	https://www.google.com/maps/place/51.520122081224976%2C-0.31070940727049967/@51.520122081224976,-0.31070940727049967,1							
1684	It's a deathtrap, going from two car lanes to only the left one going straight on. I was a witness to the immediate aftermath of that lady who died under a lorry a few years ago and absolutely nothing has been done here. More generally, it's an embarrassment that the Uxbridge Road is marked as a cycle route on here. It's amongst the worst piece of infrastructure I've seen on my commute to London,	1	16/5/2023	https://www.google.com/maps/place/51.511172815768695%2C-0.31914686202021647/@51.511172815768695,-0.31914686202021647,1	162 Uxbridge Rd, London, W13 8JL	West Ealing	Hanwell Broadway / Walpole	Deans Garden / Lido hotspot junction	1		
1685	It's an embarrassment that the Uxbridge Road is marked as a cycle route on here. It's amongst the worst piece of infrastructure I've seen on my commute to London, from Hanwell. The fact that people are able to park on it at the weekends and evenings is such a bad decision it's almost funny. And it's such an easy fix to make.	1	16/5/2023	https://www.google.com/maps/place/51.512761966415944%2C-0.3088793659112077/@51.512761966415944,-0.3088793659112077,17	14 -16 Uxbridge Rd, London, W5 2HL	Ealing Broadway / West Ealing	Ealing Broadway / Walpole	Agreed - parking not needed in this section	1		
1686	People are allowed to park over the cycle lane which is silly. There's plenty of room for a two way segregated cycleway here as well, especially up until Elthorne Park seeing as the houses there all have driveways. It shouldn't be the general public's fault that people have more cars than will fit on their driveway.	1	16/5/2023	https://www.google.com/maps/place/51.4989127070941%2C-0.32765225326692127/@51.4989127070941,-0.32765225326692127,1	301 Boston Rd, Ealing, London W7 2AT	Boston Manor	Northfield / Hanwell Broadway	Boston Road - cycle lane parking and lack of segregation	1		

1687	Terribly unsafe	1	16/5/2023	https://www.google.com/maps/place/51.53673593633272%2C-0.347765560514417/@51.53673593633272,-0.347765560514417,17z	5 Karoline Gardens, Western Ave, Greenford UB6 9JP	Greenford	Central Greenford	Shared path but designation is very poor	1			1			1												1																				
1688	The whole of the Uxbridge Road, inconsistent signage and protection, no understanding of how cyclists use the road and risks they experience	1	16/5/2023	https://www.google.com/maps/place/51.5125570643616 16%2C-0.31221824117693586/@51.512557064361616,-0.31221824117693586,1	40 Uxbridge Rd, London, W5 2BS	Ealing Broadway / West Ealing	Ealing Broadway / Walpole	This section could have increased segregation if parking is removed (businesses have off street).	1			1	1		1			1										1																			
1689	Parking in the cycle lane at Shepherds Bush onwards, and cycle lane outside shops hazardous as pedestrians step out without looking. Those cycle lanes also full of metal detritus causing tyre punctures.	1	16/5/2023	https://www.google.com/maps/place/51.50747322093312%2C-0.2503887407774874/@51.50747322093312,-0.2503887407774874,17	57 The Vale, London, W3 7RR	East Acton	East Acton / Southfield	Cycle lane and bus lane parking should be reviewed to potentially make bus lanes 24 hours and increase segregation. Street cleaning	1			1		1	1			1							1				1																	
1690			16/5/2023	https://www.google.com/maps/place/51.51268485371347%2C-0.31099980536724914/@51.51268485371347,-0.31099980536724914,1																																										
1691			16/5/2023	https://www.google.com/maps/place/51.53176877824384%2C-0.30441856804245937/@51.53176877824384,-0.30441856804245937,1																																										
1692			16/5/2023	https://www.google.com/maps/place/51.520100780167844%2C-0.29205894890183437/@51.520100780167844,-0.29205894890183437,1																																										
1693	Cycle lane is dangerous as it does not start from Haven Green and also the way it ends dumping you into traffic at the top of the hill. It is also not great how it crosses St Sephens Road without clear priority over vehicular traffic turning in or out of this road. Furthermore pedestrians are at risk particularly near the bus stop as the bike lane is not segragated well.	1	16/5/2023	https://www.google.com/maps/place/51.52001710288755%2C-0.31159131724468825/@51.52001710288755,-0.31159131724468825,1	74 Castlebar Rd, London, W5 2DD	Castle Bar Hill	Ealing Broadway	Castle Bar Hill cycle lane hotspot. All on emerging suggestions	1	1		1	1		1	1										1	1											1								
1694	Dangerous junction for cyclists heading westbound on Uxbridge Rd - I have on average a collision here every other week with cars turning off uxbridge road into the cycle lane to access the common. Too many ignorant drivers think that they have priority and the bike lane is not clearly marked as such - surely a humped crossing with coloured tarmac and clear give way (for vehicles turning in or	1	16/5/2023	https://www.google.com/maps/place/51.512952018977806%2C-0.29633522427152226/@51.512952018977806,-0.29633522427152226,1	4 The Common, London, W5 3TR	Ealing Common	Ealing Common	Road markings are very faded and cyclists will have temporarily rejoined the main carriageway. A raised table would be preferable but certainly much clearer	1	1		1			1	1		1									1	1			1																
1695			16/5/2023	https://www.google.com/maps/place/51.506702025985525%2C-0.26478321985712094/@51.506702025985525,-0.26478321985712094,1																																										
1696	council need to clean these cycle ways more often as the road sweepers just sweep all the dirt off the mainroad into the lanes (where there are wands)	1	16/5/2023	https://www.google.com/maps/place/51.51101299469864%2C-0.2896913035118698/@51.51101299469864,-0.2896913035118698,17	8, Fielding Terrace, Uxbridge Rd, London, W5 3HQ	Ealing Common	Ealing Common	Street cleaning of segregated sections	1			1		1				1							1																						
1697	poor road surface and no cycle lanes makes this area especially hazardous especailly with all the speeding mopeds and maniac bus drivers.	1	16/5/2023	https://www.google.com/maps/place/51.51387306666799%2C-0.30300514215782615/@51.51387306666799,-0.30300514215782615,1	17 The Broadway, London, W5 2NH	Ealing Broadway	Ealing Broadway	hotspot section Ealing Broadway	1			1	1		1	1		1					1			1									1												
1698			16/5/2023	https://www.google.com/maps/place/51.51035468007147%2C-0.3204074724350714/@51.51035468007147,-0.3204074724350714,17																																										
1699	The cycle route from Sainsbury's West Ealing along dean gardens through mattock lane is often quite dangerous. Drivers close pass on the route from Sainsbury's to dean gardens but the junction at the lido is often a problem with drivers jumping the red light, cutting the corner from Northfields avenue and blocking the crossing. Drivers come down mattock lane well over the speed limit	1	16/5/2023	https://www.google.com/maps/place/51.51596327290665%2C-0.3092586017574539/@51.51596327290665,-0.3092586017574539,17	14 New Broadway, London, W5 2XA	Ealing	Ealing Broadway / Ealing Common / Walpole	Lots of points - mainly in relation to poor driver behaviour - particularly parents at the two Christ The Saviour School Sites and issues around the dean	1			1			1	1		1				1	1											1	1												
1699.1		1			6 The Grove, London, W5 5LH			Additional location for previous log	1			1			1	1		1				1	1											1	1												
1700			16/5/2023	https://www.google.com/maps/place/51.51078689456836%2C-0.30418773769642193/@51.51078689456836,-0.30418773769642193,1																																										
1701	Parents at Christ the saviour drive on the pavement here endangering children and pedestrians and are damaging the pavement causing trip hazards.	1	16/5/2023	https://www.google.com/maps/place/51.51324406608413%2C-0.30682703136707623/@51.51324406608413,-0.30682703136707623,1	Unit 18 Dickens Yard, Longfield Ave, London, W5	Ealing Broadway	Ealing Broadway	Poor driver / parent behaviour	1			1		1	1			1					1												1												
1702	Hounslow built a fantastic cycleway from the A4 to Boston Manor station, and Ealing just directed it onto shared pavement. This route deserves to continue the high-quality protected cycleway all the way up to the Uxbridge Road, and not in a way that creates conflict between people walking and people cycling. Please do better.	1	16/5/2023	https://www.google.com/maps/place/51.50011130073884%2C-0.32856424570011367/@51.50011130073884,-0.32856424570011367,1	224-214 Boston Rd, London, W7 2AT	Boston Manor	Northfield / Hanwell Broadway	Boston Road lack of segregation	1			1	1		1	1				1								1																			
1703	It is absurd that this is listed as a cycle route on this map. The wands put along the Uxbridge Road were an improvement, but they vanish at bus stops and junctions, and people drive over them and knock them out. What the Uxbridge Road needs is a route like the one from Hammersmith Roundabout through Chiswick, with proper kerbs and signals and junctions that a child could cycle through	1	16/5/2023	https://www.google.com/maps/place/51.513306780138386%2C-0.30453165292667617/@51.513306780138386,-0.30453165292667617,1	24 Spring Bridge Rd, London, W5 2ND	Ealing Broadway	Ealing Broadway	Uxbridge road in Ealing in general - increase segregation	1			1	1		1	1		1										1																			
1704	Culmington Road is a horrid rat-run, and the best thing that ever happened to Lammas and Walpole parks was the installation of the road filter at the Elers Road junction. The traffic on this route is a blight, and endangers families crossing with buggies as well as people trying to cycle places through here. Put back the LTNs, and stop pandering to the Brexit Party's anti-LTN anti-ULEZ anti-	1	16/5/2023	https://www.google.com/maps/place/51.50685643111362%2C-0.31081875085758437/@51.50685643111362,-0.31081875085758437,1	55A Culmington Rd, London, W13 9NJ	Walpole	Walpole	Culmington rat run hotspot	1			1			1	1						1				1			1							1			1							
1705	The Iron Bridge junction is terrifying. Why do there need to be so many lanes for cars here? Why do we give so much space to enable people to zoom through Ealing, instead of spending time here?	1	16/5/2023	https://www.google.com/maps/place/51.50895314802486%2C-0.3411763438753379/@51.50895314802486,-0.3411763438753379,17	Iron Bridge, Uxbridge Rd, Southall UB1 3EG	Iron Bridge	Norwood Green / Southall Broadway / Dormers Wells	Iron Bridge hotspot in general	1			1	1		1	1		1				1				1																			1	Remove vehicle lanes
1706	Why is there no cycleway between Madeley Road and Gordon Road? Why must children mix with lorries and revving luxury SUVs to cycle to a railway station? Why is there no cycleway along or around Haven Green?	1	16/5/2023	https://www.google.com/maps/place/51.51519131280991%2C-0.3021258883093769/@51.51519131280991,-0.3021258883093769,17	47 The Broadway, London, W5 2NX	Haven Green	Ealing Broadway	Haven Green / Ealing Broadway hotspot - lack of cycle infrastructure	1			1	1		1	1										1					1																
1707	These quietways are just normal streets with signs for cyclists, there's not really any changes or concessions made to encourage cycling and most of them don't link up to form continuous routes. The signage is stop/start too. It would be great if the network was made more comprehensive with i) frequent signs (can be stickers on lampposts like the Sustrans NCN network uses) or bike symbols	1	16/5/2023	https://www.google.com/maps/place/51.52595640321944%2C-0.30023714406031576/@51.52595640321944,-0.30023714406031576,1	23 Birkdale Rd, London, W5 1JZ	Montpelier	Hanger Hill	C85 in Hanger Hill / Montpelier. Should be better connected westbound ie Mount Avenue and other general blue route improvements	1			1			1											1			1																		
1708	Cycle lane along Uxbridge road is not complete - marked lanes seem to vanish near major junctions. Marked lane often blocked by parked vehicles. Surface is rather bumpy in places, to the extent that I avoid the marked lane e.g. section westwards from Hanwell down to river.	1	16/5/2023	https://www.google.com/maps/place/51.513684887834344%2C-0.30106879291253996/@51.513684887834344,-0.30106879291253996,1	142 Uxbridge Rd, London, W7 3SL	Hanwell / West Ealiing	Hanwell Broadway / Walpole / Ealing Broadway	Uxbridge road in Ealing in general. Mainly West Ealing - Hanwell in particular which is bumpy / faded and poor around junctions	1			1	1		1			1					1			1	1				1																
1709	Some sections separated from traffic by markers, but such markers only exist in short sections.	1	16/5/2023	https://www.google.com/maps/place/51.50909098215734%2C-0.2827010255785556/@51.50909098215734,-0.2827010255785556,17	354 Uxbridge Rd, London, W3 9SL	Ealing Common - Acton	Ealing Common / North Acton	Uxbridge patchy segregation	1			1			1	1		1										1																			
1710			17/5/2023	https://www.google.com/maps/place/51.521603677896586%2C-0.2636671022776027/@51.521603677896586,-0.2636671022776027,17																																										
1711	Lower Boston Road is tricky being one-way for a cyclist. Many resort to pavements to traverse in the counter direction	1	17/5/2023	https://www.google.com/maps/place/51.50713515758081%2C-0.3395199732187648/@51.50713515758081,-0.3395199732187648,17	13 Lower Boston Rd, London, W7 3TX	Hanwell	Hanwell Broadway	Generally poor cycle infrastructure and narrow / busy road. Far too narrow for contraflow unless resident parking is removed.	1																	1																					
1712	Whilst there is a lane west bound here (up the steep hill) invariably mopeds park across the cycle lane.	1	17/5/2023	https://www.google.com/maps/place/51.50838364814376%2C-0.2751746933263477/@51.50838364814376,-0.2751746933263477,17	264 High St, London, W3 9BH	Acton	North Acton / South Acton	hotspot styne roundabout / Gunnersbury junction. Parking in cycle lane	1			1		1	1															1																	
1713	LTN was great, making it safe even for children, but sadly it was removed	1	17/5/2023	https://www.google.com/maps/place/51.50304388976294%2C-0.3050425452010619/@51.50304388976294,-0.3050425452010619,17	Roberts Alley, London, W5 4HH	South Ealing	Ealing Common	Near former LTNs in Walpole	1																															1							
1714	Cars drive too quickly here. Removing off street parking to make room for dedicated, separate cycle lane would improve safety	1	17/5/2023	https://www.google.com/maps/place/51.50790515528589%2C-0.31222910717631613/@51.50790515528589,-0.31222910717631613,1	27 Culmington Rd, London, W13 9NJ	Walpole	Walpole	Walpole / Lammas / Culmington hotspot area. known rat run lacking infrastructure. Parking appears plentiful and could potentially become one side	1			1	1		1											1		1															1				
1715	This crossing ambiguous and dangerous. Either side are separate cycle lanes but the spit you out into heavy traffic to cross north circular. Continuous dedicated cycle lane is an imperative for cyclists to feel safe	1	17/5/2023	https://www.google.com/maps/place/51.5114855781394%2C-0.2913690549130177/@51.5114855781394,-0.2913690549130177,17	2-8 Hanger Ln, London, W5 3HN	Ealing Common	Ealing Common	Agreed - Uxbridge / A406 hotspot junction - lack of infrastructure	1			1	1		1	1		1	1							1				1																	
1716	Great quiet way but gets congested due to parked cars. Allowing Parking on only one side of road would help	1	17/5/2023	https://www.google.com/maps/place/51.51495757639802%2C-0.30862102329680674/@51.51495757639802,-0.30862102329680674,1	32-28 Gordon Rd, London, W5 2AH	Ealing Broadway	Ealing Broadway	Agreed - section furthest east ie closest to Ealing Broadway etc is the only area with parking on both sides of the road	1			1			1														1	1																	
1717	Stretch of Uxbridge road from Ealing through Hanwell to Ealing hospital is busy, and does not feel safe. Parking restrictions would allow more space for cycling and ideally encourage people out of cars to travel more actively for mostly short trips to shops	1	17/5/2023	https://www.google.com/maps/place/51.512177388922076%2C-0.3130996350129922/@51.512177388922076,-0.3130996350129922,17	Exchange Plaza, 58 Uxbridge Rd, London, W5 2ST	West Ealing / Hanwell	Hanwell Broadway	West Ealing hotspot - parking in cycle lanes	1			1	1		1															1																	
1718			17/5/2023	https://www.google.com/maps/place/51.49767590069173%2C-0.30582046740103896/@51.49767590069173,-0.30582046740103896,1																																										
1719			17/5/2023	https://www.google.com/maps/place/51.49766254229365%2C-0.3102192901854628/@51.49766254229365,-0.3102192901854628,17																																										
1720			17/5/2023	https://www.google.com/maps/place/51.49803657596011%2C-0.30834611272931634/@51.49803657596011,-0.30834611272931634,1																																										
1721			17/5/2023	https://www.google.com/maps/place/51.49854418816935%2C-0.30592139577985344/@51.49854418816935,-0.30592139577985344,1																																										
1722			17/5/2023	https://www.google.com/maps/place/51.50443474793573%2C-0.30740197515607415/@51.50443474793573,-0.30740197515607415,1																																										
1723	Junction road is incredibly busy in morning And afternoon school runs preventing us from cycling to school as a family. Cars from side roads, speed and volume of traffic	1	17/5/2023	https://www.google.com/maps/place/51.49593684773134%2C-0.3090378415485606/@51.49593684773134,-0.3090378415485606,17	12A Junction Rd, London, W5 4XL	South Ealing	Northfield	hotspot - general concern around Little Ealing School and Radbourn / Junction known rat run.	1			1	1		1							1													1												
1724	There is insufficient cycle storage near little Ealing school to encourage cycling	1	17/5/2023	https://www.google.com/maps/place/51.498263161 4173%2C-0.3086621692322655/@51.4982631614173,-0.3086621692322655,17	37A Temple Rd, London, W5 4SL	South Ealing	Northfield	hotspot Little Ealing Cycle Parking	1			1	1		1																		1														
1725			17/5/2023	https://www.google.com/maps/place/51.49746966181732%2C-0.31052419723477165/@51.49746966181732,-0.31052419723477165,1																																										
1726	Extremely unsafe junction for cyclists particularly when cars park on double lines at drop off / pick up	1	17/5/2023	https://www.google.com/maps/place/51.4973475839178%2C-0.31039352860301683/@51.4973475839178,-0.31039352860301683,1	Charlotte House, 87 Little Ealing Ln, London, W5 4EH	South Ealing	Northfield	hotspot - general concern around Little Ealing School and Radbourn / Junction known rat run.	1			1	1		1							1													1												
1727	This junction (popes lane/little ealing) is horrendous. Cars turn randomly and ignore the lights. Needs at least a filter and needs longer pedestrian crossings	1	17/5/2023	https://www.google.com/maps/place/51.499270668102604%2C-0.3060248554264633/@51.499270668102604,-0.3060248554264633,17	161 S Ealing Rd, London, W5 4QP	South Ealing	Northfield / Ealing Common	Appears to be a difficult junction lacking road markings. Advanced stop lines have been added but appear badly observed.	1			1			1	1															1				1												
1728			17/5/2023	https://www.google.com/maps/place/51.49994446597167%2C-0.29961731700201666/@51.49994446597167,-0.29961731700201666,1																																										
1729			17/5/2023	https://www.google.com/maps/place/51.50320481896831%2C-0.3169984280174942/@51.50320481896831,-0.3169984280174942,17																																										
1730			17/5/2023	https://www.google.com/maps/place/51.497024611707275%2C-0.31375821554841865/@51.497024611707275,-0.31375821554841865,1																																										
1731			17/5/2023	https://www.google.com/maps/place/51.50386369509975%2C-0.3086083742398249/@51.50386369509975,-0.3086083742398249,17																																										
1732			17/5/2023	https://www.google.com/maps/place/51.499902210570376%2C-0.311925742739525/@51.499902210570376,-0.311925742739525.17z																																										
1733			17/5/2023	https://www.google.com/maps/place/51.50182568506119%2C-0.3158739544094469/@51.50182568506119,-0.3158739544094469,17																																										
1734			17/5/2023	https://www.google.com/maps/place/51.49643533164832%2C-0.31422929842884306/@51.49643533164832,-0.31422929842884306,1																																										
1735			17/5/2023	https://www.google.com/maps/place/51.49783173572309%2C-0.3133261236060325/@51.49783173572309,-0.3133261236060325,17																																										
1736	There's no actual cycle route here	1	17/5/2023	https://www.google.com/maps/place/51.5069527345298%2C-0.3108026666233199/@51.5069527345298,-0.3108026666233199,17	55A Culmington Rd, London, W13 9NJ	Walpole	Walpole	C86 - hotspot / lack of infrastructure and poor driver behaviour	1			1	1		1											1			1																		
1737	There's no real route. Cars are speeding on the turn and there's nothing to slow them down	1	17/5/2023	https://www.google.com/maps/place/51.50445515446825%2C-0.30815264411660603/@51.50445515446825,-0.30815264411660603,1	8 Church Ln, London, W5 5HB	South Ealing	Ealing Common / Walpole	C86 - lack of infrastructure and poor driver behaviour	1			1			1							1				1			1						1									1			
1738	During school drop off, there are many cars and a lot of chaos and it feels unsafe to ride a bicycle	1	17/5/2023	https://www.google.com/maps/place/51.49862388840911%2C-0.30880425082197904/@51.49862388840911,-0.30880425082197904,1	82 Weymouth Ave, London, W5 4SB	South Ealing	Northfield	General concern around Little Ealing Primary School	1			1	1									1																									
1739	The cycle route is only 1 way	1	17/5/2023	https://www.google.com/maps/place/51.497691447225414%2C-0.3099183141868389/@51.497691447225414,-0.3099183141868389,17	52 Little Ealing Ln, London, W5 4EA	South Ealing	Northfield	Agreed - lack of cycle infrastructure other than the segregated cycle lane. It appears challenging to add two way segregation however a simple cycle lane could be	1			1			1	1										1																					
1740	no bicycle storage next to Little Ealing primary school. Ideally a covered bicycle storage	1	17/5/2023	https://www.google.com/maps/place/51.498413414520535%2C-0.30869582439054577/@51.498413414520535,-0.30869582439054577,1	37A Temple Rd, London, W5 4SL	South Ealing	Northfield	Lack of cycle parking around Little Ealing School	1			1	1		1																		1														
1741	no covered bicycle storage next to south ealing station	1	17/5/2023	https://www.google.com/maps/place/51.50144562050488%2C-0.3068504645882997/@51.50144562050488,-0.3068504645882997,17	82B S Ealing Rd, London, W5 4QB	South Ealing	Northfield	Agreed - it may be possible to retrofit a shelter over existing provision near Maytree Rest Gardens	1			1			1																		1														
1742	no bicycle storage next to LEPS	1	17/5/2023	https://www.google.com/maps/place/51.49892102253286%2C-0.3095112159310731/@51.49892102253286,-0.3095112159310731,17	23 Hereford Rd, London, W5 4SE	South Ealing	Northfield	Lack of cycle parking around Little Ealing School	1			1	1		1																		1														

1743	No cycle storage for children attending school	1	17/5/2023	https://www.google.com/maps/place/51.498202512713014%2C-0.3086021843124942/@51.498202512713014,-0.3086021843124942,17	4 Weymouth Ave, London, W5 4SA	South Ealing	Northfield	Lack of cycle parking around Little Ealing School	1			1	1		1																				1													
1744			17/5/2023	https://www.google.com/maps/place/51.49944081185656%2C-0.3080607369543453/@51.49944081185656,-0.3080607369543453,17																																												
1745	No bike storage cages on the residential road	1	17/5/2023	https://www.google.com/maps/place/51.49930055391277%2C-0.3079641774298092/@51.49930055391277,-0.3079641774298092,17	35 Netherbury Rd, London, W5 4SP	South Ealing	Northfield	Agreed - no cycle hangers nearby and those in the general area are full	1			1			1																				1													
1746	No cycle lane here when lots of students at uni	1	17/5/2023	https://www.google.com/maps/place/51.505788301543824%2C-0.30509353111307425/@51.505788301543824,-0.30509353111307425,1	SRG, 43 St Mary's Rd, London, W5 5RG	University West London,	Walpole / Ealing Common	Agreed - lack of cycle infrastructure of St Marys / South Ealing Road including signed / designated connections to east - west routes	1			1			1	1										1																					
1747	Hardly any places to lock bikes here	1	17/5/2023	https://www.google.com/maps/place/51.51253795937624%2C-0.3047074638429015/@51.51253795937624,-0.3047074638429015,17	39 High St, London, W5 5DB	Ealing Broadway	Ealing Broadway	Clear use of visirails on Google Maps indicating a lack of formal provision	1			1			1																				1													
1748			17/5/2023	https://www.google.com/maps/place/51.5050425260247%2C-0.31891096845821254/@51.5050425260247,-0.31891096845821254,1																																												
1749			17/5/2023	https://www.google.com/maps/place/51.497985275510175%2C-0.3070934934856262/@51.497985275510175,-0.3070934934856262,17																																												
1750			17/5/2023	https://www.google.com/maps/place/51.49926990942044%2C-0.3061697708083977/@51.49926990942044,-0.3061697708083977,17																																												
1751			17/5/2023	https://www.google.com/maps/place/51.49892956806998%2C-0.3026806155373496/@51.49892956806998,-0.3026806155373496,17																																												
1752			17/5/2023	https://www.google.com/maps/place/51.508608514612185%2C-0.3192252219640701/@51.508608514612185,-0.3192252219640701,17																																												
1753	It would help many cyclists if easier to get from Castlebar Road to Uxbridge Road	1	17/5/2023	https://www.google.com/maps/place/51.51448515570752%2C-0.3022578519717345/@51.51448515570752,-0.3022578519717345,17	39 The Broadway, London, W5 2NP	Ealing Broadway	Ealing Broadway	hotspot - lack of cycle infrastructure around Haven Green / Ealing Broadway particularly connecting to Uxbridge Road	1			1	1		1	1										1																					
1754	Going from West to East on Acton roundabout	1	17/5/2023	https://www.google.com/maps/place/51.50852413126975%2C-0.27422281384694935/@51.50852413126975,-0.27422281384694935,1	250 High St, London, W3 9BH	Acton	North Acton / South Acton	Agreed - hotspot roundabout	1			1	1		1	1		1									1																				
1755	Road is very narrow here and cars travel too quickly to make it safe, espeically for children.	1	17/5/2023	https://www.google.com/maps/place/51.51847372720247%2C-0.3103478485606481/@51.51847372720247,-0.3103478485606481,17	64 Castlebar Rd, London, W5 2DG	Montpelier	Ealing Broadway	Agreed - difficult to improve other than road markings and traffic calming	1			1			1							1													1												
1756			17/5/2023	https://www.google.com/maps/place/51.49900425109632%2C-0.3089934523874738/@51.49900425109632,-0.3089934523874738,17																																												
1757			17/5/2023	https://www.google.com/maps/place/51.498439871814426%2C-0.308687680559776/@51.498439871814426,-0.308687680559776,17z																																												
1758			17/5/2023	https://www.google.com/maps/place/51.49955860500744%2C-0.3092348511988141/@51.49955860500744,-0.3092348511988141,17																																												
1759			17/5/2023	https://www.google.com/maps/place/51.499816578608936%2C-0.3093243695379755/@51.499816578608936,-0.3093243695379755,17																																												
1760			17/5/2023	https://www.google.com/maps/place/51.49817358395801%2C-0.30320136744610426/@51.49817358395801,-0.30320136744610426,1																																												
1761			17/5/2023	https://www.google.com/maps/place/51.49715990878732%2C-0.30848756585335035/@51.49715990878732,-0.30848756585335035,1																																												
1762			17/5/2023	https://www.google.com/maps/place/51.499257152470236%2C-0.30900254998420973/@51.499257152470236,-0.30900254998420973,1																																												
1763			17/5/2023	https://www.google.com/maps/place/51.499257152470236%2C-0.303852708675616/@51.499257152470236,-0.303852708675616,17z																																												
1764			17/5/2023	https://www.google.com/maps/place/51.502803755397%2C-0.3088915730060626/@51.502803755397,-0.3088915730060626,17																																												
1765	Somewhere to lock up bikes near little Ealing school	1	17/5/2023	https://www.google.com/maps/place/51.49791341442693%2C-0.30858728196216045/@51.49791341442693,-0.30858728196216045,1	49 Little Ealing Ln, London, W5 4ED	South Ealing	Northfield	Frequency of comment noted and added to emerging suggestions	1			1			1																				1													
1766	Cars drive up to 35 to 40 miles perhour along this stretch of road. It's dangerous for cyclists. Traffic calming needs to be put in place.	1	17/5/2023	https://www.google.com/maps/place/51.49640092589529%2C-0.3144406832260094/@51.49640092589529,-0.3144406832260094,17	336 Windmill Rd, London, W5 4UR	Northfield	Northfield	Speeding	1			1			1	1																			1	1									1			
1767			17/5/2023	https://www.google.com/maps/place/51.49675895908424%2C-0.3055398410443466/@51.49675895908424,-0.3055398410443466,17																																												
1768			17/5/2023	https://www.google.com/maps/place/51.49840204524672%2C-0.3058402484540146/@51.49840204524672,-0.3058402484540146,17																																												
1769			17/5/2023	https://www.google.com/maps/place/51.5008331697669%2C-0.2968709415082138/@51.5008331697669,-0.2968709415082138,17																																												
1770			17/5/2023	https://www.google.com/maps/place/51.5084195816353%2C-0.2753274387005966/@51.5084195816353,-0.2753274387005966,17																																												
1771			17/5/2023	https://www.google.com/maps/place/51.50672343368224%2C-0.2657144015912216/@51.50672343368224,-0.2657144015912216,17																																												
1772			17/5/2023	https://www.google.com/maps/place/51.50176967216215%2C-0.30627021621173256/@51.50176967216215,-0.30627021621173256,1																																												
1773			17/5/2023	https://www.google.com/maps/place/51.500166780420635%2C-0.30275305239258365/@51.500166780420635,-0.30275305239258365,1																																												
1774			17/5/2023	https://www.google.com/maps/place/51.508898425027034%2C-0.31166841634009623/@51.508898425027034,-0.31166841634009623,1																																												
1775			17/5/2023	https://www.google.com/maps/place/51.51279794930328%2C-0.30840685017798686/@51.51279794930328,-0.30840685017798686,1																																												
1776			17/5/2023	https://www.google.com/maps/place/51.49780810075202%2C-0.30885799854916796/@51.49780810075202,-0.30885799854916796,1																																												
1777			17/5/2023	https://www.google.com/maps/place/51.497222991305826%2C-0.31263388356760125/@51.497222991305826,-0.31263388356760125,1																																												
1778			17/5/2023	https://www.google.com/maps/place/51.5099756629215%2C-0.31913400017668625/@51.5099756629215,-0.31913400017668625,1																																												
1779			17/5/2023	https://www.google.com/maps/place/51.504157008277005%2C-0.30676538242090823/@51.504157008277005,-0.30676538242090823,1																																												
1780			17/5/2023	https://www.google.com/maps/place/51.49774978460387%2C-0.30538807241564214/@51.49774978460387,-0.30538807241564214,1																																												
1781	The amazing cycle track stops at Boston Manor station. Please extend it!!	1	17/5/2023	https://www.google.com/maps/place/51.50237670483859%2C-0.3303399830339293/@51.50237670483859,-0.3303399830339293,17	217A Boston Rd, London, W7 2AA	Boston Manor	Northfield / Hanwell Broadway	Straight forward	1			1	1			1				1								1																			
1782	Crazy traffic outside Little Ealing. One bike rack for whole school of children. Weymouth Avenue end near the school should be no car zone	1	17/5/2023	https://www.google.com/maps/place/51.49811842605331%2C-0.3087033326280175/@51.49811842605331,-0.3087033326280175,17	58 Little Ealing Ln, London, W5 4EA	South Ealing	Northfield	Request for school street essentially + cycle parking	1		1	1			1	1																	1												1		
1783	Crazy busy. Speeding cars	1	17/5/2023	https://www.google.com/maps/place/51.505414674656954%2C-0.3351985203807506/@51.505414674656954,-0.3351985203807506,17	145-147 Boston Rd, London, W7 3SA	Boston Manor	Hanwell Broadway / Northfield	General Boston Road concern + speeding	1			1	1		1					1														1	1												
1784	Constant traffic. Not safe	1	17/5/2023	https://www.google.com/maps/place/51.49874548258075%2C-0.3272468944550244/@51.49874548258075,-0.3272468944550244,17	311 Boston Rd, London, W7 2AT	Boston Manor	Hanwell Broadway / Northfield	General Boston Road concern					1							1		1																									
1785	Very unsafe, so many buses	1	17/5/2023	https://www.google.com/maps/place/51.509724219326245%2C-0.3260421853540274/@51.509724219326245,-0.3260421853540274,17	99 Broadway, London, W13 9BP	West Ealing / Hanwell	Hanwell Broadway / Walpole	Uxbridge Road hotspot west ealing	1			1	1		1	1		1									1	1		1																1	Bus concerns
1786	I cycle down northfields avenue with my 8 year old daughter and there are no cycle lanes on the way to little ealing so we have to use the pavement because she us too young to use a main road	1	17/5/2023	https://www.google.com/maps/place/51.50331869589895%2C-0.31569670315351406/@51.50331869589895,-0.31569670315351406,1	135 Northfield Ave, London, W13 9QT	Northfield	Northfield / Walpole	Agreed - lack of cycle infrastructure on Northfield Ave	1			1														1																					
1787	There is no obvious cycle route at the top/north end of Boston Manor road	1	17/5/2023	https://www.google.com/maps/place/51.504805486716634%2C-0.33392171145614213/@51.504805486716634,-0.33392171145614213,1	122 Boston Rd, London, W7 2EP	Boston Manor	Hanwell Broadway																																								
1788	The North edge of gunnersbury park has no cycle lanes, its very busy and often blocked by motor vehicles during the weekdays at rush hours	1	17/5/2023	https://www.google.com/maps/place/51.49974907031723%2C-0.30166396662555384/@51.49974907031723,-0.30166396662555384,1	80 Popes Ln, London, W5 4NT	Gunnersbury Park	Northfield / Ealing Common	Agreed - lack of cycle infrastructure on Popes Lane	1			1	1		1	1										1																					
1789			17/5/2023	https://www.google.com/maps/place/51.49901097193197%2C-0.30908996359094276/@51.49901097193197,-0.30908996359094276,1																																												
1790	Cycle lanes interrupted by parking bays, which confuse cyclists into using them and having to join traffic on the road which can be quite dangerous. The amount of traffic sometimes in standstill makes it unhealthy as you're breathing cars fumes and gases. Not a pleasant cycling route and one where we should have more people on bikes.	1	17/5/2023	https://www.google.com/maps/place/51.50673501528475%2C-0.26929113430984364/@51.50673501528475,-0.26929113430984364,1	135 High St, London, W3 6LY	Acton	South Acton	Uxbridge Road in Acton. Segregation is interrupted by loading bays	1			1	1		1	1		1										1																			
1791	Too busy too dangerous no priority lights for bicycles	1	17/5/2023	https://www.google.com/maps/place/51.51394838196947%2C-0.30325218567924583/@51.51394838196947,-0.30325218567924583,1	Haart Estate Agents, 17 The Broadway, London, W5	Acton Town										1						1									1																
1792	Have to wait WAY WAY WAY too long for these lights to prioritise bikes	1	17/5/2023	https://www.google.com/maps/place/51.51007221082913%2C-0.29190578773666376/@51.51007221082913,-0.29190578773666376,1	5 Leopold Rd, London, W5 3PB	Ealing Common	Ealing Common	Agreed - long traffic light phasing	1							1			1												1																
1793			17/5/2023	https://www.google.com/maps/place/51.50872335983245%2C-0.29411592796493524/@51.50872335983245,-0.29411592796493524,1																																												
1794	Path not good enough. Pedestrians aren't considerate as path too narrow and they think it's only for them.	1	17/5/2023	https://www.google.com/maps/place/51.506639907540205%2C-0.29780664756942743/@51.506639907540205,-0.29780664756942743,1	17 Elm Grove Rd, London, W5 3JH	Ealing Common	Ealing Common	Location unclear - there do not appear to be any shared paths in this area																																							
1795	Crossing can be treacherous!!	1	17/5/2023	https://www.google.com/maps/place/51.51149630276292%2C-0.29194272182339276/@51.51149630276292,-0.29194272182339276,1	2-8 Hanger Ln, London, W5 3HN	Ealing Common	Ealing Common	Uxbridge / A406 hotspot junction.	1			1	1		1	1		1	1							1					1																
1796			17/5/2023	https://www.google.com/maps/place/51.502058324434714%2C-0.31654647597584296/@51.502058324434714,-0.31654647597584296,1																																												
1797	Link up these routes	1	17/5/2023	https://www.google.com/maps/place/51.51772914549353%2C-0.3064075346080064/@51.51772914549353,-0.3064075346080064,17	18 Eaton Rise, London, W5 2ER	Montpelier	Ealing Broadway	Exact location unclear but likely to be connecting Castlebar Hill to Gordon Road and Haven Green	1			1			1	1										1																					
1798	Link up route acriss Hanwell to the station	1	17/5/2023	https://www.google.com/maps/place/51.51795588470435%2C-0.3361068949578083/@51.51795588470435,-0.3361068949578083,17	32 Homefarm Rd, London, W7 1NP	Hanwell	North Hanwell	Not entirely clear which routes / station but there is a lack of cycle routes in this area	1			1			1	1										1																					
1799	need better segregation all along here	1	17/5/2023	https://www.google.com/maps/place/51.506898712908814%2C-0.25896951786767985/@51.506898712908814,-0.25896951786767985,1	201 The Vale, London, W3 7QS	Acton Park	Southfield / East Acton	Uxbridge road segregation	1			1	1		1	1		1										1																			

1800	take this one all the way up the A406	1	17/5/2023	https://www.google.com/maps/place/51.508180841388345%2C-0.29373094670068767/@51.508180841388345,-0.29373094670068767,1	10 Gunnersbury Ave, London, W5 3NJ	Ealing Common	Ealing Common	Existing cycle lanes north - south along the west side of the A406 end at Elm Avenue and no lanes are provided across the hotspot junction with Uxbridge Road	1			1	1		1	1		1	1							1																					
1801	cycle crossing at corner of Popes Lane and gunnersbury park, and put cycle lane along Popes lane	1	17/5/2023	https://www.google.com/maps/place/51.4988311602825852C-0.30197069279443767/@51.498831160282585,-0.30197069279443767,1	70 Popes Ln, London, W5 4NT	South Ealing	Northfield / Ealing Common	Improvements to Popes lane and this junction with Lionel Road would be beneficial	1			1			1	1										1			1		1																
1802	Safer to cycle to school	1	17/5/2023	https://www.google.com/maps/place/51.49827775 3169255%2C-0.308682601161534/@51.498277753169255,-0.308682601161534,17z	37A Temple Rd, London, W5 4SL	South Ealing	Northfield	Likely to be a request for improvement but no clear action																																						
1803	Very busy road on the school run	1	17/5/2023	https://www.google.com/maps/place/51.4959499 5818962%2C-0.3091883148901875/@51.49594995818962,-0.3091883148901875,17	16 Junction Rd, London, W5 4XL	South Ealing	Northfield	Known rat run as well as high levels of school traffic.																																						
1804			17/5/2023	https://www.google.com/maps/place/51.49661098 2666084%2C-0.30569761525748085/@51.496610982666084,-0.30569761525748085,1																																										
1805			17/5/2023	https://www.google.com/maps/place/51.50427684 5676735%2C-0.30693654978724894/@51.504276845676735,-0.30693654978724894,1																																										
1806		1130																																													
1807																																															

Original order	Where would you like to cycle? Use pins to show start and end of a journey	Reviewed	Date	Google Maps link	Address of issue or pin	General area	Ward if known	Summary of comment	Identifiable action	Priority flag	Interesting / complicated	Valid and straight forward	Hot spot	Quick	Short	Long	General undefined route improveme	General poor road safety (without	Uxbridge Road / A4020 etc (any	Boston (Manor) Road	Canal / River improveme nts (nb	Poor highway surfaces / potholes /	Hedge / branch trimming	Lack of cycle infrastructure	Improve cycle lane designation	Increase cycle lane physical segregation	Improve residential blue routes etc	Parking in cycle lanes	Traffic lights	Cargo bike issue or cycle lane too narrow	Cycle parking	Law / highway code enforcement	Poor driver behaviour	Poor cycle behaviour	Street cleaning	Reduce rat running	Speed bump concerns	Bus stops	Re-introduce LTNS (etc)	Personal Safety	Remove cycle infrastructure etc	Remove Parking	Traffic Calming	School traffic	Other numeric	Other detail	Survey issue
	Tab methodology: This is a manual subjective log of comments left alongside the pin locations provided in question 3.								242	2	22	222	73	5	182	193	11	2	39	10	8	18	2	176	26	25	58	4	13	4	9	9	13	1	1	10	0	0	11	4	3	5	3	2	13	0	15
0001	No where. I'd love to be able to use my mobility scooter safely on the pavements without cyclists being on the pavements and GET RID of the cycle lanes as it's illegal for me to use my scooter in them, but you don't care about the disabled	1	5/4/2023	https://www.google.com/maps/place/51.506750 6502519%2C-0.2464503928282058/@51	1 The Vale, London, W3 7SH	Acton	East Acton / Southfield	Prioritise disabled by removing cycle lanes.	1			1				1																1		1							1						
0002			5/4/2023	https://www.google.com/maps/place/51.518810 3935548%2C-0.289094804092751/@51																																										
0003			5/4/2023	https://www.google.com/maps/place/51.501396 4110798%2C-0.28694903688083695/@5																																										
0004			5/4/2023	https://www.google.com/maps/place/51.518624 2256539%2C-0.28893610008513537/@5																																										
0005			6/4/2023	https://www.google.com/maps/place/51.499976 985601%2C-0.310997696476667/@51																																										
0006			6/4/2023	https://www.google.com/maps/place/51.494918 1055627%2C-0.30539582373145135/@5																																										
0007			6/4/2023	https://www.google.com/maps/place/51.500016 46428875%2C-0.31068913299907797/@5																																										
0008			6/4/2023	https://www.google.com/maps/place/51.512010 91581916%2C-0.3055822070347225/@51																																										
0009			6/4/2023	https://www.google.com/maps/place/51.519419 8456445%2C-0.31537830766799724/@5																																										
0010	I would like to be able to cycle from Ealing to Acton and Shepherds Bush. However, I've never cycled this directly because I wouldn't consider cycling along Uxbridge Road in its current state.	1	6/4/2023	https://www.google.com/maps/place/51.506867 4432438%2C-0.2466520050812182/@51	The Newman Bldg, 16 The Vale,	Uxbridge Road	East Acton / Southfield / North	Improve Uxbridge Road	1			1	1			1			1								1																				
0010.1		1			26 Noel Rd, London, W3 0JX			Additional location for previous log	1			1	1			1			1								1																				
0011	Within Ealing, my most common cycle journey is from St Stephens to central Ealing and on to South Ealing. However, the lack of cycling infrastructure around central Ealing	1	6/4/2023	https://www.google.com/maps/place/51.495977 8367097%2C-0.30154487457902945/@5	32 Churchfield Rd, London,	Ealing	Northfield	Increase cycle infrastructure in Central Ealing and reduce car use / rat running on residential streets	1			1	1			1			1					1			1									1			1								
0011.1		1			2 Broadway, London, W13 0NG			Additional location for previous log	1			1	1			1			1					1			1									1			1								
0012			6/4/2023	https://www.google.com/maps/place/51.504859 8724215%2C-0.30682502106960774/@5																																										
0013			6/4/2023	https://www.google.com/maps/place/51.494917 07491065%2C-0.30543152172561205/@5																																										
0014			6/4/2023	https://www.google.com/maps/place/51.513010 3879826%2C-0.308454726800933/@51.																																										
0015			6/4/2023	https://www.google.com/maps/place/51.513116 69884585%2C-0.3088838802433158/@51																																										
0016			6/4/2023	https://www.google.com/maps/place/51.512689 4403614%2C-0.30399153100015175/@5																																										
0017			6/4/2023	https://www.google.com/maps/place/51.512930 15319135%2C-0.3088838802433158/@51																																										
0018			6/4/2023	https://www.google.com/maps/place/51.508097 9514832%2C-0.2462676953281573/@51																																										
0019			6/4/2023	https://www.google.com/maps/place/51.514508 0804397%2C-0.30497588624612604/@5																																										
0020			6/4/2023	https://www.google.com/maps/place/51.512478 3654534%2C-0.29168656784136715/@5																																										
0021			6/4/2023	https://www.google.com/maps/place/51.502328 2236189%2C-0.28524926620562496/@5																																										
0022			6/4/2023	https://www.google.com/maps/place/51.501596 6235436%2C-0.3167391125820296/@51																																										
0023			6/4/2023	https://www.google.com/maps/place/51.516595 4936493%2C-0.30182495828839473/@5																																										
0024			6/4/2023	https://www.google.com/maps/place/51.500810 4088124%2C-0.3002800058958166/@51																																										
0025			6/4/2023	https://www.google.com/maps/place/51.514904 0409077%2C-0.32051602945316615/@5																																										
0026			6/4/2023	https://www.google.com/maps/place/51.512956 54690705%2C-0.3092443531979816/@51																																										
0027			6/4/2023	https://www.google.com/maps/place/51.501205 7344108%2C-0.2855811903682004/@51																																										
0028			6/4/2023	https://www.google.com/maps/place/51.514462 1566802%2C-0.31694124302399374/@5																																										
0029			6/4/2023	https://www.google.com/maps/place/51.501721 17735885%2C-0.28741548618805624/@5																																										
0030			6/4/2023	https://www.google.com/maps/place/51.514330 6723457%2C-0.31698894228423535/@5																																										
0031			6/4/2023	https://www.google.com/maps/place/51.499585 0169699%2C-0.3132123919912666/@51																																										
0032			6/4/2023	https://www.google.com/maps/place/51.505351 0586002%2C-0.2492055499040302/@51																																										
0033			6/4/2023	https://www.google.com/maps/place/51.514542 5428089%2C-0.3201419564183783/@51																																										
0034			6/4/2023	https://www.google.com/maps/place/51.535151 755481%2C-0.3299601958514864/@51																																										
0035			6/4/2023	https://www.google.com/maps/place/51.510870 1526007%2C-0.3415187250738705/@51																																										
0036			6/4/2023	https://www.google.com/maps/place/51.515998 6563448%2C-0.27794678815731055/@5																																										
0037			6/4/2023	https://www.google.com/maps/place/51.513934 198691%2C-0.3088672229807865/@51																																										
0038			6/4/2023	https://www.google.com/maps/place/51.495860 67767115%2C-0.30194474076173483/@5																																										
0039			6/4/2023	https://www.google.com/maps/place/51.509403 8333362%2C-0.31321131967173343/@5																																										
0040			6/4/2023	https://www.google.com/maps/place/51.501175 85970425%2C-0.30900561593638187/@5																																										
0041			6/4/2023	https://www.google.com/maps/place/51.510914 08343126%2C-0.3058029512198908/@51																																										
0042			6/4/2023	https://www.google.com/maps/place/51.505358 48432224%2C-0.30578918931803534/@5																																										
0043	routes from parts of Ealing out to the beginnings of Chilterns would be useful	1	6/4/2023	https://www.google.com/maps/place/51.530996 37094415%2C-0.30418842036358473/@5	15 Greystoke Park Terrace,	Hanger Lane	Hanger Hill / Pitshanger		1			1				1	1																														
0044	I would like to cycle from Merrick road to Southall Broadway but there are no safe cycle lanes on South Road	1	6/4/2023	https://www.google.com/maps/place/51.510045 6630023%2C-0.37676175089928376/@5	30 South Rd, Southall UB1 1RB	Southall	Southall Broadway	Improve South Road	1			1				1								1																							
0045	It is very hard to cycle in Kind Street	1	6/4/2023	https://www.google.com/maps/place/51.501335 7289167%2C-0.382985461888752/@51.	29 King St, Southall UB2 4DG	Southall	Southall Green	Improve King Street	1			1				1		1						1																							
0046			6/4/2023	https://www.google.com/maps/place/51.511242 90069964%2C-0.3737940073796109/@51																																										
0047			6/4/2023	https://www.google.com/maps/place/51.510548 54961685%2C-0.3612412691899136/@51																																										
0048			6/4/2023	https://www.google.com/maps/place/51.509926 9231665%2C-0.35703020664928253/@5																																										
0049			6/4/2023	https://www.google.com/maps/place/51.509405 5193182%2C-0.3519447383570462/@51																																										
0050			6/4/2023	https://www.google.com/maps/place/51.515587 3632103%2C-0.30272479106358663/@5																																										
0051			6/4/2023	https://www.google.com/maps/place/51.521672 5199951%2C-0.3355375352401957/@51																																										
0052			6/4/2023	https://www.google.com/maps/place/51.512056 89856944%2C-0.3191645029678791/@51																																										
0053			6/4/2023	https://www.google.com/maps/place/51.500463 8597489%2C-0.3143579844131916/@51																																										
0054			6/4/2023	https://www.google.com/maps/place/51.498850 89371416%2C-0.30984474322185873/@5																																										
0055			6/4/2023	https://www.google.com/maps/place/51.496857 4799396%2C-0.31566848954544424/@5																																										
0056			6/4/2023	https://www.google.com/maps/place/51.502297 3681339%2C-0.31525171177386957/@5																																										
0057			6/4/2023	https://www.google.com/maps/place/51.511281 9906868%2C-0.3055681433282431/@51																																										
0058	The roads in Southall are much too narrow and crowded for buses, cars and bikes all at once. Very dangerous for cyclists and obstructive for cars.	1	6/4/2023	https://www.google.com/maps/place/51.516310 7794884%2C-0.37096469599835036/@5	156 North Rd., Southall UB1 2LF	Southall	Dormers Wells	Narrow / busy streets in Southall				1				1	1	1																													
0059	Same comment as for Southall: there is not enough space here for buses, taxis, motorcycles, cars and bikes all at once on the same road. It is therefore dangerous for cyclists and obstructive for cars and other vehicles.	1	6/4/2023	https://www.google.com/maps/place/51.518233 5985153%2C-0.3040167589866316/@51	12A Mount Park Rd, London, W5 2RP	Ealing Broadway	Ealing Broadway	Narrow / busy streets in Ealing					1			1	1	1																													
0060	The proposed St. Stephens Cycleway plan is unnecessary, expensive, hazardous, dangerous for cyclists and inconvenient for local residents, as well as conducive to anti-social behaviour.	1	6/4/2023	https://www.google.com/maps/place/51.525709 7342042%2C-0.31809299189678786/@5	St Stephens Church Centre, St	West Ealing	Ealing Broadway	Objection to St Stephens Roundabout changes	1																																					1	Objection to St Stephens Roundabout changes	
0061			6/4/2023	https://www.google.com/maps/place/51.507571 0187561%2C-0.2609145690921233/@51																																										
0062			6/4/2023	https://www.google.com/maps/place/51.507998 25732626%2C-0.2455508758548186/@51																																										
0063			6/4/2023	https://www.google.com/maps/place/51.514928 28318605%2C-0.319637944289366/@51.																																										
0064			6/4/2023	https://www.google.com/maps/place/51.530128 6799154%2C-0.32332866389385817/@5																																										
0065	From the town centre I'd like a safe route to cycle to areas north of Haven Green	1	6/4/2023	https://www.google.com/maps/place/51.515200 3927916%2C-0.30185235265516974/@5	41 Haven Grn, London, W5 2NX	Ealing Broadway	Ealing Broadway	Cycle route North from Ealing Broadway	1			1	1		1		1							1			1																				
0066	A better route under the A40. The subway entrances need total reconstruction, taking property if required. [I can't work out how to make the "finish" pin work.	1	6/4/2023	https://www.google.com/maps/place/51.531109 79121945%2C-0.300242444712433/@51.	15 Western Ave, London,	Hanger Lane	Hanger Hill	Improve subway ease of use	1		1					1																														1	Improve A40 subway / crossing	1
0067	A safe connection from Coronation Road to Masons Green Lane is required. Use the abandoned railway bridge.	1	6/4/2023	https://www.google.com/maps/place/51.528248 2865244%2C-0.27865596446714713/@5	1 Coronation Rd, London,	Park Royal	North Acton / Hanger Hill	Improve access to Mason Green Lane from Coronation Road	1		1					1								1		1																			1	Additional access to A40 crossing for Mason Green Lane	
0068	Alliance Road needs reconstruction to make it safe for cyclists. It may be privately owned but the council need to initiate improvements. How else can one cycle safely to B&Q?	1	6/4/2023	https://www.google.com/maps/place/51.523962 5867645%2C-0.2754587713213952/@51	Heron Trading Estate, Alliance	Park Royal	North Acton	Alliance Road general condition	1		1					1						1		1																							
0069			6/4/2023	https://www.google.com/maps/place/51.509113 7641104%2C-0.3344467955388364/@51																																										
0070			6/4/2023	https://www.google.com/maps/place/51.508012 4620974%2C-0.2456040497047618/@51																																										
0071			6/4/2023	https://www.google.com/maps/place/51.497933 3481905%2C-0.300411870070616/@51.																																										
0072			6/4/2023	https://www.google.com/maps/place/51.545784 14683266%2C-0.3258177538596785/@51																																										
0073			6/4/2023	https://www.google.com/maps/place/51.516422 11438946%2C-0.30266789454794774/@5																																										
0074			6/4/2023	https://www.google.com/maps/place/51.515087 9049014%2C-0.30265785989288085/@5																																										
0075			6/4/2023	https://www.google.com/maps/place/51.516422 5094609%2C-0.3026708876214568/@51																																										
0076			6/4/2023	https://www.google.com/maps/place/51.494887 631431%2C-0.2601987111763182/@51																																										
0077	Pins don't work !	1	6/4/2023	https://www.google.com/maps/place/51.522179 44813174%2C-0.3355973644034993/@51	109 Westcott Cres, London,			Survey issue																																								1
0078			6/4/2023	https://www.google.com/maps/place/51.505514 6297923%2C-0.3453756859600232/@51																																										
0079			6/4/2023	https://www.google.com/maps/place/51.510540 99703956%2C-0.34322991874810915/@5																																										
0080			6/4/2023	https://www.google.com/maps/place/51.516350 2009314%2C-0.34867263993621167/@5																																										
0081			6/4/2023	https://www.google.com/maps/place/51.525209 6139311%2C-0.3439010280721222/@51																																										
0082			6/4/2023	https://www.google.com/maps/place/51.508097 62618746%2C-0.2454961437337433/@51																																										
0083			6/4/2023	https://www.google.com/maps/place/51.511507 8577171%2C-0.3166497844808136/@51																																										
0084			6/4/2023	https://www.google.com/maps/place/51.499968 73272374%2C-0.31471859399009094/@5																																										
0085			6/4/2023	https://www.google.com/maps/place/51.514306 10659585%2C-0.3011578592225365/@51.																																										

0263			6/4/2023	https://www.google.com/maps/place/51.508101 80608874%2C-0.3499676463672219/@51																																										
0264			6/4/2023	https://www.google.com/maps/place/51.507643 9329934%2C-0.25953696510763624/@5																																										
0265			6/4/2023	https://www.google.com/maps/place/51.508877 4092225%2C-0.2593253895687475/@51																																										
0266	I can't get this to work! I can only put one pin on the map; after that, they disappear.	1	6/4/2023	https://www.google.com/maps/place/51.509876 84457%2C-0.31908297492640125/@5	62 Mattock Ln, London W13 9LA			Survey issue																																						1
0267			6/4/2023	https://www.google.com/maps/place/51.494312 9050682%2C-0.3078176970638524/@51																																										
0268			6/4/2023	https://www.google.com/maps/place/51.507443 66838074%2C-0.2635046740256941/@51																																										
0269			6/4/2023	https://www.google.com/maps/place/51.514494 42730374%2C-0.3246161242210066/@51																																										
0270			6/4/2023	https://www.google.com/maps/place/51.522713 8156752%2C-0.3232804692481839/@51																																										
0271			6/4/2023	https://www.google.com/maps/place/51.504861 78581356%2C-0.3185660671085122/@51																																										
0272			6/4/2023	https://www.google.com/maps/place/51.515068 2848444%2C-0.30207591349317164/@5																																										
0273			6/4/2023	https://www.google.com/maps/place/51.525570 8030844%2C-0.3169578208669921/@51																																										
0274			6/4/2023	https://www.google.com/maps/place/51.510545 21627596%2C-0.2954858874873989/@51																																										
0275	Creffield road	1	6/4/2023	https://www.google.com/maps/place/51.497189 4039427%2C-0.257205400426852/@51.	49 Creffield Rd, London,	Acton / Ealing Common	Ealing Common / North Acton	Infrastructure / designation could be improved on Creffield Road	1			1			1												1																			
0276	From North Hanwell to West Ealing shops	1	6/4/2023	https://www.google.com/maps/place/51.526350 7746595%2C-0.34470050532452223/@5	42 Brookbank Ave, London,	North Hanwell	North Hanwell	C87 provides this connection but improvements could be made to Greenford Ave																			1																			
0277			6/4/2023	https://www.google.com/maps/place/51.516678 68798405%2C-0.3098417852869817/@51																																										
0278	From North Hanwell into Northfields and South Ealing	1	6/4/2023	https://www.google.com/maps/place/51.505888 0750005%2C-0.32202974305065357/@5	149 Westfield Rd, London,	Walpole	Walpole	North South through Walpole / Northfields Ave not currently designated	1			1												1			1																			
0279			6/4/2023	https://www.google.com/maps/place/51.513351 8670639%2C-0.3007473396677174/@51																																										
0280			6/4/2023	https://www.google.com/maps/place/51.496018 63388915%2C-0.30575124144571086/@5																																										
0281			6/4/2023	https://www.google.com/maps/place/51.513962 8049536%2C-0.3007979746719869/@51																																										
0282			6/4/2023	https://www.google.com/maps/place/51.510952 2261607%2C-0.28579653017872353/@5																																										
0283			6/4/2023	https://www.google.com/maps/place/51.503111 4034511%2C-0.30762195655321234/@5																																										
0284			6/4/2023	https://www.google.com/maps/place/51.510644 54554606%2C-0.30541181632494085/@5																																										
0285			6/4/2023	https://www.google.com/maps/place/51.504872 0649933%2C-0.3060715392163571/@51																																										
0286			6/4/2023	https://www.google.com/maps/place/51.513472 43501956%2C-0.30429055243046843/@5																																										
0287	A way to get through to Osterley fro Hanwell	1	6/4/2023	https://www.google.com/maps/place/51.500827 9590736%2C-0.3381100939813475/@51	Trumpers Way, London, W7 2LZ	Trumpers Way / Windmill Lane	Hanwell Broadway / Norwood Green	No existing route - would most likely require Windmill Lane improvement	1		1					1								1																						
0288	A way to get to Osterley from Hanwell	1	6/4/2023	https://www.google.com/maps/place/51.498536 72055284%2C-0.3437678792769727/@51	Warren Farm Nature Reserve,			As above																																						
0289	Could there be dedicated cycle routes on residential streets in Northfields?	1	6/4/2023	https://www.google.com/maps/place/51.503013 45308225%2C-0.3305713592430215/@51	14 Elthorne Ave, London,	Walpole / Northfields	Hanwell Broadway / Northfield	Only existing route is East / West on c41 (Oaklands). Are would benefit from designated North / South and also another East / West further south	1			1			1									1																						
0290			6/4/2023	https://www.google.com/maps/place/51.505543 239088%2C-0.3058347373998016/@51																																										
0291			6/4/2023	https://www.google.com/maps/place/51.511345 3056018%2C-0.30531975326894223/@5																																										
0292			6/4/2023	https://www.google.com/maps/place/51.513574 2355405%2C-0.30404302177785336/@5																																										
0293			6/4/2023	https://www.google.com/maps/place/51.511504 4743588%2C-0.3051588207280487/@51																																										
0294			6/4/2023	https://www.google.com/maps/place/51.509793 80064186%2C-0.27740924555889723/@5																																										
0295			6/4/2023	https://www.google.com/maps/place/51.521481 0980362%2C-0.3088921646644449/@51																																										
0296			6/4/2023	https://www.google.com/maps/place/51.507422 330829%2C-0.29945830836308085/@5																																										
0297			6/4/2023	https://www.google.com/maps/place/51.514683 63289376%2C-0.3008032899596169/@51																																										
0298			6/4/2023	https://www.google.com/maps/place/51.505068 9280923%2C-0.30621062333364035/@5																																										
0299	From South Ealing to Ealing Broadway	1	6/4/2023	https://www.google.com/maps/place/51.513642 8533675%2C-0.30625353867787863/@5	Wardens House, St Mary's Rd, London,	Ealing Broadway / South Ealing	Walpole / Ealing Common	Routes here head South or NW. Requires improvement to St Marys Road	1			1			1	1								1																						
0300	Commute to work	1	6/4/2023	https://www.google.com/maps/place/51.502233 6625627%2C-0.3147040234258158/@51	Lammas Park, Ealing	Walpole	Walpole	Unknown																																						
0301	Home. This area has a lot of through traffic or rat running. It has become a hostile place to cycle.	1	6/4/2023	https://www.google.com/maps/place/51.502658 9999064%2C-0.3262246262507973/@51	19 Balmoral Gardens, London,	Walpole	Walpole	Lack of designated routes and known area of rat running	1			1			1									1																						
0302	The children's school. Lots of traffic at pick up an drop off times. No action is take by the council or school to improve parking, vehicle speed or volume. Likely to lead to a serious incident in the near future	1	6/4/2023	https://www.google.com/maps/place/51.501523 294179%2C-0.3217618897332475/@51	50 Wyndham Rd, London,	Walpole	Walpole	Fielding Primary School - engagement with the council is known to be poor	1			1			1	1								1									1															
0303			6/4/2023	https://www.google.com/maps/place/51.511896 4972646%2C-0.30397941112938476/@5																																										
0304			6/4/2023	https://www.google.com/maps/place/51.512274 1075013%2C-0.3371027731420462/@51																																										
0305			6/4/2023	https://www.google.com/maps/place/51.527677 1370981%2C-0.3422136088516492/@51																																										
0306	A safe cycle route to Gunnersbury Park from West Chiswick. Another road with too many parked cars on both sides of the road especially east the level crossings and near the roundabout at Acton Town tube station Getting across the north circular can also be very scary	1	6/4/2023	https://www.google.com/maps/place/51.494781 0263086%2C-0.2678792158682608/@51	94 Bollo Ln, London, W4 5LX	South Acton Bollo Lane	South Acton / Southfield	No connection between Acton Town and Chiswick Park - Bollo Lane is the only option	1			1			1	1																														
0307			6/4/2023	https://www.google.com/maps/place/51.502812 5595142%2C-0.29422495488696576/@5																																										
0308	I would cycle to Ealing more often if there was a segregated cycle lane (same design as C9) along Uxbridge Road. At the moment it is too dangerous and the wands offer very little protection. Drivers ignore the cycle lane	1	6/4/2023	https://www.google.com/maps/place/51.507723 7734009%2C-0.249081416254191/@51.	1 The Vale, London, W3 7RU	East Acton	East Acton / Southfield	Uxbridge Road - poor driver behaviour and increase segregation	1			1	1		1	1			1							1							1														
0309			6/4/2023	https://www.google.com/maps/place/51.514359 96960786%2C-0.3020703657163337/@51																																										
0310			6/4/2023	https://www.google.com/maps/place/51.507566 8548722%2C-0.3198188919691458/@51																																										
0311			6/4/2023	https://www.google.com/maps/place/51.501050 6799901%2C-0.3340355401483941/@51																																										
0312			6/4/2023	https://www.google.com/maps/place/51.503401 11003985%2C-0.3307739739862847/@51																																										
0313			6/4/2023	https://www.google.com/maps/place/51.505752 3273989%2C-0.32493748716987847/@5																																										
0314			6/4/2023	https://www.google.com/maps/place/51.513358 7219199%2C-0.3902905038137616/@51																																										
0315			6/4/2023	https://www.google.com/maps/place/51.510747 6148248%2C-0.30545831921597877/@5																																										
0316			6/4/2023	https://www.google.com/maps/place/51.512446 5482658%2C-0.3275303327106105/@51																																										
0317	Coldershaw Road to Warren Farm	1	6/4/2023	https://www.google.com/maps/place/51.505693 3540339%2C-0.32557544058629206/@5	117 Coldershaw Rd, London,	Boston Manor	Hanwell Broadway	Trumpers Way is the missing link here as an extension to c41	1			1				1								1																						
0318			6/4/2023	https://www.google.com/maps/place/51.502651 7985153%2C-0.34365427421025885/@5																																										
0319			6/4/2023	https://www.google.com/maps/place/51.495802 7641166%2C-0.2995033084527954/@51																																										
0320			6/4/2023	https://www.google.com/maps/place/51.515142 2460586%2C-0.3161544620172485/@51																																										
0321			6/4/2023	https://www.google.com/maps/place/51.515779 3454801%2C-0.30397651448667906/@5																																										
0322			6/4/2023	https://www.google.com/maps/place/51.509834 1850992%2C-0.24743306560407685/@5																																										
0323	Link Dane Road to network	1	6/4/2023	https://www.google.com/maps/place/51.510451 68880074%2C-0.3148150430996499/@51	41 Dane Rd, London, W13 9NS	Walpole	Walpole	Culmington Road would provide better connections but would be tricky owing to two way traffic volumes																																						
0324	Complete a route from Dane Road to St Nicholas's	1	6/4/2023	https://www.google.com/maps/place/51.528779 4602995%2C-0.3097203952286165/@51	St Mary with St Nicholas Church,	Montpelier	Pitshanger / Perivale / Ealing Broadway	Tricky - no existing routes, the north / south connections across Uxbridge Road and the Main Line should certainly be improved as a start point																																						
0325	Cycle route for Ruislip Road	1	6/4/2023	https://www.google.com/maps/place/51.529047 5356338%2C-0.35209811609509645/@5	4 The Broadway, Greenford UB6 9PR	Greenford	Greenford Broadway	No cycle infrastructure on this section of Ruislip Road	1			1			1	1			1					1																						
0326			6/4/2023	https://www.google.com/maps/place/51.534080 7296579%2C-0.37888603427252976/@5																																										
0327			6/4/2023	https://www.google.com/maps/place/51.509669 4807582%2C-0.2771594187753368/@51																																										
0328			6/4/2023	https://www.google.com/maps/place/51.496670 912545%2C-0.2636840006845165/@51																																										
0329			6/4/2023	https://www.google.com/maps/place/51.519107 67161766%2C-0.2663447520272899/@51																																										
0330	There is no cycling infrastructure throughout the West Ealing and Southall sections of the Uxbridge Road	1	6/4/2023	https://www.google.com/maps/place/51.512998 2994951%2C-0.366329838820616/@51.	90-94 Uxbridge Rd, London,	West Ealing / Southall	Hanwell Broadway / Walpole / Southall	Southall / West Ealing hot spots	1			1			1	1			1					1																						
0330.1		1			6 High St, Southall UB1 3DA			Additional location for previous log	1			1			1	1			1					1																						
0331			6/4/2023	https://www.google.com/maps/place/51.509580 0205451%2C-0.27462691177241094/@5																																										
0332	Rat-running makes these West Ealing backroads horrible to cycle down and the narrow width causes congestion, hostility and dangerous driving every single day. The LTN should never have been taken out. Reinstall the LTNs	1	6/4/2023	https://www.google.com/maps/place/51.510755 1870582%2C-0.32865359415045203/@5	29-11 Eccleston Rd, London,	West Ealing	Hanwell Broadway	Former LTN 20 rat running issues	1			1				1																	1			1		1									
0333			6/4/2023	https://www.google.com/maps/place/51.497238 9684752%2C-0.3246195517920536/@51																																										
0334	Start of journey to Chiswick station, or somewhere near Halfords cycle store in Chiswick high road	1	6/4/2023	https://www.google.com/maps/place/51.499545 13122456%2C-0.3036452919302768/@51	45 Durham Rd, London, W5 4JR			C86 and C35 cover most of this route along with the cycle paths on Great West Road. Designation could be improved but no new route required	1			1			1												1																			
0334.1		1			512-518 Chiswick High Rd., Chiswick,			Additional location for previous log	1			1			1												1																			
0335			6/4/2023	https://www.google.com/maps/place/51.494711 6859948%2C-0.26716602321318783/@5																																										
0336			6/4/2023	https://www.google.com/maps/place/51.504722 23275005%2C-0.3061880878655887/@51																																										
0337	I don't like cycling up to Ealing Broadway from South Ealing station, traffic is frequently inconsiderate and feels threatening.	1	6/4/2023	https://www.google.com/maps/place/51.510595 7808124%2C-0.3055416229006891/@51	25 The Grn, London, W5 5DA	South Ealing	Walpole / Ealing Common	No north / south option. hotspot	1			1	1		1	1								1									1															
0338			6/4/2023	https://www.google.com/maps/place/51.524409 6922982%2C-0.264948555078135/@51.																																										
0339			6/4/2023	https://www.google.com/maps/place/51.529375 06572824%2C-0.2664935074707131/@51																																										
0340			6/4/2023	https://www.google.com/maps/place/51.520040 27378934%2C-0.27988309487305685/@5																																										
0341			6/4/2023	https://www.google.com/maps/place/51.513116 0273927%2C-0.27287822855971866/@5																																										
0342			6/4/2023	https://www.google.com/maps/place/51.520317 7617973%2C-0.26209137105809743/@5																																										
0343			6/4/2023	https://www.google.com/maps/place/51.529397 66807855%2C-0.24980544683264272/@5																																										
0344	I would like to start on Shakespeare road where I live, howeve Drayton bridge road is very busy and doesn't feel safe. It would be good to improve this area for cycling.	1	6/4/2023	https://www.google.com/maps/place/51.515809 5683461%2C-0.3302540594982428/@51	130 Shakespeare Rd, London,	Drayton Green	North Hanwell / Pitshanger	No designated routes in the area. The railway is a barrier and Drayton Bridge Road which lacks infrastructure or designation is the	1			1			1	1								1																						
0345	I would finish by journey at Ealing Broadway where I would go shopping so a safe route along Uxbridge road.	1	6/4/2023	https://www.google.com/maps/place/51.515343 64883086%2C-0.3047300466004854/@51	3 Haven Grn, London, W5 2PR	Ealing Broadway	Ealing Broadway	General Uxbridge Road Ealing concerns	1			1	1			1			1																											
0346	Nowhere! This survey is just a biased joke... I shall be reporting this to my local concillors. But then again, do you really care?	1	6/4/2023	https://www.google.com/maps/place/51.522399 0884947%2C-0.33251254756085036/@5	27 Ditchley Ct, Templeman Rd,	Drayton Green	North Hanwell	Survey issue																																						1
0347			6/4/2023	https://www.google.com/maps/place/51.513452 6044877%2C-0.31989543635479567/@5																																										
0348	Narrow road, Argyle Road, immediately north of West Ealing station up to the junction with Sutherland Road, very tempting for cars to overtake, despite the curving nature of the road, that prevents all from seeing fully ahead	1	6/4/2023	https://www.google.com/maps/place/51.516497 1864045%2C-0.32204120356670973/@5	70 Argyle Rd, London, W13 8EL	West Ealing	Pitshanger / Ealing Broadway	Valid point but the designated route is parallel (The Avenue) so better awareness of the cycle routes would be the obvious solution	1			1			1												1						1															
0349			6/4/2023	https://www.google.com/maps/place/51.515120 2831245%2C-0.34016317202530066/@5																																										

0439	It shouldn't be a life threatening experience to cycle with children to Acton library and sports facility. The Uxbridge Road is unsafe.	1	7/4/2023	https://www.google.com/maps/place/51.508396 3211205%2C-0.2693065984649601/@51	104a Churchfield Rd, London,	Acton Central	South Acton	Generally poor infrastructure on Churchfield / Uxbridge Road despite cycle route designation	1			1			1	1										1	1																			
0440			7/4/2023	https://www.google.com/maps/place/51.526094 5771855%2C-0.30796121404449206/@5																																										
0441	I would like to see safe routes linking with other boroughs in order to safely get around beyond Ealing	1	7/4/2023	https://www.google.com/maps/place/51.501155 23896524%2C-0.3908869335996812/@51	48 Emerald Square, Southall	LBE		General request								1	1																													
0442	Along the canal from Bulls Bridge to Glade Lane Park. The path is terrible, in places muddy, in others overgrown, with rough sleeping, street drinking and drug dealing making it unsafe at night.	1	7/4/2023	https://www.google.com/maps/place/51.503275 522315%2C-0.3637555441091367/@51	2 Glade Ln, Southall UB2 4PL	Southall Green / Norwood Green	Southall Green / Norwood Green	Canal tow path is narrow dirt track through this section. Various short and long term concerns	1			1			1	1					1	1	1									1								1							
0442.1		1			2 Bulls Bridge Rd, Southall UB2 5LU			Additional location for previous log	1			1			1	1					1	1	1									1								1							
0443	Windmill Lane is very dangerous for cyclists from 3 bridges down towards Osterley/Brentford. Road is narrow, people are driving too fast and cut cyclists up all the time.	1	7/4/2023	https://www.google.com/maps/place/51.497612 3627911%2C-0.3412679037282773/@51	Earl of Jerseys Field, Southall	Windmill Lane Norwood Green	Norwood Green	Windmill Lane lack of cycle infrastructure. Make the path as wide as possible then shared?	1			1	1			1								1									1														
0444	The way through from Boston Manor Road to Northfields is an often sued cut for cyclists (to avoid the narrow and congested side streets) but, hard to navigate through the car park.	1	7/4/2023	https://www.google.com/maps/place/51.497309 7499209%2C-0.32376105791606546/@5	105 Burnham Way, London,	Northfield / Boston Manor	Northfield	Interesting - potential East / West connection that avoids the political challenge of the area but this does not appear to be a formal right of way																																						
0445			7/4/2023	https://www.google.com/maps/place/51.507120 7889203%2C-0.3118214919298601/@51																																										
0446			7/4/2023	https://www.google.com/maps/place/51.494054 7333335%2C-0.30794575356445586/@5																																										
0447	Pitshanger Lane Kent Gardens Castlebar Road Argyle Road	1	7/4/2023	https://www.google.com/maps/place/51.525897 36048885%2C-0.3171089479185851/@51	1 Curzon Rd, London, W5 1NE	Pitshanger / Montpelier	Pitshanger / Ealing Broadway	Pitshanger Lane is the key route as there are no East / West designated routes in the area; Pitshanger / Mount / Montpelier Roads should all	1			1			1	1								1			1																			
0448			7/4/2023	https://www.google.com/maps/place/51.528122 4240006%2C-0.30650464205636885/@5																																										
0449	Woodville Road	1	7/4/2023	https://www.google.com/maps/place/51.527374 16897%2C-0.30880342297516794/@5	11 Denison Rd, London,	Montpelier	Pitshanger	General lack of infrastructure / designation in this area	1			1			1									1																						
0450			7/4/2023	https://www.google.com/maps/place/51.522374 6187796%2C-0.3069799995302924/@51																																										
0451	From the start of Elthorne park Road (usefully linking up to Elthorne Park and the Grand Union Canal)	1	7/4/2023	https://www.google.com/maps/place/51.502644 0817921%2C-0.3308889271309079/@51	1 Elthorne Park Rd., London, W7 2JB	Hanwell	Hanwell Broadway / Northfield	This start / finish is the lack of designated route through Hanwell (former LTN 21) between Boston Road and Northfield	1			1				1								1																						
0452	Linking the parks e.g. linking Elthorne Park via Elthorne Park Road and then some back streets to the southern tip of Lammas Park!	1	7/4/2023	https://www.google.com/maps/place/51.501805 66457%2C-0.3152539638304308/@51	183 Northfield Ave, London,																																									
0453			7/4/2023	https://www.google.com/maps/place/51.502312 7644223%2C-0.3647022981531589/@51																																										
0454			7/4/2023	https://www.google.com/maps/place/51.498928 469775%2C-0.33439937635104/@51.4																																										
0455			7/4/2023	https://www.google.com/maps/place/51.500852 5835699%2C-0.3646240807480261/@51																																										
0456			7/4/2023	https://www.google.com/maps/place/51.507544 5373771%2C-0.37650272775541005/@5																																										
0457	queens drive to horn lane via noel road should also have cycling paths	1	7/4/2023	https://www.google.com/maps/place/51.521782 49783695%2C-0.264466954274738/@51.	2 Noel Rd, London, W3 0JE	West Acton	Hanger Hill / North Acton	Agreed - flagged as a possible east-west route	1			1			1	1								1																						
0458			7/4/2023	https://www.google.com/maps/place/51.521603 132788%2C-0.32486388926456833/@5																																										
0459			7/4/2023	https://www.google.com/maps/place/51.516996 128565%2C-0.3019418631009052/@51																																										
0460			7/4/2023	https://www.google.com/maps/place/51.514455 4546397%2C-0.321116529753831/@51.																																										
0461			7/4/2023	https://www.google.com/maps/place/51.497592 5339529%2C-0.3125388496322201/@51																																										
0462			7/4/2023	https://www.google.com/maps/place/51.528151 7971056%2C-0.29977781164391315/@5																																										
0463			7/4/2023	https://www.google.com/maps/place/51.497023 4814119%2C-0.30479890691979206/@5																																										
0464			7/4/2023	https://www.google.com/maps/place/51.533130 5689203%2C-0.2981041132186202/@51																																										
0465			7/4/2023	https://www.google.com/maps/place/51.545750 5036725%2C-0.38334008667507247/@5																																										
0466			7/4/2023	https://www.google.com/maps/place/51.523119 6518651%2C-0.3365895052634871/@51																																										
0467			7/4/2023	https://www.google.com/maps/place/51.513127 67526375%2C-0.3368491066795709/@51																																										
0468	I'd like to cycle from Northfields to Knightsbridge along the Uxbridge Road. There are big gaps in the cycle paths so I go on the tube.	1	7/4/2023	https://www.google.com/maps/place/51.509045 0264586%2C-0.3184363146506941/@51	66 Radbourne Walk, London	Uxbridge Road	West London,	General unconnected infrastructure on Uxbridge Road	1			1	1		1	1			1					1																						
0469			7/4/2023	https://www.google.com/maps/place/51.507763 9850944%2C-0.25286166865460036/@5																																										
0470			7/4/2023	https://www.google.com/maps/place/51.499856 9241336%2C-0.26110141474835036/@5																																										
0471			7/4/2023	https://www.google.com/maps/place/51.511182 6269914%2C-0.28582065302960036/@5																																										
0472			7/4/2023	https://www.google.com/maps/place/51.531690 6047014%2C-0.2971503039085066/@51																																										
0473			7/4/2023	https://www.google.com/maps/place/51.514173 5841116%2C-0.2792975207053816/@51																																										
0474	Bicycle lanes to connect the different parks to allow the younger generations to move around on their bike	1	7/4/2023	https://www.google.com/maps/place/51.530398 400609%2C-0.315730895109001/@51.	130 Meadvale Rd, London,	Ealing	Ealing	General request for parks to be connected - nice idea	1			1				1								1																						
0475	Safe crossing around north/south circular specific for bikes	1	7/4/2023	https://www.google.com/maps/place/51.512488 7216941%2C-0.29012936600419037/@5	2-8 Hanger Ln, London, W5 3HN	Ealing Common	Ealing Common	Logged as the Uxbridge / A406 hotspot but the issue is valid around all off the north circular	1			1	1		1	1			1					1					1																	
0476	Maybe leverage the tube lines for bicycle path	1	7/4/2023	https://www.google.com/maps/place/51.516210 2330484%2C-0.3094101888448164/@51	45 Castlebar Rd, London,	Ealing	Ealing	Would require huge ambition on the part of TfL - unlikely unless TfL bring it to the table			1					1																														
0477	Uxbridge road between hanwell and Ealing is unpleasant and often dangerous to cycle. The 20 mile speed limit helps when enforced, but is still on a major road with lorries. Creating a new path through the Kensington cemetery by connecting Holly Park Road with Felix	1	7/4/2023	https://www.google.com/maps/place/51.511149 89199416%2C-0.33500746816396365/@5	50 Church Rd, London, W7 1LB	Hanwell / West Ealing	Hanwell Broadway / Walpole / Ealing	Same comment in Q2: Uxbridge Road West Ealing / Hanwell. Suggestion of a new East-West route though Kensington Cemetery which would	1		1					1			1					1		1																					
0478			7/4/2023	https://www.google.com/maps/place/51.512143 7379024%2C-0.3288704092220085/@51																																										
0479			7/4/2023	https://www.google.com/maps/place/51.508699 9874097%2C-0.3445112057688715/@51																																										
0480	Through meadow if surface improved.	1	7/4/2023	https://www.google.com/maps/place/51.512238 8002392%2C-0.34246606979861705/@5	483 Uxbridge Rd, Southall			Paths through Brent Meadow worth considering to improve connections between C87 and Ealing Hospital / Canal Path etc without use of the	1		1				1	1								1																			1	Paths through parkland	
0481	I would like to cycle from Northfields avenue up argyle road but it is currently unsafe to cycle along Northfields allotments and the first section of argyle road	1	7/4/2023	https://www.google.com/maps/place/51.506916 3622532%2C-0.31942697300200606/@5	Northfield Allotments, Northfield	West Ealing / Walpole / Pitshanger	Pitshager / Ealing Broadway / Walpole	Limited infrastructure on Northfield the has to cross hotspot Lido junction followed by no infrastructure on Drayton Green Road	1			1	1		1	1			1					1					1																	
0481.1		1			1, Castle Hill Parade, The			Additional location for previous log	1			1	1		1	1			1					1					1																	
0482			7/4/2023	https://www.google.com/maps/place/51.513354 6759444%2C-0.31971583464393216/@5																																										
0483			7/4/2023	https://www.google.com/maps/place/51.511342 81917004%2C-0.3194684957081395/@51																																										
0484			7/4/2023	https://www.google.com/maps/place/51.497638 1690889%2C-0.3122372602039891/@51																																										
0485	Acton Lane to join up Chiswick Park tube station with Acton Main Line	1	7/4/2023	https://www.google.com/maps/place/51.498461 96916654%2C-0.2635214988828616/@51	11 Evelyn Rd, London, W4 5JL	Chiswick - Acton	Southfield / South Acton / East Acton	Some coverage via C49 but Acton Lane lacks infrastructure and there are missing links around Acton Main Line (Horn Lane etc and general lack of	1			1			1	1								1																						
0486			7/4/2023	https://www.google.com/maps/place/51.542542 2858898%2C-0.3798927310002487/@51																																										
0487			7/4/2023	https://www.google.com/maps/place/51.518546 5667117%2C-0.3073413436492789/@51																																										
0488			7/4/2023	https://www.google.com/maps/place/51.515389 15909806%2C-0.3489950530025965/@51																																										
0489			7/4/2023	https://www.google.com/maps/place/51.508191 70563656%2C-0.3862425585471785/@51																																										
0490			7/4/2023	https://www.google.com/maps/place/51.502635 2117236%2C-0.39963214594952223/@5																																										
0491			7/4/2023	https://www.google.com/maps/place/51.507763 9850946%2C-0.39001910884014723/@5																																										
0492			7/4/2023	https://www.google.com/maps/place/51.497719 0118615%2C-0.36941974360577223/@5																																										
0493			7/4/2023	https://www.google.com/maps/place/51.498520 91821954%2C-0.3055352830503244/@51																																										
0494			7/4/2023	https://www.google.com/maps/place/51.505831 7524544%2C-0.2898249400314601/@51																																										
0495	the avenue road cycle way is poor signed - the sign on the contraflow at the top is nearly invisible - there needs to be a warning sign for traffic that there may be bikes coming the other way	1	7/4/2023	https://www.google.com/maps/place/51.506474 9825143%2C-0.27371852595440505/@5	21B Mill Hill Rd, London, W3 8JE	Acton	South Acton	Langley Drive appears to be the referenced section - signs and lane are present therefore it appears better than some contraflows but	1			1			1										1	1	1																			
0496	Popes lane has a 20 limit but people often go along here at 40. There are no speed cameras, it's a wide road but because of dispersed park cars cyclists are quite vulnerable here - controlling speed would really help - also see previous comments re crossing	1	7/4/2023	https://www.google.com/maps/place/51.502039 51137525%2C-0.288052250929991/@51.	200 Popes Ln, London, W5 4LY	Gunnersbury Park	Ealing Common	Popes Lane should be improved as a key east - west route. Enforcement of 20mph could help	1			1			1																	1	1													
0497	traffic drives far too fast on Southfield road - it is narrow with parked cars on both sides and buses, no room for a cycle path - needs cameras and proper enforcement to make it safe for cyclists. Also there is no crossing between this end and when it meets the	1	7/4/2023	https://www.google.com/maps/place/51.503028 6708297%2C-0.26547877986065505/@5	224 Southfield Rd, London,	Southfield	Southfield	Lack of cycle crossing once beyond the bridge on Acton Lane. Speed enforcement may indeed be helpful	1			1			1	1																1	1												1	Additional crossing needed on Acton Lane between The Avenue and Southfield	
0498			7/4/2023	https://www.google.com/maps/place/51.496189 58313966%2C-0.2556940813743269/@51																																										
0499			7/4/2023	https://www.google.com/maps/place/51.507445 3397485%2C-0.2508593534401271/@51																																										
0500			7/4/2023	https://www.google.com/maps/place/51.498082 3405257%2C-0.2574025419704018/@51																																										
0501			7/4/2023	https://www.google.com/maps/place/51.500621 2089257%2C-0.3140930325871727/@51																																										
0502			7/4/2023	https://www.google.com/maps/place/51.512354 767428%2C-0.3048789189309886/@51																																										
0503			7/4/2023	https://www.google.com/maps/place/51.524389 16724014%2C-0.33570008766289794/@5																																										
0504			7/4/2023	https://www.google.com/maps/place/51.509177 6563519%2C-0.24812964600351872/@5																																										
0505			7/4/2023	https://www.google.com/maps/place/51.517564 27156235%2C-0.29713209827992193/@5																																										
0506			7/4/2023	https://www.google.com/maps/place/51.546268 1466866%2C-0.3371855770500165/@51																																										
0507			7/4/2023	https://www.google.com/maps/place/51.501452 6324918%2C-0.2851158308016388/@51																																										
0508			7/4/2023	https://www.google.com/maps/place/51.508959 41491366%2C-0.27593194713464664/@5																																										
0509			7/4/2023	https://www.google.com/maps/place/51.507316 46348084%2C-0.268196059773933/@51.																																										
0510			7/4/2023	https://www.google.com/maps/place/51.522000 3691267%2C-0.26441950948096427/@5																																										
0511			7/4/2023	https://www.google.com/maps/place/51.503672 2113116%2C-0.27962095161307765/@5																																										
0512	Bollo bridge road and the underpass at Acton Lane are very difficult for cyclists. Bollo bridge road has parking on both sides despite being too narrow even for a car and bus to cross paths safely. Eliminating parking on one side would make this a much safer	1	7/4/2023	https://www.google.com/maps/place/51.503151 0924711%2C-0.2621544065080972/@51	317b Acton Ln, London, W3 8NT	Southfield / South Acton	Southfield / South Acton	Bridge/Underpass on Acton Lane is narrow but very difficult to improve. Bollo Bridge Road improvements could provide additional east - west	1		1	1			1	1								1																	1						
0513			7/4/2023	https://www.google.com/maps/place/51.504521 46936634%2C-0.2800632699717376/@51																																										
0514	please make a cycling lane on Bollo Lane from Acton town station to Chiswick park station	1	7/4/2023	https://www.google.com/maps/place/51.495492 33055826%2C-0.26736032807720633/@5	5A Bollo Ln, London, W4 5LW	Southfield / South Acton	Southfield / South Acton	Bollo Lane - hotspot route suggestion	1			1	1		1	1								1																						
0515	please do make a cycling lane from Acton town station to Uxbridge Road or at least Mill Hill Road	1	7/4/2023	https://www.google.com/maps/place/51.503072 5562429%2C-0.28126489961040946/@5	37 Gunnersbury Cres, London,	Acton Town	South Acton	This link is needed and has been outlined (but to The Avenue rather than Mill Hill Road to reduce distance on Gunnersbury Lane and	1			1			1	1								1																						
0516			7/4/2023	https://www.google.com/maps/place/51.508321 81335325%2C-0.2764154657114837/@51																																										
0517			7/4/2023	https://www.google.com/maps/place/51.506315 7187317%2C-0.2783927183787194/@51																																										
0518	Northfield avenue very exposed for younger and less experienced cyclists	1	7/4/2023	https://www.google.com/maps/place/51.497653 5454192%2C-0.3116157037245637/@51	62 Little Ealing Ln, London, W5 4EA	Northfield	Northfield / Walpole	Agreed - lack of infrastructure	1			1	1		1	1								1																						
0519			7/4/2023	https://www.google.com/maps/place/51.510562 1511988%2C-0.3187596032223272/@51																																										
0520	Pope's Lane is very exposed, particularly due to parked vehicles. Protected space needed	1	7/4/2023	https://www.google.com/maps/place/51.499499 2878077%2C-0.3019268436563971/@51	78 Popes Ln, London, W5 4NT	South Ealing	Northfield / Ealing Common	Agreed - poor cycle infrastructure which could be improved if parking is reduced	1			1			1	1								1		1																				
0521			7/4/2023	https://www.google.com/maps/place/51.501360 7738913%2C-0.28581050201804903/@5																																										
0522			7/4/2023	https://www.google.com/maps/place/51.507917 9527333%2C-0.3137444399369671/@51																																										
0523			7/4/2023	https://www.google.com/maps/place/51.506883 8015294%2C-0.31726081266965966/@5																																										
0524	no safe cycle ways	1	7/4/2023	https://www.google.com/maps/place/51.543249 7710767%2C-0.3237624873217593/@51	Horsenden Farm, Horsenden Ln N,	Horsenden Hill	Perivale / North Greenwood	There are challenges around the bridge and lack of well designated / segregated routes south of the bridge however there are segregated routed	1			1			1	1								1			1																			
0525			7/4/2023	https://www.google.com/maps/place/51.499283 6313954%2C-0.31366207708245053/@5																																										

0526			7/4/2023	https://www.google.com/maps/place/51.5017262 36006604%2C-0.29338832940101645/@5																																											
0527			7/4/2023	https://www.google.com/maps/place/51.5043975 28485555%2C-0.28075414593595527/@5																																											
0528			7/4/2023	https://www.google.com/maps/place/51.4957951 78270285%2C-0.266677913025799/@51																																											
0529			7/4/2023	https://www.google.com/maps/place/51.5174869 78771366%2C-0.2913781901084578/@51																																											
0530			7/4/2023	https://www.google.com/maps/place/51.5180210 79201446%2C-0.2803489466392195/@51																																											
0531	From Acton Town to S Ealing. Too many parked cars Westbound and dreadful potholes at S Ealing Road end after Lionel Park Rd	1	7/4/2023	https://www.google.com/maps/place/51.5043261 3901562%2C-0.28008244090212076/@5	Bronte Court, Gunnersbury Ln,	South Ealing / Acton Towr	Northfield / Ealing Common / South	Lack of cycle infrastructure east - west therefore Popes Lane / Gunnersbury Lane should be considered for improvement. Additionally the road	1			1			1	1						1		1																							
0531.1		1			9 The Pavement, Popes Ln, London,			Additional location for previous log	1			1			1	1						1		1																							
0532			7/4/2023	https://www.google.com/maps/place/51.5280595 441646%2C-0.3095099230491316/@51																																											
0533	I gave up cycling in Ealing some years ago because of the state of the roads - cracks, potholes and uneven cambers. If the roads were properly maintained I would cycle.	1	7/4/2023	https://www.google.com/maps/place/51.5141739 58411185%2C-0.31053989131085036/@5	59 Craven Ave, London,	Ealing	Ealing	Poor road surfaces in general														1																									
0534			7/4/2023	https://www.google.com/maps/place/51.5118236 7117295%2C-0.32495944697491286/@5																																											
0535			7/4/2023	https://www.google.com/maps/place/51.5122510 05144684%2C-0.2992102404319441/@51																																											
0536			7/4/2023	https://www.google.com/maps/place/51.5252827 6571319%2C-0.3156395688137348/@51																																											
0537			7/4/2023	https://www.google.com/maps/place/51.5160434 1848701%2C-0.3023358120998676/@51																																											
0538	Ealing tube station	1	7/4/2023	https://www.google.com/maps/place/51.5151477 11594224%2C-0.2995118861837609/@51	Ealing Broadway Station, The	Uxbridge Road		Just route designation																																						
0539	Southall iron bridge	1	7/4/2023	https://www.google.com/maps/place/51.5099733 45159594%2C-0.3543433888300518/@51	Iron Bridge, Uxbridge Rd,	Uxbridge Road		Just route designation																																						
0540			7/4/2023	https://www.google.com/maps/place/51.5104231 1844266%2C-0.3522419625835371/@51																																											
0541			7/4/2023	https://www.google.com/maps/place/51.5024096 17895374%2C-0.3298401528911543/@51																																											
0542			7/4/2023	https://www.google.com/maps/place/51.5000141 6362672%2C-0.2999465775209065/@51																																											
0543			7/4/2023	https://www.google.com/maps/place/51.5094704 4167103%2C-0.31900099036270335/@5																																											
0544			7/4/2023	https://www.google.com/maps/place/51.5045141 5947069%2C-0.280769914997272/@51																																											
0545			7/4/2023	https://www.google.com/maps/place/51.5089482 65811355%2C-0.2762208885080142/@51																																											
0546			7/4/2023	https://www.google.com/maps/place/51.5193071 7246966%2C-0.3004211624209452/@51																																											
0547			7/4/2023	https://www.google.com/maps/place/51.5348324 4865397%2C-0.2783783628064085/@51																																											
0548			7/4/2023	https://www.google.com/maps/place/51.5188744 868229%2C-0.30037937109272717/@5																																											
0549			7/4/2023	https://www.google.com/maps/place/51.5219627 87436%2C-0.31916834091222146/@5																																											
0550			7/4/2023	https://www.google.com/maps/place/51.5022975 329913%2C-0.26172503263328206/@5																																											
0551			7/4/2023	https://www.google.com/maps/place/51.5016563 90486225%2C-0.2591501119789852/@51																																											
0552			7/4/2023	https://www.google.com/maps/place/51.5093627 79283755%2C-0.31866133269197405/@5																																											
0553			7/4/2023	https://www.google.com/maps/place/51.4933309 9963339%2C-0.31117719407277367/@5																																											
0554			7/4/2023	https://www.google.com/maps/place/51.5149896 9554561%2C-0.3048652215918457/@51																																											
0555			7/4/2023	https://www.google.com/maps/place/51.5073475 9409537%2C-0.24746235526019733/@5																																											
0556			7/4/2023	https://www.google.com/maps/place/51.5032109 6984934%2C-0.27995810065762017/@5																																											
0557			7/4/2023	https://www.google.com/maps/place/51.5088738 9005278%2C-0.276267381053128/@51																																											
0558			7/4/2023	https://www.google.com/maps/place/51.5110835 69090246%2C-0.2720246167761209/@51																																											
0559			7/4/2023	https://www.google.com/maps/place/51.5173330 3057517%2C-0.26704643684448026/@5																																											
0560			7/4/2023	https://www.google.com/maps/place/51.5151214 3721505%2C-0.30261955560571874/@5																																											
0561			7/4/2023	https://www.google.com/maps/place/51.5106918 69194794%2C-0.30534598203204366/@5																																											
0562			7/4/2023	https://www.google.com/maps/place/51.5244346 46359225%2C-0.2919219425682562/@51																																											
0563			7/4/2023	https://www.google.com/maps/place/51.5015869 7041122%2C-0.2854692278462667/@51																																											
0564			7/4/2023	https://www.google.com/maps/place/51.5013316 4126372%2C-0.3377023847548877/@51																																											
0565	Cycle route to Osterley House	1	7/4/2023	https://www.google.com/maps/place/51.4976429 7797656%2C-0.3415294863968832/@51	Warren Farm Nature Reserve,			Trumpers Way / Windmill Lane are mostly likely																																						
0566			7/4/2023	https://www.google.com/maps/place/51.5018236 5431481%2C-0.2908071746700247/@51																																											
0567	I'd like my kids to be able to cycle to Oxygen.	1	7/4/2023	https://www.google.com/maps/place/51.5226990 2929483%2C-0.27671385856972597/@	15, Vision Industrial Park, Kendal	West Acton	North Acton	Various hotspots and lack of segregation	1			1	1			1								1		1																					
0568			7/4/2023	https://www.google.com/maps/place/51.5139088 8967443%2C-0.32063262835709816/@5																																											
0569			7/4/2023	https://www.google.com/maps/place/51.5404908 6080489%2C-0.3110741063620459/@51																																											
0570			7/4/2023	https://www.google.com/maps/place/51.5152916 6161592%2C-0.3032736824736504/@51																																											
0571			7/4/2023	https://www.google.com/maps/place/51.5091911 9415465%2C-0.24585623787484856/@5																																											
0572	Would like to cycle on main road to access high street	1	7/4/2023	https://www.google.com/maps/place/51.4981661 98565414%2C-0.31268070677403337/@5	46 Wellington Rd, London,	Northfield	Northfield / Walpole	Lack of cycle infrastructure on Northfield Avenue	1			1	1		1	1								1																							
0573			7/4/2023	https://www.google.com/maps/place/51.5123687 9169227%2C-0.3195042465079201/@51																																											
0574	Access route from Northfields to Acton Town	1	7/4/2023	https://www.google.com/maps/place/51.4982112 57535594%2C-0.31229446867588884/@5	46 Wellington Rd, London,	Northfield / South Ealing / Ealing	Northfield / Ealing Common / South	Most likely Little Ealing Lane / Popes Lane / Gunnersbury Lane	1			1	1		1	1								1																							
0574.1		1			40 Chatsworth Gardens, London,			Additional location for previous log	1			1	1		1	1								1																							
0575			7/4/2023	https://www.google.com/maps/place/51.5096444 7598695%2C-0.2764172408926857/@51																																											
0576			7/4/2023	https://www.google.com/maps/place/51.5067692 2565229%2C-0.33652479790487577/@5																																											
0577			7/4/2023	https://www.google.com/maps/place/51.5090783 3998684%2C-0.24620261017299194/@5																																											
0578			8/4/2023	https://www.google.com/maps/place/51.5079043 8255092%2C-0.249320021198014/@51																																											
0579			8/4/2023	https://www.google.com/maps/place/51.5266869 952922%2C-0.36023690185523316/@5																																											
0580			8/4/2023	https://www.google.com/maps/place/51.5009579 9494378%2C-0.311087532849188/@51																																											
0581			8/4/2023	https://www.google.com/maps/place/51.5301044 3932397%2C-0.3009685535869999/@51																																											
0582			8/4/2023	https://www.google.com/maps/place/51.5046945 0596731%2C-0.2551293631526219/@51																																											
0583			8/4/2023	https://www.google.com/maps/place/51.5065496 1737258%2C-0.25752644753858744/@5																																											
0584			8/4/2023	https://www.google.com/maps/place/51.5036926 05263446%2C-0.2564298886960792/@51																																											
0585			8/4/2023	https://www.google.com/maps/place/51.5043886 5413145%2C-0.2550832950243098/@51																																											
0586	Bike from Gunnersbury Park.	1	8/4/2023	https://www.google.com/maps/place/51.5014825 2091883%2C-0.28504529397108236/@5	2 Park Parade, London, W3 9BD			See below																																						
0587	Connect with Uxbridge Road.	1	8/4/2023	https://www.google.com/maps/place/51.5096021 1592044%2C-0.2734066246327749/@51	Lexden Rd, London, W3 9NE	Acton Towr	Ealing Common / South Acton	Gunnersbury Lane improvements	1			1	1		1	1								1																							
0588			8/4/2023	https://www.google.com/maps/place/51.5076736 9591696%2C-0.29695001844003643/@5																																											
0589	Make a route here!	1	8/4/2023	https://www.google.com/maps/place/51.5004856 64159136%2C-0.314844575205372/@51	215b Northfield Ave, London,	Northfield	Northfield / Walpole	Lack of cycle infrastructure on Northfield Avenue and the surrounding areas	1			1	1		1	1								1																							
0590			8/4/2023	https://www.google.com/maps/place/51.5114752 7975473%2C-0.31936497863346736/@5																																											
0591			8/4/2023	https://www.google.com/maps/place/51.4978643 95625086%2C-0.3109134363365418/@51																																											
0592			8/4/2023	https://www.google.com/maps/place/51.5069630 56744%2C-0.3051198648643738/@51																																											
0593			8/4/2023	https://www.google.com/maps/place/51.5074438 58472875%2C-0.2993692087364441/@51																																											
0594	Along Northfields Avenue- shared pavement would be good.	1	8/4/2023	https://www.google.com/maps/place/51.5065769 4405621%2C-0.31974013128884815/@5	Bonneville House, Northfield Ave,	Northfield	Northfield / Walpole	Lack of cycle infrastructure on Northfield Avenue	1			1	1		1	1								1		1																					
0595			8/4/2023	https://www.google.com/maps/place/51.5110642 6758117%2C-0.31941826620706104/@5																																											
0596	I would start along at my house and then to the shops at Lidl or Ealing Broadway.	1	8/4/2023	https://www.google.com/maps/place/51.5194428 2788343%2C-0.3346583147727644/@51	16 Littlejohn Rd, London,	North Hanwell	North Hanwell / Hanwell Broadway	Greenford Avenue - generally poor infrastructure																																						
0597	I would finish here but need cycle parking that is protected, church road which connects to uxbridge road needs segregated cycling and parking removed.	1	8/4/2023	https://www.google.com/maps/place/51.5100420 3881382%2C-0.3362890978538191/@51	Hanwell Community Library, Cherington	Hanwell	North Hanwell / Hanwell Broadway	Church Road is a key link north - south route but lacks cycle infrastructure. Removing parking unlikely to be popular with residents																																						
0598			8/4/2023	https://www.google.com/maps/place/51.5185197 35094095%2C-0.334798753566079/@51																																											
0599			8/4/2023	https://www.google.com/maps/place/51.5087987 3335972%2C-0.33582872182779777/@5																																											
0600			8/4/2023	https://www.google.com/maps/place/51.5165969 6528537%2C-0.3368586900895165/@51																																											
0601			8/4/2023	https://www.google.com/maps/place/51.5146207 00619254%2C-0.30450052053385246/@5																																											
0602			8/4/2023	https://www.google.com/maps/place/51.5214355 78725686%2C-0.3376955789283853/@51																																											
0603			8/4/2023	https://www.google.com/maps/place/51.5084027 1722365%2C-0.33580730378190093/@5																																											
0604			8/4/2023	https://www.google.com/maps/place/51.5214889 844201%2C-0.33760974823990875/@5																																											
0605			8/4/2023	https://www.google.com/maps/place/51.5155071 5733545%2C-0.30284831940690093/@5																																											
0606			8/4/2023	https://www.google.com/maps/place/51.5237879 0717328%2C-0.3442713518821394/@51																																											
0607			8/4/2023	https://www.google.com/maps/place/51.5098471 9941005%2C-0.3353449602805769/@51																																											
0608			8/4/2023	https://www.google.com/maps/place/51.5239477 1579397%2C-0.3319919306866286/@5																																											
0609			8/4/2023	https://www.google.com/maps/place/51.5140137 1540603%2C-0.3040167589866316/@51																																											
0610			8/4/2023	https://www.google.com/maps/place/51.5216513 38369715%2C-0.3438043797881063/@51																																											
0611			8/4/2023	https://www.google.com/maps/place/51.5090993 22868614%2C-0.33590795644826255/@5																																											
0612			8/4/2023	https://www.google.com/maps/place/51.5217047 4381108%2C-0.3432893956572469/@51																																											

0702	Connect Boston Manor Rd safely to the Mattock Lane cycleway	1	10/4/2023	https://www.google.com/maps/place/51.50089833582802%2C-0.32845412546564257/@5	14 Cantley Rd, London, W7 2BQ	Hanwell	Hanwell Broadway / Walpole /	Only existing route is C41 to the north of this area, a central route and southern route as well as North - South would all be helpful	1			1			1	1								1			1																				
0703	Provide a safe route for children living in the heavily populated streets between Boston Manor Rd and Northfields Av to get across Northfields rd and safely into Ealing. The LTNS did this brilliantly and their removal has been a real blight especially since	1	10/4/2023	https://www.google.com/maps/place/51.50892591149576%2C-0.31259296456451535/@5	17 Culmington Rd, London,	Hanwell	Hanwell Broadway / Walpole /	Only existing route is C41 to the north of this area, a central route and southern route as well as North - South would all be helpful	1			1			1	1								1			1												1								
0704	Cycle route designated for cyclists only up Northfield avenue ie protected from traffic	1	10/4/2023	https://www.google.com/maps/place/51.498771373905726%2C-0.31010531741751945/@5	267B Northfield Ave, London,	Northfield	Northfield / Walpole	No cycle infrastructure on Northfield	1			1			1	1								1		1																					
0705			10/4/2023	https://www.google.com/maps/place/51.51108554694294%2C-0.31889683535266666/@5																																										
0706			10/4/2023	https://www.google.com/maps/place/51.51277430867019%2C-0.34240399269410027/@5																																										
0707			10/4/2023	https://www.google.com/maps/place/51.51150931097325%2C-0.30923460972841044/@5																																										
0708	Along Northfields avenue	1	10/4/2023	https://www.google.com/maps/place/51.49650613270849%2C-0.3151288543982167/@51	291 Northfield Ave, London,	Northfield	Northfield / Walpole	No cycle infrastructure on Northfield	1			1			1	1								1																							
0709			10/4/2023	https://www.google.com/maps/place/51.51018819322766%2C-0.3189732354254948/@51																																										
0710			10/4/2023	https://www.google.com/maps/place/51.51023499098177%2C-0.35446980934215055/@5																																										
0711			10/4/2023	https://www.google.com/maps/place/51.49688913673079%2C-0.3411790853244656/@51																																										
0712			10/4/2023	https://www.google.com/maps/place/51.49551075615834%2C-0.2670654506146586/@51																																										
0713			10/4/2023	https://www.google.com/maps/place/51.50443371515151%2C-0.28036920732852577/@5																																										
0714			10/4/2023	https://www.google.com/maps/place/51.51900298364521%2C-0.33605099112566483/@5																																										
0715			10/4/2023	https://www.google.com/maps/place/51.51651712820039%2C-0.3039744020189783/@51																																										
0716			10/4/2023	https://www.google.com/maps/place/51.52788201362687%2C-0.30899741215674625/@5																																										
0717			10/4/2023	https://www.google.com/maps/place/51.513676346482995%2C-0.3197956483832498/@51																																										
0718			10/4/2023	https://www.google.com/maps/place/51.49738744413304%2C-0.31265265540826315/@5																																										
0719			10/4/2023	https://www.google.com/maps/place/51.506873831753374%2C-0.305155045668144/@51.																																										
0720			10/4/2023	https://www.google.com/maps/place/51.50699414764636%2C-0.24539258356124583/@5																																										
0721			10/4/2023	https://www.google.com/maps/place/51.509654239254004%2C-0.32965318622254713/@5																																										
0722			10/4/2023	https://www.google.com/maps/place/51.50707280218011%2C-0.24724423181275323/@5																																										
0723			10/4/2023	https://www.google.com/maps/place/51.50723092192649%2C-0.3272061398164605/@51																																										
0724			10/4/2023	https://www.google.com/maps/place/51.53598633763304%2C-0.32446199818890964/@5																																										
0725			10/4/2023	https://www.google.com/maps/place/51.52859352060628%2C-0.30512251143877345/@5																																										
0726			10/4/2023	https://www.google.com/maps/place/51.51447277169262%2C-0.30218163582214297/@5																																										
0727			10/4/2023	https://www.google.com/maps/place/51.51329765093953%2C-0.3236393079412836/@51																																										
0728			10/4/2023	https://www.google.com/maps/place/51.506994213173016%2C-0.2481083020819086/@51																																										
0729			10/4/2023	https://www.google.com/maps/place/51.4932124939018%2C-0.3110340163090686/@51																																										
0730			10/4/2023	https://www.google.com/maps/place/51.51464762087889%2C-0.3037012658090088/@51																																										
0731			10/4/2023	https://www.google.com/maps/place/51.53991003577784%2C-0.34892869873017984/@5																																										
0732			10/4/2023	https://www.google.com/maps/place/51.49761448940025%2C-0.2606043250267853/@51																																										
0733			10/4/2023	https://www.google.com/maps/place/51.49846941988613%2C-0.32409832897842383/@5																																										
0734			10/4/2023	https://www.google.com/maps/place/51.54288353565016%2C-0.348140319272503/@51.																																										
0735			10/4/2023	https://www.google.com/maps/place/51.51005276245673%2C-0.31921470328410306/@5																																										
0736			10/4/2023	https://www.google.com/maps/place/51.499954938724656%2C-0.30822837515910306/@5																																										
0737			10/4/2023	https://www.google.com/maps/place/51.529225673985025%2C-0.32539451285441556/@5																																										
0738			10/4/2023	https://www.google.com/maps/place/51.51343543667901%2C-0.31984666641275084/@5																																										
0739			10/4/2023	https://www.google.com/maps/place/51.51525727476021%2C-0.31930175031306796/@5																																										
0740			10/4/2023	https://www.google.com/maps/place/51.495808383835055%2C-0.30824586301498647/@5																																										
0741			10/4/2023	https://www.google.com/maps/place/51.50689298047029%2C-0.319580258529677/@51.																																										
0742			10/4/2023	https://www.google.com/maps/place/51.498007796288114%2C-0.3102691611466435/@51																																										
0743			10/4/2023	https://www.google.com/maps/place/51.51508399707003%2C-0.33362773206069507/@5																																										
0744			10/4/2023	https://www.google.com/maps/place/51.51396783394359%2C-0.30219335406857617/@5																																										
0745			10/4/2023	https://www.google.com/maps/place/51.528862812357715%2C-0.3518779492242219/@51																																										
0746			10/4/2023	https://www.google.com/maps/place/51.53615995163518%2C-0.34720982227786745/@5																																										
0747			10/4/2023	https://www.google.com/maps/place/51.53238478367951%2C-0.3495350232009109/@51																																										
0748			10/4/2023	https://www.google.com/maps/place/51.53535399619377%2C-0.3470200403404622/@51																																										
0749			10/4/2023	https://www.google.com/maps/place/51.51150316806348%2C-0.3191229601585066/@51																																										
0750			10/4/2023	https://www.google.com/maps/place/51.50958010205453%2C-0.2504584093772566/@51																																										
0751			10/4/2023	https://www.google.com/maps/place/51.49832720357726%2C-0.3283712168418562/@51																																										
0752	My cycle to work cuts mostly down back roads but I don't feel safe because so many car drivers are dangerous around cyclists	1	10/4/2023	https://www.google.com/maps/place/51.50175695393422%2C-0.3069293806187301/@51	72B S Ealing Rd, London, W5 4QB	South Ealing	Northfield	Poor driver behaviour				1																					1														
0753	HANWELL TO EALING	1	10/4/2023	https://www.google.com/maps/place/51.509995898063494%2C-0.33875398021527836/@5	6 Springfield Rd, London,	Ealing	Hanwell Broadway / Walpole / Ealing	Essentially Uxbridge Road	1			1	1		1	1			1					1																							
0754			10/4/2023	https://www.google.com/maps/place/51.51456031877188%2C-0.3040704589488885/@51																																										
0755	HANWELL TO BRENTFORD	1	10/4/2023	https://www.google.com/maps/place/51.50852416083237%2C-0.33926104122427914/@5	Easton Lodge, George St, London,	Boston Manor	Hanwell Brodaway / Northfield	Essentially Boston Manor Road	1			1	1		1	1				1																										
0756			10/4/2023	https://www.google.com/maps/place/51.49811406977791%2C-0.25626809814674134/@5																																										
0757	I would love to be able to cycle safely on cycle lanes all the way from home in Hanwell (W7) to Hammersmith Station where I work.	1	10/4/2023	https://www.google.com/maps/place/51.50749249778404%2C-0.33887704144550446/@5	7 Westminster Rd, London,	Boston Manor	Hanwell Brodaway / Northfield	Highlights how key a link this is - the only section missing from this journey is Boston Road north of the station. There is segregated route	1			1	1		1	1				1						1																					
0758			11/4/2023	https://www.google.com/maps/place/51.4991917307908%2C-0.3032223259239375/@51																																										
0759			11/4/2023	https://www.google.com/maps/place/51.51073789000148%2C-0.3196105102072/@51.51																																										
0760			11/4/2023	https://www.google.com/maps/place/51.52808992609191%2C-0.2838650449137359/@51																																										
0761			11/4/2023	https://www.google.com/maps/place/51.52389799627865%2C-0.2645960553507476/@51																																										
0762			11/4/2023	https://www.google.com/maps/place/51.52561427808853%2C-0.2924887155753231/@51																																										
0763			11/4/2023	https://www.google.com/maps/place/51.52561427808853%2C-0.3239885782462215/@51																																										
0764			11/4/2023	https://www.google.com/maps/place/51.51472420297575%2C-0.2502701784990724/@51																																										
0765			11/4/2023	https://www.google.com/maps/place/51.507673062647655%2C-0.2457211520098146/@51																																										
0766	From South Ealing	1	11/4/2023	https://www.google.com/maps/place/51.49713162852771%2C-0.30642001826397536/@5	2 Lawrence Rd, London,	South Ealing	Northfield / Ealing Common	No cycle infrastructure on South Ealing Road	1			1			1	1								1																							
0767	Ealing Broadway Station. There is currently limited cycle accessability to the station as the gyratory is full of cars and parked cars. The last leg of the journey is often difficult and dangerous as a result. If there was better quality cycling infrastructure leading to	1	11/4/2023	https://www.google.com/maps/place/51.51582976979018%2C-0.3026434679710066/@51	Ealing Broadway Station, The	Ealing Broadway	Ealing Broadway	Ealing Broadway hotspot	1			1	1		1	1								1																							
0768	From Ealing Broadway	1	11/4/2023	https://www.google.com/maps/place/51.51438761487452%2C-0.30478923518292067/@5	Haven House, 9 Spring Bridge Rd,	Ealing Broadway	Ealing Broadway	Ealing Broadway hotspot	1			1	1		1	1								1																							
0769	Major route along Uxbridge Road is not safe and the cycle lanes are currently not up to standard. This should be a high quality, separated, safe cycle route for those who live in Ealing to go to Central London,. See for example Cycleway 9 in	1	11/4/2023	https://www.google.com/maps/place/51.507977485037664%2C-0.24599521357647536/@5	8 The Vale, London, W3 7SB			Uxbridge Road throughout Ealing	1			1			1	1										1																					
0770			11/4/2023	https://www.google.com/maps/place/51.50300901403171%2C-0.31491725642315505/@5																																										
0771	Problem - you cannot drag start and finish!!	1	11/4/2023	https://www.google.com/maps/place/51.50789025830705%2C-0.27168536859721204/@5	St Marys Church Hall, 1 The Mount,			Survey issue																																						1
0772	Home to Acton Pool	1	11/4/2023	https://www.google.com/maps/place/51.49805628232904%2C-0.31060958582133313/@5	64 Little Ealing Ln, London, W5 4EH	Popes Lane	Northfield / Ealing Common / South	Generally no / poor cycle infrastructure Popes / Gunnersbury Lane	1			1			1	1								1																							
0773			11/4/2023	https://www.google.com/maps/place/51.511351709597626%2C-0.3755525875235377/@51																																										
0774			11/4/2023	https://www.google.com/maps/place/51.50546089990636%2C-0.376242898864827/@51.																																										
0775			11/4/2023	https://www.google.com/maps/place/51.5041189906431%2C-0.37578155891426546/@5																																										
0776			11/4/2023	https://www.google.com/maps/place/51.51702846455925%2C-0.3819972611277156/@51																																										
0777			11/4/2023	https://www.google.com/maps/place/51.511362341034456%2C-0.35961156096943947/@5																																										
0778			11/4/2023	https://www.google.com/maps/place/51.51136234103441%2C-0.3791809579420957/@51																																										
0779			12/4/2023	https://www.google.com/maps/place/51.50439568200845%2C-0.31815428630875386/@5																																										
0780			12/4/2023	https://www.google.com/maps/place/51.51806274636792%2C-0.3657207806523566/@51																																										
0781			12/4/2023	https://www.google.com/maps/place/51.50986580572702%2C-0.3558125011921942/@51																																										
0782			12/4/2023	https://www.google.com/maps/place/51.51461987471114%2C-0.3008379452229559/@51																																										
0783			12/4/2023	https://www.google.com/maps/place/51.519747490223544%2C-0.3549114874268966/@51																																										
0784			12/4/2023	https://www.google.com/maps/place/51.55642380537398%2C-0.33607165130629113/@5																																										
0785			12/4/2023	https://www.google.com/maps/place/51.51438761487455%2C-0.3472754259788191/@51																																										
0786			12/4/2023	https://www.google.com/maps/place/51.51695141426875%2C-0.31877963740460036/@5																																										
0787			13/4/2023	https://www.google.com/maps/place/51.52255922235522%2C-0.3269335528098738/@51																																										
0788			13/4/2023	https://www.google.com/maps/place/51.50888564160184%2C-0.33714740473858473/@5																																										
0789			13/4/2023	https://www.google.com/maps/place/51.52299219953249%2C-0.32727687556378005/@5																																										
0790			13/4/2023	https://www.google.com/maps/place/51.51482466722909%2C-0.30263536733946106/@5																																										

1146	The ride to and from Ada Lovelace - is generally OK but become dangerous on Hillcrest Road recently with rat run traffic and no priority for school kids on bikes - Mount Avenue also does not cater well for bicyclists either	1	16/5/2023	https://www.google.com/maps/place/51.5268563 7099093%2C-0.31668771668816875/@5	33 Curzon Rd, London, W5 1NE	Montpelier	Hanger Hill	General lack of east - west connections in Montpelier. Hillcrest Road / Mount Avenue are part designated but also a rat run	1			1			1	1								1	1		1									1											
1147	Blondin Park is one of the few relaxing moments in many people's bike rides. The new in-path lights are fantastic, but we need more of them by the allotments.	1	16/5/2023	https://www.google.com/maps/place/51.4979331 3481905%2C-0.31629054743878005/@5	42 Blondin Ave, London, W5 4UP	Boston Manor / Northfield	Northfield	Unable to verify remotely but seems straight forward	1			1		1								1																									
1148	The trip to West Ealing Station ought to be a red carpet for bicycles, but instead it's a nightmare of riding through rat-run neighbourhoods that were formerly pleasant due to LTNs, or B roads like Northfield Avenue that people treat like A roads. And there are	1	16/5/2023	https://www.google.com/maps/place/51.5147615 1127402%2C-0.321011235304991/@51.	21 Argyle Rd, London, W13 0LW	West Ealing	Hanwell Broadway / Pitshanger	Agreed - lack of north - south connections across Uxbridge Road Ealing and the main line.	1			1	1		1	1			1					1					1							1			1								
1149			16/5/2023	https://www.google.com/maps/place/51.5530386 78245194%2C-0.37593929375447477/@5																																										
1150			16/5/2023	https://www.google.com/maps/place/51.5051390 8068738%2C-0.2526956174701378/@51																																										
1151			16/5/2023	https://www.google.com/maps/place/51.5192607 6364077%2C-0.2914793492023593/@51																																										
1152			16/5/2023	https://www.google.com/maps/place/51.5219091 49306275%2C-0.26521515852853117/@5																																										
1153			17/5/2023	https://www.google.com/maps/place/51.5176017 64066214%2C-0.2915178111144945/@51																																										
1154			17/5/2023	https://www.google.com/maps/place/51.5181892 7271423%2C-0.28035982161254136/@5																																										
1155			17/5/2023	https://www.google.com/maps/place/51.5168958 6396542%2C-0.29119547454194095/@5																																										
1156			17/5/2023	https://www.google.com/maps/place/51.5173765 6087289%2C-0.2807241305478003/@51																																										
1157			17/5/2023	https://www.google.com/maps/place/51.5000003 1707828%2C-0.30045596448527556/@5																																										
1158			17/5/2023	https://www.google.com/maps/place/51.5029656 3330555%2C-0.2806719907914279/@51																																										
1159			17/5/2023	https://www.google.com/maps/place/51.4968953 13244686%2C-0.30189597352188846/@5																																										
1160			17/5/2023	https://www.google.com/maps/place/51.5175964 7904216%2C-0.30146682007950565/@5																																										
1161			17/5/2023	https://www.google.com/maps/place/51.4952113 19453254%2C-0.30792035851447297/@5																																										
1162			17/5/2023	https://www.google.com/maps/place/51.4992411 9285864%2C-0.3079530256724117/@51																																										
1163			17/5/2023	https://www.google.com/maps/place/51.4975056 6655099%2C-0.3145739336692488/@51																																										
1164			17/5/2023	https://www.google.com/maps/place/51.5121457 55005655%2C-0.3172364795445848/@51																																										
1165			17/5/2023	https://www.google.com/maps/place/51.4994308 25605934%2C-0.3055635059117723/@51																																										
1166			17/5/2023	https://www.google.com/maps/place/51.5112910 81078944%2C-0.30539184453481916/@5																																										
1167			17/5/2023	https://www.google.com/maps/place/51.4952826 74249424%2C-0.3084419488846879/@51																																										
1168			17/5/2023	https://www.google.com/maps/place/51.5061153 052828%2C-0.31123153278754145/@5																																										
1169			17/5/2023	https://www.google.com/maps/place/51.5057917 4615551%2C-0.3081286516713755/@51																																										
1170			17/5/2023	https://www.google.com/maps/place/51.5151479 5562434%2C-0.30235644283886476/@5																																										
1171			17/5/2023	https://www.google.com/maps/place/51.4985342 7100734%2C-0.3087080088185923/@51																																										
1172			17/5/2023	https://www.google.com/maps/place/51.5154286 0748578%2C-0.30238165555507956/@5																																										
1173			17/5/2023	https://www.google.com/maps/place/51.5057045 4468919%2C-0.30814407813791966/@5																																										
1174			17/5/2023	https://www.google.com/maps/place/51.5154801 1930886%2C-0.30295132148508763/@5																																										
1175			17/5/2023	https://www.google.com/maps/place/51.4991471 8187171%2C-0.3088637072704836/@51																																										
1176			17/5/2023	https://www.google.com/maps/place/51.4974640 47214415%2C-0.3169895452235938/@51																																										
1177			17/5/2023	https://www.google.com/maps/place/51.4999797 4899213%2C-0.306246310618028/@51.																																										
1178			17/5/2023	https://www.google.com/maps/place/51.5104504 9912226%2C-0.30521634235630923/@5																																										
1179			17/5/2023	https://www.google.com/maps/place/51.4971664 7225379%2C-0.2732486863765615/@51																																										
1180			17/5/2023	https://www.google.com/maps/place/51.5053286 3333951%2C-0.29415923655924603/@5																																										
1181			17/5/2023	https://www.google.com/maps/place/51.4983682 8180466%2C-0.30863090703999063/@5																																										
1182			17/5/2023	https://www.google.com/maps/place/51.5000570 5832741%2C-0.30399530131451247/@5																																										
1183	Holies road, hpme	1	17/5/2023	https://www.google.com/maps/place/51.4960987 8928943%2C-0.3136976517100143/@51	10 Hollies Rd, London, W5 4UU	Northfield / West Ealing	Northfield / Walpole / Hanwell Broadway	Believed to be connected to below - mainly a lack of infrastructure on Northfield + Deans Garden hotspot	1			1	1		1	1			1					1					1																		
1184	Commute to cross rail	1	17/5/2023	https://www.google.com/maps/place/51.5144894 686349%2C-0.32011353822216204/@5	15A The Avenue, London, W13 8JB	Northfield / West Ealing	Northfield / Walpole / Hanwell Broadway	As above																																						
1185			17/5/2023	https://www.google.com/maps/place/51.4971026 848643%2C-0.31242816645733473/@5																																										
1186			17/5/2023	https://www.google.com/maps/place/51.5108866 38263486%2C-0.31929462153545973/@5																																										
1187			17/5/2023	https://www.google.com/maps/place/51.5020444 2346052%2C-0.3076865527721262/@51																																										
1188			17/5/2023	https://www.google.com/maps/place/51.4973424 7617301%2C-0.30528329349478245/@5																																										
1189			17/5/2023	https://www.google.com/maps/place/51.5055836 01511354%2C-0.3024912780377509/@51																																										
1190			17/5/2023	https://www.google.com/maps/place/51.5166763 9701835%2C-0.34048882035136563/@5																																										
1191			17/5/2023	https://www.google.com/maps/place/51.5145398 9464445%2C-0.31964256007340097/@5																																										
1192			17/5/2023	https://www.google.com/maps/place/51.5170874 5430573%2C-0.30233463468142485/@5																																										
1193			17/5/2023	https://www.google.com/maps/place/51.5042123 4657137%2C-0.3266929666279972/@51																																										
1194			17/5/2023	https://www.google.com/maps/place/51.4997518 9462882%2C-0.3087456364277208/@51																																										
1195			17/5/2023	https://www.google.com/maps/place/51.4993109 21367275%2C-0.30591322370799423/@5																																										
1196			17/5/2023	https://www.google.com/maps/place/51.5008589 4313522%2C-0.3155335436020845/@51																																										
1197	There are nowhere near enough cycle bike storage racks outside of Little Ealing primary school, only 3 for a whole school that I can see, others nearby are too far from the school for my child to keep her bike and we had a bike stolen during school hours recently while	1	17/5/2023	https://www.google.com/maps/place/51.5017953 2882368%2C-0.31009648255030164/@5	Little Ealing Primary School,	Northfield	Northfield	Unable to establish level of cycle parking within the school site. Minimal on street short stay sheffield stands - visirail use likely if	1			1		1		1															1															
1198	I leave home with my children on bikes to get to little ealing primary school, the residential streets are always blocked with motor vehicles in the mornings, if there were a few safe cycle routes through the northfields to hanwell block Shen we would feel a lot	1	17/5/2023	https://www.google.com/maps/place/51.5059066 2581769%2C-0.32918039752491524/@5	112 Oaklands Rd, London,	Northfield / Hanwell	Hanwell Broadway / Walpole /	No designated routes through this area and north - south lacking	1			1			1	1								1																							
1199	There are too few bike racks outside if little ealing school for all the children's bikes, especially if you approach from the North of the school	1	17/5/2023	https://www.google.com/maps/place/51.4990672 40254725%2C-0.3086814392767856/@51	Little Ealing Primary School,	Northfield	Northfield	Unable to establish level of cycle parking within the school site. Minimal on street short stay sheffield stands - Visirail use likely	1			1		1		1															1															
1200	There is no obvious cycle path when travelling on the road to the north of gunnersbury park from west to east or east to west, it is very busy with motor vehicles at rush hour times	1	17/5/2023	https://www.google.com/maps/place/51.5015702 99211856%2C-0.2854633385101679/@51	5 Park Parade, London, W3 9BD	Gunnersbury Park	Ealing Common	Popes / Gunnersbury Lanes lack of cycle infrastructure and hotspot junction with A406	1			1	1		1	1								1					1																		
1201			17/5/2023	https://www.google.com/maps/place/51.4976913 20776376%2C-0.3128911435027759/@51																																										
1202			17/5/2023	https://www.google.com/maps/place/51.5120755 3063513%2C-0.30579256717253145/@5																																										
1203			17/5/2023	https://www.google.com/maps/place/51.5039071 45717115%2C-0.33265909500548974/@5																																										
1204			17/5/2023	https://www.google.com/maps/place/51.4989154 79743026%2C-0.3088781692758169/@51																																										
1205			17/5/2023	https://www.google.com/maps/place/51.4987449 0403493%2C-0.3131744702766981/@51																																										
1206	To Waitrose	1	17/5/2023	https://www.google.com/maps/place/51.5156798 0580978%2C-0.3223583539436903/@51	2A Drayton Rd, London W13 0LD			Lack of cycle infrastructure on Drayton Green Road adjacent to West Ealing station	1						1	1								1																							
1207			17/5/2023	https://www.google.com/maps/place/51.4970221 52373056%2C-0.263823466757267/@51.																																										
1208	This is a main route it should be better serviced for bike use	1	17/5/2023	https://www.google.com/maps/place/51.5074940 8195482%2C-0.26828666255804823/@5	82a High St, London, W3 6QX	Acton	South Acton	Assumed to be Uxbridge Road but no clear action											1																												
1209			17/5/2023	https://www.google.com/maps/place/51.5117018 0905758%2C-0.30533613078636446/@5																																										
1210			17/5/2023	https://www.google.com/maps/place/51.5056123 1194494%2C-0.3061944376711301/@51																																										
1211			17/5/2023	https://www.google.com/maps/place/51.5065962 69800475%2C-0.2902408303349957/@51																																										
1212			17/5/2023	https://www.google.com/maps/place/51.4970859 6100473%2C-0.31573254481253477/@5																																										
1213			17/5/2023	https://www.google.com/maps/place/51.4936858 5237755%2C-0.3098423276125062/@51																																										
1214			17/5/2023	https://www.google.com/maps/place/51.4982951 4502731%2C-0.3085642171468428/@51																																										
1215			17/5/2023	https://www.google.com/maps/place/51.4937012 5951918%2C-0.31034289788953506/@5																																										
1216			17/5/2023	https://www.google.com/maps/place/51.5122588 1609911%2C-0.3049083713913392/@51																																										
		296																																													